E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402A6863:F7009.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

E&A - P2017.483.002

		Bill SID - P201			
Inspector: Bryce Wright		BIII 3ID - P201	7.463.010		Stage
inspector. Bryce wright		Mindo	or West		Otage
		GRE-201908	12-5114-GP1		1
Project Name:					
For Week Ending:		68136			
Project Location:		180th & Giles Road (SW), Sarpy County, NE		
•	Windsor West	Windsor West APT	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Grading:	90%	10%			
Sanitary Sewer:	75%				
Storm Sewer:	75%				
Paving:	70%				
Seeding:	75%				
Utilities:	60%	0%			
Overall Development:	30%	3%			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time
		•			Week
Sunday:	0.01"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.01"	10/18/2023	Sunny 51	12:25 PM	
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
Complaints:					
1					

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began in drainage area DEV C (7/28/20). Grading began in drainage area DEV C and DEV B (8/3/20). Grading began in DEV A (10/28/20). Grading on site has ceased due to winter conditions (2/9/21). Grading resumed in all drainage areas (4/5/21). Storm and sanitary began installation (7/26/21). Paving began on site (9/21/21). Grading in the southern section began (11/30/21). Grading in southern section resumed (06/01/22). Electric installation began (2/22/23). All grading on site ceased (3/8/23). Sidewalk paving on all interior streets (3/15/23). Storm sewer installation began on the southern section of the site (8/9/23). Windsor West Apartments grading began (10/11/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began in drainage area DEV C (7/28/20). Grading began in drainage area DEV C and DEV B (8/3/20). Grading began in DEV A (10/28/20). Grading on site has ceased due to winter conditions (2/9/21). Grading resumed in all drainage areas (4/5/21). Storm and sanitary began installation (7/26/21). Paving began on site (9/21/21). Grading in the southern section began (11/30/21). Grading in southern section resumed (06/01/22). Electric installation began (2/22/23). All grading on site ceased (3/8/23). Sidewalk paving on all interior streets (3/15/23). Storm sewer installation began on the southern section of the site (8/9/23). Windsor West Apartments grading began (10/11/23).

Existing vegetation (7/28/20). Entire site has volunteer vegetation growing (7/7/21). Seed and matting installed on slope along Meridian Street (12/28/21). Entire site was beginning to be seeded (4/6/22). Seed and mat around all installed sidewalks on site (3/29/23). Entire site was seeded (6/7/23). Basins seeded and matted (10/4/23).

Checklist Questions:

ent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? No

No, See BMP section

N/A

No
Create Corrective Action?
No, See BMP section
Are construction entrances and adjacent streets being maintained adequately?
No
Create Corrective Action?
No, See BMP section
Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A
Comments:
Comments:

Site was active for home construction and Lot 1 apartment building grading during the current inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) Some maintenance is required in the BMP section of this report.

2) SF-1 for SAR-20200507-5452-GP2 (Giles Road/180th Street Improvements) was installed along Giles Road on the west end of the site prior to the 8/9/21 inspection. The SF will not be included in this report and is part of the road improvement project. The SF has been marked on the SWPPP map to indicate its location within the temporary road project. Also applies to silt fence east of river on north side of Giles Rd and the fuel tank located near CE 1. The fuel tank was removed prior to the inspection on 9/19/22. Silt fence checks were installed as part of the road project along Giles Rd. prior to the inspection on 9/19/22.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	Giles Road (BB3)	-	Removed		
Current Condition:	Removed - Hawkins Construction paved the Construction entrance prior to the inspection on 5/3/23.					
CE 2	Construction Entrance	180th Street (DD9)		Removed		
Current Condition:	Removed - All entrances a	, ,	e of the site as of 5/18/22.	Ttomovou		
CE 3	Construction Entrance	L3		Removed	Т	
Current Condition:			Istruction entrance, graded the		air own eilt fonce pri	
Current Condition.		Construction entrance wi	Il not be recommended to be r			
CE 4	Construction Entrance	Southern section	8/9/2023	Active	No	
Current Condition:	Good Condition - 90% Effe	ective - TAB Construction	installed a rock construction e	entrance prior to the in	spection on 8/9/23	
D 1	Diversion	N17-E17	8/14/2020	Active	Yes	
Current Condition:			n prior to the 7/18/22 inspection of the run from sanitary sewe			
		·	ne as of the last inspection.			
D 2	Diversion	N17-U17	8/14/2020	Active	No	
Current Condition:	Good Condition - Gene Gr	aves installed the diversi	on prior to the 7/13/22 inspecti	on.		
D 3	Diversion	West of SB A	1/13/2021	Active	No	
Current Condition:	4/5/21 inspection, the inspection	ector will monitor as the	the 1/13/21 inspection. JC pa diversion is redefined. JC Excanstalled the diversion prior to the	avation/Gene Graves r	reinstalled the divers	
D 4	Diversion			ie irispection on 10/13	JI ZZ.	
		East of SB A	10/13/2022	Active	No	
Current Condition:	Good Condition - Gene Gr	aves reinstalled the diver	10/13/2022 sion prior to the inspection on Graves reinstalled the diversion	10/13/22. An unknow	n contractor remove	
D 5	Good Condition - Gene Gr diversion prior to the inspe	aves reinstalled the diversition on 11/22/22. Gene West of SB B	sion prior to the inspection on Graves reinstalled the diversion 10/13/2022	10/13/22. An unknow on prior to the inspection	n contractor remove on on 4/5/23.	
D 5 Current Condition:	Good Condition - Gene Gr diversion prior to the inspe Diversion Good Condition - Gene Gr diversion prior to the inspe	aves reinstalled the diversition on 11/22/22. Gene West of SB B aves reinstalled the diversition on 11/22/22. Gene	sion prior to the inspection on Graves reinstalled the diversion	10/13/22. An unknow on prior to the inspection Active 10/13/22. An unknow on prior to the inspection prior to the inspection 10/13/22.	n contractor remove on on 4/5/23. No n contractor remove	
D 5 Current Condition:	Good Condition - Gene Gr diversion prior to the inspe Diversion Good Condition - Gene Gr diversion prior to the inspe	aves reinstalled the diversition on 11/22/22. Gene West of SB B aves reinstalled the diversition on 11/22/22. Gene SW of SB C	sion prior to the inspection on Graves reinstalled the diversion 10/13/2022 sion prior to the inspection on Graves reinstalled the diversion prior to the inspection on Graves reinstalled the diversion 10/13/2021	10/13/22. An unknow on prior to the inspection Active 10/13/22. An unknow	n contractor remove on on 4/5/23. No n contractor remove	
D 5 Current Condition: D 6 Current Condition:	Good Condition - Gene Gr diversion prior to the inspe Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re	west of SB B aves reinstalled the diversition on 11/22/22. Gene West of SB B aves reinstalled the diversition on 11/22/22. Gene SW of SB C emoved from the SWPPF	sion prior to the inspection on Graves reinstalled the diversion 10/13/2022 sion prior to the inspection on	10/13/22. An unknow on prior to the inspection Active 10/13/22. An unknow on prior to the inspection Removed	n contractor remove on on 4/5/23. No n contractor remove	
D 5 Current Condition:	Good Condition - Gene Gr diversion prior to the inspe Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion	west of SB B west of SB B aves reinstalled the diversition on 11/22/22. Gene west of SB B aves reinstalled the diversition on 11/22/22. Gene SW of SB C emoved from the SWPPF S of SB A	sion prior to the inspection on Graves reinstalled the diversion 10/13/2022 sion prior to the inspection on Graves reinstalled the diversion prior to the inspection on Graves reinstalled the diversion 10/13/2021	10/13/22. An unknow on prior to the inspection Active 10/13/22. An unknow on prior to the inspection Removed	n contractor remove on on 4/5/23. No n contractor remove on on 4/5/23.	
D 5 Current Condition: D 6 Current Condition: D 7	Good Condition - Gene Gr diversion prior to the inspe Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving	west of SB B aves reinstalled the diversition on 11/22/22. Gene West of SB B aves reinstalled the diversition on 11/22/22. Gene SW of SB C emoved from the SWPPF S of SB A and the site being vegeta	sion prior to the inspection on Graves reinstalled the diversion 10/13/2022 sion prior to the inspection on Graves reinstalled the diversion on Graves reinstalled the diversion 2 as of the 10/6/2020 revision. Integration of the inspection on Graves reinstalled the diversion is no longer 1/20/2021	10/13/22. An unknow on prior to the inspection Active 10/13/22. An unknow on prior to the inspection Removed	n contractor remove on on 4/5/23. No n contractor remove on on 4/5/23.	
D 5 Current Condition: D 6 Current Condition: D 7 Current Condition:	Good Condition - Gene Gr diversion prior to the inspe Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving	west of SB B aves reinstalled the diversition on 11/22/22. Gene West of SB B aves reinstalled the diversition on 11/22/22. Gene SW of SB C emoved from the SWPPF S of SB A and the site being vegeta	sion prior to the inspection on Graves reinstalled the diversion 10/13/2022 sion prior to the inspection on Graves reinstalled the diversion on Graves reinstalled the diversion 2 as of the 10/6/2020 revision. Integration of the inspection on Graves reinstalled the diversion is no longer 1/20/2021	10/13/22. An unknow on prior to the inspection of the inspection o	n contractor remove on on 4/5/23. No n contractor remove on on 4/5/23. //26/22 inspection.	
D 5 Current Condition: D 6 Current Condition: D 7 Current Condition: D 8	Good Condition - Gene Gr diversion prior to the inspe Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving	west of SB B aves reinstalled the diversition on 11/22/22. Gene West of SB B aves reinstalled the diversition on 11/22/22. Gene SW of SB C emoved from the SWPPF S of SB A and the site being vegeta	sion prior to the inspection on Graves reinstalled the diversion 10/13/2022 sion prior to the inspection on Graves reinstalled the diversion on Graves reinstalled the diversion 2 as of the 10/6/2020 revision. Integration of the inspection on Graves reinstalled the diversion is no longer 1/20/2021	10/13/22. An unknow on prior to the inspection of the inspection o	n contractor remove on on 4/5/23. No n contractor remove on on 4/5/23. //26/22 inspection.	
D 5 Current Condition: D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition:	Good Condition - Gene Gr diversion prior to the inspe Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving Diversion Good Condition - JC instal Diversion Removed - Due to paving Removed - Due to paving Diversion	west reinstalled the diversition on 11/22/22. Gene West of SB B aves reinstalled the diversition on 11/22/22. Gene SW of SB C emoved from the SWPPF S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta	sion prior to the inspection on Graves reinstalled the diversion 10/13/2022 sion prior to the inspection on Graves reinstalled the diversion on Graves reinstalled the diversion 2 as of the 10/6/2020 revision. Integration of the inspection on Graves reinstalled the diversion is no longer 1/20/2021	10/13/22. An unknow on prior to the inspection prior to the inspection 10/13/22. An unknow on prior to the inspection Removed Removed Recessary as of the 7/	n contractor remove on on 4/5/23. No no contractor remove on on 4/5/23. //26/22 inspection.	
D 5 Current Condition: D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition:	Good Condition - Gene Gr diversion prior to the inspe Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been reduced - D6 has been reduced - Diversion Removed - Due to paving - Diversion Good Condition - JC instalt Diversion Removed - Due to paving - Diversion Removed - Due to paving - Diversion Removed - Due to paving - Diversion	aves reinstalled the diversition on 11/22/22. Gene West of SB B aves reinstalled the diversition on 11/22/22. Gene SW of SB C emoved from the SWPPF S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta	sion prior to the inspection on Graves reinstalled the diversion 10/13/2022 sion prior to the inspection on Graves reinstalled the diversion of Graves reinstalled the diversion of the 10/6/2020 revision. Pas of the 10/6/2020 revision. Intended the diversion is no longer 1/20/2021 the 7/26/22 inspection.	10/13/22. An unknow on prior to the inspection prior to the inspection 10/13/22. An unknow on prior to the inspection Removed Removed Recessary as of the 7/ Removed	n contractor remove on on 4/5/23. No no contractor remove on on 4/5/23. //26/22 inspection.	
D 5 Current Condition: D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition:	Good Condition - Gene Gr diversion prior to the inspe Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been rediversion Removed - Due to paving a Diversion Good Condition - JC instal Diversion Removed - Due to paving a Diversion Removed - Due to paving a Removed - Due to paving a Removed - Due to paving a Removed - D10 has been	aves reinstalled the diversition on 11/22/22. Gene West of SB B aves reinstalled the diversition on 11/22/22. Gene SW of SB C emoved from the SWPPF S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPPF	sion prior to the inspection on Graves reinstalled the diversion 10/13/2022 sion prior to the inspection on Graves reinstalled the diversion of Graves reinstalled the diversion 10/16/2020 revision. The diversion is no longer 1/20/2021 the 7/26/22 inspection.	10/13/22. An unknow on prior to the inspection prior to the inspection 10/13/22. An unknow on prior to the inspection Prior to the inspection Removed Removed Recessary as of the 7/20 Removed Removed Removed Recessary as of the 7/20 Removed Remove	n contractor remove on on 4/5/23. No n contractor remove on on 4/5/23. //26/22 inspection.	
D 5 Current Condition: D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 10 Current Condition: D 11	Good Condition - Gene Gr diversion prior to the inspe Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving Diversion Good Condition - JC instal Diversion Removed - Due to paving Diversion Removed - Due to paving Diversion Removed - Due to paving Diversion Removed - D10 has been Diversion	aves reinstalled the diversition on 11/22/22. Gene West of SB B aves reinstalled the diversition on 11/22/22. Gene SW of SB C emoved from the SWPPF S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C	sion prior to the inspection on Graves reinstalled the diversion 10/13/2022 sion prior to the inspection on Graves reinstalled the diversion on Graves reinstalled the diversion. Pas of the 10/6/2020 revision. 1/20/2021 the 7/26/22 inspection. Little the diversion is no longer in the 10/6/2020 revision. Little the diversion is no longer in the 10/6/2020 revision.	10/13/22. An unknow on prior to the inspection of the inspection o	n contractor remove on on 4/5/23. No n contractor remove on on 4/5/23. //26/22 inspection.	
D 5 Current Condition: D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition:	Good Condition - Gene Gr diversion prior to the inspe Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving Diversion Good Condition - JC instal Diversion Removed - Due to paving Diversion Removed - Due to paving Diversion Removed - Due to paving Diversion Removed - D10 has been Diversion	aves reinstalled the diversition on 11/22/22. Gene West of SB B aves reinstalled the diversition on 11/22/22. Gene SW of SB C emoved from the SWPPF S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C	sion prior to the inspection on Graves reinstalled the diversion 10/13/2022 sion prior to the inspection on Graves reinstalled the diversion of Graves reinstalled the diversion of the 10/6/2020 revision. Pas of the 10/6/2020 revision. Intended the diversion is no longer 1/20/2021 the 7/26/22 inspection.	10/13/22. An unknow on prior to the inspection of the inspection o	n contractor remove on on 4/5/23. No no contractor remove on on 4/5/23. //26/22 inspection.	

ET 1 Current Condition:	Erosion Control Terrace Removed - Due to paving	See SWPPP Map	necessary as of 5/18/22	Removed			
	· •		10003341 y 43 01 0/ 10/22.		1		
ET 2	Erosion Control Terrace	See SWPPP Map	5.5/10/00	Removed			
Current Condition:	Removed - Due to paving	the terrace is no longer r	necessary as of 5/18/22.				
ET 3	Erosion Control Terrace	See SWPPP Map	8/14/2020	Active	No		
Current Condition:	Good Condition - JC instal						
EM 1	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No		
Current Condition:			led within the seeding window				
Current Condition.	Fending - The erosion con	tioi matting will be install	led within the seeding window	wileli lile associaled a	rea reacries illiai graue.		
EM 2	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No		
Current Condition:			led within the seeding window				
			.		· · · · · · · · · · · · · · · · ·		
EM 3	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No		
Current Condition:			led within the seeding window	when the associated a	rea reaches final grade.		
		· ·	•		· ·		
EM 4	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No		
Current Condition:	Pending - The erosion con	trol matting will be install	led within the seeding window	when the associated a	rea reaches final grade.		
EM 5	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No		
Current Condition:	Pending - The erosion con	trol matting will be install	led within the seeding window	when the associated a	rea reaches final grade.		
EM 6	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No		
Current Condition:	Pending - The erosion con	trol matting will be install	led within the seeding window	when the associated a	rea reaches final grade.		
					1		
EM 7	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No		
Current Condition:	Pending - The erosion con	trol matting will be install	led within the seeding window	when the associated a	rea reaches final grade.		
					1		
FT X	Fuel Tank	On Site	8/9/2023	Active	No		
Current Condition:	Good Condition - TAB Cor	istruction installed a dou	ble walled fuel tank on site pric	or to the inspection on	8/9/23.		
FT Y	Fuel Tank	On Site		Removed			
Current Condition:		lled fuel tank was remov	ed from the site prior to the ins	pection on 11/30/21.	•		
		Interior Streets curb	1				
IF 1-32	Inlet Filters	inlets	5/17/2023	Active	No		
Current Condition:	Good Condition - Commer		et filters in all interior street cur	b inlets prior to the ins	pection on 5/17/23. D R		
		•	lots prior to the inspection on 9	•	p		
Lot 14	Individual Lot	Lot 14	9/20/2023	Active	No		
Current Condition:			e lot prior to the inspection on 9				
	· ·	· · · · · · · · · · · · · · · · · · ·	/20/23. D R Horton removed th				
	inspection on 10/4/23. D R	Horton reinstalled wat	tles along the front of the lot	prior to the inspection	on on 10/18/23.		
Lot 15	Individual Lot	Lot 15	9/20/2023	Active	No		
Current Condition:							
Guironi Gondidoni	Good Condition - D R Horton began excavating the lot prior to the inspection on 9/20/23. D R Horton removed the dirt piles from the ROW prior to the inspection on 10/4/23. D R Horton installed wattles along the front of the lot prior to the						
	inspection on 10/18/23.	1113pcction on 10/4/20. B	it florion instance watties a	long the front of the	or prior to the		
	•						
Lot 23	Individual Lot	Lot 23	9/20/2023	Active	No		
Current Condition:			e lot prior to the inspection on				
	from the ROW prior to the	inspection on 10/4/23. D	R Horton installed wattles a	long the front of the	ot prior to the		
	inspection on 10/18/23.						
Lot 25	Individual Lot	Lot 25	8/16/2023	Active	No		
Current Condition:	Good Condition - D R Hort	on began excavating the	lot prior to the inspection on 8	/16/23. A dirt pile was	observed in the ROW		
			led wattles around the perimet				
	R Horton removed the dirt	piles from the ROW prio	r to the inspection on 8/30/23.	D R Horton reposition	ed straw wattles around		
	the lot prior to the inspection			·			
1.100			0/00/0000	Λ - ι'	l N		
Lot 26	Individual Lot	Lot 26	8/23/2023	Active	No		
Current Condition:			lot prior to the inspection on 8				
			3. A dirt pile was observed in t	•	•		
			o the inspection on 8/30/23. D	R Horton repositioned	straw watties around the		
	lot prior to the inspection o	n 9/13/23.					
Lot 27	Individual Lot	Lot 27	8/23/2023	Active	No		
Current Condition:			lot prior to the inspection on 8		talled wattles around the		
			3. A dirt pile was observed in t				
	l,	•	o the inspection on 8/30/23. D	•	•		
	lot prior to the inspection o	•		•			
Lot 29	Individual Lot	Lot 29	8/23/2023	Active	No		
Current Condition:			e lot prior to the inspection on 8				
Canoni Condition.			3. A dirt pile was observed in t				
			o the inspection on 8/30/23. D	•	· · · · · · · · · · · · · · · · · · ·		
	The state of the s		epositioned the straw wattle				
	inspection on 10/18/23.	II or forzo. D K HURUII I	opositioned the straw wattle	along the front of th	io lot prior to tile		
L		1 / 1=	0/00/2020				
		Lot 45	9/20/2023	Active	No		
Lot 45	Individual Lot	201 40	0,20,2020	7101170	140		

Current Condition:	Good Condition - D R Ho from the ROW prior to the inspection on 10/18/23.		R Horton installed wattles		
MS 1	Material Storage	On Site	8/14/2020	Active	No
Current Condition:	Good condition - Sewer pi			!	
PB X	Portable Bathroom	On Site	1/25/2023	Active	No
Current Condition:			toilet on site prior to the 6/8/2		
	portable toilet prior to the i 10/13/21. MBC removed the secured a portable toilet o prior to the 7/13/22 inspec Nelson Construction instal	nspection on 9/8/21. MBC he portable toilet from the n site prior to the inspecti- tion. Cedar Construction lled and secured a portab	C brought a portable toilet on site prior to the inspection or on on 6/29/22. Cedar Construence removed the portable toilet fro le toilet on site prior to the inson of the site prior to the inspension of the site prior to the site prior to the inspension of the site prior to the site prior to the inspension of the site prior to th	site and secured it prior n 10/26/21. Cedar Consuction stood up and sec om the site prior to the i spection on 1/25/23. TA	to the inspection or truction installed and ured the portable toi nspection on 9/19/2
SB A	Sediment Basin	M10	1/20/2021	Active	No
Current Condition:	ceased dewatering prior to inspection on 5/18/22. Ker of the basin prior to the ins	o the inspection on 9/8/21 esten Construction installe spection on 7/26/22. E&A	n and installed the baffle prior. Kersten Construction was in the riser prior to the inspectinspector painted the cleanon aspection on 8/16/23. Kenny	n the process of installin tion on 6/1/22. Hausma ut mark during the 8/10,	g the riser during the n cleaned out a port /22 inspection. Kenr
SB B	Sediment Basin	V7	10/28/2020	Active	Yes
Current Condition:	mark during the 11/4/20 in will be made at this time a inspection. JC repaired the basin during the inspectior inspector repainted the cle The baffle needs to be ins JC Excavation/Gene Grave Graves were reminded on	aspection. JC Excavation and the E&A inspector will be erosion around the riser on 4/6/22. CDS Enterprise anout mark on the riser of talled per the SWPPP. The swere informed to complete 3/26/21, 4/16/21, 5/20/21	prior to the 10/28/20 inspectic is doing work on the riser dur continue to monitor. JC bac prior to the inspection on 9/1 ise completed cleanout of the luring the 8/10/22 inspection.	ing the 7/20/21 inspecti kfilled around the riser p 5/21. CDS Enterprise be basin prior to the inspe- s of the last inspection.	on. No recommenda prior to the 8/2/21 legan cleaning out the action on 6/29/22. E&
	2/10/22, 3/31/22, 6/7/22, 1		•	1 10	l N
SB C Current Condition:	Sediment Basin	Z4	10/28/2020 n prior to the 10/28/20 inspect	Active	No
SF 1 Current Condition:	Enterprise was dewatering to the inspection on 6/22/2 cleaned out the basin prior Silt fence	g the basin into silt fence of 22. Kenny Digs Dirt began r to the inspection on 8/30 N side of Site	e began cleaning out the basi during the inspection on 5/10, cleaning out the basin prior 0/23. 10/20/2020 the 10/20/20 inspection. JC E	/22. CDS completed cle to the inspection on 8/1 Active	anout of the basin p 6/23. Kenny Digs Di
	4/19/22. Great Plains reins Graves extended the silt for the silt fence prior to the in	stalled, repaired, and exterence from SB B to SB A propertion on 11/22/22. Geing extended the silt fence	onitor. Great Plains installed a ended the silt fence up to SB prior to the 7/13/22 inspection ene Graves reinstalled and re e along the west edge of the s	B prior to the inspection An unknown contractor paired the silt fence prior	on 4/19/22. Gene or removed a portion or to the inspection o
SF 2	Silt fence	West End of Meridian Street	11.5	Removed	
Current Condition:	SF 1.		0/20/20 inspection, silt fence I		
SF 3	Silt fence	N of Giles Road	10/20/2020	Active	No No
Current Condition:		•	the 10/20/20 inspection. Haw		ved a portion of this
			ence prior to the inspection o	·	•
05.4	monitor. Great Plains repa	ired the entire run of silt f	ence prior to the inspection o	n 4/19/22.	or will continue to
SF 4	monitor. Great Plains repa	nired the entire run of silt f	ence prior to the inspection of 1/28/2021	n 4/19/22. Active	or will continue to
SF 4 Current Condition:	monitor. Great Plains repa Silt fence Good Condition - Dave Do fence was backfilled prior recommended on 6/8/21. I silt fence prior to the inspe- end of the dirt piles prior to	ired the entire run of silt f NE Corner Across RR Installed some of the silt to the 3/31/21 inspection. Hawkins Construction renection on 8/17/21. Gene Go the inspection on 4/26/2	ence prior to the inspection o	Active Active Inspection. The under vegetated so silt fence fence, graded the area uce and extended the silly damaged prior to the	No No line de portion of the is no longer and installed their of tence around the vie inspection on
Current Condition:	monitor. Great Plains repa Silt fence Good Condition - Dave Do fence was backfilled prior recommended on 6/8/21. I silt fence prior to the inspe end of the dirt piles prior to 10/18/23. Due to the area	irred the entire run of silt f NE Corner Across RR Installed some of the si to the 3/31/21 inspection. Hawkins Construction reaction on 8/17/21. Gene Go the inspection on 4/26/2 a being vegetated and no	ence prior to the inspection of 1/28/2021 It fence prior to the 1/28/2021 West end of drainage is fully noved the northern run of silt feraves cleaned out the silt fence. The silt fence was partial to construction in the area in 6/13/2022	Active Active Inspection. The under vegetated so silt fence fence, graded the area ce and extended the silly damaged prior to the omaintenance is required. Active	No mined portion of the is no longer and installed their of tence around the view inspection on wired at this time.
Current Condition:	monitor. Great Plains repa Silt fence Good Condition - Dave Do fence was backfilled prior recommended on 6/8/21. I silt fence prior to the inspe end of the dirt piles prior to 10/18/23. Due to the area Silt fence Fair Condition - Gene Gra along all interior street cor Portal street that were rem of silt fence prior to the ins to monitor. Gene Graves r corners prior to the inspec	irred the entire run of silt f NE Corner Across RR Installed some of the si to the 3/31/21 inspection. Hawkins Construction ren ection on 8/17/21. Gene G to the inspection on 4/26/2 Interior streets ves installed silt fence alc mers prior to the inspection onved for utility installation spection on 11/22/22. Rein repaired the silt fence prior tion on 8/9/23.	ence prior to the inspection of 1/28/2021 It fence prior to the 1/28/2021 West end of drainage is fully noved the northern run of silt graves cleaned out the silt fence. 2. The silt fence was partial of construction in the area in the silt fence was partial of the silt fence	Active Active Inspection. The under vegetated so silt fence fence, graded the area, ice and extended the sil Illy damaged prior to the o maintenance is required. Active 3/22 inspection. Gene deinstalled multiple section	No mined portion of the is no longer and installed their of t fence around the vice inspection on uired at this time. Yes Graves installed silt ons of silt fence alor moved multiple section in spector will control in spector will spector will control in spector will specific will be spector will spector will control in spector will spector w

STR	Streets	Giles Road/180th Street	7/28/2020	Active	Yes			
Current Condition:	6/29/22. Street cleaning w	air Condition - No major signs of track off. CDS Enterprise cleaned the streets around SB B and C prior to the inspection on //29/22. Street cleaning was in progress by OPPD during the inspection on 3/1/23. Gene Graves Development cleaned the treet prior to the inspection on 5/3/23. Peter Katt cleaned the streets prior to the inspection on 8/9/23. Mud was observed in the						
	street during the 8/16/23 inspection. Streets were cleaned by Kenny Digs Dirt prior to the inspection on 8/30/23.							
	Streets in front of active lots should be cleaned daily or as needed. D R Horton was informed to complete by 8/31/23. Not done as of the last inspection. D f							
	10/5/23	, , ,	·					
SWPPP Sign	Misc./Other	S 148th Ave & Meridian St.	8/10/2020	Active	No			
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign at Y3 during the 8/10/20 inspection. E&A inspector reinstalled the SWPPP sign during the inspection on 2/22/22. E&A inspector reinstalled the SWPPP sign at S 148th Ave and Meridian St. during the inspection on 10/19/22. E&A inspector reinstalled the SWPPP sign during the inspection on 11/30/22. E&A inspector moved the SWPPP sign to the entrance on 182nd and Giles prior to the inspection on 6/7/23.							
WO 1	Concrete Washout	On Site	3/5/2021	Active	No			
Current Condition:			ashout on site prior to the insp to the inspection on 9/27/23.	ection on 8/30/23. D R	t Horton cleaned up all			
WS1	Waste Storage	On Site	3/5/2021	Pending	No			
Current Condition:	Pending - Waste will be co							
CE 1	Construction Entrance	Windsor West A Cary Street	10/18/2023	Pending	Yes			
Current Condition:	Pending -	Cary Street	10/10/2023	r ending	163			
	A rock construction entran		10/10/20 11 1					
			y 10/18/23. Not done as of the					
CE 2	Construction Entrance	S 183rd Ave	10/18/2023	Pending	Yes			
Current Condition:	Pending - A rock construction entrance should be installed.							
	•		y 10/18/23. Not done as of the	last inspection.				
CE 3 Current Condition:	Construction Entrance Pending -	Meridian Street	10/18/2023	Pending	Yes			
	A rock construction entran		y 10/18/23. Not done as of the	e last inspection.				
EM 1	Erosion Control Matting	See SWPPP Map	12/11/2023	Pending	No			
Current Condition:	Pending - The erosion con	trol matting will be install	ed within the seeding window w	when the associated a	rea reaches final grade.			
FT 1	Fuel Tank	On Site	10/11/2023	Active	Yes			
Current Condition:	A secondary containment	berm should be installed	tel tank on site prior to the inspiration of the fuel tank. y 10/18/23. Not done as of the					
IF 1	Inlet Filter	Southwest corner of	12/11/2023	Pending	No			
		site		9	INO			
Current Condition:	•	North of IF 1	stalled and is at or below grade 12/11/2023		No			
Current Condition:	Inlet Filter Pending - Inlet filter will be		stalled and is at or below grade	Pending e.	No			
IF 3	Inlet Filter	North of IF 2	12/11/2023	Pending	No			
Current Condition:			stalled and is at or below grade		•			
IF 4	Inlet Filter	North of IF 2	12/11/2023	Pending	No			
Current Condition:	<u> </u>		stalled and is at or below grade					
IF 5 Current Condition:	Inlet Filter	East of IF 4	12/11/2023 stalled and is at or below grade	Pending	No			
IF 6	Inlet Filter	South of IF 5	12/11/2023	Pending	No			
Current Condition:			stalled and is at or below grade		140			
IF 7	Inlet Filter	North of IF 3	12/11/2023	Pending	No			
Current Condition:			stalled and is at or below grade					
IF 8	Inlet Filter	North of IF 7	12/11/2023	Pending	No			
Current Condition:			stalled and is at or below grade		I			
IF 9 Current Condition:	<u> </u>		12/11/2023 stalled and is at or below grade		No			
IF 10 Current Condition:	Inlet Filter	East of IF 9	12/11/2023 stalled and is at or below grade	Pending	No			
IF 11	Inlet Filter	South of IF 10	12/11/2023	Pending	No			
	uner i iitei	I COULT OF IT	12/11/2023	ı c ılulliy	I INU			

Current Condition:	Pending - Inlet filter will be installed when inlet is installed and is at or below grade.						
IF 12	Inlet Filter	Middle of the site	12/11/2023	Pending	No		
Current Condition:	Pending - Inlet filter will be installed when inlet is installed and is at or below grade.						
IF 13	Inlet Filter	South of IF 12	12/11/2023	Pending	No		
Current Condition:	Pending - Inlet filter will be	installed when inlet is ins	talled and is at or below grad	le.			
MS 1	Material Storage	On Site	10/11/2023	Active	No		
Current Condition:	Good condition - Storm pip	es being stored on site.		•	•		
PB X	Portable Bathroom	On Site	10/11/2023	Active	No		
Current Condition:	Good Condition - Evergreen Enterprises brought and secured a portable toilet on site prior to the 10/11/23 inspection.						
SF 1	Silt fence	East side of Site	10/18/2023	Pending	Yes		
Current Condition:	Pending - Silt fence should be installed. Evergreen Enterprises was informed to complete by 10/18/23. Not done as of the last inspection.						
SF 2	Silt fence	West side of site	10/18/2023	Pending	Yes		
Current Condition:	Pending -			1			
	•	s informed to complete by	/ 10/18/23. Not done as of t h	· · · · · · · · · · · · · · · · · · ·			
SF 3	Silt fence	North side of site	10/11/2023	Active	No		
Current Condition:	Good Condition - Evergree	n Enterprises installed th	e silt fence prior to the inspec	ction on 10/11/23.			
STR 01	Streets	External and Internal Streets	10/11/2023	Active	Yes		
Current Condition:	Fair Condition - External streets should be cleaned daily or as needed. Evergreen Enterprises was informed to complete by 10/12/23. Not done as of the last inspection.						
WO 1	Concrete Washout	On Site	11/11/2023	Pending	No		
Current Condition:	Pending - Concrete washo	ut will be installed on site	when paving begins.				
WS 1	Waste Storage	On Site	11/11/2023	Pending	No		
Current Condition:	Pending - Waste will be co			1	1		
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."						
Inspector Signature:	Broga M Waght			Reviewed By:	But Sur		