E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



nspector: Alex Brown Project Name: For Week Ending: Project Location: Grading: Sanitary Sewer: Storm Sewer: Paving: Seeding: Jtilities:	98% 90% 90% 75% 0%	Ds Transportat IA - 39 12 h Street and 21st Ave	ion Trucking Termin 1263 - 38898 1/25/2021 nue in Council Bluffs, IA (Po		Stage 1 51501
Project Name: For Week Ending: Project Location: Grading: Sanitary Sewer: Storm Sewer: Paving: Geeding: Jtilities:	98% 90% 90% 75% 0%	IA - 39 12 h Street and 21st Ave	263 - 38898 /25/2021		1
For Week Ending: Project Location: Grading: Ganitary Sewer: Storm Sewer: Paving: Geeding: Jtilities:	98% 90% 90% 75% 0%	IA - 39 12 h Street and 21st Ave	263 - 38898 /25/2021		·
Project Location: Grading: Sanitary Sewer: Storm Sewer: Paving: Seeding: Jtilities:	98% 90% 90% 75% 0%	h Street and 21st Ave		ottawattamie County)	51501
Project Location: Grading: Sanitary Sewer: Storm Sewer: Paving: Seeding: Jtilities:	98% 90% 90% 75% 0%		nue in Council Bluffs, IA (Po	ottawattamie County)	
Sanitary Sewer: Storm Sewer: Paving: Seeding: Jtilities:	90% 90% 75% 0%				
Storm Sewer: Paving: Seeding: Utilities:	90% 75% 0%				
Paving: Seeding: Jtilities:	75% 0%				
Seeding: Jtilities:	0%				
Jtilities:					
	50%				
Overall Development:	40%				
RAIN FALL AMOUNTS An	mount in tenths	Date inspected	Weather Conditions	Time	
					Wee
Sunday 0.	0.00"				
Monday 0.	0.00"				
Tuesday 0.	0.00"	12/21/2021	Partly Cloudy 46/17	11:10 AM	
Wednesday 0.	0.00"				
Thursday 0.	0.00"				
riday 0.	0.00"				
Saturday 0.	0.00"				
Complaints:	lone				
Construction Sequencing:					
Vhich portion(s) (i.e. drainage basins)) of the site have had a temper	orary or permanent cessation	on of grading, earthwork, or groun	d disturbance in the last 14 days?	
Rough grading began on site (6/2 9/21/21). Storm sewer installatio				n site (8/24/21). Paving on so	outhern part of the site
	3 (** **	<i>,</i>	, ,		

Rough grading began on site (6/29/21). Began shaping PCSMP basin (7/20/21). Sanitary installation began on site (8/24/21). Paving on southern part of the site (9/21/21). Storm sewer installation began on site (9/28/21). Grading and sidewalk installation (12/14/21).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (6/29/21).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

Comments:

- 1.) Site was active for building construction during the last inspection.
 2.) Rich Engdahl began shaping the PCSMP basin on the western portion of the site during the inspection on 7/20/21.
 Findings / Corrective Actions (Date):
 Findings / Corrective Actions (Date):
 1.) No maintenance is required in the BMP section.

	1				1	
Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
CE 01	Construction Entrance	J3	r to the increation on 42/	Removed		
Current Condition:			r to the inspection on 12/		1	
CE 02	Construction Entrance	Z7		Removed		
CW 04			rance prior to the inspection		I N-	
CW 01	Concrete Washout	On Site	8/10/2021	Active	No	
Current Condition:	cleaned up the concrete w Rich Engdahl installed a c	raste from around the site a oncrete washout west of th	ary concrete washouts on s and installed a third concret he former CE 01 prior to the aste prior to the inspection	e washout on site prior to a inspection on 10/26/21. R	the inspection on 9/14	
D 01	Diversion Check	Z6 to Z8		Removed		
Current Condition:	Removed - The diversion	check was regraded prior t	to the inspection on 8/10/21			
IP 01	Inlet Protection	F13	8/29/2021	Pending	No	
Current Condition:	Pending - Rich Engdahl i	nstalled the inlet prior to	the inspection on 12/21/2	1. Due to the area being	paved, inlet protecti	
	not recommended at this	s time. E&A inspector wil	I continue to monitor.	·		
IP 02	Inlet Protection	F3	6/29/2021	Active	No	
Current Condition:						
Curront Conditions	Active - This is an existing inlet located off of 21st Avenue. Due to the location of the inlet no BMP recommendation is needed at time. E&A inspector will continue to monitor.					
IP 03	Inlet Protection	F2	6/29/2021	Active	No	
Current Condition:			enue. Due to the location of			
	time. E&A inspector will co					
IP 04	Inlet Protection	M4	8/29/2021	Pending	No	
Current Condition:			inspection on 10/26/21. Du			
Carrone Containon.		. E&A inspector will continu		20 to 110 at oa 2011.9 paroa	,,or p. otootio 10 110	
ID OF		<u>'</u>		A =45:	l NI-	
IP 05	Inlet Protection	P3	6/29/2021	Active	No	
Current Condition:	"		renue. Due to the location o	of the inlet no BIMP recomm	nendation is needed a	
	time. E&A inspector will co				1	
IP 06	Inlet Protection	P2	6/29/2021	Active	No	
Current Condition:	time. E&A inspector will co	ontinue to monitor.	renue. Due to the location of			
IP 07	Inlet Protection	Q4	10/5/2021	Pending	No No	
Current Condition:	recommended at this time	. E&A inspector will continu				
IP 08	Inlet Protection	U4	10/5/2021	Active	No	
Current Condition:			inlet protection prior to the			
IP 09	Inlet Protection	X3	6/29/2021	Active	No No	
Current Condition:	1		enue. Due to the location of	of the inlet no BIMP recomm	nendation is needed a	
ID 40	time. E&A inspector will co		0/00/0004	A =45:	l N-	
IP 10	Inlet Protection	X2	6/29/2021	Active	No No	
Current Condition:	Active - This is an existing inlet located off of 21st Avenue. Due to the location of the inlet no BMP recommendation is needed at					
IP 11	time. E&A inspector will co	Y6	10/5/2021	Active	No.	
	Inlet Protection		inlet protection prior to the		No	
Current Condition: IP 12		ydani installed the inlet and Y7	10/5/2021	Pending	No	
Current Condition:	Inlet Protection					
ourient condition:	Pending - Rich Engdahl installed the inlet and inlet protection prior to the inspection on 10/05/21. Rich Engdahl rem protection prior to the inspection on 11/23/21. Due to the area being paved, reinstallation is not recommended at th inspector will continue to monitor.					
IP 13	Inlet Protection	Y8	10/5/2021	Pending	No	
Current Condition:			rotection prior to the inspec			
- Little Collabor.						
	protection prior to the inspection on 11/23/21. Due to the area being paved, reinstallation is not recommended at this time. E&A inspector will continue to monitor.					
IP 14	Inlet Protection	Y11	10/5/2021	Activo	N ₁	
			inlet protection prior to the	Active	No	
Current Condition:					No	
PB 01	Portable toilet	On Site	7/6/2021	Active	No No 7/6/21 Pich Eng	
Current Condition:	Good Condition - Rich Engdahl installed/secured a portable toilet adjacent to CE 01 prior to the inspection on 7/6/21. Rich Engdah					
	relocated the portable toilet just south of CE 2 prior to the inspection on 11/23/21. Rich Engdahl secured the portable toilet put to the inspection on 12/21/21. Rich Engdahl informed the inspector that position and storage capacity of the portable to preclude leakage into nearby inlets. Therefore, the recommendation to relocate has been removed. E&A inspector will					
	continue to monitor.	,				
SF 01 - SF 06	Silt Fence	G3 to B15		Removed		
Current Condition:			of SF 3-6 on 9/23/21. SF 3		r to the inspection on	
	10/05/21. Rich Engdahl re approved silt fence remove	moved the remaining secti	on of SF 6 prior to the inspinstallation. Rich Engdahl r	ection on 11/30/21. As of 1	11/30/21, the City has	
	12/14/21.					
SF 07 - SF 12	Silt Fence	B16 to P12	6/29/2021	Active	No	

Current Condition:	Good Condition - Rich En	gdahl installed SF 07 to SF	12 prior to the inspection	on 6/29/21. Rich Engdahl v	was observed actively			
	working in the area where	SF 12 was damaged during	g the 9/14/21 inspection. E	&A inspector will continue	to monitor. Rich Engdahl			
	reinstalled/repaired SF 11	where damaged by utility w	ork prior to the inspection	on 9/14/21. Minor damage	was observed to SF 7			
	south of the PCSMP basin prior to the inspection on 10/05/21. E&A inspector will monitor and make recommendations as necessary. Rich Engdahl informed the E&A inspector that equipment and space constraints prevent SF 12 from being repaired.							
	to these constraints and completion of paving in the area, the recommendation has been modified, but the same reminder dates							
	apply. As of 11/30/21, the City has approved silt fence removal in this area. Rich Engdahl removed a majority of SF 7 - 12 prior to							
		E&A inspector will continue						
SF 13 - SF 17	Silt Fence	S12 to Z5	6/29/2021	Active	No			
Current Condition:	Good Condition - Rich En	gdahl installed SF 13 to SF	17 prior to the inspection	on 6/29/21. Rich Engdahl i	informed the E&A			
	inspector that equipment and space constraints prevent SF 13 / SF 14 from being repaired. Due to these constraints and composition of paving in the area, the recommendation has been modified, but the same reminder dates apply. A small section of SF 16 sc CE 2 was removed during sewer installation prior to the inspection on 11/8/21. Due to active work in the area, reinstallation is recommended at this time. E&A inspector will continue to monitor. As of 11/30/21, the City has approved silt fence removal in							
	area. Rich Engdahl remov	ed SF 13 and SF 14 prior to	o the inspection on 12/7/21	<u>.</u>				
SF 18 - SF 22	Silt Fence	Z3 to K3	6/29/2021	Active	No			
Current Condition:	Good Condition - Rich En	gdahl installed SF 18 to SF	22 prior to the inspection	on 6/29/21. Rich Engdahl ı	reinstalled/repaired the silt			
	fence where damaged by utility work prior to the inspection on 9/14/21. Rich Engdahl removed a small portion of SF 18 prior to the							
	inspection on 10/19/21. Ri	ch Engdahl reinstalled the i	removed portion of SF 18 p	prior to the inspection on 1	1/16/21. As of 11/30/21,			
	the City has approved silt	fence removal in this area f	or sprinkler installation. Ric	ch Engdahl removed silt fe	nce posts from SF 18 - 22			
	prior to the inspection on 1	2/14/21. E&A inspector wil	I continue to monitor for re	moval and clean up of silt	fence fragments.			
STR	Streets	On Site	6/29/2021	Active	No			
Current Condition:	Good Condition - Rich Eng	gdahl cleaned up the tracko	out on 21st Ave. prior to the	inspection on 9/7/21. Rich	n Engdahl cleaned up			
	trackout around CE 1 prior	to the inspection on 10/12	/21. Rick Engdahl cleaned	up trackout around CE 02	prior to the inspection on			
	11/2/21. Minor sedimentat	ion was observed around C	E 1 during the 12/14/21 in	spection. Due to active wo	rk on the entrance, street			
	cleaning is not recommend	ded at this time. E&A inspe	ctor will continue to monito	r.				
SWPPP Sign 01	SWPPP Signs	Adjacent to CE 1	8/3/2021	Active	No			
Current Condition:	Good Condition - The E&A	inspector installed the SW	/PPP sign adjacent to CE	01 during the inspection or	า 8/3/21.			
Certification Statement								
accordance with a system designed to assure that qualified personnel properly gathered and evaluated the informa								
	Based on my inquiry of the	person or persons who ma	anage the system or those	persons directly responsib	le for gathering the			
	information, the informatio	n submitted is, to the best of	of my knowledge and belie	f, true, accurate, and comp	olete. I am aware that there			
	are significant penalties fo	r submitting false information	on including the possibility	of fines and imprisonment	for knowing violations."			
		_		•	_			
	14							
	/k_1				2. / .			
Inspector Signature:	11.			Reviewed By:	to Sol			
	7	l						