E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



ry A Jilek CPESC CISEC

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager				Enainee	Engineering Answers		
Environmental Services D	ері. Мапаует	F&Δ. P2	020.056.003	2			
Inspector: Alex Brown		Lun-12	.020.000.000		Stage		
nispector. Alex Brown		EDo Trononortot	ion Trucking Termi	201	Clage		
		•	•	ıaı	1 51501		
Project Name:			263 - 38898				
For Week Ending:		4	/9/2022				
Project Location:	Southwest of S 29	Southwest of S 29th Street and 21st Avenue in Council Bluffs, IA (Pottawattamie County)					
	1	.1			T		
Grading:	100%						
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving:	100%						
Seeding:	0%						
Utilities:	100%						
Overall Development:	90%	0					
		<u></u>					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time			
					Week		
Sunday	0.00"						
Monday	0.00"						
Tuesday	0.00"	4/5/2022	Light Rain 60/42	10:15 AM			
Wednesday	0.00"						
Thursday	0.12"						
Friday	0.00"						
Saturday	0.00"						
	None						
Complaints:							
Construction Sequencing							
		orary or permanent cessati	on of grading, earthwork, or grou	nd disturbance in the last 14 day	vs?		
			. Sanitary installation began				
	, , , ,	,	lk installation (12/14/21). Gra	, ,			
Grading ceased (3/8/22).	J (** **	, - 5	( , , , , ,	5 5 1	(3 ,		
			disturbance scheduled in the next				
			. Sanitary installation began				
	allation began on site (9/28/2	21). Grading and sidewa	lk installation (12/14/21). Gra	iding along the northern per	rimeter ROW (3/1/22).		
Grading ceased (3/8/22).							
What temporary or permanent of	abilization measures listed in this	s section are being impleme	nted?				
Existing vegetation (6/29/21		s section are being impleme	inteu:				
	<i>J</i> ·						
Checklist Questions:							
Are receiving waters adjac	cent to the project free of a	ny significant signs of	f erosion or sediment that v	would be associated with	the construction activity		
Yes							

Create Corrective Action?

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

**Create Corrective Action?** 

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

**Create Corrective Action?** 

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

Yes		
Create	Corrective	Action?

N/A

## Comments:

- 1.) Site was active during the last inspection.
- 2.) Rich Engdahl began shaping the PCSMP basin on the western portion of the site during the inspection on 7/20/21.

  Findings / Corrective Actions (Date):

- Findings / Corrective Actions (Date):

  1.) No maintenance is required in the BMP section.
- 2.) All non-paved portions of the site are disturbed and should be stabilized. Rich Engdahl was informed to stabilize the site as soon as possible on 3/11/22. Rich Engdahl informed the E&A inspector on 3/11/22 that the site will be stabilized within approximately three weeks. E&A inspector will continue to monitor for stabilization.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 01	Construction Entrance	J3		Removed		
Current Condition:			the inspection on 12/21/21			
CE 02	Construction Entrance	<b>Z</b> 7		Removed		
Current Condition:			rance prior to the inspection		ı	
CW 01	Concrete Washout	On Site	  4	Removed		
Current Condition:	<u> </u>		hout prior to the inspection		T	
D 01	Diversion Check	Z6 to Z8	to the inequation on 0/10/21	Removed		
Current Condition: IP 01	Inlet Protection	F13	o the inspection on 8/10/21 8/29/2021	. Active	No	
Current Condition:			nspection on 12/21/21. Due			
Current Condition.	recommended at this time	. E&A inspector will continu	ue to monitor.	to allo alloa solling parou, il		
IP 02	Inlet Protection	F3	6/29/2021	Active	No	
Current Condition:			of 21st Avenue. Rich Engda			
	inspection.	g				
IP 03	Inlet Protection	F2	6/29/2021	Active	No	
Current Condition:			enue. Due to the location of			
	time. E&A inspector will co					
IP 04	Inlet Protection	M4	8/29/2021	Active	No	
Current Condition:			spection on 10/26/21. Due	to the area being paved, i	nlet protection is not	
	recommended at this time	. E&A inspector will continu	ue to monitor.			
IP 05	Inlet Protection	P3	6/29/2021	Active	No	
Current Condition:		n existing inlet located off	of 21st Avenue. Rich Engda	ahl installed inlet protection	prior to the 3/22/22	
	inspection.					
IP 06	Inlet Protection	P2	6/29/2021	Active	No	
Current Condition:			enue. Due to the location of	of the inlet no BMP recomm	nendation is needed	
	time. E&A inspector will co					
IP 07	Inlet Protection	Q4	10/5/2021	Active	No	
Current Condition:			nspection on 10/05/21. Due	to the area being paved, i	nlet protection is not	
10.00		. E&A inspector will continu				
IP 08	Inlet Protection	U4	10/5/2021	Active	No	
Current Condition: IP 09	Inlet Protection	X3	d inlet protection prior to the 6/29/2021	Active	No	
Current Condition:			of 21st Avenue. Rich Engda			
ourrone condition.	inspection.	oznatnig imat isolatou on i	o. 2 . o	ann motamou mnot protoction	. p.10. to tilo 0/22/22	
IP 10	Inlet Protection	X2	6/29/2021	Active	No	
Current Condition:			renue. Due to the location of			
	time. E&A inspector will co	ontinue to monitor.				
IP 11	Inlet Protection	Y6	10/5/2021	Active	No	
Current Condition:			inlet protection prior to the			
IP 12	Inlet Protection	Y7	10/5/2021	Active	No	
Current Condition:	Active - Rich Engdahl installed the inlet and inlet protection prior to the inspection on 10/05/21. Rich Engdahl removed the inlet protection prior to the inspection on 11/23/21. Due to the area being paved, reinstallation is not recommended at this time. E&A					
	Inspector will continue to monitor.					
IP 13	Inlet Protection	Y8	10/5/2021	Active	No	
Current Condition:			tection prior to the inspection			
	protection prior to the inspection on 11/23/21. Due to the area being paved, reinstallation is not recommended at this time. E&A					
	inspector will continue to monitor.					
IP 14	Inlet Protection	Y11	10/5/2021	Active	No	
Current Condition:	Good Condition - Rich En	gdahl installed the inlet and	inlet protection prior to the	inspection on 10/05/21.	•	
PB 01	Portable toilet	On Site	7/6/2021	Active	No	
Current Condition:			ortable toilet adjacent to Cl		•	
			the inspection on 11/23/2			
		•	ne inspector that position a		•	
	leakage into nearby inlets.	I nerefore, the recommen	dation to relocate has beer	removed. E&A inspector	wiii continue to moni	
SE 04 SE 06	Oilt T	00 to 045	I	Dom:		
SF 01 - SF 06	Silt Fence	G3 to B15	Lof SF 3-6 on 9/23/21. SF 3	Removed	r to the increation of	
Current Condition:	, '					
	10/05/21. Rich Engdahl removed the remaining section of SF 6 prior to the inspection on 11/30/21. As of 11/30/21, the City has approved silt fence removal in this area for sprinkler installation. Rich Engdahl removed all silt fence prior to the inspection on					
	SPPIOTOG OIL IONOG IONOV	aroa ioi opiiiikici		ss voa an ont lonoe phon	o mopoodom om	

SF 07 - SF 12	Silt Fence	B16 to P12		Removed		
Current Condition:	Removed - As of 11/30/21	, the City has approved silt	fence removal in this area	. Rich Engdahl removed a	majority of SF 7 - 12 prior	
	to the inspection on 12/7/21. Rich Engdahl removed the remainder of SF 7 - 12 prior to the inspection on 3/8/22.					
SF 13 - SF 17	Silt Fence	S12 to Z5		Removed		
Current Condition:	Removed - As of 11/30/21	, the City has approved silt	fence removal in this area	. Rich Engdahl removed S	F 13 and SF 14 prior to	
	the inspection on 12/7/21. Rich Engdahl removed SF 15 - 17 prior to the inspection on 3/8/22.					
SF 18 - SF 22	Silt Fence	Z3 to K3		Removed		
Current Condition:	Removed - Rich Engdahl removed the silt fence posts from SF 18 - 22 prior to the inspection on 12/14/21. Rich Engdahl removed					
	the trenched silt fence fabric prior to the inspection on 3/1/22.					
STR	Streets	On Site	6/29/2021	Active	No	
Current Condition:	Good Condition - Rich Engdahl cleaned up the trackout on 21st Ave. prior to the inspection on 9/7/21. Rich Engdahl cleaned up					
	trackout around CE 1 prior	r to the inspection on 10/12	2/21. Rick Engdahl cleaned	up trackout around CE 02	prior to the inspection on	
	11/2/21. Minor sedimentat	ion was observed around (	CE 1 during the 12/14/21 in	spection. Rich Engdahl cle	aned up the sediment	
	around CE 1 prior to the 1	2/28/21 inspection. Rich Er	ngdahl cleaned 21st Avenu	e prior to the 3/22/22 inspe	ection.	
SWPPP Sign 01	SWPPP Signs	Adjacent to CE 1	8/3/2021	Active	No	
Current Condition:	Good Condition - The E&A inspector installed the SWPPP sign adjacent to CE 01 during the inspection on 8/3/21. The E&A					
	inspector reinstalled the SWPPP sign during the 2/1/22 inspection.					
Certification Statement	"I certify, under penalty of	law, that this document and	d all attachments were prep	pared under my direction or	r supervision in	
	accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted.  Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there					
	are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."					
		5		·	9	
	1.					
1	42					
Inspector Signature:	Inspector Signature:			Reviewed By:	Se	
inspector organization						