E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager

Erosion Control Specialist- Manage	ger			ENGINEERING • PLANNING	6 • FIELD SERVICES
		E&A- P200	8.207.000		
Inspector: Patrick Pierce					Stage
Project Name:			Bell Brook		3
For Week Ending:			12/11/2010		
Project Location:	Southwest of	orner of 192nd an		maha, NE (Douglas County)	68135
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer: Paving:	100% 100%				
Seeding:	100%				
Utilities:	100%				
Overall Development:	60%	)			
		T	1		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected			Week
Sunday:	Trace				
Monday	Trace				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday Friday	0.00"				
Saturday	Trace				
					Week
Sunday:	Trace				
Monday	0.01"				
Tuesday	0.00"				
Wednesday Thursday	7race 0.00"				
Friday	0.00"				
Saturday	0.00"				
,					Week
Sunday:	0.00"				
Monday	Trace	11/29/10			
Tuesday Wednesday	0.01" Trace				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week
Sunday:	0.00"				
Monday	0.00"				
Tuesday Wednesday	0.00"				
Thursday	0.00"				
Friday	Trace				
Saturday	0.20"				
					Week
Sunday:	NA	NA			
Monday	NA NA	NA NA			
Tuesday Wednesday	NA NA	NA NA			
Thursday	NA NA	NA			
Friday	NA	NA			
Saturday	NA	NA			
			•		
Camandainta.	None				
Complaints:					
Construction Sequencing:	1	1	1		

Which portion(s) (i.e. drainage basins) of the site I	nave had a temporary	or permanent cessation of	grading, earthwork, or gro	ound disturbance in the last 14 d	lays?		
Entire Site; grading completed and site seed	ded prior to 4/2008.						
Which portion(s) (i.e. drainage basins) of the site of			bance scheduled in the no	ext 14 days? :			
Entire Site; grading completed and site seed	ded prior to 4/2008.						
What temporary or permanent stabilization measu							
Existing Vegetation (4/2008), Harrison St. F Seeding and Matting on the hill south of the (05/09)					basin 8 seeded		
Comments:							
Comments: Home construction is active in many areas of	of the development.						
Findings / Corrective Actions (Date):							
Findings / Corrective Actions (Date):  1) Some maintenance is required in the BM	P section.						
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
	Concrete						
CW 1 Current Condition:	Washout Fair Condition	Lot 393	11/4/2010	Active	Yes		
Current Condition.	Fair Condition						
	this work to be do		g sent E&A an estimat	by 11/11/10. Chad asked for e for this which was forwarde 11/29/10.	•		
Lot 13	Silt Fence	Lot 13	9/2/2010	Active	No		
Current Condition:	Good Condition-S				-		
	-silt fence was rep	aired prior to inspection	on 10/14/10 by Wood	land Homes.			
Lot 17	Silt Fence	Lot 17	11/11/2010	Pending	Yes		
Current Condition:	No BMP's installed	d and construction is ac	tive on this lot				
	There is active home construction on this lot and no lot level BMP installed as of inspection on 11/4/10.  Prairie Homes was called and requested to install some silt fence at the back of the lot by 11/11/10. This was not complete prior to inspection on 11/13/10, but due to recent rains an extension will be given to complete this maintenance. The new completion date is 11/20/10. Russ with Prarie Homes was called and requested to install						
	this ASAP on 11/2	29/10. This was not com	plete prior to inspectio	n on 11/29/10.			
Lot 43	Silt Fence	Lot 43	5/24/2010	Active	No		
Current Condition:	Good Condition -Chris with Pro-Lir	ne Homes installed silt f	ence at the front of this	lot prior to inspection on 8/1	19/10.		
Lot 48	Silt Fence	Lot 48	9/2/2010	Active	Yes		
Current Condition:	11/29/10.			is down and damaged as of	inspection on		
Lot 67	Silt Fence	Lot 67	5/1/2010	Active	Yes		

Current Condition:	Fair Condition											
	-BHI repaired silt fence prior to inspection on 6/11/10.  BHI is developing a lot North of the school site- there are a few areas that are full, one area that is not trenched in and a blowout spot that has a lot of silt running out towards the 192nd St. ROW.											
								and a blowout spe	or that has a lot of silt ful	illing out towards the 1	1921Id St. INOVV.	
								A plan was sent to	BHI requesting them to	take care of all mainte	enance by 9/3/09. As of insp	ection on 06/11/10 all
	A plan was sent to BHI requesting them to take care of all maintenance by 9/3/09. As of inspection on 06/11/10 all silt fence is in good condition and there does not seem to be a problem with runoff anymore. Once this lot is											
		starting to be stab	ilized, there will need to	be some silt cleaned u	up and sod repaired or replac	ced.						
1 400	0.11 E	1 100		5	V							
Lot 92  Current Condition:	Silt Fence Fair Condition	Lot 92		Removed	Yes							
Current Condition:	Fair Condition											
	Most of the silt fence on this lot has been removed prior to inspection on 11/29/10 in order to pour sidewalks.											
	Sandy Creek was	called and requested to	re-install this silt fence	e by 12/06/10.								
Lot 94	Silt Fence	Lot 94	10/14/2010	Active	No							
Current Condition:	Good Condition	20101	10/11/2010	71070								
	-stockpile was ren	noved from ROW and a	diversion ditch was cu	t to prevent runoff prior to in:	spection on 10/14/10							
	by Chris with Barr	Homes.										
		I	I									
Lot 97	Silt Fence	Lot 97	8/19/2010	Active	No							
Current Condition:	Good Condition											
	-Chris with Barr H	omes installed a berm a	at the front of the lot to	prevent runoff prior to inspec	tion on 8/19/10.							
Lot 173	Silt Fence	Lot 173	10/14/2010	Active	No							
Current Condition:	Good Condition	LOT 173	10/14/2010	Active	110							
		noved from ROW and a	diversion ditch was cu	t to prevent runoff prior to in:	spection on 10/14/10							
	by Chris with Barr	Homes.			•							
		I	ı									
	011. 5		40/44/0040	A								
Lot 215 Current Condition:	Silt Fence Good Condition	Lot 215	10/14/2010	Active	No							
Current Condition:		noved from ROW and a	diversion ditch was cu	t to prevent runoff prior to in:	spection on 10/14/10							
	by Chris with Barr		arvoroion arton was sa	it to provont ranon prior to in	50000011 011 1071 1710							
Lot 314	Silt Fence	Lot 314		Removed	Yes							
Current Condition:	Removed		<u> </u>									
	The silt fence on this lot was removed prior to inspection on 10/14/10.											
	Manalli Construction was called and regulated to rejuncted the said force and the letter 40/04/40. The											
	Manelli Construction was called and requested to re-install this silt fence or sod the lot by 10/21/10. This was not complete prior to inspection on 11/4/10. Manelli was called during inspection on 11/29/10 and requested to re-											
	install this silt fence ASAP. This was not complete prior to inspection on 12/06/10.											
			1 2 2 1 2 2 2 2 2									
Lot 389	Silt Fence	Lot 389	11/4/2010	Active	Yes							
Current Condition:	Good Condition											
	-Chris with Barr Homes removed stockpile and cut a diversion ditch around the lot to contain runoff prior to											
	inspection on 11/2	29/10.										
Lot 416	Silt Fence	Lot 416	12/6/2010	Pending	Yes							
Current Condition:		d and construction is ac										
	There is active ho	me construction on this	lot and no lot level BM	P installed as of inspection of	on 11/29/10.							
	Russ with Prairie	Homes was called and	requested to install con	ne silt fence at the back of th	e lot by 12/06/10							
	Auss With France	i iomes was called allu i	equested to install soll	no siit ierioe at the Dack Of II	0 19t by 12/00/10.							
Lot 422	Silt Fence	Lot 422	11/4/2010	Active	Yes							
Current Condition:	Good Condition		44/00/404									
	-silt tence was rep	paired prior to inspection	on 11/29/10 by KRT C	construction.								

Lot 483	Silt Fence	Lot 483	10/14/2010	Active	Yes		
Current Condition:	Fair Condition						
	-down silt fence was repaired prior to inspection on 11/29/10.						
	Thorois some silt i						
	There is some silt fence that is full from a sand stockpile that was dumped against silt fence as of inspection 10/14/10.						
	10/14/10.						
	Melvin Sudbeck was called and requested to clean this out by 10/21/10. Melvin was called on 11/4/10 and						
	11/29/10 reminding him to complete this ASAP. This was not complete prior to inspection on 12/06/10.						
		N41d00m00s		<u> </u>	T .		
SB 4	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- 24		iii i idoc	7101170	140		
our tent condition.	-Devegetation was completed by Commercial Seeding prior to inspection on 8/16/09.						
	N41d00m00s						
SB 5	Sediment Basin	W96d00m00s		Removed			
Current Condition:	Removed	W 90000III00S		Removed			
Julient Continuon.	IVEIIIOVEU	N41d00m00s					
SB 6	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- 1						
	-Devegetation was completed by Commercial Seeding prior to inspection on 8/16/09.						
		N41d00m00s		•			
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- 18		11111000	7101170	110		
Carroni Conditioni	-Devegetation was completed by Commercial Seeding prior to inspection on 8/16/09.						
	· · · · · · · · · · · · · · · · ·			F	1		
00.0	0 " 10 1	N41d00m00s					
SB 8	Sediment Basin	W96d00m00s	5.40.00	Removed			
Current Condition:	Basin removed by O'Brien grading prior to inspection on 5-13-09. Silt fence has been installed on the toe of slope, and the area seeded.						
	slope, and the area	seeded.					
		N41d00m00s					
SB 9	Sediment Basin	W96d00m00s		Removed			
Current Condition:	Removed						
		N41d00m00s					
SF 1	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed due to d	N41d00m00s			1		
STR	Streets	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- N		III Flace	Active	INU		
Current Condition.	Good Condition- N	o signs of track on					
			,				
					No		
SWPPP Sign	0 1 111	5 signs	8-19-08	Active			
Current Condition:	Good condition						
	-195th and Harrison -197th and Harrison						
	-197th and Harrison						
	-201st and Harrison						
	-192nd and Bellbro						
	10211d and Delibit	JON DIVG.					
				Z1 / 1/2			
_							
tor Signature:	Fire		Reviewed By:	Zadrany L. Jilek			