

E&A Consulting Group, Inc.
 330 North 117th Street
 Omaha, NE 68154-2509
 tel 402.895.4700
 fax 402.895.3599
 www.eacg.com



E&A CONSULTING GROUP, INC.
 ENGINEERING • PLANNING • FIELD SERVICES

Zachary A. Jilek, CPESC, CISEC
 Erosion Control Specialist- Manager

E&A- P2008.207.000

Inspector: Mike Jacobson, CISEC		Stage 3
Project Name:	Bell Brook	
For Week Ending:	2/11/2012	
Project Location:	Southwest corner of 192nd and Harrison Street- Omaha, NE (Sarpy County)	68135

Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
Overall Development:	60%			

RAIN FALL AMOUNTS	Amount in tenths	Date inspected			
Week 1					
Sunday:	0.00"				
Monday	0.00"				
Tuesday	Trace				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
Week 2					
Sunday:	0.08"				
Monday	Trace				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	Trace				
Saturday	0.00"				
Week 3					
Sunday:	0.00"				
Monday	0.00"	01/30/12			
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.18"				
Saturday	1.06"				
Week 4					
Sunday:	0.00"				
Monday	0.00"	02/06/12			
Tuesday	Trace				
Wednesday	0.00"				
Thursday	0.00"				
Friday	Trace				
Saturday	0.00"				
Week 5					
Sunday:	N/A	N/A			
Monday	N/A	N/A			
Tuesday	N/A	N/A			
Wednesday	N/A	N/A			
Thursday	N/A	N/A			
Friday	N/A	N/A			
Saturday	N/A	N/A			

Complaints:	None				
-------------	------	--	--	--	--

Construction Sequencing:
 Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site; grading completed and site seeded prior to 4/2008.

--	--	--	--	--	--

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :					
Entire Site; grading completed and site seeded prior to 4/2008.					
What temporary or permanent stabilization measures listed in this section are being implemented?					
Existing Vegetation (4/2008). Harrison St. ROW between 201st and 197th St seed and matting by Sarpy County (8/19/08) Seeding and Matting on the hill south of the ROW between 197th and 199th St. (9/08), seeding and matting on outlet 'O' (3/09), removed basin 8 seeded (05/09), Silt Basin 3 seeded and matted (4/2011); Disturbed area behind sediment basin #7 was re-seeded/matted(10/2011)					
Comments:					
Comments: Home construction is active in many areas of the development.					
An inspection was not conducted on Saturday 2/4/12 due to winter weather and dangerous driving conditions. An inspection will be conducted as conditions allow. This inspection took place on 2/6/12. This inspection was a drive thru inspection due to winter conditions and snow cover.					
Findings / Corrective Actions (Date):					
Findings / Corrective Actions (Date): 1) Some maintenance is required in the BMP section.					
Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CW 1	Concrete Washout	Lot 393	11/4/2010	Active	No
Current Condition:	Good Condition Washout was cleaned out prior to inspection on 6/18/11 by Chad with Synergy.				
Lot 42	Silt Fence	Lot 42		Removed	
Current Condition:	Silt fence was removed prior to inspection on 2/6/12 by Ron w/ Proline Homes.				
Lot 53	Misc/Other	Lot 53	1/9/2012	Active	No
Current Condition:	Good Condition.- Active Home construction on the lot. Maintenance was completed prior to inspection on 2/6/12 by Zych construction.				
Lot 87	Silt Fence	Lot 87	7/6/2011	Active	No
Current Condition:	Good Condition- Active home construction on the lot. A berm was installed on the back of the lot prior to inspection on 7/6/11 by Proline Homes.				
Lot 93	Silt Fence	Lot 93	5/14/2011	Active	Yes
Current Condition:	Fair Condition- Vacant Lot (There is a few rows of silt fence on this lot.) 1) The East section of the lot has down/damaged silt fence and it needs to be removed. (Note: This silt fence was installed by the builder from lot 94.) 2) The West section of the lot has down/damaged silt fence and it needs to be removed. (Note: This silt fence was installed by the builder from lot 92.) 1) Builder Proline Homes was informed to complete maintenance by 1/16/12. On 2/1/12 Ron w/ Proline Homes was reminded that maintenance needs to be completed ASAP. 2) Builder Sandy Creek was informed to complete maintenance by 1/16/12. Maintenance not completed as of last inspection.				
Lot 111	Misc/Other	Lot 111	11/3/2011	Active	No
Current Condition:	Good Condition.- Active Home construction on the lot. Maintenance was completed prior to inspection on 1/30/12 by KRT construction.				
Lot 208	Silt Fence	Lot 208	8/5/2011	Active	No
Current Condition:	Good Condition- Active Home construction on the lot. Dirt was removed prior to inspection on 8/7/11 by Proline Homes.				
Lot 233	Misc/Other	Lot 235	8/14/2011	Active	No
Current Condition:	Good Condition.- Active Home construction on the lot. Dirt in the R.O.W. was removed prior to inspection on 8/30/11 by Proline Homes.				
Lot 236	Misc/Other	Lot 236	8/5/2011	Active	Yes

Current Condition:	<p>Pending - Active Home construction on the lot. Dirt in the R.O.W. was removed prior to inspection on 8/30/11 by Proline Homes.</p> <p>Silt fence needs to be installed on the Northeast corner of the lot.</p> <p>Proline Homes was informed to complete maintenance by 8/14/11. Maintenance not completed as of last inspection due to wet and muddy conditions, therefore another seven days is given to complete maintenance until 8/19/11. Maintenance not completed due to wet and muddy conditions therefore another seven days is given to complete maintenance until 8/26/11. Maintenance not completed due to wet and muddy conditions therefore another seven days is given to complete maintenance until 8/29/11. On 10/3/11 Proline Homes was reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection. On 11/28/11, 1/9/12 and again on 2/1/12 Proline Homes was reminded to complete overdue maintenance ASAP. Maintenance not completed as of last inspection.</p>				
Lot 245	Silt Fence	Lot 245	8/8/2011	Active	No
Current Condition:	<p>Good Condition- Vacant lot. Maintenance was completed prior to inspection on 8/30/11 by Proline Homes.</p>				
Lot 304	Misc/Other	Lot 304	8/5/2011	Active	Yes
Current Condition:	<p>Lot was sodded prior to inspection on 11/28/11 by HBC.</p> <p>Due to active home construction on this lot the Outlot needs to be re-seeded.</p> <p>On 11/28/11 HBC was informed to complete maintenance by 12/5/11. Maintenance not completed as of last inspection. Due to winter conditions this maintenance will need to be completed when conditions allow in the spring.</p>				
Lot 339	Silt Fence	Lot 339	11/21/2011	Active	No
Current Condition:	<p>Good Condition - Active Home construction on the lot. Silt fence is installed along the back of the lot prior to inspection on 11/28/11</p>				
Lot 346	Silt Fence	Lot 346	5/20/2011	Active	No
Current Condition:	<p>Good Condition- Vacant Lot. Silt fence installed on the back of the lot prior to inspection on 5/220/2011 by Bob Roth.</p>				
Lot 347	Silt Fence	Lot 347	5/20/2011	Active	No
Current Condition:	<p>Good Condition- Vacant Lot. Silt fence installed on the back of the lot prior to inspection on 5/220/2011 by Bob Roth.</p>				
Lot 356	Silt Fence	Lot 356		Removed	
Current Condition:	<p>Lot was sodded prior to inspection on 11/3/11 by Butch Michael Homes.</p>				
Lot 438	Misc/Other	Lot 438	1/9/2012	Active	Yes
Current Condition:	<p>Pending - Active home construction on the lot</p> <p>Silt fence needs to be installed on the back of the lot.</p> <p>John Caniglia was informed to complete maintenance by 1/16/12. Maintenance not completed as of last inspection.</p>				
Lot 457	Misc/Other	Lot 457	1/9/2012	Active	No
Current Condition:	<p>Good Condition- Active home construction on the lot Silt fence was installed prior to inspection on 2/6/12 by Ron w/ Barr Homes.</p>				
SB 3	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	<p>Basin has been removed and seeded and matted prior to inspection on 4/17/11 by Beaver Excavation.</p>				
SB 4	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	<p>Good Condition- 24% Filled Trees/vegetation was removed from basin area by Commercial Seeding prior to inspection on 8/16/09.</p>				
SB 5	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	<p>Removed</p>				
SB 6	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	<p>Good Condition- 17% Filled Trees/vegetation was removed from basin area by Commercial Seeding prior to inspection on 8/16/09.</p>				
SB 7	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No

Current Condition:	Good Condition- 2% Filled Basin was cleaned out prior to inspection on 6/18/11 by Bob Roth. The outlet pipe was buried and extended to the creek area prior to inspection on 10/3/11 by Tim Geis.				
SB 8	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Basin removed by O'Brien grading prior to inspection on 5-13-09. Silt fence has been installed on the toe of the slope, and the area seeded.				
SB 9	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Removed				
SF 1	Silt Fence	N41d00m00s W96d00m00s		Removed	
Current Condition:	Removed due to dense vegetation				
STR	Streets	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	Good Condition- No major signs of track off.				
SWPPP Sign	SWPPP Sign	5 signs	8-19-08	Active	No
Current Condition:	Good condition -195th and Harrison -197th and Harrison -198th and Harrison -201st and Harrison -192nd and Bellbrook Blvd.				
Inspector's Signature: <i>Michael Paulson</i>			Reviewed By: <i>Zachary K. Gilke</i>		

