

E & A Consulting Group, Inc.
 330 North 117th Street
 Omaha, NE 68154-2509
 tel 402.895.4700
 fax 402.895.3599
 www.eacg.com



Engineering Answers

E & A CONSULTING GROUP, INC.
 ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES

Zachary A. Jilek, CPESC, CISEC
 Environmental Services Dept. Manager

E&A- P2008.207.000

Inspector: Mike Jacobson, CISEC		Stage 3
Project Name:	Bell Brook NER111506	
For Week Ending:	7/13/2013	
Project Location:	Southwest corner of 192nd and Harrison Street- Omaha, NE (Sarpy County)	68022

Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
Overall Development:	60%			

RAIN FALL AMOUNTS	Amount in tenths	Date inspected			
					Week 1
Sunday:	0.11"				
Monday	0.00"	06/10/13			
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	1.47"				
Saturday	0.00"				
					Week 2
Sunday:	0.00"	06/16/13			
Monday	0.00"				
Tuesday	0.12"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.13"				
					Week 3
Sunday:	0.56"				
Monday	0.48"	06/24/13			
Tuesday	0.01"				
Wednesday	0.00"				
Thursday	0.16"				
Friday	0.00"				
Saturday	0.00"				
					Week 4
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week 5
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.11"				
Wednesday	0.01"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				

Complaints:	None
-------------	------

Construction Sequencing:
 Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site; grading completed and site seeded prior to 4/2008.


Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :					
Entire Site; grading completed and site seeded prior to 4/2008.					
What temporary or permanent stabilization measures listed in this section are being implemented?					
Existing Vegetation (4/2008), Harrison St. ROW between 201st and 197th St seed and matting by Sarpy County (8/19/08) Seeding and Matting on the hill south of the ROW between 197th and 199th St. (9/08), seeding and matting on outlot 'O' (3/09), removed basin 8 seeded (05/09), Silt Basin 3 seeded and matted (4/2011); Disturbed area behind sediment basin #7 was re-seeded/matted(10/2011); lots 331-335;340-345 were re-seeded(6/5/12)					
Comments:					
Comments: Home construction is active in many areas of the development.					
Findings / Corrective Actions (Date):					
Findings / Corrective Actions (Date): 1) Some maintenance is required in the BMP section.					
Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CW 1	Concrete Washout	Lot 393	11/4/2010	Active	Yes
Current Condition:	Fair Condition One section of the silt fence is down/damaged and has concrete debris piled on it and it needs to be removed and the silt fence will need replaced. There is some concrete spoils around the washout pit and they need to be cleaned up. Chad with Synergy was informed to complete maintenance by 6/6/13. Maintenance not completed as of last inspection.				
Lot 22	Misc/Other	Lot 22	3/12/2013	Pending	Yes
Current Condition:	Pending There is no BMP currently in place on this lot as of inspection on 04/12/2013. Homeowner Jeffrey Gustafson was informed to install silt fence or some other type of BMP by 04/19/2013. Silt fence has not been installed as of inspection on 4/21/13 due to wet and muddy condition, therefore another seven days is given to install silt fence until 4/26/13. Silt fence has not been installed as of inspection on 4/25/13 due to wet and muddy condition, therefore another seven days is given to install silt fence until 5/1/13. Silt fence has not been installed as of inspection on 5/4/13 due to wet and muddy condition, therefore another seven days is given to install silt fence until 5/11/13. Silt fence has not been installed as of inspection on 5/9/13 due to wet and muddy condition, therefore another seven days is given to install silt fence until 5/16/13. Maintenance not completed as of last inspection.				
Lot 36	Silt Fence	Lot 36		Removed	
Current Condition:	Lot was sodded prior to inspection on 6/24/13 by Prairie Homes.				
Lot 93	Silt Fence	Lot 93		Removed	
Current Condition:	Lot was sodded prior to inspection on 6/10/13 by Ron w/ Barr Homes.				
Lot 98	Silt Fence	Lot 98	4/24/2013	Active	No
Current Condition:	Good Condition Silt fence was installed on the back of the lot prior to inspection on 04/24/13 Zych Construction.				
Lot 99	Silt Fence	Lot 99	4/24/2013	Active	No
Current Condition:	Good Condition Silt fence was installed on the back of the lot prior to inspection on 04/24/13 Zych Construction.				
Lot 101	Silt Fence	Lot 101	4/24/2013	Active	Yes

Current Condition:	<p>Good condition- Some straw wattle was installed on the lot prior to inspection on 4/24/13 by Barr Homes.</p> <p>1) Additional straw wattle or silt fence needs to be installed above the curb inlet. 2) One section of the straw wattle is damaged and it needs to be repaired. 3) There is a full dumpster on the lot and it needs to be emptied or covered.</p> <p>1) Ron w/ Barr Homes was informed to install some BMP by 5/1/13. On 6/16/13 Ron w/ Barr Homes was reminded to install some BMP ASAP. 2) Ron w/ Barr Homes was informed to complete maintenance by 6/23/13. Maintenance not completed as of last inspection. 3) Ron w/ Barr Homes was informed to complete maintenance by 6/23/13. Maintenance not completed as of last inspection.</p>				
Lot 232	Silt Fence	Lot 232	6/10/2013	Active	No
Current Condition:	<p>Good condition- Some straw wattle was installed on the lot prior to inspection on 6/10/13 by Barr Homes.</p>				
Lot 237	Silt Fence	Lot 237		Removed	
Current Condition:	<p>Lot sodded prior to inspection on 6/10/13 by Castlebridge Homes.</p>				
Lot 238	Silt Fence	Lot 238	6/17/2013	Pending	Yes
Current Condition:	<p>Pending</p> <p>Silt fence needs to be installed on the front of the lot.</p> <p>Castlebridge Homes was informed to install silt fence by 6/17/13. Maintenance not completed as of inspection on 6/16/13 due to wet and muddy conditions, therefore another seven days is given to install silt fence until 6/23/13. Maintenance not completed as of last inspection.</p>				
Lot 243	Silt Fence	Lot 243	4/19/2013	Pending	Yes
Current Condition:	<p>Pending</p> <p>Home construction is active on this lot and there is no BMP in place.</p> <p>Heavican Homes was called and requested to install silt fence or some other type of BMP by 04/19/2013. Silt Fence has not been installed as of inspection on 4/21/13 due to wet and muddy condition, therefore another seven days is given to complete maintenance until 4/26/13. Silt Fence has not been installed as of inspection on 4/25/13 due to wet and muddy condition, therefore another seven days is given to complete maintenance until 5/1/13. Silt Fence has not been installed as of inspection on 5/4/13 due to wet and muddy condition, therefore another seven days is given to complete maintenance until 5/11/13. Silt Fence has not been installed as of inspection on 5/9/13 due to wet and muddy condition, therefore another seven days is given to complete maintenance until 5/16/13. On 6/16/13 Josh w/ Heavican Homes was reminded that silt fence or some other type of BMP needs to be installed ASAP. Maintenance not completed as of last inspection.</p>				
Lot 244	Silt Fence	Lot 244		Removed	
Current Condition:	<p>Lot was sodded prior to inspection on 6/24/13 by Proline Homes.</p>				
Lot 247	Misc/Other	Lot 247	4/24/2013	Removed	
Current Condition:	<p>Lot was sodded prior to inspection on 5/29/13 by Dynasty Homes.</p>				
Lot 248	Silt Fence	Lot 248	4/19/2013	Pending	Yes
Current Condition:	<p>Pending</p> <p>Home Construction is active as of inspection on 04/12/2013 and there is not BMP in place.</p> <p>Proline Homes was called and requested to install silt fence or some other type of BMP by 04/19/2013. Silt fence has not been installed as of inspection on 4/21/13 due to wet and muddy condition, therefore another seven days is given to install silt fence until 4/26/13. Silt fence has not been installed as of inspection on 4/25/13 due to wet and muddy condition, therefore another seven days is given to install silt fence until 5/1/13. Silt fence has not been installed as of inspection on 5/4/13 due to wet and muddy condition, therefore another seven days is given to install silt fence until 5/11/13. Silt fence has not been installed as of inspection on 5/9/13 due to wet and muddy condition, therefore another seven days is given to install silt fence until 5/16/13. On 6/16/13 Proline Homes was reminded that silt fence or some other type of BMP needs to be installed ASAP. Maintenance not completed as of last inspection.</p>				
Lot 266	Silt Fence	Lot 266	6/5/2013	Pending	Yes

Current Condition:	Pending Silt fence needs to be installed on the back of the lot. Proline Homes was informed to install silt fence by 6/6/13. On 6/16/13 Proline Homes was reminded that silt fence or some other type of BMP needs to be installed ASAP. Maintenance not completed as of last inspection.				
Lot 272	Silt Fence	Lot 272	4/24/2013	Active	No
Current Condition:	Good Condition Nelson Builders installed silt fence on this lot prior to inspection on 04/24/2013.				
Lot 289	Silt Fence	Lot 289		Removed	
Current Condition:	Lot was sodded prior to inspection on 6/24/13 by Kainesville Homes.				
Lot 323	Silt Fence	Lot 323	6/6/2013	Pending	Yes
Current Condition:	Pending 1) Silt fence needs to be installed on the back of the lot. 2) Silt fence needs to be installed on the front of the lot. 1) Prairie Homes was informed to install silt fence by 6/6/13. On 6/10/13 Prairie Homes was reminded that silt fence needs to be installed ASAP. Silt fence not installed as of last inspection. 2) Prairie Homes was informed to install silt fence by 6/23/13.				
Lot 326	Silt Fence	Lot 326	6/10/2013	Active	Yes
Current Condition:	Fair Condition 1) Silt fence installed on the back of the lot is not trenched in correctly and it needs to be trenched in properly. 2) One area of the silt fence is down/damaged and it needs to be repaired. 1) D & J Vogel Construction Inc. was informed to install silt fence by 6/17/13. Maintenance was completed prior to inspection on 6/16/13 by Vogel Construction Inc. 2) Vogel Construction Inc was informed to complete maintenance by 6/23/13. Maintenance not completed as of last inspection.				
Lot 327	Silt Fence	Lot 327	2/14/2013	Pending	Yes
Current Condition:	Pending Silt fence needs to be installed on the back of the lot. Marcuso Homes was informed to install silt fence by 2/14/13. On 3/5/13, 4/12/13, 4/25/13 and 6/10/13 Marcuso Homes was reminded that silt fence needs to be installed ASAP. Maintenance not completed as of last inspection.				
Lot 337	Silt Fence	Lot 337	6/6/2013	Pending	Yes
Current Condition:	Pending Silt fence needs to be installed on the back of the lot. Lifestyle was informed to install silt fence by 6/6/13. On 6/16/13 Lifestyle was reminded that silt fence needs to be installed ASAP. Maintenance not completed as of last inspection.				
Lot 338	Silt Fence	Lot 337	6/17/2013	Pending	Yes
Current Condition:	Pending Silt fence needs to be installed on the back of the lot. As of inspection on 6/24/13 some silt fence was installed on the lot, but additional silt fence needs to be installed on the back of the lot. Geiger Construction was informed to install silt fence by 6/17/13. Maintenance not completed as of inspection on 6/16/13 due to wet and muddy conditions, therefore another seven days is given to install silt fence until 6/23/13. On 6/24/13 Geiger Construction was informed to install silt fence ASAP.				
Lot 347	Silt Fence	Lot 347	5/20/2011	Active	Yes
Current Condition:	Good Condition Additional silt fence needs to be installed on the front of the lot. Commercial Seeding installed silt fence was informed to complete maintenance by 6/23/13. Maintenance was completed prior to inspection on 6/24/13 by CS.				
Lot 369	Silt Fence	Lot 369	5/9/2013	Active	No
Current Condition:	Good Condition Dumpster was emptied prior to inspection on 5/30/13 by Kennington Homes.				

Lot 371	Silt Fence	Lot 371		Removed	
Current Condition:	As of inspection on 6/10/13 the lot has filled in, therefore silt fence is no longer needed.				
Lot 374	Silt Fence	Lot 374	6/6/2013	Pending	Yes
Current Condition:	<p>Pending</p> <p>Silt fence needs to be installed on the back of the lot.</p> <p>Marcuso Homes was informed to install silt fence by 6/6/13. On 6/16/13 Marcuso Homes was reminded that silt fence needs to be installed ASAP. Maintenance not completed as of last inspection.</p>				
Lot 381	Silt Fence	Lot 381	4/19/2013	Pending	No
Current Condition:	<p>Pending</p> <p>Home construction is active on this lot by Ideal Designs and no BMP is in place as of inspection on 04/12/2013.</p> <p>Ideal Designs was called and requested to install silt fence or some other type of BMP by 04/19/2013. Silt fence has not been installed as of inspection on 4/21/13 due to wet and muddy condition, therefore another seven days is given to install silt fence until 4/26/13. Silt fence has not been installed as of inspection on 4/25/13 due to wet and muddy condition, therefore another seven days is given to install silt fence until 5/1/13. Silt fence has not been installed as of inspection on 5/4/13 due to wet and muddy condition, therefore another seven days is given to install silt fence until 5/11/13. Silt fence has not been installed as of inspection on 5/9/13 due to wet and muddy condition, therefore another seven days is given to install silt fence until 5/16/13. On 6/10/13 Ideal Design was reminded that silt fence needs to be installed ASAP. Maintenance not completed as of last inspection.</p>				
Lot 383	Silt Fence	Lot 383	6/17/2013	Pending	Yes
Current Condition:	<p>Pending</p> <p>Silt fence needs to be installed on the South side of the lot.</p> <p>Woodland Homes was informed to install silt fence by 6/17/13. Maintenance not completed as of inspection on 6/16/13 due to wet and muddy conditions, therefore another seven days is given to install silt fence until 6/23/13. Maintenance not completed as of last inspection.</p>				
Lot 386	Silt Fence	Lot 386	4/12/2013	Active	No
Current Condition:	<p>Good Condition</p> <p>-Woodland Homes installed silt fence on this lot prior to inspection on 04/12/2013.</p>				
Lot 388	Misc/Other	Lot 388		Removed	
Current Condition:	<p>Stockpile was removed from the ROW prior to inspection on 04/12/2013 by Woodland Homes</p> <p>-No BMP in place on this lot at this time, but there is currently no silt leaving the site. If silt fence is needed at a later time Woodland Homes will be requested to install it.</p>				
Lot 394	Silt Fence	Lot 394	3/12/2013	Pending	Yes
Current Condition:	<p>Pending</p> <p>Silt fence needs to be installed on the back and the front of the lot.</p> <p>Kennington Homes was informed to complete maintenance by 6/6/13. On 6/16/13 Kennington Homes was reminded that silt fence needs to be installed ASAP. Maintenance not completed as of last inspection.</p>				
Lot 409	Silt Fence	Lot 409	9/12/2012	Active	Yes
Current Condition:	<p>Fair Condition-</p> <p>1) As of inspection on 2/7/13 there is active home construction on the lot, therefore the silt fence check needs to be replaced.</p> <p>2) Some lot level BMP needs to be installed above the two curb inlets in the South section of the lot.</p> <p>1) On 2/7/13, 3/5/13, 4/12/13 and again on 6/10/2013 Ideal Design was reminded to complete maintenance ASAP. This was not complete prior to last inspection.</p> <p>2) Ideal Design was informed to install a BMP by 2/14/13. On 3/5/13, 4/12/13 and 6/10/13 Ideal Design was reminded to install a BMP on the lot ASAP. This was not complete prior to last inspection.</p>				
Lot 411	Silt Fence	Lot 411	1/7/2013	Active	Yes

Current Condition:	Fair Condition-				
	<p>1) One area of the silt fence is down/damaged and it needs to be replaced. 2) There is a full dumpster on the lot and it needs to be emptied or covered.</p> <p>1) Silverstone Building Company was informed to complete maintenance by 6/17/13. Maintenance not completed as of inspection on 6/16/13 due to wet and muddy conditions, therefore another seven days is given to install silt fence until 6/23/13. Maintenance not completed as of last inspection. 2) Silverstone Building Company was informed to complete maintenance by 6/23/13. Dumpster was emptied prior to inspection on 6/24/13 by Silverstone Building Company.</p>				
Lot 413	Silt Fence	Lot 413	5/9/2013	Active	Yes
Current Condition:	Fair Condition-				
	<p>One area of the silt fence is down/damaged and it needs to be repaired.</p> <p>Ed Beaudin was informed to complete maintenance by 6/23/13. Maintenance was completed prior to inspection on 6/24/13 by Ed Beaudin.</p>				
Lot 417	Silt Fence	Lot 417	2/14/2013	Pending	Yes
Current Condition:	Pending				
	<p>1) Silt fence needs to be installed on the front of the lot. 2) There is a full dumpster and it needs to be emptied or covered.</p> <p>1) Showcase Builders was informed to install silt fence by 2/14/13. On 3/5/13, 4/12/13 and again on 6/16/13 Showcase Builders was reminded that silt fence needs to be installed on the lot ASAP. 2) Showcase Builders was informed to complete maintenance by 6/23/13. Maintenance not completed as of last inspection.</p>				
Lot 461	Silt Fence	Lot 461		Removed	
Current Condition:	Silt fence was removed prior to inspection on 5/29/13 by Bill w/ Regency Homes.				
Lot 475	Silt Fence	Lot 475	4/19/2013	Active	No
Current Condition:	Good Condition- One little section of straw wattle was installed on the Southeast section of the lot prior to inspection on 4/24/13 by Barr Homes.				
	Silt fence installed on the lot prior to inspection on 6/24/13 by Barr Homes. Dumpster was emptied prior to inspection on 6/24/13 by Barr Homes.				
Lot 480	Silt Fence	Lot 480	4/24/2013	Active	Yes
Current Condition:	Fair Conditions- Silt Fence				
	Fair Conditions- Gator Guard				
	<p>One area of the silt fence is undermined and it needs to be backfilled and compacted. One area of the silt fence is full and down/damaged and it needs to be replaced. One section of the gator guard is full and it needs to be cleaned out.</p> <p>G. Lee construction was informed to complete maintenance by 6/17/13. Maintenance not completed as of inspection on 6/16/13 due to wet and muddy conditions, therefore another seven days is given to install silt fence until 6/23/13. Maintenance not completed as of last inspection.</p>				
SB 3	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Basin has been removed and seeded and matted prior to inspection on 4/17/11 by Beaver Excavation.				
SB 4	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Sediment basin was removed prior to inspection on 6/5/12 Beaver Excavation. Area was seeded prior to inspection on 6/5/12 by Beaver Excavation.				
SB 5	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Removed				
SB 6	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Sediment basin was removed prior to inspection on 6/5/12 Beaver Excavation. Area was seeded prior to inspection on 6/5/12 by Beaver Excavation.				
SB 7	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
Current Condition:	Good Condition- 4% Filled				
	Basin was cleaned out prior to inspection on 6/18/11 by Bob Roth.				
SB 8	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Basin removed by O'Brien grading prior to inspection on 5-13-09. Silt fence has been installed on the toe of the slope, and the area seeded.				
SB 9	Sediment Basin	N41d00m00s W96d00m00s		Removed	

Current Condition:	Removed				
SF 1	Silt Fence	Lots, 331 and 332	5/3/2012	Active	Yes
Current Condition:	<p>Fair Condition Lot 331 was sodded prior to inspection on 6/24/13 by Landmark Homes.</p> <p>1) One area of the silt fence on lot 332 is down/damaged and it needs to be replaced. 2) One area of the silt fence on lot 331 down/damaged and it needs to be replaced. Additional silt fence needs to be installed on the back of the lot. Some silt on the trail and it needs to be cleaned off.</p> <p>1) Landmark Homes was informed to complete maintenance by 6/17/13. Maintenance not completed as of inspection on 6/16/13 due to wet and muddy conditions, therefore another seven days is given to install silt fence until 6/23/13. On 6/24/13 Steve w/ Landmark Homes was reminded that maintenance needs to be completed ASAP. 2) Landmark Homes was informed to complete maintenance by 6/17/13. Silt fence was removed and lot 331 was sodded prior to inspection on 6/24/13 by Landmark Homes.</p>				
SF 2	Silt Fence	Lots, 333 - 335	5/3/2012	Active	Yes
Current Condition:	<p>Good Condition</p> <p>One area of the silt fence on lot 333 is full and damaged and it needs to be cleaned out and repaired. One area of the silt fence on lot 333 is damaged and it needs to be replaced.</p> <p>Commercial Seeding was informed to complete maintenance by 6/17/13. Maintenance not completed as of inspection on 6/16/13 due to wet and muddy conditions, therefore another seven days is given to install silt fence until 6/23/13. Maintenance was completed prior to inspection on 6/24/13 by CS.</p>				
SF 3	Silt Fence	Lots, 340 - 345	5/3/2012	Active	Yes
Current Condition:	<p>Fair Condition Silt fence was installed behind the damaged silt fence on lot 345 prior to inspection on 6/24/13 by Commercial Seeding. Lot 343 was sodded prior to inspection on 6/24/13 by HBC.</p> <p>One section of the silt fence on lot 344 is down/damaged and it needs to be replaced. Silt fence needs to be installed on the front of the lot.</p> <p>Lifestyle Homes was informed to complete maintenance by 6/17/13. Maintenance not completed as of inspection on 6/16/13 due to wet and muddy conditions, therefore another seven days is given to install silt fence until 6/23/13. Maintenance not completed as of last inspection.</p>				
STR	Streets	N41d00m00s W96d00m00s	In Place	Active	Yes
Current Condition:	<p>Fair Condition- Street was cleaned up prior to inspection on 6/16/13 for lot 36 by Prairie Homes. Street was cleaned up prior to inspection on 6/16/13 for lot 369 by Kennington Homes. Street was cleaned up prior to inspection on 6/16/13 for lot 409 by Ideal Homes.</p> <p>1) There is some minor signs of run off on lot 232 and it needs to be cleaned up. 2) There is some minor signs of run off on lot 101 and it needs to be cleaned up. 3) There is some minor signs of run off on lot 244 and it needs to be cleaned up. 4) There is some minor signs of run off on lot 244 and it needs to be cleaned up. 5) There is some minor signs of run off on lot 289 and it needs to be cleaned up. 6) There is some minor signs of run off on lot 394 and it needs to be cleaned up. 7) There is some minor signs of run off on lot 480 and it needs to be cleaned up. 8) There is some minor signs of run off on lot 343 and it needs to be cleaned up. 9) There is some minor signs of run off on lot 344 and it needs to be cleaned up. 10) There is some minor signs of run off on lot 345 and it needs to be cleaned up.</p> <p>1) Proline Homes was informed to clean up by 5/21/13. On 6/16/13 Barr Homes was reminded to clean up street AS 2) Barr Homes was informed to clean up by 5/31/13. On 6/16/13 Barr Homes was reminded to clean up street ASAF 3) Proline Homes was informed to clean up by 6/17/13. Maintenance not completed as of last inspection. 4) Heavican Homes was informed to clean up by 6/17/13. Maintenance not completed as of last inspection. 5) Kainesville Homes was informed to clean up by 6/17/13. Maintenance not completed as of last inspection. 6) Kennington Homes was informed to clean up by 6/17/13. Maintenance not completed as of last inspection. 7) G. Lee was informed to clean up by 6/17/13. Maintenance not completed as of last inspection. 8) HBC Homes was informed to clean up by 6/17/13. Maintenance not completed as of last inspection. 9) Landmark Homes was informed to clean up by 6/17/13. Maintenance not completed as of last inspection. 10) Landmark Homes was informed to clean up by 6/17/13. Maintenance not completed as of last inspection.</p>				
SWPPP Sign	SWPPP Sign	5 signs	8-19-08	Active	No
Current Condition:	<p>Good condition SWPPP signs are installed at the entrances at 195th and Harrison, 197th and Harrison, 198th and Harrison, 201st and Harrison and 192nd and Bellbrook Blvd.</p>				
Inspector's Signature: 			Reviewed By: 