E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

Environmental Services Dept. Man	ager	E&A- P200	8 207 000		
nspector: Patrick Sechser		LQA- F200	0.201.000		Stage
inspector. Fatrick Sectises		Bell Brook NER111506			3
Project Name:					
For Week Ending:		9/12/2015			
Project Location:	Southw	Southwest corner of 192nd and Harrison Street- Omaha, NE (Sarpy County)			68028
				, :: <u>-</u> (ca.p) cca)	00020
Grading:	10	00%			
Sanitary Sewer:		00%			
Storm Sewer:		00%			
aving: Seeding:		00%			
Itilities:		00%			
Overall Development:		71%			
•		•			
AIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		
					Weel
unday:	1.45"				
londay	0.01"				
uesday	0.00"	8/11/2015	84/62 Cloudy		
Vednesday	0.00"			+	
hursday riday	0.00" 0.00"			+	
riday Saturday	0.00"				
	0.00				Weel
unday:	0.00"				
londay	0.83"				
uesday	3.37"	8/18/2015	72/58 Light Rain		
/ednesday	0.00"				
hursday	0.00"				
riday	0.00"				
aturday	0.04"				Mod
Sunday:	0.01"				Week
londay	0.00"				
uesday	0.00"				
Vednesday	0.00"				
hursday	0.08"				
riday	0.91"				
aturday	0.00"	8/29/2015	Cloudy 70/61		
	0.00"				Weel
Sunday:	0.00"			+	
londay uesday	0.00" 0.00"			+	
Vednesday	0.00"				
hursday	0.00"			+	
riday	0.00"				
aturday	0.00"				
					Weel
unday:	0.03"				
londay	0.05"				
uesday	0.63"	0/0/00:=	0		
Vednesday 'hursday	0.14"	9/9/2015	Sunny 81/60	+	
nursday riday	0.00" 0.00"			+	
aturday	0.00"				
	10.00	- 1	1	+	
	None				
Complaints:					
				T T	
Construction Sequencing:	<u> </u>			1	
hich portion(s) (i.e. drainage basins) of the	e site have had a tempora	ry or permanent cessation	n of grading, earthwork, or grou	und disturbance in the last 14 days?	
ntire Site; grading completed and si					

Entire Site; grading completed and site seeded prior to 4/2008. Existing Vegetation (4/2008), Harrison St. ROW between 201st and 197th St seed and matting by Sarpy County (8/19/08) Seeding and Matting on the hill south of the ROW between 197th and 199th St. (9/08), seeding and matting on outlot 'O' (3/09), removed basin 8 seeded (05/09), Silt Basin 3 seeded and matted (4/2011); Disturbed area behind sediment basin #7 was re-seeded/matted(10/2011); lots 331-335;340-345 were reseeded(6/5/12): Basin #7 area was seeded and the area where the outfall was removed was matted (4/29/2014). CHECKLIST QUESTIONS Comments: Home construction is active in many areas of the development as of the last inspections Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section. Projected Install **Unique Name** Location Date Status Maintenance Type Concrete CW₁ Washout Lot 393 11/4/2010 Active No Good Condition- Washout pit was cleaned out by Synergy prior to 6/12/2015. Current Condition: Silt Fence Lot 10 Removed **Current Condition** Removed - Oakwood Homes sodded the lot prior to the 6/25/15 Misc/Other Lot 23 **Current Condition** emoved- Bluestone Builders sodded the lot prior to 9/9/2015 Lot 30 Misc/Other Lot 30 Removed Removed- Prairie eels behind the lot prior to the inspection on 3/25/201 **Current Condition:** lomes removed the Lot 32 Silt Fence 5/8/2015 Lot 32 **Current Condition:** Sood Condition- Ramm Construction repaired the silt fence on the front prior to Silt Fence Lot 41 4/21/2015 Yes Lot 41 Active **Current Condition:** air Condition The silt fence on the front of the lot needs to be repaired. andmark Homes was informed to complete by 7/2/15. Not done as of last inspection. Landmark Homes was reminded on 9/1/2015. Lot 46 Silt Fence Lot 46 Removed **Current Condition:** Removed- Vogel sodded the lot prior to 6/12/2015 Lot 78 Silt Fence Lot 78 Removed **Current Condition:** Removed- Outlot C has been come established as of 6/12/2015 Lot 88 Individual Lot Lot 88 6/12/2015 Active No Current Condition: Active- Lot was excavated by Proline Homes prior to 6/12/2015. E&A will monitor due to vegetated buffer strip in olace Lot 135 Silt Fence Lot 135 Removed **Current Condition** Removed- Lot was sodded by Landmark prior to 6/12/2015 1.) Dirt needs to be removed from the ROW 2.) Silt fence is needed on the north side of the lot. 1.) Pinecrest Homes was informed to complete by 9/16/2015. 2.) Pinecrest Homes was informed to complete by 9/16/2015. Misc/Other Lot 247 Removed **Current Condition:** Removed - Nelson Builders sodded the lot prior to the 5/5/15 inspection. Lot 269 Active Silt Fence Lot 269 4/21/2015 Yes **Current Condition:** 1.) The silt fence on the side of the lot is torn and needs to be repaired. 2.) The adjoining lot that was silted in needs to be sodded. 1.) Landmark Homes was informed to complete by 8/25/2015. Not done as of the last inspection. 2.) Landmark Homes was informed to complete by 8/25/2015. Not done as of the last inspection. Lot 301 Silt Fence Removed Current Condition: Removed- Lot was sodded and the silted in area was sodded prior to the inspection on 4/3/2015 Silt Fence Lot 308 Removed

Current Condition:	Removed- Lot was sodded by Woodlands prior to 6/12/2015.				
Lot 315	Silt fence	Lot 315	prior to 0/12/2010.	Removed	
Current Condition:		Life Homes sodded the	lot prior to the 5/5/15 i		
Lot 320	Silt Fence	Lot 320	6/12/2015	Active	Yes
Current Condition:	Fair Condition- S	ilt fence was reinstalle		mark Homes prior to 8/29	/2015.
Guirein Gonanion.	Fair Condition- Silt fence was reinstalled in the rear by Landmark Homes prior to 8/29/2015. 1.) Silt fence in the NE corner needs to be entrenched.				
	2.) Silt needs to be removed from the sidewalk.				
	1.) Landmark Homes was informed to complete by 9/5/2015. Not done as of the last inspection. 2.) Landmark Homes was informed to complete by 9/5/2015. Not done as of the last inspection.				
Lot 324	Silt fence	Lot 324		Removed	İ
Current Condition:	Removed-Lot wa	s sodded by Landmar	k Homes prior to 8/29	9/2015.	
Lot 334	Individual Lot	Lot 334	8/18/2015	Active	No
Current Condition:	Good Condition-	Landmark Homes ins	talled silt fence in the	e rear prior to 8/18/2015.	
Lot 335	Silt Fence	Lot 335		Removed	
Current Condition:	Removed- Al Bel	t Homes removed the	silt fence prior to 9/9/	/2015.	
Lot 340	Silt Fence	Lot 340	6/12/2015	Active	No
Current Condition:			n the rear and east sid	e by Landmark Homes prior	to 6/12/2015.
Lot 347	Silt Fence	Lot 347		Removed	
Current Condition:		ark Homes sodded th			
Lot 348	Silt fence	Lot 348	8/25/2015	Active	Yes
Current Condition:	Fair Condition-				
	Silt fence in the r	rear needs to be clean	ed out.		
			nplete by 8/25/2015. N	lot done as of the last insp	ection.
Lot 361	Silt Fence	Lot 361		Removed	
Current Condition:		Construction sodded the			
Lot 364	Silt Fence	Lot 364	5/8/2015	Active	No
Current Condition:				nce in the front prior to 9/9	
Lot 370	Silt fence	Lot 370	8/18/2015	Active	No
Current Condition:				ot by Landmark Homes pr	
Lot 372	Silt Fence	Lot 372	6/23/2014	Active	No
Current Condition:			of 8/29/2015. Silt fend	ce on the side and front wa	as repaired by
		s prior to 9/9/2015.			
Lot 374	Silt fence	Lot 374		Removed	
Current Condition:		one Custom Builders so	odded the lot prior to the		
Lot 378	Silt Fence	Lot 378		Removed	
Current Condition:		nark Homes sodded the	lot prior to the 5/5/15 i		
Lot 384	Silt Fence	Lot 384		Removed	
Current Condition:		s sodded by Landmark	prior to 6/12/2015.		
Lot 391	Silt Fence	Lot 391		Removed	
Current Condition:		s sodded by Landmark	prior to 6/12/2015.		1
Lot 392	Silt Fence	Lot 392		Removed	
Current Condition:		s sodded by Landmark		A - 17	NI.
Lot 393	Silt fence	Lot 393	8/18/2015	Active	No
Current Condition:				ot by Landmark Homes pr	
Lot 399	Silt Fence	Lot 399	4/11/2014	Active	No
Current Condition:				the North side of the lot prio	r to the inspection on
		tone Builders sodded th	ie ioi biioi io iue iusbe		_
Lot 421	Silt Fence	Lot 421		Removed	
Current Condition:		land Homes sodded the	7/04/0045	inspection.	
Lot 431	Individual Lot	Lot 431		Active	No
Current Condition:			s were installed in th	e NE rear prior to 9/9/2015).
Lot 432	Silt Fence	Lot 432	ho lot prior to 4/04/004	Removed	L
Current Condition:	Silt Fence	ustom Homes sodded t Lot 461	12/17/2014		No
Lot 461 Current Condition:				Active es prior to the inspection on	No 12/17/2014
Lot 463	Silt Fence	Lot 463	6/12/2015	Active	12/17/2014. Yes
Current Condition:	Fair Condition-	LUI 400	0/12/2010	HOUVE	163
Current Condition.					
	Silt fence in the rear needs to be repaired or removed. Landmark Homes was informed to complete by 8/25/2015. Not done as of the last inspection.				nection
Lot 464	Silt Fence	Lot 464	.p. 010 07 012012013. N	Removed	
Current Condition:		nark Homes sodded the	lot prior to the 7/31/15		I
Lot 482	Silt Fence	Lot 482	iot phor to the 1/01/10	Removed	
Current Condition:		s sodded by Marasco H	omes prior to 6/12/201		1
STR	Streets	Streets	In Place	Active	No
Current Condition:				r to 8/18/2015 by Landmarl	
		ere cleaned by Renna			
OWDER 5:			•		
SWPPP Sign	SWPPP Signs	6 signs	8/19/2008	Active	No
Current Condition:		&A inspector reinstalle	d the SWPPP sign at 1	197th and Harrison during th	e inspection on
	4/11/2014.				
	2, 1,			77	ary L. Jilek
Inspector's Signature:	But Sul			Reviewed By:	ary ic. your

ı