E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Entire Site; grading completed and site seeded prior to 4/2008.

| Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager | | | | Engineering Answers | | |
|--|-----------------------|---|--------------------|---------------------|-------|--|
| | | E&A- P2008 | 3.207.000 | | Stage | |
| spector: Patrick Sechser | | | | | | |
| | | | Bell Brook | | 3 | |
| roject Name: | | NER111506 9/10/2016 Southwest corner of 192nd and Harrison Street- Omaha, NE (Sarpy County) | | | | |
| or Week Ending: | | | | | | |
| roject Location: | Southwe | | | | | |
| • | | | | | | |
| Grading: | 100 | | | | • | |
| anitary Sewer: | 100 | | | | | |
| torm Sewer: | 100 | | | | | |
| Paving: Geeding: | 100 100 | | | | | |
| Itilities: | 100 | | | | | |
| Overall Development: | 82 | | | | | |
| | | | | | | |
| AIN FALL AMOUNTS | Amount in tenths | Date inspected | Weather Conditions | | | |
| AIN I ALL AMOUNTO | y arrodite in contrib | Date Inspected | Weather Conditions | | Wee | |
| unday: | 0.00" | | | | | |
| londay | 0.00" | | | | | |
| uesday | 0.04" | | | | | |
| Vednesday | 0.00" | | | | | |
| hursday | 0.00" | | | | | |
| riday | 0.56" | | | | | |
| aturday | 0.05" | | | | | |
| Samuel and a | 0.00" | | | | Wee | |
| Sunday: Monday | 0.00" | 08/22/16 | Sunny 84/61 | | | |
| uesday | 2.49" | 00/22/10 | Sullity 64/01 | + | | |
| Vednesday | 0.00" | 08/24/16 | Cloudy 84/69 | + | | |
| Thursday | 0.00" | 00/2 !/ 10 | oloudy oliveo | | | |
| riday | 0.00" | | | | | |
| Saturday | 0.00" | | | | | |
| | | | | | Wee | |
| Sunday: | 0.00" | | | | | |
| Monday | 1.02" | | | | | |
| uesday Vednesday | 0.01" 0.00" | 08/31/16 | 7E/E0 ouppy | + | | |
| Thursday | 0.00" | 00/31/10 | 75/59 sunny | + | | |
| riday | 0.00" | | | | | |
| Saturday | 0.00" | | | | | |
| | 0.00 | | | | Wee | |
| Sunday: | 0.00" | | | | | |
| Monday | 0.00" | | | | | |
| uesday | 0.00" | | | | | |
| Vednesday | 0.03" | | | 1 | | |
| hursday | 0.00" | | | + | | |
| riday Saturday | 0.70" 0.00" | | | + | | |
| atur uay | 0.00 | | | | Wee | |
| unday: | 0.00" | | | | | |
| londay | 0.00" | | | | | |
| uesday | 0.00" | | | | | |
| Vednesday | 0.00" | | | | | |
| hursday | 0.00" | | | 1 | | |
| riday | 0.00" | | | | | |
| aturday | 0.00" | | | 1 | | |
| | Nors | | | | | |
| Complaints: | None | | | | | |
| omplants. | | | | | | |
| | | | | | | |
| | | | | | | |

Entire Site; grading completed and site seeded prior to 4/2008. What temporary or permanent stabilization measures listed in this section are being implemented? Existing Vegetation (4/2008). Harrison St. ROW between 201st and 197th St seed and matting by Sarpy County (8/19/08) Seeding and Matting on the hill south of the ROW between 197th and 199th St. (9/08), seeding and matting on outlot '0' (3/09), removed basin 8 seeded (05/09). Silt Basin 3 seeded and matted (4/2011); Disturbed area behind sediment basin #7 was re-seeded/matted(10/2011); lots 331-335;340-345 were re-seeded/(05/12); Basin #7 area was seeded and the area where the outfall was removed was matted (4/29/2014). SUMMARY QUESTIONS: Are approved entrances and adjacent streets being maintained adequately? Yes CHECKLIST QUESTIONS: Are vereiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes CHECKLIST QUESTIONS: Are waste materials (concrete, construction material, hazardous, etc.) being managed property? Yes Location the street selections (Date): Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section. Projected Install Unique Name Type Location Projected Install Date Status Maintenance Concrete Washout Lot 393 Removed

| | | | Projected Install | | | | |
|-------------------------------|--|------------------------------------|----------------------------|-------------------------------|-------------|--|--|
| Unique Name | Туре | Location | Date | Status | Maintenance | | |
| | Concrete | | | | | | |
| CW 1 | Washout | Lot 393 | | Removed | | | |
| Current Condition: | | | t pit prior to 11/13/2015. | | | | |
| Lot 10 | Silt Fence | Lot 10 | | Removed | | | |
| Current Condition: | | | lot prior to the 6/25/15 | | • | | |
| Lot 20 | Silt Fence | Lot 20 | 8/12/2016 | Active | No | | |
| Current Condition: | Good Condition- L | andmark Homes instal | lled silt fence on the sid | e and in the rear prior to 8/ | 12/2016. | | |
| Lot 23 | Misc/Other | Lot 23 | | Removed | | | |
| Current Condition: | Removed- Bluesto | one Builders sodded th | e lot prior to 9/9/2015. | | | | |
| Lot 30 | Misc/Other | Lot 30 | | Removed | | | |
| Current Condition: | Removed- Prairie | Homes removed the e | els behind the lot prior t | to the inspection on 3/25/20 | 15. | | |
| Lot 32 | Silt Fence | Lot 32 | | Removed | | | |
| Current Condition: | Removed- Ramm | Construction sodded to | he lot prior to 9/25/2015 | j | | | |
| Lot 41 | Silt Fence | Lot 41 | | Removed | | | |
| Current Condition: | Removed- Landm | ark Homes sodded the | lot prior to 9/25/2015. | | | | |
| Lot 46 | Silt Fence | Lot 46 | | Removed | | | |
| Current Condition: | Removed- Vogel : | sodded the lot prior to 6 | 6/12/2015. | | | | |
| Lot 54 | Individual Lot | Lot 54 | | Removed | | | |
| Current Condition: | Removed- Proline | Homes sodded the lot | t prior to 4/21/2016. | | | | |
| Lot 78 | Silt Fence | Lot 78 | | Removed | | | |
| Current Condition: | Removed- Outlot | C has been come estal | blished as of 6/12/2015 | | • | | |
| Lot 88 | Individual Lot | Lot 88 | | Removed | | | |
| Current Condition: | Removed-Proline | Homes sodded the lot | prior to 4/21/2016. | | • | | |
| Lot 135 | Silt Fence | Lot 135 | | Removed | | | |
| Current Condition: | | s sodded by Landmark | prior to 6/12/2015 | | | | |
| Lot 138 | Silt Fence | Lot 138 | D. 10. 10 0/ 12/20 10. | Removed | | | |
| Current Condition: | | st sodded the lot prior | to 8/12/2016. | | <u> </u> | | |
| | | • | | | | | |
| Lot 149 | Individual Lot | Lot 149 | 3/17/2016 | Active | Yes | | |
| Current Condition: | Fair Condition- Di | rt was removed from th | e ROW by Marasco Ho | omes prior to 4/21/2016. | | | |
| | Silt fence on the side and front of the lot needs to be repaired in multiple areas. Marasco Homes was informed to complete by 4/28/2016. Not done as of the last inspection. Marasco Homes was informed to complete by 4/28/2016. | | | | | | |
| | reminded on 7/6/2 | reminded on 7/6/2016, 8/29/16. | | | | | |
| Lot 247 | Misc/Other | Lot 247 | | Removed | 1 | | |
| | | | ot prior to the 5/5/15 ins | | 1 | | |
| Current Condition: Lot 269 | Silt Fence | Lot 269 | ot phor to the 5/5/15 Ins | Removed | | | |
| Current Condition: | | | Lot prior to 0/25/2015 | Removed | 1 | | |
| Lot 301 | Silt Fence | ark Homes sodded the Lot 301 | 101 101 10 9/25/2015. | Removed | | | |
| | | | l in area was andded a | ior to the inspection on 4/3/ | 2015 | | |
| Current Condition: Lot 306 | Silt Fence | s sodded and the slited Lot 306 | 5/3/2016 | Active | | | |
| LUI 300 | SIIL FELICE | LUI 300 | 3/3/2010 | Active | Yes | | |

| Current Condition: | Fair Condition- | | | | | |
|-------------------------------|--|--|--------------------------------|---------------------------------|------------------------|--|
| | | | | | | |
| | Silt fence needs to be reinstalled along the side of the lot. Silt fence needs to be repaired in the corner and silt needs to be removed from adjoining yard. | | | | | |
| | Landmark Homes was informed to complete by 6/25/2016. Not done as of the last inspection. Landmark | | | | | |
| | | | | Not done as of the last insp | ection. Landmark | |
| | Homes was reminded on 7/1/2016, 8/6/2016, 8/26/2016. 2.) Landmark Homes was informed to complete by 8/31/2016. | | | | | |
| 1 1000 | , | 1 1000 | | | T | |
| Lot 308 Current Condition: | Silt Fence Removed- Lot wa | Lot 308 sodded by Woodlands | s prior to 6/12/2015 | Removed | | |
| Lot 314 | Silt Fence | Lot 314 | 5/3/2016 | Active | No | |
| Current Condition: | Good Condition-Silt fence was installed on the side and in the rear prior to 5/3/2016 by Landmark Homes. | | | | | |
| Lot 315 | Silt fence | Lot 315 | | Removed | | |
| Current Condition: | | Life Homes sodded the | lot prior to the 5/5/15 i | | | |
| Lot 320 | Silt Fence | Lot 320 | | Removed | | |
| Current Condition: Lot 322 | Silt Fence | s sodded by Landmark p Lot 322 | 12/15/2015. | Active | No | |
| Current Condition: | | | | rior to the 8/31/16 inspect | | |
| Lot 324 | Silt fence | Lot 324 | | Removed | | |
| Current Condition: | | sodded by Landmark F | | | | |
| Lot 333 Current Condition: | Silt Fence | Lot 333 | 11/13/2015 | Active Trail was cleaned up by | Yes | |
| Current Condition. | prior to 8/24/2010 | | nes prior to 6/30/2010. | Trail was cleaned up by | Landinark Homes | |
| | | | | | | |
| | Adjoining area to | the SW needs to be rese | eeded. | | | |
| | Landmark Homes | was informed to comple | ete the re-seeding by 7 | 7/7/2016. Not done as of la | st inspection | |
| | | s was reminded on 8/6 | | 77720701 1101 00110 00 0110 | ot mopodao | |
| Lot 334 | Individual Lot | Lot 334 | | Removed | 1 | |
| Current Condition: | | ark Homes sodded the I | lot prior to 12/15/2015. | removed | | |
| Lot 335 | Silt Fence | Lot 335 | | Removed | | |
| Current Condition: Lot 340 | Removed- Al Belt Silt Fence | Homes removed the sill Lot 340 | t fence prior to 9/9/201 | 5. Removed | T | |
| Current Condition: | | s sodded by Landmark I | Homes prior to 8/5/201 | | | |
| Lot 347 | Silt Fence | Lot 347 | - | Removed | | |
| Current Condition: | | ark Homes sodded the lo | ot prior to inspection of | | | |
| Lot 348 Current Condition: | Silt fence | Lot 348 s sodded by Landmark I | Homes prior to 6/18/20 | Removed | | |
| Lot 360 | Silt Fence | Lot 360 | 1/20/2016 | Active | l No | |
| Current Condition: | | | | or runoff from lot 360 and D | | |
| | update the report | accordingly. Sidewalk w | as installed prior to 8/ | 12/2016. | | |
| Lot 361 | Silt Fence | Lot 361 | | Removed | | |
| Current Condition: Lot 364 | Removed- Vogel Silt Fence | Construction sodded the Lot 364 | lot prior to 6/12/2015. | Removed | 1 | |
| Current Condition: | | sance Builders sodded | the lot prior to 2/25/20 | | <u> </u> | |
| Lot 366 | Silt Fence | Lot 366 | 3/3/2016 | Active | Yes | |
| Current Condition: | | Changed to lot 366 from e 8/31/16 inspection. | m lot 367. Landmark | Homes reinstalled the sil | t fence on the back of | |
| | the lot prior to th | e ora ir re inspection. | | | | |
| | Silt fence on the | front of the lot was rei | moved and needs to | be reinstalled. | | |
| | Landmark Harra | s was informed to com | anlote by 9/6/46 | | | |
| | | | , | | | |
| Lot 370 Current Condition: | Silt fence | Lot 370 - Landmark Homes rep | 8/18/2015 | Active | No | |
| | | • | Jameu the silt tence p | | | |
| Lot 372 | Silt Fence | Lot 372 | ot prior to 6/2/2010 | Removed | | |
| Current Condition: Lot 374 | Removed-Woodla Silt fence | nd Homes sodded the I Lot 374 | ot prior to 6/3/2016. | Removed | | |
| Current Condition: | Removed - Bluest | one Custom Builders so | odded the lot prior to th | e 5/5/15 inspection. | | |
| Lot 378 | Silt Fence | Lot 378 | latarianta W 5/5/45 | Removed | | |
| Current Condition: Lot 384 | Removed - Landn Silt Fence | nark Homes sodded the Lot 384 | iot prior to the 5/5/15 i | nspection. Removed | | |
| Current Condition: | | s sodded by Landmark | | | | |
| Lot 390 | Silt fence | Lot 390 | 7/20/2016 | Active | No No | |
| Current Condition: | Good Condition- | Trademark Homes ins | stalled silt fence alon | g the street prior to the 8/ | 31/16 inspection. | |
| 1 004 | OH France | 1 =4 004 | | Democrat | T | |
| Lot 391 Current Condition: | Silt Fence Removed- Lot wa | Lot 391 s sodded by Landmark i | prior to 6/12/2015 | Removed | 1 | |
| Lot 392 | Silt Fence | Lot 392 | | Removed | | |
| Current Condition: | | s sodded by Landmark | prior to 6/12/2015. | Dancered | | |
| Lot 393 Current Condition: | Silt fence Removed-Landma | Lot 393 ark Homes sodded the lo | L of prior to inspection of | Removed n 6/3/2016 | | |
| Carrent Condition. | | | po. to mopositori O | | | |

| Lot 398 | Silt Fence | Lot 398 | 6/28/3024 | Active | Yes | |
|------------------------|--|--------------------------|----------------------------|------------------------------|--------------------|--|
| Current Condition: | Fair Condition- Landmark Homes repaired the silt fence on the back of the lot prior to the 8/31/16 | | | | | |
| | inspection. Silt fence on the side needs to be repaired/cleaned out. | | | | | |
| | | | | | | |
| | Landmark Homes | was informed to comp | ete by 5/5/2016. Not do | ne as of the last inspection | on. Landmark Homes | |
| | was reminded on 6/7/2016, 6/21/2016, 7/1/2016, 8/5/2016, 8/26/2016. | | | | | |
| Lot 399 | Silt Fence | Lot 399 | | Removed | | |
| Current Condition: | Removed-Silverstone Builders sodded the lot prior to the inspection on 7/24/2014. Lot 399 will be removed as of 11/2/2015. See Lot 398 | | | | | |
| Lot 421 | Silt Fence | Lot 421 | | Removed | | |
| Current Condition: | Removed - Woodland Homes sodded the lot prior to the 5/5/15 inspection. | | | | | |
| Lot 431 | Individual Lot | Lot 431 | | Removed | | |
| Current Condition: | Removed-Lot was | s sodded by the homeo | wner prior to 6/3/2016. | | • | |
| Lot 432 | Silt Fence | Lot 432 | | Removed | | |
| Current Condition: | Removed- D&E C | Custom Homes sodded | the lot prior to 4/21/2015 | 5. | | |
| Lot 461 | Silt Fence | Lot 461 | 12/17/2014 | Active | Yes | |
| Current Condition: | Fair Condition- | | | | | |
| | Silt fence in the rear needs to be repaired. Landmark Homes was informed to complete by 8/12/2016. Not done as of the last inspection. Landmark Homes was reminded on 8/26/2016. | | | | | |
| Lot 463 | Silt Fence | Lot 463 | 6/12/2015 | Active | No | |
| Current Condition: | Good Condition- Silt fence was installed and extended along the SE corner and side prior to 8/24/2016 by Landmark Homes. | | | | | |
| Lot 464 | Silt Fence | Lot 464 | | Removed | | |
| Current Condition: | Removed - Landr | nark Homes sodded the | lot prior to the 7/31/15 | inspection. | | |
| Lot 482 | Silt Fence | Lot 482 | | Removed | | |
| Current Condition: | Removed- Lot wa | s sodded by Marasco H | lomes prior to 6/12/2019 | 5. | | |
| STR | Streets | Streets | In Place | Active | Yes | |
| Current Condition: | Fair Condition | | | | | |
| | The street in front of lot 370 needs to be cleaned. Landmark Homes was informed to complete by 7/14/16. Not done as of the last inspection. Landmark Homes was reminded on 8/6/2016, 8/26/2016. | | | | | |
| | | | | | | |
| | reminded on 6/6/2 | 2010, 0/20/2010. | | | | |
| SWPPP Sign | SWPPP Signs | 6 signs | 8/19/2008 | Active | No | |
| Current Condition: | Good Condition- I 4/11/2014. | E&A inspector reinstalle | ed the SWPPP sign at 1 | 97th and Harrison during | the inspection on | |
| Inspector's Signature: | Put Sil | | | Reviewed By: | our Sta | |