E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept. Man		E&A- P2008	3.207.000				
nspector: Matthew Russell		EGA- F 2000	J. 201.000		Stage		
mopostor. matthew Nussell			Bell Brook		3		
Project Name:			NER111506				
<u> </u>							
For Week Ending:	Caushina	3/10/2018 Southwest corner of 192nd and Harrison Street- Omaha, NE (Sarpy County)					
Project Location:	Southwes	t corner of 192nd a	nd Harrison Street- Oma	ana, NE (Sarpy County)	68028		
Grading:	1009	6					
Sanitary Sewer:	1009	6					
Storm Sewer:	1009						
Paving:	1009						
Geeding: Utilities:	999						
Overall Development:	999						
Sveran Bevelopment.		<u> </u>					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions				
unday:	0.00"						
londay	0.00"				1		
uesday	0.00"						
Vednesday	0.00"						
hursday	0.00"						
riday	0.00"	1					
Saturday	0.00"				Most		
Sunday:	0.00"	T			Week		
Monday	0.03"		+		 		
uesday	0.03"						
Vednesday	0.00"						
hursday	0.24"	02/22/18	Snow 30/21				
riday	0.00"						
Saturday	0.06"				100 - 1		
Sunday:	0.00"	1			Week		
londay	0.00"						
uesday	0.00"						
Vednesday	0.00"						
hursday	0.00"						
riday	0.00"						
Saturday	0.00"						
	0.00"				Week		
Sunday: Monday	0.13"						
uesday	0.01"						
Vednesday	0.00"						
hursday	0.00"						
riday	0.00"						
Saturday	0.00"						
Sunday	N/A				Week		
Sunday: Monday	N/A N/A	1			 		
Tuesday	N/A						
Vednesday	N/A						
Thursday Thursday	N/A						
riday	N/A						
Saturday	N/A				1		
	None						
Complaints:							
Construction Sequencing: Vhich portion(s) (i.e. drainage basins) of the	a sita haya had a tampa	or normanort coccetion	of grading parthwork of and	und dieturhanco in the last 4.4 days	2		
intire Site; grading completed and si			or graunig, earthwork, or gro	und disturbance in the last 14 days	•		
and one, grading completed and si	10 30000 prior to 4/200	J.					
	:	arthwork or around dia	turbance scheduled in the nex	xt 14 days? :	1		
Which portion(s) (i.e. drainage basins) of the	e site do not have grading, e	artiiwork, or ground dis	tarbance senedaled in the nex	at uujo			

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (4/2008), Harrison St. ROW between 201st and 197th St seed and matting by Sarpy County (8/19/08)

Seeding and Matting on the hill south of the ROW between 197th and 199th St. (9/08), seeding and matting on outlot 'O' (3/09), removed basin 8 seeded (05/09), Silt Basin 3 seeded and matted (4/2011); Disturbed area behind sediment basin #7 was re-seeded/matted(10/2011); lots 331-335;340-345 were reseeded(6/5/12); Basin #7 area was seeded and the area where the outfall was removed was matted (4/29/2014).

SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes

CHECKLIST QUESTIONS:

terial, hazardous, etc.) being managed properly?

Yes

Yes

Comments:

Comments:

Home construction is active in one area of the development as of the last inspection.

Due to frozen conditions and the site being covered in about 2" of snow, not all BMPs may have been fully inspected during the last inspection. BMPs will be fully inspected when weather conditions allow.

Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP section at this time.

			Projected Install		
Unique Name	Type	Location	Date	Status	Maintenance
	Concrete				
CW 1	Washout	Lot 393		Removed	
Current Condition:	Removed-Synera	v removed the washou	ut pit prior to 11/13/2015.		
Lot 10	Silt Fence	Lot 10		Removed	
Current Condition:	Removed - Oakw	ood Homes sodded th	e lot prior to the 6/25/15 ins	spection.	!
Lot 20	Silt Fence	Lot 20		Removed	
Current Condition:		ot was sodded prior to	inspection on 6/8/17.		
Lot 23	Misc/Other	Lot 23		Removed	
Current Condition:			he lot prior to 9/9/2015.		
Lot 30	Misc/Other	Lot 30		Removed	
Current Condition:	Removed- Prairie	Homes removed the	eels behind the lot prior to t	he inspection on 3/25/2	2015.
Lot 32	Silt Fence	Lot 32		Removed	
Current Condition:	Removed- Ramm	Construction sodded	the lot prior to 9/25/2015.		•
Lot 41	Silt Fence	Lot 41		Removed	
Current Condition:	Removed- Landm	nark Homes sodded th	e lot prior to 9/25/2015.		
Lot 46	Silt Fence	Lot 46		Removed	
Current Condition:	Removed- Vogel	sodded the lot prior to	6/12/2015.		-
Lot 54	Individual Lot	Lot 54		Removed	
Current Condition:	Removed- Proline	Homes sodded the lo	ot prior to 4/21/2016.		•
Lot 78	Silt Fence	Lot 78	i	Removed	
Current Condition:			ablished as of 6/12/2015.	7.00.000	
Lot 88	Individual Lot	Lot 88	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Removed	
Current Condition:		Homes sodded the lo	t prior to 4/21/2016	rtomovou	
Lot 135	Silt Fence	Lot 135	t pilor to 4/2 1/2010.	Removed	
Current Condition:		s sodded by Landmar	k prior to 6/12/2015	rtcillovcu	
Lot 138	Silt Fence	Lot 138	K prior to 0/12/2015.	Removed	
Current Condition:		est sodded the lot prior	r to 9/12/2016	Removed	
Lot 149	Individual Lot	Lot 149	1 10 6/12/2010.	Removed	
Current Condition:			e lot prior to the 10/24/16 ins		
Lot 247	Misc/Other	Lot 247		Removed	1
Current Condition:			lot prior to the 5/5/15 inspe		
Lot 269	Silt Fence	Lot 269	Tot prior to the 5/5/15 inspe	Removed	1
Current Condition:			e lot prior to 9/25/2015.	Removed	
Lot 301	Silt Fence	Lot 301		Removed	1
Current Condition:			d in area was sodded prior		2/2015
Lot 306	Silt Fence	Lot 306	u iii area was soqqeq prior	Removed	JIZU 10.
			lot prior to 11/23/2016.	Removed	
Current Condition:			101 prior to 11/23/2016.	Domovod	
Lot 308	Silt Fence	Lot 308		Removed	
Current Condition:		s sodded by Woodlan	as prior to 6/12/2015.	Damarrad	1
Lot 314	Silt Fence	Lot 314	1.1.0.00013	Removed	
Current Condition:			e lot prior to 11/23/2016.	D	1
Lot 315	Silt fence	Lot 315	. 1.4 1 4 5/5/45 :	Removed	
Current Condition:			ne lot prior to the 5/5/15 insp		
Lot 320	Silt Fence	Lot 320	1	Removed	
Current Condition:		s sodded by Landmar	k prior to 11/2/2015.		
Lot 322	Silt Fence	Lot 322		Removed	
Current Condition:	Removed - Landr	nark Homes sodded th	ne lot prior to inspection on	11/8/17.	
Lot 324	Silt fence	Lot 324		Removed	
Current Condition:			Homes prior to 8/29/2015.		-

			1	T	1
Lot 333	Silt Fence	Lot 333	11	Removed	
Current Condition:				016. Trail was cleaned up by f the 10/24/16 inspection.	Landmark Homes
1 -4 224	· .		T vegetated as o	<u> </u>	
Lot 334	Individual Lot	Lot 334		Removed	
Current Condition: Lot 335	Silt Fence	Lot 335	lot prior to 12/15/2015	Removed	
Current Condition:			L It fence prior to 9/9/201		
Lot 340	Silt Fence	Lot 340		Removed	
Current Condition:			Homes prior to 8/5/20		
Lot 347	Silt Fence	Lot 347	Tiomes prior to 6/5/20	Removed	
Current Condition:			ot prior to inspection o		
Lot 348	Silt fence	Lot 348	T prior to inoposition o	Removed	
Current Condition:	Removed- Lot was		Homes prior to 6/18/20)16.	
Lot 358	Silt fence	Lot 358	9/18/2017	Active	Yes
Current Condition:	fence is in place on The silt fence need	s to be retied.		on on the lot prior to inspection	
			mance Homes was re		ils allow. Not doi:
1 1000	<u> </u>		Indice nomes was re		
Lot 360	Silt Fence	Lot 360		Removed	
Current Condition:		omes sodded the lot p	rior to 10///2016.	Dom:	
Lot 361	Silt Fence	Lot 361	Lot prior to 6/40/0045	Removed	
Current Condition: Lot 364	Silt Fence	Lot 364	e lot prior to 6/12/2015 I	Removed	
Current Condition:			the lot prior to 2/25/20		1
Lot 366	Silt Fence	Lot 366	101 pilot to 2/20/20	Removed	
Current Condition:		rk Homes sodded the I	ot prior to 10/7/2016		
Lot 370	Silt fence	Lot 370	2. 00. 30 10///2010.	Removed	
Current Condition:		rk Homes sodded the I	ot prior to 10/7/2016.	. toevea	
Lot 372	Silt Fence	Lot 372	T	Removed	
Current Condition:		nd Homes sodded the	lot prior to 6/2/2016	Removed	
Lot 374	Silt fence	Lot 374	ot prior to 6/3/2010.	Removed	
Current Condition:			I odded the lot prior to th		
Lot 378	Silt Fence	Lot 378	Tuded the lot phot to the	Removed	
Current Condition:			lot prior to the 5/5/15		
Lot 384	Silt Fence	Lot 384	lot prior to the 5/5/15	Removed	
Current Condition:		sodded by Landmark	prior to 6/12/2015	removed	
Lot 390	Silt fence	Lot 390	prior to 0/12/2015.	Removed	
Current Condition:			e lot prior to the 12/26/		
Lot 391	Silt Fence	Lot 391		Removed	
Current Condition:		sodded by Landmark	prior to 6/12/2015.		
Lot 392	Silt Fence	Lot 392		Removed	
Current Condition:		sodded by Landmark	prior to 6/12/2015.	Damayad	
Lot 393	Silt fence	Lot 393	ot prior to inspection o	Removed	
Current Condition: Lot 398	Silt Fence	Lot 398	T prior to inspection o	Removed	
Current Condition:			lot prior to the 12/26/1		
			10t prior to the 12/20/1		
Lot 399	Silt Fence	Lot 399	L	Removed	<u></u>
Current Condition:			e lot prior to the inspec	ction on 7/24/2014. Lot 399 w	ılı be removed as
	11/2/2015. See Lot				
Lot 421	Silt Fence	Lot 421		Removed	
Current Condition:			lot prior to the 5/5/15		
Lot 431	Individual Lot	Lot 431	<u> </u>	Removed	
Current Condition:		sodded by the homeov	vner prior to 6/3/2016.		T
Lot 432	Silt Fence	Lot 432		Removed	
Current Condition:			the lot prior to 4/21/201		
Lot 461	Silt Fence	Lot 461	12/17/2014	Removed	No
Current Condition:	Removed-The stoc		iii uie KOvv as of the t	5/23/17 inspection. Woodland	a mornes sodded t
Lot 463	Silt Fence	Lot 463		Removed	
Current Condition:			lot prior to inspection of		<u> </u>
			T T T T T T T T T T T T T T T T T T T		
Lot 464	Silt Fence	Lot 464	1-4	Removed	
Current Condition:			lot prior to the 7/31/15		
Lot 482	Silt Fence	Lot 482	lamaa prise ta 0/40/00	Removed	
Current Condition: STR	Streets	Streets	lomes prior to 6/12/201 In Place	15. Active	No
Current Condition:			ed the street prior to in		INU
			•		
SWPPP Sign	SWPPP Signs	6 signs	8/19/2008	Active	No
	IGood Condition- Fa	ልA inspector reinstalle	d the SWPPP sign at '	197th and Harrison during the	e inspection on
Current Condition:		•			
Current Condition:	4/11/2014.				
	4/11/2014.				
		<u> </u>		63	t 500