	E&A	- P2008.207.000							
Inspector: Sean Conway									
Project Name:		Bell Brool	Stage 2						
For Week Ending:		6/14/2008							
I OF PACEN LIMING. U/ 14/2000									
Grading:	100%			T					
Sanitary Sewer:	100%								
Storm Sewer:	100%								
Paving:	100%								
Seeding:	100%								
Utilities: Overall Development:	100% 45%								
Overall Development.	4570								
DAIN FALL AMOUNTS	Amount in tenths	Data la caracte d							
RAIN FALL AMOUNTS	Amount in tenths	Date inspected		Wook 4					
Sunday:	0.01"			Week 1					
Monday	0.02"								
Tuesday	0.52"								
Wednesday	0.26"	05/28/08							
Thursday	0.13"								
Friday	2.25"	05/30/08							
Saturday	0.00"								
	0.000 4.550	N 0/0/00		Week 2					
Sunday:	0.00"; <b>1.55"</b> 0.00"; <b>0.10"</b>	None; 6/8/08 None: 6/9/08							
Monday Tuesday	0.13"; 0.00"	None, 6/9/06							
Wednesday	0.68"; 2.24"								
Thursday	0.99"; 0.04"	6/5/2008; 6/12/08							
Friday	0.00"; 0.00"								
Saturday	<b>0.06"</b> ; 0.00"								
	None								
Complaints:									
Construction Sequencing:									
Which portion(s) (i.e. drainage basins) of th	e site have had a tempo	rary or permanent cessati	ion of grading, earthwork, o	or ground disturbance in the last					
14 days?	•			•					
Entire Site; grading completed and si	te seeded prior to 4/2	2008.							
				Τ					
Which portion(s) (i.e. drainage basins) of th	ne site do not have gradi	ng, earthwork, or ground	disturbance scheduled in the	he next 14 days? :					
, , , , , , , , , , , , , , , , , , , ,		3, ,							
Entire Site; grading completed and si	te seeded prior to 4/2	2008.							
			1	Т					
What temporary or permanent stabilization	measures listed in this	section are being impleme	ented?						
Existing Vegetation (4/2008)									
zwewig regeration ( wzeee)									
Comments:									
Comments:									
Home construction is the only activity on site.									
Findings / Corrective Actions (Date									
Findings / Corrective Actions (Date	0).								
,	,	and needs to be repaire	ed and/or cleaned out 1	Bryan with Groundworks					
1) Varies lot level silt fence is down/damaged and/or full and needs to be repaired and/or cleaned out. Bryan with Groundworks was directed to complete maintenance by 5/2/08. As of inspection on 6/5/08 maintenance was not complete. Groundworks is									
aware of overdue maintenance and was reminded to complete ASAP.									
aware of overduc mannerance and was reminded to complete AGA.									

- 2) Erosion rills in outlot south of the club house and erosion in outlot northeast of closed sediment basin #9 needs to be repaired and area needs to be seeded and matted. Bryan with Groundworks was directed to complete maintenance by 5/2/08. As of inspection on 6/5//08 maintenance was not complete. Groundworks is aware of overdue maintenance and was reminded to complete ASAP.
- 3) Straw wattle at the bottom of the slope along Harrison Street is damaged and needs to be removed. Erosion rills also need to be repaired and slope needs to seeded and matted. Bryan with Groundworks was directed to complete maintenance by 5/2/08. As of inspections on 5/21 and 5/23 maintenance was not completed. As of inspection on 5/30/08 maintenance was not complete. Groundworks is aware of overdue maintenance and was reminded to complete ASAP.
- 4) Some maintenance is required in the BMP section.

			Projected Install		
Unique Name	Type	Location	Date	Status	Maintance

	Sediment	N41d00m00s					
SB 1	Basin	W96d00m00s		Removed			
Current Condition:	Removed						
	Sediment	N41d00m00s					
SB 2	Basin	W96d00m00s		Removed			
Current Condition:	Removed						
	Sediment	N41d00m00s					
SB 3	Basin	W96d00m00s	In Place	Active	Yes		
Current Condition:	Good Condition						
	Outlet pipe is damaged and needs to be repaired. Rip rap needs to be added at outlet pipe.						
	As of inspection on 6/5/08 maintenance was not complete. Groundworks is aware of overdue maintenance and was reminded to complete ASAP						
	Sediment	N41d00m00s					
SB 4	Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition						
	Sediment	N41d00m00s					
SB 5	Basin	W96d00m00s		Removed			
Current Condition:	Removed	Removed					
	Sediment	N41d00m00s					
SB 6	Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition	Good Condition					
	Sediment	N41d00m00s					
SB 7	Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition						
00.0	Sediment	N41d00m00s					
SB 8	Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition Sediment	Good Condition Sediment N41d00m00s					
SB 9	Basin	W96d00m00s		Removed			
Current Condition:	Removed	vv 30000111005		Nemoveu			
ourient condition.	Removed	N41d00m00s					
SF 1	Silt Fence	W96d00m00s	In Place	Active	No		
Current Condition:	Fair Condition- Partially removed						
		N41d00m00s					
STR	Streets	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition	<ul> <li>No majors signs of tra</li> </ul>	ack off.				
nspector Signature:	Reviewed By: Zachany K. Jilda						