E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	- P2005.198.000		-	
			Stage	
	Clearwat	ter Falls	3	
	3/12/2016			
48th	68123			
	75%			
	1			
Amount in tenths	Date inspected	Weather Conditions		
2.22			Wee	
0.00"			Wee	
lo oo"			vvee	
	02/23/16	Suppy 48/28		
	02/23/10	Juliny 40/20		
0.00			Wee	
0.00"				
0.00"				
0.00"				
			Wee	
0.00"				
0.00"				
0.00"				
0.00"				
0.00"				
0.00"				
0.12"				
			Wee	
N/A	N/A			
N/A				
N/A	N/A			
N/A	N/A			
N/A	N/A			
Ta.				
None				
	Amount in tenths Amount in tenths 0.00"	NER12 3/12/2	100% 100%	

Construction Sequencing:

sins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

hich portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance schedul

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011); Outlot L was graded, seed and matted (5/22/2014); 42nd Street and 43rd Avenue was temp seeded (5/22/2014); Additional matting was installed on the South side of Outlot L (8/4/2014); Matting has been installed on the side slopes surrounding outlot M Basin (12/15/2014);

SUMMARY QUESTIONS:

re approved entrances and adjacent streets being maintained adequately?

No. See BMP Section

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

CHECKLIST QUESTIONS:

Yes

s dust associated with the construction activity adequately controlled on the site?

Comments:

Comments:

Celebrity Homes is actively building in the South part of the development. Home Construction is active in the North part of the development by various builders.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP Section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CW 5	Concrete Washout	Lot 387		Removed		
Current Condition:		Removed-Celebrity Homes removed the concrete washout prior to inspection on 11/12/2015.				
CW 6	Concrete Washout	Lot 359	11/12/2015	Active	No	
Current Condition:	Good Condition- A berm was	Good Condition- A berm was installed in front of the washout prior to 12/23/2015 by Celebrity Homes.				
Lot 16	Individual Lot	Lot 16	6/12/2015	Active	No	
Current Condition:	Active- Excavation has begur rear of the lot, BMPs are pres				fer strip in the	
Lot 17	Individual Lot	Lot 17		Removed		
Current Condition:	Removed- Newport Homes s	odded the lot prior to	11/12/2015.			
Lot 54	Silt Fence	Lot 54		Removed		
Current Condition:	Removed-Nick Peterson sod	ded the lot prior to ins	spection on 5/28/15.			
Lot 57	Silt Fence	Lot 57		Removed		
Current Condition:	Removed-Horizon Homes so	dded the lot prior to in	nspection on 5/28/15.			
Lot 59	Individual Lot	Lot 59		Removed		
Current Condition:	Removed- Horizon Homes so	odded the lot prior to	11/12/2015.			
Lot 76	Silt Fence	Lot 76		Removed		
Current Condition:	Removed- Lot was sodded by	y Proline Homes prior	to 7/31/2015.			
Lot 80	Silt Fence	Lot 80		Removed		
Current Condition:	Removed- Horizon Homes so	Removed- Horizon Homes sodded the lot prior to 6/11/2015.				
Lot 82	Silt Fence	Lot 82		Removed		
Current Condition:	Removed- Lot was sodded by	Legacy Homes prior	r to 9/18/2015.			
Lot 89	Individual Lot	Lot 89	12/14/2015	Active	No	
Current Condition:	Active- Lot was excavated by monitor runoff.		prior to 12/14/2015. Due to	the lot being f	lat, E&A will	
Lot 132	Silt Fence	Lot 132		Removed		
Current Condition:		Removed- Regency Homes sodded the lot prior to 4/19/2015.				
Lot 155	Silt Fence	Lot 155		Removed		
Current Condition:	Removed- Regency Homes s	odded the lot prior to	4/19/2015.			
Lot 255	Individual Lot	Lot 255		Removed		
Current Condition:	Removed - Legacy Homes so	odded the lot prior to	the 6/24/15 inspection.	•		
Lot 258	Silt Fence	Lot 258		Removed		

Current Condition:	Removed-Charleston Homes	sodded the lot prior to ir	spection on 5/14/15.		
Lot 259	Silt Fence	Lot 259		Removed	
Current Condition:	Removed-Charleston Homes				
Lot 260	Individual Lot	Lot 260	9/8/2015	Active	No No
Current Condition:	Active- Dirt was removed from will monitor runoff.	1 the ROW prior to 10/28	8/2015 by Sherwood Hol	mes. Lot is curren	пу пат. Е&А
Lot 261	Individual Lot	Lot 261	10/28/2015	Active	No
Current Condition:	Active- Dirt was removed fron will monitor runoff.	n the ROW prior to 10/28	3/2015 by Sherwood Ho		tly flat. E&A
Lot 272	Silt Fence	Lot 272	3/1/2016	Pending	Yes
Current Condition:	Pending				
	Silt fence needed in the real	ormed to complete by 3			
Lot 284	Silt Fence	Lot 284	12/14/2015	Active	Yes
Current Condition:	1.) Dirt needs to be removed 2.) Silt fence needs to be en 1.) Sherwood Homes was in 2.) Sherwood Homes was in	trenched and repaired	y 3/1/2016.		
Lot 282	Silt Fence	Lot 282	0/1/2010.	Removed	
Current Condition:	Removed- Oakwood Homes		the rear prior to 7/26/20		
Lot 286	Silt Fence	Lot 286		Removed	
Current Condition:	Removed-Sherwood Homes		spection on 7/8/15.		
Lot 300	Silt Fence	Lot 300	21/2215	Removed	
Current Condition:	Removed- Pinecrest Homes		31/2015. 3/1/2016	Dandina	V
Lot 307 Current Condition:	Silt Fence Pending	Lot 307	3/1/2016	Pending	Yes
	Silt fence needed in the real			1.	
	Sherwood Homes was infor		1/2016.		
Lot 324	Silt Fence	Lot 324		Removed	
Current Condition:	Removed-Sherwood Homes		spection on 7/8/15.		
Lot 325 Current Condition:	Silt fence Removed- Lot was sodded by	Lot 325	to 11/17/2015	Removed	
Lot 326	Silt Fence	Lot 326	10 11/1//2015.	Removed	
Current Condition:	Removed-Sherwood Homes		spection on 7/16/15.	rtomovou	
Lot 328	Silt Fence	Lot 328		Removed	
Current Condition:	Removed-Oakwood Homes re		odded the lot prior to insp		
Lot 329	Temp. Seeding	Lot 329		Removed	
Current Condition:	Removed- As of 8/10/2015, Id	ot has filled in and temp s Lot 336	seeding is not needed.	Domested	
Lot 336 Current Condition:	Temp. Seeding Removed- As of 8/18/2015, Id		acadina is not needed	Removed	
Lot 336	Silt Fence	Lot 336	3/1/2016	Pending	Yes
Current Condition:	Pending	201 000	0/ 1/2010	1 origing	100
	Silt fence needed in the real			1.	
Lot 337	Sherwood Homes was infor	med to complete by 3/	1/2016.		
	Silt Fence	Lot 337	1/2016.	Removed	
Current Condition:		Lot 337		inspection on 5/2	8/15.
Current Condition: Pod F	Silt Fence Removed-Sherwood Homes r Silt Fence	Lot 337 removed the silt fence ar Lots 426-454	nd sodded the lot prior to	nspection on 5/2 Removed	8/15.
Current Condition: Pod F Current Condition:	Silt Fence Removed-Sherwood Homes r Silt Fence Removed-Lots 427 and 428 w	Lot 337 removed the silt fence an Lots 426-454 vere sodded prior to 12/1	nd sodded the lot prior to	inspection on 5/2 Removed es.	
Current Condition: Pod F Current Condition: Pod G	Silt Fence Removed-Sherwood Homes r Silt Fence Removed-Lots 427 and 428 v Silt Fence	Lot 337 removed the silt fence at Lots 426-454 vere sodded prior to 12/1 Lots 404-425	nd sodded the lot prior to //2015 by Celebrity Hom 4/8/2014	n inspection on 5/2 Removed es. Active	Yes
Current Condition: Pod F Current Condition:	Silt Fence Removed-Sherwood Homes of Silt Fence Removed-Lots 427 and 428 of Silt Fence Fair Condition-Silt fence on the and repaired in the rear of lot 1.) Silt fence needs to be entre 2.) Silt fence needs to be repaired.	Lot 337 removed the silt fence at Lots 426-454 vere sodded prior to 12/1 Lots 404-425 refront and side of lot 40 404 prior to 12/23/2015. renched in the rear of lot paired on complete by 12/2 med to complete by 12/2	nd sodded the lot prior to 1/2015 by Celebrity Hom 4/8/2014 95 were repaired by Cele 405. 404 and side of lot 405	inspection on 5/2 Removed es. Active brity Homes prior	Yes to 12/14/2015
Current Condition: Pod F Current Condition: Pod G	Silt Fence Removed-Sherwood Homes of Silt Fence Removed-Lots 427 and 428 of Silt Fence Fair Condition-Silt fence on the silt fence on the silt fence needs to be entered to be silt fence needs to be reported to the silt fence needs to	Lot 337 removed the silt fence at Lots 426-454 vere sodded prior to 12/1 Lots 404-425 ee front and side of lot 40 404 prior to 12/23/2015. enched in the rear of lot paired on corner of lot med to complete by 12/2 26/2015, 2/23/2016.	nd sodded the lot prior to 1/2015 by Celebrity Hom 4/8/2014 15 were repaired by Cele 405. 404 and side of lot 405 21/2015. Not done as of	inspection on 5/2 Removed es. Active brity Homes prior	Yes to 12/14/2015
Current Condition: Pod F Current Condition: Pod G Current Condition:	Silt Fence Removed-Sherwood Homes of Silt Fence Removed-Lots 427 and 428 of Silt Fence Fair Condition-Silt fence on the and repaired in the rear of lot 1.) Silt fence needs to be entre 2.) Silt fence needs to be repaired. 1.) Celebrity Homes was infor Homes was reminded on 12/2 2.) Celebrity Homes was infor the single single sill fence needs to be repaired.	Lot 337 removed the silt fence at Lots 426-454 vere sodded prior to 12/1 Lots 404-425 ee front and side of lot 40 404 prior to 12/23/2015. enched in the rear of lot paired on corner of lot med to complete by 12/2 26/2015, 2/23/2016. ormed to complete by 19/2	nd sodded the lot prior to 1/2015 by Celebrity Hom 4/8/2014 15 were repaired by Cele 405. 404 and side of lot 405 21/2015. Not done as of	inspection on 5/2 Removed es. Active brity Homes prior the last inspection	Yes to 12/14/2015
Current Condition: Pod F Current Condition: Pod G Current Condition:	Silt Fence Removed-Sherwood Homes of Silt Fence Removed-Lots 427 and 428 of Silt Fence Fair Condition-Silt fence on the and repaired in the rear of lot 1.) Silt fence needs to be entre 2.) Silt fence needs to be repaired. 1.) Celebrity Homes was infor Homes was reminded on 12/2 2.) Celebrity Homes was infor Silt Fence	Lot 337 removed the silt fence at Lots 426-454 vere sodded prior to 12/1 Lots 404-425 ee front and side of lot 40 404 prior to 12/23/2015. enched in the rear of lot paired on corner of lot med to complete by 12/2 26/2015, 2/23/2016. ormed to complete by Lots 455-473	nd sodded the lot prior to 1/2015 by Celebrity Hom 4/8/2014 15 were repaired by Cele 405. 404 and side of lot 405 21/2015. Not done as of 3/1/2016.	inspection on 5/2 Removed es. Active brity Homes prior the last inspection Removed	Yes to 12/14/2015
Current Condition: Pod F Current Condition: Pod G Current Condition:	Silt Fence Removed-Sherwood Homes of Silt Fence Removed-Lots 427 and 428 of Silt Fence Fair Condition-Silt fence on the and repaired in the rear of lot 1.) Silt fence needs to be entre 2.) Silt fence needs to be repaired. 1.) Celebrity Homes was infor Homes was reminded on 12/2 2.) Celebrity Homes was infor the single single sill fence needs to be repaired.	Lot 337 removed the silt fence at Lots 426-454 vere sodded prior to 12/1 Lots 404-425 ee front and side of lot 40 404 prior to 12/23/2015. enched in the rear of lot paired on corner of lot med to complete by 12/2 26/2015, 2/23/2016. ormed to complete by Lots 455-473	nd sodded the lot prior to 1/2015 by Celebrity Hom 4/8/2014 15 were repaired by Cele 405. 404 and side of lot 405 21/2015. Not done as of 3/1/2016.	inspection on 5/2 Removed es. Active brity Homes prior the last inspection Removed	Yes to 12/14/2015
Current Condition: Pod F Current Condition: Pod G Current Condition: Pod H Current Condition:	Silt Fence Removed-Sherwood Homes in Silt Fence Removed-Lots 427 and 428 w Silt Fence Fair Condition-Silt fence on the and repaired in the rear of lot 1.) Silt fence needs to be entre 2.) Silt fence needs to be reputable. 1.) Celebrity Homes was infor Homes was reminded on 12/2 2.) Celebrity Homes was infor Silt Fence Removed- Lot 460 was sodde	Lot 337 removed the silt fence ar Lots 426-454 vere sodded prior to 12/1 Lots 404-425 re front and side of lot 40 404 prior to 12/23/2015. renched in the rear of lot paired on corner of lot med to complete by 12/2 26/2015, 2/23/2016. remed to complete by 12/3 Lots 455-473 red by Celebrity Homes p Lots 346-355	nd sodded the lot prior to 1/2015 by Celebrity Hom 4/8/2014 15 were repaired by Cele 405. 404 and side of lot 405 21/2015. Not done as of 3/1/2016.	inspection on 5/2 Removed es. Active brity Homes prior the last inspection Removed 4/25/2015.	Yes to 12/14/2015

Current Condition:	Fair Condition-					
	1.) Silt fence needs to be reinstalled on the side of lot 387.					
	2.) Silt fence needs to be repaired in the rear of lot 387.					
	3.) Silt fence needs to be installed on the front of lots 381-387.					
	4.) Silt fence repair needed in the rear and side of lot 381.					
	5.) Silt fence needs to be extended along the curb line of lot 381.					
	6.) Silt fence needs to be reinstalled in the rear of lot 382.					
	1.) Celebrity Homes was in	formed to complete by 11/4	1/2015. Not done as of t	he last inspection	n. Celebrity	
	Homes was reminded on 1				Ť	
	2.) Celebrity Homes was informed to complete by 12/8/2015. Not done as of the last inspection. Celebrity					
	Homes was reminded on 1					
	3.) Celebrity Homes was informed to complete by 3/1/2016. 4.) Celebrity Homes was informed to complete by 3/1/2016.					
	5.) Celebrity Homes was i	nformed to complete by	3/1/2016.			
	6.) Celebrity Homes was i	nformed to complete by	3/1/2016.			
Pod K	Silt Fence	Lots 372-403	4/9/2015	Active	Yes	
Current Condition:	Fair Condition- Celebrity		ence in the rear of lot	374 and remove	d the dirt from	
	the ROW on lots 374 and	375 prior to 2/23/2016.				
	1.) Silt fence needed on the	ne front of lots 374 and 3	75.			
	2.) Lots 372 and 373 need					
	 Celebrity Homes was in 2.) Celebrity Homes was in 			a last inspection	Colobritu	
	Homes was reminded on 2		2016. Not done as of th	e last inspection.	Celebrity	
Pod L	Silt Fence	Lots 371-356	11/4/2015	Active	Yes	
Current Condition:	Fair Condition-	2003 07 1 000	11/4/2010	7 touve	103	
	1.) Silt fence needs to be e		0 1 000			
	2.) Dirt needs to be remove 3.) Wattles need to be ren			stalled on the no	orth side of lot	
	371.	noved on the front of lot	or i and silt lence tens	staned on the ne	orth side of lot	
	4.) Silt fence needed in the rear of lot 366 and to have the silt fence extended towards the south.					
	5.) Silt fence needs to be	installed on the front of l	ots 371-366.			
	4 \ Colobeits Lorgon upo informed to acceptate by 40/00/0045 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					
	 Celebrity Homes was informed to complete by 12/30/2015. Not done as of the last inspection. Celebrit Homes was reminded on 2/23/2016. Celebrity Homes was informed to complete by 12/8/2015. Not done as of the last inspection. Celebrity 					
	Homes was reminded on 1					
	3.) Celebrity Homes was i					
		/ Homes was informed to complete by 3/1/2016. / Homes was informed to complete by 3/1/2016.				
SB 1	Sediment Basin	Outlot "M"	In Place	Active	No	
Current Condition:	Good Condition-30% Filled		from the basin and the	slopes were seed	ded and matted	
	by the SID prior to inspection	on on 10/23/14.				
SB 3	Sediment Basin	School Lot 165	In Place	Active	No	
Current Condition:	Good Condition-20% Filled					
	-Cleaned out 02/06					
SB 5	Sediment Basin Good Condition- 15% Filled	Outlot "L"	11/17/2009	Active	No	
Current Condition:	- JC Excavating installed pr	=	09.			
	oo Excavating metanoa pr	48th Street & Interior		T		
STR	Street Cleaning	streets	5/1/2007	Active	Yes	
Current Condition:	Fair Condition- Celebrity Ho	omes and Horizon Homes	street cleaned prior to 1	0/29/2015		
	Onward and St.					
	Several areas of the curb lines need to be cleaned, especially on 42nd Avenue. Celebrity Homes was informed to complete by 10/29/2015. Not done as of the last inspection. Celebrity Homes was reminded on 12/2/2015, 12/16/2015, 12/26/2015, 2/23/2016.					
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No	
Current Condition:	Good Condition: 48th and E	DITCHWOOD DIIVE				
	to Sul			Zadrany L	ا علمالمال. م	
Inspector Signature:	5 AV		Reviewed By:		4	
-p		<u>-1</u>	- · · · · · · · · · · · · · · · · · · ·			