E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	E&P	۸- P2005.198.000		•	
nspector: Branson Starns				Stage	
		Clearwater Falls			
Project Name:		NER110			
For Week Ending:		4/8/2017			
Project Location:	48th	n and Fairview Road- Belle	evue, NE (Sarpy County)	68123	
	-		, , , , , , , , , , , , , , , , , , , ,		
Grading:	1	100%			
Sanitary Sewer:		100%			
Storm Sewer:		100%			
Paving:	1	100%			
Seeding:	1	100%			
Jtilities:	1	100%			
Overall Development:		85%			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	West	
Sunday:	0.01"			Weel	
Monday	0.01"				
uesday	0.00"				
Vednesday	0.00"				
Thursday	0.00"				
riday	0.00"				
Saturday	0.00"				
				Weel	
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
riday	0.39"				
Saturday	0.36"				
	0.00"			Weel	
Sunday:	0.00"	2/22/22/2			
Monday	0.00"	3/27/2017	Overcast 50/44		
Tuesday	0.00"				
Wednesday	1.60"				
Thursday	0.00"	2/24/2047	0		
Friday	0.00"	3/31/2017	Overcast 54/40		
Saturday	0.02"			Week	
Sunday	0.06"			Week	
Sunday: Monday	0.06" 0.01"		 		
ruesday	0.01"		 		
Vednesday Vednesday	0.00"		+ +		
Thursday	0.00"	1	+ +		
Friday	0.00"	1			
Saturday	0.00"		+		
	10.00			Wee	
Sunday:	N/A			vvee	
Monday	N/A	1	+		
Tuesday	N/A	1	+		
Vednesday	N/A N/A		+ + + + + + + + + + + + + + + + + + + +		
Thursday	N/A		+ + + + + + + + + + + + + + + + + + + +		
-riday	N/A	<u> </u>	 		
Saturday	N/A	<u> </u>	 		
- m.m. muj	11000	L	<u> </u>	I	
Complaints:	None				

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading completed and entire site seeded prior to 2005.

Entire Site; JC Excavating completed grading Lots 346 through 480 Section II, drainage area 1 and 2 (11/2009).

Entire site is now inactive for major grading activities as of the inspection on 11/20/2013.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, dense vegetation and landscaping, Seed and straw mulch over ROW in Northwest quarter of SID (10/08), Sod on various lots (Fall '08), New phase, lots 346-480, seeded (4/10); Outlot B was seeded (6/2011); Lots 16-19 was seeded (8/2011); Outlot L was graded, seed and matted (5/22/2014); 42nd Street and 43rd Avenue was temp seeded (5/22/2014); Additional matting was installed on the South side of Outlot L (8/4/2014); Matting has been installed on the side slopes surrounding outlot M Basin (12/15/2014);

SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

CHECKLIST QUESTIONS:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No- see BMP section.

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

Celebrity Homes is actively building in the South part of the development. Home Construction is active in the North part of the development by various builders.

Findings / Corrective Actions (Date)

Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP Section.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance	
CW 5	Concrete Washout	Lot 387	1 Tojecteu mstan Date	Removed	Wantenance	
Current Condition:	Removed-Celebrity Homes		washout prior to inspection			
CW 6	Concrete Washout	Lot 359	Wadnest prior to inopositori	Removed		
Current Condition:	Removed- Washout pit was removed by Celebrity Homes prior to 3/30/2016.					
CW 7	Concrete Washout	Lot 361		Removed		
Current Condition:	Removed- due to the progre Builders will washout on the install a washout.					
Lot 16	Individual Lot	Lot 16		Removed		
Current Condition:	Removed- Outlot B was see	ded and matted by Ho	rizon Homes prior to 5/27/20	016.		
Lot 17	Individual Lot	Lot 17		Removed		
Current Condition:	Removed- Newport Homes	sodded the lot prior to	11/12/2015.			
Lot 54	Silt Fence	Lot 54		Removed		
Current Condition:	Removed-Nick Peterson so	dded the lot prior to ins	spection on 5/28/15.		•	
Lot 57	Silt Fence	Lot 57		Removed		
Current Condition:	Removed-Horizon Homes s	odded the lot prior to in	nspection on 5/28/15.			
Lot 59	Individual Lot	Lot 59		Removed		
Current Condition:	Removed- Horizon Homes s	sodded the lot prior to	11/12/2015.			
Lot 60	Silt Fence	Lot 60		Removed		
Current Condition:	Removed- Horizon Homes s	sodded the lot prior to	11/1/16.		•	
Lot 69	Silt Fence	Lot 69	2/3/2017	Active	No	
Current Condition:	prior to 1/27/17. The silt fend	Good Condition- Sherwood Homes started construction on the lot and installed silt fence in the rear of the lot prior to 1/27/17. The silt fence in the rear of the lot does not need extended further southward upon re-evaluation of the lot due to the grade. Inspector will continue to monitor the lot.				
Lot 76	Silt Fence	Lot 76		Removed		
Current Condition:	Removed- Lot was sodded I	ov Proline Homes prior	to 7/31/2015.		•	
Lot 80	Silt Fence	Lot 80		Removed		
Current Condition:	Removed- Horizon Homes s	sodded the lot prior to 6	6/11/2015.		-	
Lot 82	Silt Fence	Lot 82		Removed		
Current Condition:	Removed- Lot was sodded I	by Legacy Homes prior	to 9/18/2015.			
Lot 88	Silt Fence	Lot 88		Removed		
Current Condition:	Removed- Legacy Homes s	odded the lot prior to 1	1/22/16.		•	
Lot 89	Individual Lot	Lot 89		Removed		
Current Condition:	Removed- the Home Compa	any sodded the lot prio	r to 11/1/16.		•	
Lot 132	Silt Fence	Lot 132		Removed		

Lot 155	Silt Fence	Lot 155		Removed	
Current Condition:	Removed- Regency Homes		19/2015.		
Lot 209-210 Current Condition:	Silt Fence Removed- Celebrity Homes	Lots 209-210	/1/16 Colobrity Homos	Removed	aining ailt fanca
Current Condition.	prior to 3/27/17.	souded the lot phot to 11	71710. Celebrity Florites i	emoved the rem	alling silt lence
Lot 255	Individual Lot	Lot 255		Removed	
Current Condition:	Removed - Legacy Homes		6/24/15 inspection.		
Lot 256	Silt Fence	Lot 256	100.140	Removed	
Current Condition:	Removed- Regency Homes	sodded the lot prior to 11	/22/16.		
Lot 258	Silt Fence	Lot 258		Removed	
Current Condition: Lot 259	Removed-Charleston Home Silt Fence	es sodded the lot prior to it	rspection on 5/14/15.	Removed	I
Current Condition:	Removed-Charleston Home		nspection on 5/14/15.	removed	
		·	' T		1
Lot 260 Current Condition:	Individual Lot Removed- Sherwood Home	Lot 260	/27/2016	Removed	
Lot 261	Individual Lot	Lot 261	12112010.	Removed	
Current Condition:	Removed- Sherwood Home		/27/2016.		•
Lot 272	Silt Fence	Lot 272		Removed	
Current Condition:	Removed- Dean Vogel sodo	ded the lot prior to 8/12/20	116.		
Lot 273	Silt Fence	Lot 273	9/26/2016	Active	No
Current Condition:	Good Condition- The drivey				
	need for a BMP along the frethe lot prior to 3/27/17.	ont of the lot. Sherwood I	nomes retied the silt fe	nce to the t-pos	t in the rear of
	-				
Lot 274 Current Condition:	Silt Fence Removed- Regency Homes	Lot 274	/14/16	Removed	
	Removed- Regency Homes	1	1	Γ	
Lot 276	Silt Fence	Lot 276	9/13/2016	Active	Yes
Current Condition:	Fair Condition-				
	Silt fence needs reinstalle	d in the rear of the lot or	the lot needs sodded.		
	Dean Vogel was informed	to complete by 4/3/17.			
Lot 277	Silt Fence	Lot 277		Removed	
Current Condition:		ken as lot 276 This was a	, ,	Γ	
Lot 280	Silt Fence	Lot 280	3/6/2017	Active	No ot prize to
	Silt Fence Good Condition- Sherwoo	Lot 280	3/6/2017		
Lot 280	Silt Fence	Lot 280	3/6/2017		
Lot 280 Current Condition:	Silt Fence Good Condition- Sherwood 3/27/17.	Lot 280 d Homes entrenched th	3/6/2017 e silt fence along the si	de/rear of the lo	ot priro to
Lot 280 Current Condition: Lot 281 Current Condition:	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sode	Lot 280 d Homes entrenched th Lot 281 ded the lot prior to 8/12/20	3/6/2017 e silt fence along the si	de/rear of the leader of the l	ot priro to
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence	Lot 280 d Homes entrenched th Lot 281 ded the lot prior to 8/12/20	3/6/2017 e silt fence along the silt 16 and removed the silt	de/rear of the lo	ot priro to
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition:	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Home	Lot 280 d Homes entrenched th Lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5	3/6/2017 e silt fence along the silt 16 and removed the silt	Removed Removed Removed	ot priro to
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Home Silt Fence	Lot 280 d Homes entrenched the Lot 281 ded the lot prior to 8/12/20 Lot 284 as sodded the lot prior to 5 Lot 282	3/6/2017 e silt fence along the silt 116 and removed the silt 127/2016.	Removed Removed Removed Removed	ot priro to
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition:	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Home	Lot 280 d Homes entrenched the Lot 281 ded the lot prior to 8/12/20 Lot 284 as sodded the lot prior to 5 Lot 282	3/6/2017 e silt fence along the silt 116 and removed the silt 127/2016.	Removed Removed Removed Removed	ot priro to
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition:	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodd Silt Fence Removed- Sherwood Home Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additiona	Lot 280 d Homes entrenched the lot 281 ded the lot prior to 8/12/20 Lot 284 es sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 al t-post was needed in the	3/6/2017 e silt fence along the silt into and removed the silt into an analysis and removed the silt and removed the silt into an analysis and removed the silt into an analysis and removed the silt and removed the silt into an analysis and removed the silt into	Removed Removed Removed Removed Active Relot and the si	Yes It fence needed
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Home Silt Fence Removed- Oakwood Homes Silt Fence	Lot 280 d Homes entrenched the lot 281 ded the lot prior to 8/12/20 Lot 284 es sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 al t-post was needed in the	3/6/2017 e silt fence along the silt into and removed the silt into an analysis and removed the silt and removed the silt into an analysis and removed the silt into an analysis and removed the silt and removed the silt into an analysis and removed the silt into	Removed Removed Removed Removed Active Relot and the si	Yes It fence needed
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additional repaired. Sherwood Homes	Lot 280 d Homes entrenched the lot 281 ded the lot prior to 8/12/20 Lot 284 is sodded the lot prior to 5 Lot 282 s removed the slit fence in Lot 285 all t-post was needed in the repaired the slit fence and	3/6/2017 e silt fence along the silt 16 and removed the silt 1/27/2016. 1 the rear prior to 7/26/20 1 the rear prior to 7/26/20 2 silt fence in the rear of the diadded t-posts prior the	Removed Removed Removed Removed Active Relot and the si	Yes It fence needed
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodd Silt Fence Removed- Sherwood Home Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additiona	Lot 280 Lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 al t-post was needed in the repaired the silt fence and from construction on lot 2	3/6/2017 e silt fence along the silt 16 and removed the silt 1727/2016. 1 the rear prior to 7/26/20 1 the rear prior to rear of the silt fence in the rear of the dadded t-posts prior the 85 needs replaced.	Removed Removed Removed Removed Active Relot and the si	Yes It fence needed
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additional repaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed	Lot 280 Lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 al t-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the	3/6/2017 e silt fence along the silt 16 and removed the silt 1727/2016. 1 the rear prior to 7/26/20 10/6/2016 e silt fence in the rear of the dadded t-posts prior the 85 needs replaced.	Removed Removed Removed Removed 15. Active he lot and the si inspection on 12	Yes It fence needed 2/26/16.
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additional repaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in	Lot 280 Lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 al t-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the	3/6/2017 e silt fence along the silt 16 and removed the silt 1727/2016. 1 the rear prior to 7/26/20 10/6/2016 e silt fence in the rear of the dadded t-posts prior the 85 needs replaced.	Removed Removed Removed Removed 15. Active he lot and the si inspection on 12	Yes It fence needed 2/26/16.
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additionarepaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in was reminded on 3/8/17.	Lot 280 d Homes entrenched the lot 281 Lot 284 es sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 al t-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the formed to complete by 2/3	3/6/2017 e silt fence along the silt into and removed the silt into an and removed the silt into	Removed Removed Removed 15. Active he lot and the si inspection. Sher	Yes It fence needed 2/26/16.
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additional repaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in	Lot 280 d Homes entrenched the lot 281 Lot 284 es sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 al t-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the formed to complete by 2/3	3/6/2017 e silt fence along the silt into and removed the silt into an and removed the silt into	Removed Removed Removed 15. Active he lot and the si inspection. Sher	Yes It fence needed 2/26/16.
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285 Current Condition:	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additional repaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in was reminded on 3/8/17. 2) Sherwood Homes was in was reminded on 3/8/17.	Lot 280 d Homes entrenched the lot 281 ded the lot prior to 8/12/20 Lot 284 es sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 alt-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the formed to complete by 2/3 formed to complete by 2/3 formed to complete by 2/3	3/6/2017 e silt fence along the silt into and removed the silt into an and removed the silt into	Removed Removed Removed 15. Active the lot and the si inspection. Sher	Yes It fence needed 2/26/16.
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285 Current Condition: Lot 285 Lot 286	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additionarepaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in was reminded on 3/8/17. 2) Sherwood Homes was in was reminded on 3/8/17. Silt Fence	Lot 280 Id Homes entrenched the lot 281 Lot 284 Es sodded the lot prior to 5 Lot 282 s removed the silt fence in Lot 285 It-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the formed to complete by 2/3 formed to complete by 2/3 Lot 286	3/6/2017 e silt fence along the silt into and removed the silt into an	Removed Removed Removed 15. Active he lot and the si inspection. Sher	Yes It fence needed 2/26/16.
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285 Current Condition:	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additionarepaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in was reminded on 3/8/17. 2) Sherwood Homes was in was reminded on 3/8/17. Silt Fence Removed-Sherwood Homes Silt Fence	Lot 280 d Homes entrenched the lot 281 ded the lot prior to 8/12/20 Lot 284 es sodded the lot prior to 5 Lot 282 s removed the silt fence in lot 285 al t-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the formed to complete by 2/3 formed to complete by 2/3 formed to complete by 2/3 lot 286 s sodded the lot prior to in lot 294	3/6/2017 e silt fence along the silt 116 and removed the silt 116 and removed the silt 117/27/2016. 118 the rear prior to 7/26/20 119 10/6/2016 119 silt fence in the rear of the diadded t-posts prior the silt fence in the rear of the silt fence in the rear of the diadded t-posts prior the silt fence in the rear of the silt fence in the silt fence	Removed Removed Removed Removed 15. Active the lot and the si inspection. Sher inspection. Sher Removed Removed	yes It fence needed 2/26/16. wood Homes wood Homes
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285 Current Condition: Lot 286 Current Condition:	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additiona repaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in was reminded on 3/8/17. 2) Sherwood Homes was in was reminded on 3/8/17. Silt Fence Removed-Sherwood Homes Silt Fence Good Condition- Sherwood	Lot 280 d Homes entrenched the lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5 Lot 282 s removed the silt fence in lot 285 all t-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the formed to complete by 2/3 formed to complete by 2/3 formed to complete by 2/3 lot 286 s sodded the lot prior to in lot 294 Homes installed silt fence	3/6/2017 e silt fence along the silt 116 and removed the silt 116 and removed the silt 117/27/2016. 118 the rear prior to 7/26/20 119 10/6/2016 119 silt fence in the rear of the diadded t-posts prior the silt fence in the rear of the silt fence in the rear of the diadded t-posts prior the silt fence in the rear of the silt fence in the silt fence	Removed Removed Removed Removed 15. Active the lot and the si inspection. Sher inspection. Sher Removed Removed	yes It fence needed 2/26/16. wood Homes wood Homes
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285 Current Condition: Lot 286 Current Condition: Lot 294 Current Condition:	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additional repaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in was reminded on 3/8/17. 2) Sherwood Homes was in was reminded on 3/8/17. Silt Fence Removed-Sherwood Homes Silt Fence Good Condition- Sherwood 3/31/17. No construction ha	Lot 280 d Homes entrenched the lot 281 ded the lot prior to 8/12/20 Lot 284 s sodded the lot prior to 5 Lot 282 s removed the silt fence in lot 285 all t-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the formed to complete by 2/3 formed to complete by 2/3 formed to complete by 2/3 lot 286 s sodded the lot prior to in lot 294 Homes installed silt fence	3/6/2017 e silt fence along the silt 116 and removed the silt 116 and removed the silt 117/27/2016. 118 the rear prior to 7/26/20 119 10/6/2016 119 silt fence in the rear of the diadded t-posts prior the silt fence in the rear of the silt fence in the rear of the diadded t-posts prior the silt fence in the rear of the silt fence in the silt fence	Removed Removed Removed Removed 15. Active the lot and the si inspection. Sher inspection. Sher Removed Active e south side of the	yes It fence needed 2/26/16. wood Homes wood Homes
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285 Current Condition: Lot 286 Current Condition: Lot 286 Current Condition: Lot 286 Current Condition: Lot 294	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additiona repaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in was reminded on 3/8/17. 2) Sherwood Homes was in was reminded on 3/8/17. Silt Fence Removed-Sherwood Homes Silt Fence Good Condition- Sherwood	Lot 280 d Homes entrenched the lot 281 ded the lot prior to 8/12/20 Lot 284 es sodded the lot prior to 5 lot 282 s removed the silt fence in Lot 285 all t-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the formed to complete by 2/3 formed to complete by 2/3 Lot 286 s sodded the lot prior to in Lot 294 Homes installed silt fence and coursed on the lot Lot 300	3/6/2017 e silt fence along the silt into and removed the silt into an	Removed Removed Removed Removed 15. Active the lot and the si inspection. Sher inspection. Sher Removed Removed	yes It fence needed 2/26/16. wood Homes wood Homes
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285 Current Condition: Lot 286 Current Condition: Lot 294 Current Condition: Lot 300 Current Condition: Lot 307	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additionarepaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in was reminded on 3/8/17. 2) Sherwood Homes was in was reminded on 3/8/17. Silt Fence Removed-Sherwood Homes Silt Fence Good Condition- Sherwood 3/31/17. No construction ha Silt Fence Removed- Pinecrest Homes Silt Fence	Lot 280 d Homes entrenched the lot 281 Lot 284 s sodded the lot prior to 8/12/20 Lot 282 s removed the silt fence in Lot 285 alt-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the formed to complete by 2/3 formed to complete by 2/3 Lot 286 s sodded the lot prior to in Lot 294 Homes installed silt fence d occurred on the lot. Lot 300 s sodded the lot prior to 7/1 Lot 307	3/6/2017 e silt fence along the silt 16 and removed the silt 16 and removed the silt 17/27/2016. 18 the rear prior to 7/26/20 18 silt fence in the rear of 17/26/20 19 dadded t-posts prior the 18/2016. 19 10 dadded t-posts prior the 18/2017. Not done as of last 19 17. Not done as of last 19 18 19 19 19 19 19 19 19 19 19 19 19 19 19	Removed Removed Removed Removed 15. Active the lot and the si inspection. Sher inspection. Sher Removed Active e south side of the	yes It fence needed 2/26/16. wood Homes wood Homes
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285 Current Condition: Lot 286 Current Condition: Lot 294 Current Condition: Lot 294 Current Condition:	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additionarepaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in was reminded on 3/8/17. 2) Sherwood Homes was in was reminded on 3/8/17. Silt Fence Removed-Sherwood Homes Silt Fence Good Condition- Sherwood 3/31/17. No construction has Silt Fence Removed- Pinecrest Homes	Lot 280 d Homes entrenched the lot 281 Lot 284 s sodded the lot prior to 8/12/20 Lot 282 s removed the silt fence in Lot 285 alt-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the formed to complete by 2/3 formed to complete by 2/3 Lot 286 s sodded the lot prior to in Lot 294 Homes installed silt fence d occurred on the lot. Lot 300 s sodded the lot prior to 7/1 Lot 307	3/6/2017 e silt fence along the silt 16 and removed the silt 16 and removed the silt 17/27/2016. 18 the rear prior to 7/26/20 18 silt fence in the rear of 17/26/20 19 dadded t-posts prior the 18/2016. 19 10 dadded t-posts prior the 18/2017. Not done as of last 19 17. Not done as of last 19 18 19 19 19 19 19 19 19 19 19 19 19 19 19	Removed Removed Removed Removed 15. Active he lot and the si inspection. Sher inspection. Sher Removed Active e south side of tt	yes It fence needed 2/26/16. wood Homes wood Homes
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285 Current Condition: Lot 286 Current Condition: Lot 294 Current Condition: Lot 300 Current Condition: Lot 307	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sode Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additionarepaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in was reminded on 3/8/17. 2) Sherwood Homes was in was reminded on 3/8/17. Silt Fence Removed-Sherwood Homes Silt Fence Good Condition- Sherwood 3/31/17. No construction ha Silt Fence Removed- Pinecrest Homes Silt Fence	Lot 280 d Homes entrenched the lot 281 Lot 284 s sodded the lot prior to 8/12/20 Lot 282 s removed the silt fence in Lot 285 alt-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the formed to complete by 2/3 formed to complete by 2/3 Lot 286 s sodded the lot prior to in Lot 294 Homes installed silt fence d occurred on the lot. Lot 300 s sodded the lot prior to 7/1 Lot 307	3/6/2017 e silt fence along the silt 16 and removed the silt 16 and removed the silt 17/27/2016. 18 the rear prior to 7/26/20 18 silt fence in the rear of 17/26/20 19 dadded t-posts prior the 18/2016. 19 10 dadded t-posts prior the 18/2017. Not done as of last 19 17. Not done as of last 19 18 19 19 19 19 19 19 19 19 19 19 19 19 19	Removed Removed Removed Removed 15. Active he lot and the si inspection. Sher inspection. Sher Removed Active e south side of tt	yes It fence needed 2/26/16. wood Homes wood Homes
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285 Current Condition: Lot 286 Current Condition: Lot 294 Current Condition: Lot 300 Current Condition: Lot 307 Current Condition:	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additionarepaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in was reminded on 3/8/17. 2) Sherwood Homes was in was reminded on 3/8/17. Silt Fence Removed-Sherwood Homes Silt Fence Good Condition- Sherwood 3/31/17. No construction has Silt Fence Removed- Pinecrest Homes Silt Fence Removed- Pinecrest Homes Silt Fence Removed-Sherwood Homes	Lot 280 d Homes entrenched the lot 281 Lot 284 es sodded the lot prior to 5 Lot 285 all t-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the formed to complete by 2/3 Lot 286 s sodded the lot prior to in Lot 284 Homes installed silt fence docurred on the lot Lot 300 s sodded the lot prior to 7/ Lot 307 s sodded the lot prior to 8/1 Lot 310	3/6/2017 e silt fence along the silt into and removed the silt into an	Removed Removed Removed Removed 15. Active he lot and the si inspection. Sher inspection. Sher Removed Active e south side of tt Removed Active	Yes It fence needed 2/26/16. wood Homes wood Homes No ne lot prior to
Lot 280 Current Condition: Lot 281 Current Condition: Lot 284 Current Condition: Lot 282 Current Condition: Lot 285 Current Condition: Lot 286 Current Condition: Lot 294 Current Condition: Lot 300 Current Condition: Lot 307 Current Condition: Lot 310	Silt Fence Good Condition- Sherwood 3/27/17. Silt Fence Removed- Dean Vogel sodo Silt Fence Removed- Sherwood Homes Silt Fence Removed- Oakwood Homes Silt Fence Fair Condition- An additionarepaired. Sherwood Homes 1) Sod damaged on lot 286 2) Silt fence needs installed 1) Sherwood Homes was in was reminded on 3/8/17. 2) Sherwood Homes was in was reminded on 3/8/17. Silt Fence Removed-Sherwood Homes Silt Fence Removed-Sherwood Homes Silt Fence Removed- Pinecrest Homes Silt Fence Removed-Sherwood Homes Silt Fence Removed-Sherwood Homes Silt Fence Removed-Sherwood Homes Silt Fence	Lot 280 d Homes entrenched the lot 281 Lot 284 es sodded the lot prior to 5 Lot 285 all t-post was needed in the repaired the silt fence and from construction on lot 2 along the east side of the formed to complete by 2/3 Lot 286 s sodded the lot prior to in Lot 284 Homes installed silt fence docurred on the lot Lot 300 s sodded the lot prior to 7/ Lot 307 s sodded the lot prior to 8/1 Lot 310	3/6/2017 e silt fence along the silt into and removed the silt into an	Removed Removed Removed Removed 15. Active he lot and the si inspection. Sher inspection. Sher Removed Active e south side of tt Removed Active	Yes It fence needed 2/26/16. wood Homes wood Homes No ne lot prior to

Current Condition:	Pending- The Home Company started construction on the lot prior to 3/27/17.				
	Silt fence needs installed along the rear of the lot.				
	THC was informed to complete by 4/3/17. Not done as of last inspection. THC was reminded on 4/1/17.				
Lot 315 Current Condition:	Silt Fence Removed- Legacy Homes s	Lot 315	2/16	Removed	
	ű ,	•	.2/10.		
Lot 319 Current Condition:	Silt Fence Removed-Sherwood Homes	Lot 319	13/2016	Removed	
Lot 324	Silt Fence	Lot 324	T0/2010.	Removed	1
Current Condition:	Removed-Sherwood Homes		spection on 7/8/15.	Removed	l
Lot 325	Silt fence	Lot 325		Removed	
Current Condition:	Removed- Lot was sodded I		to 11/17/2015.	Daman	1
Lot 326 Current Condition:	Silt Fence Removed-Sherwood Homes	Lot 326	spection on 7/16/15	Removed	
Lot 328	Silt Fence	Lot 328	Special on 7710/10.	Removed	
Current Condition:	Removed-Oakwood Homes				
Lot 329 Current Condition:	Silt Fence Good Condition- Pacesetter	Lot 329	3/6/2017	Active	No t of the let prior
Current Condition.	to 3/6/17. No construction w			ortion of the from	t of the lot phor
Lot 336	Temp. Seeding	Lot 336		Removed	
Current Condition:	Removed- As of 8/18/2015,		seeding is not needed.		
Lot 336	Silt Fence	Lot 336	0/0/40	Removed	
Current Condition:	Removed- Sherwood Home	s sodded the lot prior to 1	0/6/16.		
Lot 337	Silt Fence	Lot 337		Removed	
Current Condition:	Removed-Sherwood Homes	s removed the silt fence a	nd sodded the lot prior to	inspection on 5	5/28/15.
L at 244	Cilt Fonce	Lot 244		Romovad	
Lot 344 Current Condition:	Silt Fence Removed- the Home Comp	Lot 344	11/1/16	Removed	
Pod F	Silt Fence	Lots 426-454	I	Removed	1
Current Condition:	Removed-Lots 427 and 428		1/2015 by Celebrity Hom		l.
Pod G	Silt Fence	Lots 404-425		Removed	
Current Condition:	Removed-Lot 404 was sodo		d has been built out.		1
Pod H	Silt Fence	Lots 455-473		Removed	1
Current Condition:	Removed- Lot 460 was sode		rior to the inspection on		1
Pod I	Silt Fence	Lots 346-355		Removed	
Current Condition:	Removed-Lot 355 was sodd		Celebrity Homes.		1
Pod J Current Condition:	Silt Fence	Lots 381-394	nd the silt was removed	Removed from behind lot	383 prior to
Current Condition.	Removed- Lot 385 was sodded by Celebrity Homes and the silt was removed from behind lot 383 prior to 5/27/2016. Lot 383 was sodded and the silt fence was repaired on the sides of 386 prior to 6/29/2016. Lot 386				
	was sodded prior to 8/12/2016. Pod J is built out as of 8/12/2016.				
Pod K	Silt Fence	Lots 372-403		Removed	
Current Condition:	Removed-Celebrity Homes				
	front of lots 380, 378-376 prior to 9/13/2016. Lot 380, 376, and 377 were sodded prior to 9/26/16. Lot 378 was				
	sodded by Celebrity Homes prior to 11/1/16. The silt fence on the front of lot 379 isn't needed anymore due to completion of the sidewalk as of 11/1/16. Celebrity Homes sodded lot 379 prior to 11/22/16 completing the				
	pod.		moo oodada lot ol o pilo		p.oug uo
Pod L	Silt Fence	Lots 371-356		Removed	
Current Condition:	Removed- Silt fence was re	paired in the rear of lot 36	0 prior to 9/13/2016 by C	Celebrity Homes.	Lot 365 was
	sodded prior to inspection o				
	on the front of lot 360 prior t Celebrity Homes prior to 11/		•		•
	front of the lots prior to 11/1/	•			
	will monitor for sodding of th		_	_	·
SB 1	Sediment Basin	Outlot "M"	In Place	Active	No
Current Condition:	Good Condition-45% Filled.				
	by the SID prior to inspectio				
SB 3	Sediment Basin	School Lot 165	In Place	Active	No
Current Condition:	Good Condition-20% Filled -Cleaned out 02/06				
SB 5	Sediment Basin	Outlot "L"	11/17/2009	Active	No
Current Condition:	Good Condition- 15% Filled		11/11/2009	Active	140
	- JC Excavating installed pri		09.		
STR	Street Cleaning	48th Street & Interior	5/1/2007	Active	Yes
•		•	•	•	

Current Condition:	Fair Condition- no major signs of track out. Sherwood Homes cleaned the street along lot 280 prior to 3/31/17.				30 prior to
	1)Track out needs removed from the street in front of lot 314. 2) Track out needs removed from the street in front of lot 69. 1) The Home Company was informed to complete by 4/1/17.				
SWPPP Sign Current Condition:	Signs Good Condition: 48th and	1 sign on site	8-19-08	Active	No
Inspector Signature:	in Stune		Reviewed By:	Plette Vann	