E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CIS	250	E & A CONS				
Environmental Services Dep						
	•	E&A- P2006.056.019		Engineering		
nspector: Zach Roza					Stage	
	Courtyards @ Iron Horse CSW-202207403					
Project Name:						
For Week Ending:		10/28/2023			68003	
Project Location:	South Lakeview Way	and Courtyard Court - A	Ashland, NE (Saunders Co	ounty)		
Grading:	80%					
Sanitary Sewer:	0%					
Storm Sewer:	0%					
Paving:	0%					
Seeding:	0%					
Utilities:	5%					
Overall Development:	570					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration	
Sunday:	0.00"				Week	
Monday:	0.00"			+		
Tuesday:	0.07"			1		
Wednesday:	0.02"	10/25/2023	Cloudy 68 / 63	8:50 AM		
Thursday:	0.00"					
Friday:	0.08"					
Saturday:	0.00"					
	None					
Complaints:						
Construction Sequencing:						
Which portion(s) (i.e. drainage basi	ns) of the site have had a temporary or permanent ce	ssation of grading, earthwork	, or ground disturbance in the la	ast 14 days?		
Grubbing began (7/5/23). Grad	ling began (9/13/23).					
Which portion(s) (i.e. drainage basi	ns) of the site do not have grading, earthwork, or gro	und disturbance scheduled in	the next 14 days?			
Grubbing began (7/5/23). Grad			<u> </u>			
What temporary or permanent stabi Existing Vegetation (7/5/23).	ilization measures listed in this section are being imp	lemented?				
Laisting vegetation (113/23).						
Checklist Questions:						
	nt to the project free of any significant signs	of erosion or sediment	that would be associated	with the construction	n activity?	
Yes Create Corrective Action?					in douvity.	
					The doctority .	
N/A					wa doubley :	
	seeded or otherwise stabilized as required?	List inactive portions of	f the project and if stabiliz	ation measure are ac		
Have disturbed areas been s prevent erosion. Yes	seeded or otherwise stabilized as required?	List inactive portions of	f the project and if stabiliz	ation measure are ac		
Have disturbed areas been sorevent erosion. Ves Create Corrective Action?	eeded or otherwise stabilized as required?	List inactive portions o	f the project and if stabiliz	ation measure are ac		
Have disturbed areas been s prevent erosion. /es Create Corrective Action?				ation measure are ac		
Have disturbed areas been s prevent erosion. Yes Create Corrective Action?	eeded or otherwise stabilized as required?			ation measure are ac		
Have disturbed areas been s prevent erosion. Yes Create Corrective Action?				ation measure are ac		
Have disturbed areas been s prevent erosion. Yes Create Corrective Action? N/A Are waste materials (concret No Create Corrective Action? No-See BMP Section	te, construction material, hazardous, etc.) b	eing managed properly		ation measure are ac		
Have disturbed areas been s prevent erosion. //es Create Corrective Action? N/A Are waste materials (concret No Create Corrective Action? No- See BMP Section Are construction entrances and		eing managed properly		ation measure are ac		
Have disturbed areas been s prevent erosion. Yes Create Corrective Action? N/A Are waste materials (concret No Create Corrective Action? No-See BMP Section	te, construction material, hazardous, etc.) b	eing managed properly		ation measure are ac		
Are waste materials (concret to See BMP Section Are Construction entrances a No Create Corrective Action? Are waste materials (concret to Create Corrective Action? Are construction entrances a No Create Corrective Action?	te, construction material, hazardous, etc.) b	eing managed properly uately?		ation measure are ac		
Have disturbed areas been s prevent erosion. Yes Create Corrective Action? Are waste materials (concret to construction entrances at the construction entrances at the construction? No- See BMP Section Create Corrective Action? No- See BMP Section Is dust associated with the construction entrances at	te, construction material, hazardous, etc.) b and adjacent streets being maintained adeq	eing managed properly uately?		ation measure are ac		
Are waste materials (concreted of the construction entrances as the construction entrances are the construction	te, construction material, hazardous, etc.) b and adjacent streets being maintained adeq	eing managed properly uately?		ation measure are ac		
Are construction entrances a No See BMP Section Are Corrective Action? Are waste materials (concret No Create Corrective Action? Are construction entrances a No Create Corrective Action? No- See BMP Section See GMP Section Is dust associated with the create Corrective Action? No- See Create Corrective Action?	te, construction material, hazardous, etc.) b and adjacent streets being maintained adeq	eing managed properly uately?		ation measure are ac		
Have disturbed areas been s prevent erosion. Yes Create Corrective Action? Are waste materials (concret to concret to construction entrances at the constr	te, construction material, hazardous, etc.) b and adjacent streets being maintained adeq	eing managed properly uately?		ation measure are ac		
Have disturbed areas been s prevent erosion. Yes Create Corrective Action? NA Are waste materials (concret No Create Corrective Action? No-See BMP Section Are construction entrances a No Create Corrective Action? No-See BMP Section	te, construction material, hazardous, etc.) be and adjacent streets being maintained adequately controlled on the construction activity activity.	eing managed properly uately?		ation measure are ac		

- Findings / Corrective Actions (Date):
 1.) There are some findings in the BMP Section.
 2.) Silt fence should be installed along western boundary. Pruss Excavation was informed to complete by 11/1/23.

			I				
Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
CE 01	Construction Entrance	Off 113th Street	9/20/2023	Pending	Yes		
Current Condition:	Pending - Pruss Excavation installed a construction entrance prior to the inspection on 9/20/23. Pruss Excavation removed the						
	construction entrance prior to the inspection on 10/25/23.						
	Construction entrance chould be as installed or harm should be installed to assure a climant running outs street						
	Construction entrance should be re-installed or berm should be installed to prevent sediment running onto street.						
	Pruss Excavation was informed to complete by 11/1/23.						
DB 01	Diversion Berm	North Side of Site	10/11/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation instal	led a diversion berm prior to	the inspection on 10/11/23		•		
DB 02	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation instal	led a diversion berm prior to	the inspection on 10/18/23				
DB 03	Diversion Berm	Eastern Side of Site	10/18/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation instal		the inspection on 10/18/23				
FT 01	Fuel Tank	On Site	9/20/2023	Active	Yes		
Current Condition:	Fair Condition- Pruss Excavation installe	d a fuel tank on site prior to t	he inspection on 9/20/23.	-			
	The fuel tank should be bermed or have	some form of secondary con	itainment.				
	Pruss Excavation was informed to comp	lete by 9/27/23. Not done as	of the last inspection Prus	ss Excavation was r	eminded on 10/26/23.		
	Trade Excavation was informed to some	1010 by 0/21/20. 1401 dollo do	or the last mopeodon. 1 1 a	DO EXCUTATION WAS I	011111111111111111111111111111111111111		
IP 1 - 2	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	Yes		
Current Condition:	Pending-						
	Inter and offer all the state of the						
	Inlet protection should be installed.						
	Pruss Excavation was informed to co	mplete by 11/1/23.					
IP 3 - 4	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No		
Current Condition:	Pending- Inlet protection will be installed			, ,			
IP 5 - 6	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No		
Current Condition:	Pending- Inlet protection will be installed	once paving is complete.					
IP 7	Inlet Protection	Along Courtyard Court	8/5/2023	Pending	No		
Current Condition:	Pending- Inlet protection will be installed	once paving is complete.	•		•		
	Fracian Matting	South East portion of the	8/5/2023	Ponding	No		
MT 01	Erosion Matting	site	0/5/2023	Pending	INO		
Current Condition:	Pending- Erosion Matting will be installed	l once grading is complete.					
	Erosion Matting	South East portion of the	8/5/2023	Pending	No		
MT 02 Current Condition:	Pending- Erosion Matting will be installed	site					
Current Condition:	Pending- Erosion Matting will be installed		T	Γ	1		
MT 03	Erosion Matting	South West portion of the site	8/5/2023	Pending	No		
Current Condition:	Pending- Erosion Matting will be installed						
MT 04	Erosion Matting	ADJ to Private Drive	8/5/2023	Pending	No		
Current Condition:	Pending- Erosion Matting will be installed		6/3/2023	rending	INU		
MT 05	Erosion Matting	ADJ to Private Drive	8/5/2023	Pending	No		
Current Condition:	Pending- Erosion Matting will be installed	once grading is complete.	0/3/2020	l cliding	140		
MT 06	Erosion Matting	North of Courtvard Court	8/5/2023	Pending	No		
Current Condition:	Pending- Erosion Matting will be installed		5/5/2020	ı i onding	1 140		
MT 07	Erosion Matting	North of Courtyard Court	8/5/2023	Pending	No		
Current Condition:	Pending- Erosion Matting will be installed		3,5,2020	, c.ming			
PT 01	Portable Toilet	On Site	9/20/2023	Active	No		
Current Condition:	Good Condition- Pruss Excavation instal						
	toilet prior to the inspection on 10/4/23.						
SF 01 - 09	Silt Fence	Eastern Perimeter	8/5/2023	Pending	Yes		
Current Condition:	Pending-						
	Davis standik fanns albertel be installed						
	Perimeter silt fence should be installed.						
	Pruss Excavation was informed to complete by 9/27/23. Not done as of the last inspection. Pruss Excavation was reminded on 10/26/23.						
	and the complete of the control of t						
SF 10 - 14	Silt Fence	Northern Checks	7/12/2023	Pending	Yes		
Current Condition:	Pending- Pruss Excavation installed SF	11 prior to the inspection on 7	7/12/23. Pruss excavation	removed SF 11 due t	o grading prior to the		
	inspection on 9/20/23.						
	Silt fence 11, 13, and 14 should be installed when work allows.						
	ont tence 11, 10, and 14 should be installed when work allows.						
	Pruss Excavation was informed to complete by 11/1/23.						
SF 15 - 18	Silt Fence	Western Perimeter	8/5/2023	Pending	Yes		

Current Condition:	Pending-						
	Perimeter silt fence should be installed.						
	Pruss Excavation was informed to complete by 9/27/23. Not done as of the last inspection. Pruss Excavation was reminded on 1						
SF 19	Silt Fence	Northern Perimeter	7/12/2023	Active	Yes		
Current Condition:	Fair Condition- Pruss Excavation in	stalled the silt fence prior to the ins	pection on 7/12/23. Part	of the silt fence was de	own during the inspection		
	on 9/27/23.						
	Silt fence should be repaired where	e down.					
	·						
	Pruss excavation was informed to d	complete by 10/4/23. Not done as o	of the last inspection. Pru	ss Excavation was re	eminded on 10/26/23.		
		Southern Half of Courtyard		I	I		
SF 20 - 30	Silt Fence	Court	8/5/2023	Pending	No		
Current Condition:	Pending- Silt fence will be installed	once grading starts.					
	Silt Fence	Northern Half of Courtyard	8/5/2023	Pendina	No		
SF 31 - 34		Court	0/3/2023	rending	NO		
Current Condition:	Pending- Silt fence will be installed	once grading starts.					
SF 35 - 42	Silt Fence	Eastern Perimeter Checks	8/5/2023	Pending	No		
Current Condition:	Pending- Silt fence will be installed	once grading starts.		1			
	C:4 F	Southern Half of Western	0/5/0000	Ddi	N-		
SF 43 - 48	Silt Fence	Perimeter	8/5/2023	Pending	No		
Current Condition:	Pending- Silt fence will be installed once grading starts.						
SF 49 - 51	Silt Fence	West of Courtyard Court	8/5/2023	Pending	No		
Current Condition:	Pending- Silt fence will be installed	0 0		1	T		
SF 52 - 55	Silt Fence	Northern Half of Western	8/5/2023	Pending	No		
Current Condition:	Pending- Silt fence will be installed once grading starts.						
STR	Streets	ADJ and Internal Streets	8/5/2023	Active	Yes		
Current Condition:	Fair Condition-						
	A discount atmosts altoyed by allow						
	Adjacent streets should be cleaned.						
	Pruss Excavation was informed	to complete by 10/26/23.					
SWPPP Sign	SWPPP Sign	On Site	10/11/2023	Active	No		
Current Condition:	Good Condition- E&A inspector ins	-					
WO 01	Concrete Washout	On Site	8/5/2023	Pending	No		
Current Condition:	Pending- A concrete washout will b						
WS 01	Waste Storage Area	On Site	8/5/2023	Pending	No		
Current Condition:	Pending- Waste storage will be inst "I certify, under penalty of law, that	-	ware prepared under my	direction or conceniois	n in accordance with a		
Certification Statement	system designed to assure that qua						
	person or persons who manage the						
	the best of my knowledge and belie			gnificant penalties for	submitting false		
	information including the possibility	of fines and imprisonment for know	ving violations."				
	Joh Rago			Ga	to See		
Inspector Signature:				Reviewed By:			