E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Thursday

Friday

0.00"

0.00"



Zachary A. Jilek, CPESC, CISEC

E & A CONSULTING GROUP, INC.

ENGINEERING · PLANNING · ENVIRONMENTAL & FIELD SERVICES **Environmental Services Dept. Manager** E&A - P2006.135.000 Inspector: Mike Jacobson, CISEC Stage **Kennedy Town Center** NER110532 Project Name: 4/13/2013 For Week Ending: 68147 **Project Location:** 25th & Chandler Road- Bellevue, NE (Sarpy County) Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% 100% Seeding: **Utilities:** 100% Overall Development: 30% RAIN FALL AMOUNTS Amount in tenths Date inspected Week Sunday: 0.20" Monday 0.00" Tuesday 0.00" Wednesday 0.00' Thursday 0.00' Friday 0.00' Saturday 0.00" Week 2 Sunday: 0.15" Monday 0.00" Tuesday 0.00' 03/20/13 Wednesday 0.00" 0.00" Thursday Friday 0.00' Saturday 0.02" Week 3 Sunday: 0.01" 0.00" Monday Tuesday 0.00' Wednesday 0.00" Thursday 0.00" Friday 0.00" Saturday 0.29" Week 4 Sunday: 0.00" Monday 0.01" Tuesday 0.00" Wednesday 0.00' Thursday 0.00' Friday 0.00' Saturday 0.00' Week 0.02" Sunday: Monday 0.04" Tuesday 0.42" Wednesday 0.66 04/10/13

Saturday	0.00"						
0	None						
Complaints:	-						
Construction Sequencing:							
Which portion(s) (i.e. drainage basins) of th	e site have had a temporary or perma	anent cessation of gradin	g, earthwork, or gro	ound disturbance in	the last 14 days?		
Entire Site, Grading was completed a	nd entire site was seeded Fall 2	2006.					
Which portion(s) (i.e. drainage basins) of th	e site do not have grading, earthwork	k, or ground disturbance	scheduled in the ne	xt 14 days? :			
Entire Site, Grading was completed and entire site was seeded Fall 2006.							
What temporary or permanent stabilization		<u> </u>					
Seeding (Fall 2006), stabilized entran		,	,.		, ,,		
seeded the north east corner of the lot where the area inlet was installed(4/2009); Re-seeded around the SB A and SB B(4/2009); The disturbed							
areas of the South section of lot 5 Kennedy Town Center Replat Three was re-seeded prior to inspection on 7/18/12; The West side slope of Basin							
B was hydro seeded (8/2012); The East side of Basin B was sodded 9/13/12; The West side of the R.O.W. along 19th Circle was seeded(10/10/12)							
Comments:							
Comments:							
Condo construction along 23rd and 2	2nd Street in the Southwest sec	ction of the site is acti	ve.				
Findings / Corrective Actions (Date	e):						
Findings / Corrective Actions (Date):							
1) Some maintenance is required in the BMP section.							

			Projected		
Unione Nome	Time	l acation	Install Date	Ctatus	Maintanana
Unique Name	Туре	Location	install Date	Status	Maintenance
		N41d00m00s			
CE A	Construction Entrance	W96d00m00s		Removed	No
Current Condition:	Removed paved entrance				
		N41d00m00s			
DD 1	Swale	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition - Partially removed due to paving of street.				
	Diversion ditch was redefined prior to inspection on 4/8/09 by M.E. Collins.				
			-		
		N41d00m00s			
DD 2	Swale	W96d00m00s		Removed	
				Removed	
Current Condition:	Removed due to paving of street.				
		Lot 4 Kennedy			
Lot 4 Kennedy Town Center Replat		Town Center Replat			
Three	Silt Fence	Three	10/10/2012	Active	No
Current Condition:	Good Condition	111100	10/10/2012	7101170	110
Current Condition.					
	Silt fence check was installed prior to inspection on 10/10/12 by CS.				
POD B	Misc/Other	Lots 28-44	2/9/2011	Active	Yes

Current Condition:	Good Condition- Silt fence is installed on lot 28. The construction debris on lots 29-33 was cleaned up prior to inspection on 3/20/13 by builder Larry Bayer. 1) There is a pile of construction debris/concrete debris on lot 44 and it needs to be cleaned up. 2) There is some concrete spoils in the R.O.W. on lot 44 and it needs to be cleaned up. 3) There is a portable toilet on lot 28 and it needs to be staked down. 4) A few areas of the silt fence on lot 28 are down/damaged and need to be repaired. 5) One area of the silt fence on lot 28 is down/damaged and it needs to be replaced. 1) Builder Larry Bayer was informed to complete maintenance by 12/5/12. On 1/17/13, 3/21/13 and again on 4/12/13 Larry Bayer was reminded that needs to be completed ASAP. 2) Builder Larry Bayer was informed to complete maintenance by 3/27/13. On 4/12/13 Larry Bayer was reminded that needs to be completed ASAP. 3) Builder Larry Bayer was informed to complete maintenance by 3/27/13. On 4/12/13 Larry Bayer was reminded that needs to be completed ASAP.					
	4) Builder Larry Bayer was informed to complete maintenance by 3/27/13. On 4/12/13 Larry Bayer was remit 5) Builder Larry Bayer was informed to complete maintenance by 4/18/13.					
DOD C	Mico/Othor	Loto 10.27	11/29/2012	Danding	Voc	
POD C Current Condition:	Misc/Other Lots 10-27 11/28/2012 Pending Yes Pending Concrete spoils on lot 22 was cleaned up and the trash and construction debris on lots 25 and 26 prior to inspection on 4/10/13 by Builder Larry Bayer.					
	 There is a pile of construction debris/concrete debris on lot 16 and it needs to be cleaned up. There is some concrete spoils in the R.O.W. along Albert Street on lot 10 and it needs to be cleaned up. Silt fence needs to be installed on the West and North side of the lot 27 due to active home construction. 					
	1) Builder Larry Bayer was informed to complete maintenance by 3/27/13. On 4/12/13 Larry Bayer was reminded that needs to be completed ASAP. 2) Builder Larry Bayer was informed to complete maintenance by 3/27/13. On 4/12/13 Larry Bayer was reminded that needs to be completed ASAP. 3) Builder Larry Bayer was informed to complete maintenance by 3/27/13. On 4/12/13 Larry Bayer was reminded that needs to be completed ASAP.					
SB A	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - 23% filled Cleaned out 10/2007 by Dave Hausman. Erosion maintenance was completed prior to inspection on 4/8/09 by M.E. Collins.					
SB B Current Condition:	Sediment Basin Good Condition - 25% filled	N41d00m00s W96d00m00s	10/6/2007	Active	No	
	Cleanout and riser maintenance was completed on 4/1/09 by M.E. Collins. The East side of the basin was sodded prior to inspection on 9/13/12 by Duane w/ Village Builders.					
SF A	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	Partially removed due to good vegetation and a berm installed. The remainder of silt fence was removed prior to inspection on 4/4/11 by Commercial Seeding.					
SF B Current Condition:	Silt Fence W96d00m00s Removed Silt fence run was removed due to good vegetation and no activity in the area at this time prior to inspection on 3/24/10 by CS. Note: Silt fence may need to be reinstalled once there is construction activity in the area.					
CE C	Cilk Fance	N41d00m00s		Damayad		
SF C Current Condition:	Silt Fence Silt fence run was removed du	W96d00m00s le to good vegetation	prior to inspectio	Removed in on 3/24/10 by	CS.	
		N41d00m00s				
SF D Current Condition:	Silt Fence W96d00m00s Removed Silt Fence removed and diversion ditch installed in this area.					
	and divole	N41d00m00s				

Current Condition:	Fair Condition-				
	There is some minor signs of track off along the curb lines of 23rd Street and it needs to be cleaned up.				
	Builder Larry Bayer was informed to cleaned up by 3/21/13. On 4/12/13 Larry Bayer was reminded that street needs to be cleaned up ASAP.				
CWDDD Cian	CW/DDD Cian	Two signs on site	0/0/0000	Activo	No
SWPPP Sign Current Condition:	SWPPP Sign Two signs on site. 8/8/2008 Active No Good Condition A SWPPP sign has been installed at 22nd & Chandler Road and 25th and Sautter Ave entrances. SWPPP sign was removed from 19th Street as of inspection on 3/28/12.				
Inspector Signature:			Reviewed By:	Zachary L. Jilde	