E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Wednesday

Thursday

Friday

N/A

N/A

N/A



Zachary A. Jilek, CPESC, CISEC

E & A CONSULTING GROUP, INC.

ENGINEERING · PLANNING · ENVIRONMENTAL & FIELD SERVICES **Environmental Services Dept. Manager** E&A - P2006.135.000 Stage Inspector: Mike Jacobson, CISEC **Kennedy Town Center** NER110532 Project Name: 5/11/2013 For Week Ending: 68147 **Project Location:** 25th & Chandler Road- Bellevue, NE (Sarpy County) Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% Seeding: 100% Utilities: 100% Overall Development: 30% RAIN FALL AMOUNTS Amount in tenths Date inspected Week 0.04" Sunday: Monday 0.00" Tuesday 0.00" Wednesday 0.96 Thursday 0.40" Friday 0.00" 04/20/13 Saturday 0.00" Week 2 Sunday: 0.54" Monday 0.90" 0.00" 04/23/13 Tuesday Wednesday 0.01" Thursday 0.00" Friday 0.00" Saturday 0.00" Week Sunday: 0.00" Monday 0.00" Tuesday 0.00" Wednesday 0.89" Thursday 0.32 05/02/13 Friday 0.00" Saturday 0.03 Week 4 Sunday: 0.03" Monday 0.00" Tuesday 0.00" Wednesday 0.01" 05/09/13 Thursday 0.78 Friday 0.00" Saturday 0.00" Week N/A N/A Sunday: Monday N/A N/A Tuesday N/A N/A

N/A

N/A

N/A

Saturday	N/A	N/A			
Complaints:	None				
Construction Sequencing:	•				
Which portion(s) (i.e. drainage basins) of the	site have had a temporary or perma	nent cessation of grading	g, earthwork, or gro	und disturbance in t	he last 14 days?
Entire Site, Grading was completed ar	ad antiro sita was saadad Fall 2	006			
Entire Site, Grading was completed at	id entire site was seeded Fall 2	000.			
Which portion(s) (i.e. drainage basins) of the	site do not have grading, earthwork	, or ground disturbance s	scheduled in the nex	kt 14 days? :	
Entire Site, Grading was completed ar	nd entire site was seeded Fall 2	006.			
What temporary or permanent stabilization m	neasures listed in this section are be	ing implemented?			
Seeding (Fall 2006), stabilized entrand seeded the north east corner of the lot areas of the South section of lot 5 Ker	where the area inlet was instal	lled(4/2009); Re-seed	ded around the S	B A and SB B(4/	2009); The disturbed
B was hydro seeded (8/2012); The Ea seeded(10/10/12)		•	•	,	•
Comments:	•		•		
Comments:					
Condo construction along 23rd and 22nd Street in the Southwest section of the site is active.					
Findings / Corrective Actions (Date)):				
Findings / Corrective Actions (Date)):				
1) Some maintenance is required in the					

			Projected			
Unique Name	Type	Location	Install Date	Status	Maintenance	
		N41d00m00s				
CE A	Construction Entrance	W96d00m00s		Removed	No	
Current Condition:	Removed paved entrance			•		
		N41d00m00s				
DD 1	Swale	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - Partially ren	noved due to paving of	f street.			
	Diversion ditch was redefined	prior to inspection on	4/8/09 by M.E. C	Collins.		
		N41d00m00s				
DD 2	Swale	W96d00m00s		Removed		
Current Condition:	Removed due to paving of str	Removed due to paving of street.				
		Lot 4 Kennedy				
Lot 4 Kennedy Town Center Replat		Town Center Replat				
Three	Silt Fence	Three	10/10/2012	Active	No	
Current Condition:	Good Condition	•				
	Silt fence check was installed prior to inspection on 10/10/12 by CS.					
POD B	Misc/Other	Lots 28-44	2/9/2011	Active	Yes	

Current Condition:	Good Condition- Silt fence is in	nstalled on lot 28.				
	 There is a pile of construction debris/concrete debris on lot 44 and it needs to be cleaned up. There is some concrete spoils in the R.O.W. on lot 44 and it needs to be cleaned up. There is a portable toilet on lot 28 and it needs to be staked down. A few areas of the silt fence on lot 28 are down/damaged and need to be repaired. One area of the silt fence on lot 28 is down/damaged and it needs to be replaced. 					
	1) Builder Larry Bayer was informed to complete maintenance by 12/5/12. On 1/17/13, 3/21/13 and again on 4/12/13 Larry Bayer was reminded that needs to be completed ASAP. On 4/23/13 Legacy Homes was reminded that needs to be completed ASAP. Maintenance not completed as of last inspection. 2) Builder Larry Bayer was informed to complete maintenance by 3/27/13. On 4/12/13 Larry Bayer was reminded that needs to be completed ASAP. On 4/23/13 Legacy Homes was reminded that needs to be completed ASAP. Maintenance not completed as of last inspection. 3) Builder Larry Bayer was informed to complete maintenance by 3/27/13. On 4/12/13 Larry Bayer was rer 4) Builder Larry Bayer was informed to complete maintenance by 3/27/13. On 4/12/13 Larry Bayer was rer 5) Builder Larry Bayer was informed to complete maintenance by 4/18/13. As of inspection on 4/20/13 silt					
POD C Current Condition:	Misc/Other Pending	Lots 10-27	11/28/2012	Pending	Yes	
	2) There is some concrete spo 3) Silt fence needs to be instal 1) Builder Larry Bayer was informeminded that needs to be composed ASAP. Maintenance 2) Builder Larry Bayer was informeminded that needs to be composed ASAP. Maintenance 3) Builder Larry Bayer was informeminded that needs to be composed that needs to be composed that needs to be composed ASAP. Maintenance	primed to complete manufactured ASAP. On 4/2 e not completed as of primed to complete manufactured ASAP. On 4/2 e not completed as of primed to complete as of primed to complete manufactured ASAP. On 4/2 e not completed ASAP. On 4/2 e not complete manufactured ASAP. On 4/2 e not complete manufactured ASAP. On 4/2 e not complete manufactured ASAP.	North side of the aintenance by 3/2 23/13 Legacy Ho f last inspection. aintenance by 3/2 23/13 Legacy Ho of last inspection. aintenance by 3/2 23/13 Legacy Ho 23/2 23/13 Legacy Ho	lot 27 due to act 27/13. On 4/12/1 mes was remind 27/13. On 4/12/1 mes was remind 27/13. On 4/12/1 mes was remind	3 Larry Bayer was ed that needs to be 3 Larry Bayer was ed that needs to be 3 Larry Bayer was ed that needs to be 3 Larry Bayer was	
SB A	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - 23% filled Cleaned out 10/2007 by Dave by M.E. Collins.	Good Condition - 23% filled Cleaned out 10/2007 by Dave Hausman. Erosion maintenance was completed prior to inspection on 4/8/09				
SB B	Sediment Basin	N41d00m00s W96d00m00s	10/6/2007	Active	No	
Current Condition:	Good Condition - 25% filled Cleanout and riser maintenand The East side of the basin was	•	•		llage Builders.	
SF A	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	Partially removed due to good The remainder of silt fence was	vegetation and a ber			l Seeding.	
SF B	Silt Fence	N41d00m00s W96d00m00s		Removed		
Current Condition:	Silt fence run was removed du	Silt Fence Weddumous Removed Silt fence run was removed due to good vegetation and no activity in the area at this time prior to inspection on 3/24/10 by CS. Note: Silt fence may need to be reinstalled once there is construction activity in the area.				
05.0	Cilt Fanna	N41d00m00s		Domessed		
SF C Current Condition:	Silt Fence Silt fence run was removed du	W96d00m00s e to good vegetation	prior to inspectio	Removed on on 3/24/10 by	CS.	
		N41d00m00s		,		
SF D	Silt Fence	W96d00m00s	a :	Removed		
Current Condition:	Silt Fence removed and divers		tnis area.			
STR	Street Cleaning	N41d00m00s W96d00m00s		Active	No	

Current Condition:	Good Condition- Track off was cleaned up pri	Good Condition- Track off was cleaned up prior to inspection on 4/23/13 by Legacy Homes.			
SWPPP Sign	SWPPP Sign	Two signs on site.	8/8/2008	Active	No
Current Condition:		Good Condition A SWPPP sign has been installed at 22nd & Chandler Road and 25th and Sautter Ave entrances. SWPPP sign was removed from 19th Street as of inspection on 3/28/12.			
Inspector Signature:	I Jawlen			Reviewed By:	Zadrany K. Jilek