E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager E & A CONSULTING GROUP, INC.

ENGINEERING · PLANNING · ENVIRONMENTAL & FIELD SERVICES

		&A - P2006.135.000			
Inspector: Tyler Wolfe				Stage	
		Kennedy Town Center		3	
Project Name:		NER110532			
Project Name:					
For Week Ending:		8/10/2013 25th & Chandler Road- Bellevue, NE (Sarpy County)			
Project Location:	25th &				
	1		<u> </u>		
Grading:		100%			
Sanitary Sewer:		100%			
Storm Sewer:		100%			
Paving:		100%			
Seeding:		100%			
Utilities:		100%			
Overall Development:		30%			
RAIN FALL AMOUNTS	Amount in tenths	Data increased			
NAM FALL AMOUNTS	Amount ill telltila	Date inspected		Week 1	
Sunday:	0.00"			vveek	
Monday	0.00"				
Tuesday	0.00"	07/16/13			
Wednesday	0.00"	0.7.10,110			
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
	2.22			Week 2	
Sunday:	0.02"				
Monday	0.00"				
Tuesday Wednesday	0.04" 0.00"				
Thursday	0.01"				
Friday	0.00"				
Saturday	0.00"				
outui uuy	0.00			Week	
Sunday:	0.00"				
Monday	0.05"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.20"				
Friday	0.00"				
Saturday	0.00"				
Sunday:	0.00"			Week 4	
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
				Week !	
Sunday:	N/A	N/A			
Monday	N/A	N/A			
Tuesday	N/A	N/A			
Wednesday	N/A	N/A			
Thursday	N/A	N/A			
Friday	N/A	N/A			

Saturday	N/A	N/A					
	None						
Complaints:							
		1	T	T	T		
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the	-Ne have held a town and a			and distant and the	the lead 44 desce 0		
which portion(s) (i.e. drainage basins) of the	site nave nad a temporary or perma	nent cessation of grading	g, eartnwork, or gro	und disturbance in t	me last 14 days?		
Entire Site, Grading was completed and entire site was seeded Fall 2006.							
Which portion(s) (i.e. drainage basins) of the	site do not have grading, earthwork	, or ground disturbance s	scheduled in the ne	kt 14 days? :			
Entire Site, Grading was completed and entire site was seeded Fall 2006.							
What temporary or permanent stabilization m	neasures listed in this section are be	ing implemented?					
Seeding (Fall 2006), stabilized entrance, Paved streets (10/2007), Paved entrance (11/2007); Re-seed part of the lot to west of SB B(4/2009); Re-seeded the north east corner of the lot where the area inlet was installed(4/2009); Re-seeded around the SB A and SB B(4/2009); The disturbed							
areas of the South section of lot 5 Ker				•	, ,		
B was hydro seeded (8/2012); The Ea							
seeded(10/10/12)				· ·			
Comments:							
Comments:							
A few lots are under construction at th	is time.						
Findings / Corrective Actions (Date)):						
Findings / Corrective Actions (Date)							
1) Some maintenance is required in the							
2) Tom with Legacy Homes was notified to install concrete washout to prevent numerous piles of concrete spoils accumulating throughout the							
development, no date was given to complete. This was not complete prior to last inspection							

Uniternal Manage	T	Laadian	Projected	01-1		
Unique Name	Туре	Location	Install Date	Status	Maintenance	
		N41d00m00s				
CE A	Construction Entrance	W96d00m00s		Removed	No	
Current Condition:	Removed paved entrance					
		N41d00m00s				
DD 1	Swale	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - Partially rer	noved due to paving of	f street.			
	Diversion ditch was redefined prior to inspection on 4/8/09 by M.E. Collins.					
			-			
		N41d00m00s				
DD 2	Swale	W96d00m00s		Removed		
Current Condition:	Removed due to paving of street.					
	, ,	Lot 4 Kennedy				
Lot 4 Kennedy Town Center Replat		Town Center Replat				
	0:14	•		A -45	NI-	
Three	Silt Fence	Three	10/10/2012	Active	No	
Current Condition: Good Condition						
	Silt fence check was installed prior to inspection on 10/10/12 by CS.					
POD B	Misc/Other	Lots 28-44	2/9/2011	Active	Yes	

Current Condition:	Good Condition Portable toilet was removed p	rior to inspection on 7	7/16/13 by Legacy	/ Homes.		
	1) There is a pile of construction debris/concrete debris on lot 44 and it needs to be cleaned up. 2) There is some concrete spoils in the R.O.W. on lot 44 and it needs to be cleaned up.					
	1) Builder Larry Bayer was inf on 4/12/13 Larry Bayer was re		,		,	
	reminded that needs to be comaintenance ASAP on 5/20/1	mpleted ASAP. Kurt I	Hansen with Lega	<mark>cy Homes was n</mark>	otified to complete	
	6/5/13, 6/25/13, 7/18/13 to co 2) Builder Larry Bayer was inf	•				
	reminded that needs to be co- completed ASAP. Kurt Hanse 5/20/13. Tom Kafonef with Le	en with Legacy Home	s was notified to d	complete mainte	nance ASAP on	
POD C	Misc/Other	Lots 10-27	11/28/2012	Active	Yes	
Current Condition:	Active Lots Lots 26 and 27 were sodded p	orior to inspection on	7/17/13.			
	 There is a pile of construction debris/concrete debris on lot 16 and it needs to be cleaned up. There is some concrete spoils in the R.O.W. along Albert Street on lot 10 and it needs to be cleaned up. Lot 17 has dirt in the R.O.W. and needs removed or silt fence installed around it. Lot 15 has concrete debris in the R.O.W. and needs removed. 					
	1) Builder Larry Bayer was informed to complete maintenance by 3/27/13. On 4/12/13 Larry Bayer was reminded that needs to be completed ASAP. On 4/23/13 Legacy Homes was reminded that needs to be completed ASAP. Tom Kafonef with Legacy Homes was sent a reminder plan on 5/29/13, 6/5/13, and 6/25/13 to complete maintenance ASAP. Not done as of last inspection. 2) Builder Larry Bayer was informed to complete maintenance by 3/27/13. On 4/12/13 Larry Bayer was reminded that needs to be completed ASAP. Tom Kafonef with Legacy Homes was sent a reminder plan on 5/29/13, 6/5/13, 6/25/13,					
	7/18/13 to complete maintena 3) Tom with Legacy Homes w 4) Tom with Legacy Homes w	ince ASAP. Not done as notified to complete	as of last inspect te by 7/1/13. A rei	ion. minder plan was		
SB A	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - 23% filled Cleaned out 10/2007 by Dave Hausman. Erosion maintenance was completed prior to inspection on 4/8/09 by M.E. Collins.					
	by M.E. Collins.				to inspection on 4/8/09	
SB B	Sediment Basin	N41d00m00s W96d00m00s	10/6/2007	Active	No	
SB B Current Condition:		W96d00m00s ce was completed on	4/1/09 by M.E. C	collins.	No	
Current Condition:	Sediment Basin Good Condition - 25% filled Cleanout and riser maintenan	W96d00m00s ce was completed on s sodded prior to insp N41d00m00s	4/1/09 by M.E. C	collins.	No	
	Sediment Basin Good Condition - 25% filled Cleanout and riser maintenan The East side of the basin wa	w96d00m00s ce was completed on s sodded prior to insp N41d00m00s w96d00m00s	4/1/09 by M.E. Coection on 9/13/12 rm installed.	collins. 2 by Duane w/ Vi Removed	No Ilage Builders.	
Current Condition: SF A Current Condition:	Sediment Basin Good Condition - 25% filled Cleanout and riser maintenan The East side of the basin wa Silt Fence Partially removed due to good The remainder of silt fence was	W96d00m00s ce was completed on s sodded prior to insp N41d00m00s W96d00m00s d vegetation and a be as removed prior to in N41d00m00s	4/1/09 by M.E. Coection on 9/13/12 rm installed.	collins. 2 by Duane w/ Vi Removed 1 by Commercia	No Ilage Builders.	
Current Condition:	Sediment Basin Good Condition - 25% filled Cleanout and riser maintenan The East side of the basin wa Silt Fence Partially removed due to good	W96d00m00s ce was completed on s sodded prior to insp. N41d00m00s W96d00m00s d vegetation and a be as removed prior to in N41d00m00s W96d00m00s ue to good vegetation	4/1/09 by M.E. Coection on 9/13/12 rm installed. spection on 4/4/1	Removed Removed Removed Removed Removed Removed the area at this	No Ilage Builders. Il Seeding. time prior to inspection	
SF A Current Condition: SF B Current Condition:	Sediment Basin Good Condition - 25% filled Cleanout and riser maintenan The East side of the basin wa Silt Fence Partially removed due to good The remainder of silt fence wa Silt Fence Silt fence run was removed due on 3/24/10 by CS. Note: Silt fe	W96d00m00s ce was completed on s sodded prior to insp N41d00m00s W96d00m00s d vegetation and a be as removed prior to in N41d00m00s W96d00m00s ue to good vegetation ence may need to be N41d00m00s	4/1/09 by M.E. Coection on 9/13/12 rm installed. spection on 4/4/1	Removed Removed Removed Removed Removed Removed the area at this here is construct	No Ilage Builders. Il Seeding. time prior to inspection	
SF A Current Condition: SF B	Sediment Basin Good Condition - 25% filled Cleanout and riser maintenan The East side of the basin wa Silt Fence Partially removed due to good The remainder of silt fence was Silt Fence Silt fence run was removed di	W96d00m00s ce was completed on s sodded prior to insp N41d00m00s W96d00m00s d vegetation and a be as removed prior to in N41d00m00s W96d00m00s ue to good vegetation ence may need to be N41d00m00s W96d00m00s W96d00m00s	4/1/09 by M.E. Coection on 9/13/12 rm installed. spection on 4/4/1 a and no activity in reinstalled once t	Removed Removed Removed Removed Removed the area at this here is construct	No Ilage Builders. Il Seeding. time prior to inspection activity in the area.	
SF A Current Condition: SF B Current Condition: SF B SF C	Sediment Basin Good Condition - 25% filled Cleanout and riser maintenan The East side of the basin wa Silt Fence Partially removed due to good The remainder of silt fence wa Silt Fence Silt fence run was removed do on 3/24/10 by CS. Note: Silt fence	W96d00m00s ce was completed on s sodded prior to insp N41d00m00s W96d00m00s d vegetation and a be as removed prior to in N41d00m00s W96d00m00s ue to good vegetation ence may need to be N41d00m00s W96d00m00s W96d00m00s	4/1/09 by M.E. Coection on 9/13/12 rm installed. spection on 4/4/1 a and no activity in reinstalled once t	Removed Removed Removed Removed Removed the area at this here is construct	No Ilage Builders. Il Seeding. time prior to inspection activity in the area.	

Current Condition:	Silt Fence removed and diversion ditch installed in this area.					
STR	Street Cleaning	N41d00m00s W96d00m00s		Active	Yes	
Current Condition:	Fair Condition Track of near lot 27 was clean up prior to inspection on 7/17/13 by Legacy Homes. Mud in curb line along lots 11-16 needs to be cleaned up. Tom w/Legacy Homes was notified to clean curb lines by 7/18/13.					
SWPPP Sign Current Condition:	SWPPP Sign Two signs on site. 8/8/2008 Active No Good Condition A SWPPP sign has been installed at 22nd & Chandler Road and 25th and Sautter Ave entrances. SWPPP sign was removed from 19th Street as of inspection on 3/28/12.					
Inspector Signature: Reviewed By:						