E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager E & A CONSULTING GROUP, INC.

ENGINEERING · PLANNING · ENVIRONMENTAL & FIELD SERVICES

Environmental Services Dept.	. Manager	Eno	INEERING • PLANNING •	Environmenti		
		E&A - P2006.135.0	00			
Inspector: Alex Emerson					Stage	
Kennedy Town Center					3	
		NER11				
Project Name:						
For Week Ending:						
Project Location:	25th &	1/11/2014 25th & Chandler Road- Bellevue, NE (Sarpy County)				
	//	68147				
Grading:		100%				
Sanitary Sewer:		100%				
Storm Sewer:		100%				
Paving:		100%				
Seeding:		100%				
Utilities:		100%				
Overall Development:		30%				
		5070				
RAIN FALL AMOUNTS	Amount in tenths	Data inanastad				
		Date inspected			Week 1	
Sunday:	0.00"				WEEKI	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"	12/18/13				
Thursday	0.00"	12/10/10				
Friday	0.00"					
Saturday	0.00"					
					Week 2	
Sunday:	0.01"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Week 3	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.03" 0.00"					
Thursday Friday	0.00"					
Saturday	0.00"					
	0.00				Week 4	
Sunday:	0.00"				Week 4	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.01"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Week 5	
Sunday:	N/A	N/A				
Monday	N/A	N/A				
Tuesday	N/A	N/A				
Wednesday	N/A	N/A				
Thursday	N/A	N/A				
Friday	N/A	N/A				

Saturday	N/A	N/A					
	None						
Complaints:							
				1	1		
Construction Sequencing:							
Which portion(s) (i.e. drainage basins) of the	he site have had a temporary or perm	nanent cessation of gradin	g, earthwork, or gro	und disturbance in	the last 14 days?		
Entire Site, Grading was completed a	and entire site was seeded Fal	2006.					
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :							
Entire Site, Grading was completed a	and entire site was seeded Fal	2006.					
What temporary or permanent stabilization measures listed in this section are being implemented?							
Seeding (Fall 2006), stabilized entrai	nce, Paved streets (10/2007),	Paved entrance (11/20	07); Re-seed par	t of the lot to wes	st of SB B(4/2009); Re-		
seeded the north east corner of the I	ot where the area inlet was ins	talled(4/2009); Re-see	ded around the S	B A and SB B(4/	2009); The disturbed		
areas of the South section of lot 5 Ke	ennedy Town Center Replat Th	ree was re-seeded prid	or to inspection o	n 7/18/12; The W	lest side slope of Basin		
B was hydro seeded (8/2012); The E seeded(10/10/12)	ast side of Basin B was sodde	d 9/13/12; The West s	side of the R.O.W	along 19th Circ	le was		
Comments:	+		•	•			

Comments:

A few lots are under construction at this time. Site was inactive during inspection on 12/18/13.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) Some maintenance is required in the BMP section.

2) Tom with Legacy Homes was notified to install concrete washout to prevent numerous piles of concrete spoils accumulating throughout the development, no date was given to complete. A reminder plan was sent on 08/16/2013, 9/3/2013, 10/7/13, 10/15/13, 10/30/13, 11/8/13, 12/4/13 requesting to complete this ASAP. This was not done prior to last inspection.

			Projected			
Unique Name	Туре	Location	Install Date	Status	Maintenance	
		N41d00m00s				
CE A	Construction Entrance	W96d00m00s		Removed		
Current Condition:	Removed paved entrance					
		N41d00m00s				
DD 1	Swale	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - Partially rem	oved due to paving of	f street.	•		
	Diversion ditch was redefined prior to inspection on 4/8/09 by M.E. Collins.					
		N41d00m00s				
DD 2	Swale	W96d00m00s		Removed		
Current Condition:	Removed due to paving of street.					
		Lot 4 Kennedy				
Lot 4 Kennedy Town Center Replat		Town Center Replat				
Three	Silt Fence	Three	10/10/2012	Active	No	
Current Condition:	rrent Condition: Good Condition					
	Silt fence check was installed prior to inspection on 10/10/12 by CS.					
POD B	Misc/Other	Lots 28-44	2/9/2011	Active	Yes	

Current Condition:	Fair Condition Portable toilet was removed p	rior to inspection on 7	7/16/13 by Legac	y Homes.			
	2) There is some concrete spo	 There is a pile of construction debris/concrete debris on lot 44 and it needs to be cleaned up. There is some concrete spoils in the R.O.W. on lot 44 and it needs to be cleaned up. There is some concrete debris on lot 28 as of inspection on 08/15/2013. 					
	 Builder Larry Bayer was informed to complete maintenance by 12/5/12. On 1/17/13, 3/21/13 and again on 4/12/13 Larry Bayer was reminded that needs to be completed ASAP. Legacy Homes was sent a reminder plan on 4/23/13, 5/20/13, 5/29/13, 6/5/13, 6/25/13, 7/18/13, 08/16/2013, 9/3/2013, 10/7/13, 11/8/13, 12/4/13 requesting to complete maintenance ASAP. Not done as of last inspection. Builder Larry Bayer was informed to complete maintenance by 3/27/13. On 4/12/13 Larry Bayer was reminded that needs to be completed ASAP. Legacy Homes was sent a reminder plan on 4/12/13, 4/23/13, 5/20/13, 5/29/13, 6/5/13, 6/25/13, 7/18/13, 08/16/2013, 9/3/2013, 10/7/13, 11/8/13, 12/4/13 requesting to complete maintenance ASAP. Not done as of last inspection. Legacy Homes was sent a plan requesting to clean this up by 08/22/2013. Note done as of last inspection 						
POD C	Misc/Other	Lots 10-27	11/28/2012	Active	Yes		
Current Condition:	Active Lots -The stockpile of dirt on lot 26 12/18/13.	was removed from th	ne ROW by Lega	cy Homes prior to	o inspection on		
	There is some concrete spoils Builder Larry Bayer was inform reminded that needs to be con 6/5/13, 6/25/13, 7/18/13, 08/1	ned to complete main npleted ASAP. Legad	tenance by 3/27/ cy Homes was rel	13. On 4/12/13 L minded on 4/23/	arry Bayer was 13, 5/20/13, 5/29/13,		
POD D	Misc/Other	Lots 1-9	8/23/2013	Pending	Yes		
Current Condition:	Pending -The portable toilet on lot 3 was staked down by Legacy Homes prior to inspection on 10/30/13. Home construction is active on lot 9 and no BMP is in place as of inspection on 08/13/2013 Legacy Homes was sent a plan requesting to install silt fence or some other type of BMP by 08/20/2013. Not done as of last inspection. Legacy Homes was reminded on 9/3/13, 10/7/13, 10/15/13, 10/30/13, 11/8/13, 12/4/13.						
	Legacy Homes was sent a pla Not done as of last inspection.	n lot 9 and no BMP is n requesting to instal	in place as of in I silt fence or son	spection on 08/1	3/2013 3MP by 08/20/2013.		
	Legacy Homes was sent a pla Not done as of last inspection. 11/8/13, 12/4/13.	n lot 9 and no BMP is n requesting to instal Legacy Homes was N41d00m00s	in place as of in: I silt fence or son reminded on 9/3	spection on 08/1 ne other type of B 3/13, 10/7/13, 10/	3/2013 BMP by 08/20/2013. (15/13, 10/30/13,		
SB A Current Condition:	Legacy Homes was sent a pla Not done as of last inspection.	n lot 9 and no BMP is n requesting to instal Legacy Homes was N41d00m00s W96d00m00s	in place as of in: I silt fence or son reminded on 9/3	spection on 08/1 ne other type of B 3/13, 10/7/13, 10/ Active	3/2013 BMP by 08/20/2013. (15/13, 10/30/13, No		
Current Condition:	Legacy Homes was sent a pla Not done as of last inspection. 11/8/13, 12/4/13. Sediment Basin Good Condition - 23% filled Cleaned out 10/2007 by Dave by M.E. Collins.	n lot 9 and no BMP is n requesting to instal Legacy Homes was N41d00m00s W96d00m00s Hausman. Erosion m	I silt fence as of in: reminded on 9/3 In Place	spection on 08/1 ne other type of F 3/13, 10/7/13, 10/ Active completed prior	3/2013 BMP by 08/20/2013. (15/13, 10/30/13, No to inspection on 4/8/09		
	Legacy Homes was sent a pla Not done as of last inspection. 11/8/13, 12/4/13. Sediment Basin Good Condition - 23% filled Cleaned out 10/2007 by Dave	n lot 9 and no BMP is n requesting to instal Legacy Homes was N41d00m00s W96d00m00s Hausman. Erosion m N41d00m00s W96d00m00s ce was completed on	I silt fence as of in: I silt fence or son reminded on 9/3 In Place naintenance was 10/6/2007 4/1/09 by M.E. C	spection on 08/1 ne other type of f 3/13, 10/7/13, 10/ Active completed prior f Active Collins.	3/2013 3MP by 08/20/2013. (15/13, 10/30/13, No to inspection on 4/8/09 No		
Current Condition: SB B Current Condition:	Legacy Homes was sent a pla Not done as of last inspection. 11/8/13, 12/4/13. Sediment Basin Good Condition - 23% filled Cleaned out 10/2007 by Dave by M.E. Collins. Sediment Basin Good Condition - 25% filled Cleanout and riser maintenand The East side of the basin was	n lot 9 and no BMP is n requesting to instal Legacy Homes was N41d00m00s W96d00m00s Hausman. Erosion m N41d00m00s W96d00m00s ce was completed on s sodded prior to insp N41d00m00s	I silt fence as of in: I silt fence or son reminded on 9/3 In Place naintenance was 10/6/2007 4/1/09 by M.E. C	spection on 08/1 ne other type of F 3/13, 10/7/13, 10/ Active completed prior to Active Collins. 2 by Duane w/ Vi	3/2013 3MP by 08/20/2013. (15/13, 10/30/13, No to inspection on 4/8/09 No		
Current Condition: SB B	Legacy Homes was sent a pla Not done as of last inspection. 11/8/13, 12/4/13. Sediment Basin Good Condition - 23% filled Cleaned out 10/2007 by Dave by M.E. Collins. Sediment Basin Good Condition - 25% filled Cleanout and riser maintenance	h lot 9 and no BMP is n requesting to instal Legacy Homes was W96d00m00s Hausman. Erosion m N41d00m00s W96d00m00s ce was completed on s sodded prior to insp N41d00m00s W96d00m00s vegetation and a bei	I silt fence or son reminded on 9/3 I n Place naintenance was 10/6/2007 4/1/09 by M.E. C ection on 9/13/12	spection on 08/1 he other type of F /13, 10/7/13, 10/ Active completed prior to Active Collins. 2 by Duane w/ Vi Removed	3/2013 BMP by 08/20/2013. (15/13, 10/30/13, No to inspection on 4/8/09 No Ilage Builders.		
Current Condition: SB B Current Condition: SF A	Legacy Homes was sent a pla Not done as of last inspection. 11/8/13, 12/4/13. Sediment Basin Good Condition - 23% filled Cleaned out 10/2007 by Dave by M.E. Collins. Sediment Basin Good Condition - 25% filled Cleanout and riser maintenand The East side of the basin was Silt Fence Partially removed due to good	h lot 9 and no BMP is n requesting to instal Legacy Homes was W96d00m00s Hausman. Erosion m N41d00m00s W96d00m00s ce was completed on s sodded prior to insp N41d00m00s W96d00m00s vegetation and a bei	I silt fence or son reminded on 9/3 I n Place naintenance was 10/6/2007 4/1/09 by M.E. C ection on 9/13/12	spection on 08/1 he other type of F /13, 10/7/13, 10/ Active completed prior to Active Collins. 2 by Duane w/ Vi Removed	3/2013 BMP by 08/20/2013. (15/13, 10/30/13, No to inspection on 4/8/09 No Ilage Builders.		
Current Condition: SB B Current Condition: SF A Current Condition:	Legacy Homes was sent a pla Not done as of last inspection. 11/8/13, 12/4/13. Sediment Basin Good Condition - 23% filled Cleaned out 10/2007 by Dave by M.E. Collins. Sediment Basin Good Condition - 25% filled Cleanout and riser maintenand The East side of the basin was Silt Fence Partially removed due to good The remainder of silt fence was	n lot 9 and no BMP is n requesting to instal Legacy Homes was W96d00m00s Hausman. Erosion m N41d00m00s W96d00m00s ce was completed on s sodded prior to insp N41d00m00s W96d00m00s vegetation and a ber is removed prior to in N41d00m00s w96d00m00s is to good vegetation	in place as of in: I silt fence or son reminded on 9/3 In Place naintenance was 10/6/2007 4/1/09 by M.E. C ection on 9/13/12 rm installed. spection on 4/4/1 and no activity ir	spection on 08/1 ne other type of F 3/13, 10/7/13, 10/ Active completed prior to Active collins. 2 by Duane w/ Vi Removed 1 by Commercia Removed on the area at this	3/2013 3MP by 08/20/2013. (15/13, 10/30/13, (15/13, 10/30, (15/13, 10, 10/30, (15/13, 1		
Current Condition: SB B Current Condition: SF A Current Condition: SF B	Legacy Homes was sent a pla Not done as of last inspection. 11/8/13, 12/4/13. Sediment Basin Good Condition - 23% filled Cleaned out 10/2007 by Dave by M.E. Collins. Sediment Basin Good Condition - 25% filled Cleanout and riser maintenand The East side of the basin was Silt Fence Partially removed due to good The remainder of silt fence was Silt Fence Silt Fence Silt Fence Silt Fence Silt Fence	n lot 9 and no BMP is n requesting to instal Legacy Homes was W96d00m00s Hausman. Erosion m N41d00m00s W96d00m00s ce was completed on s sodded prior to insp N41d00m00s W96d00m00s vegetation and a ber is removed prior to in N41d00m00s w96d00m00s is to good vegetation	in place as of in: I silt fence or son reminded on 9/3 In Place naintenance was 10/6/2007 4/1/09 by M.E. C ection on 9/13/12 rm installed. spection on 4/4/1 and no activity ir	spection on 08/1 ne other type of F 3/13, 10/7/13, 10/ Active completed prior to Active collins. 2 by Duane w/ Vi Removed 1 by Commercia Removed on the area at this	3/2013 3MP by 08/20/2013. (15/13, 10/30/13, (15/13, 10/30, (15/13, 10, 10/30, (15/13, 1		
Current Condition: SB B Current Condition: SF A Current Condition: SF B Current Condition:	Legacy Homes was sent a pla Not done as of last inspection. 11/8/13, 12/4/13. Sediment Basin Good Condition - 23% filled Cleaned out 10/2007 by Dave by M.E. Collins. Sediment Basin Good Condition - 25% filled Cleanout and riser maintenand The East side of the basin was Silt Fence Partially removed due to good The remainder of silt fence was Silt Fence Silt fence run was removed du on 3/24/10 by CS. Note: Silt fence	n lot 9 and no BMP is n requesting to instal Legacy Homes was N41d00m00s W96d00m00s Hausman. Erosion m N41d00m00s W96d00m00s ce was completed on s sodded prior to insp N41d00m00s W96d00m00s vegetation and a beil is removed prior to in: N41d00m00s W96d00m00s ie to good vegetation ence may need to be N41d00m00s w96d00m00s ie to good vegetation	I silt fence or son reminded on 9/3 I n Place naintenance was 10/6/2007 4/1/09 by M.E. C pection on 9/13/12 rm installed. spection on 4/4/1 and no activity ir reinstalled once t	spection on 08/1 the other type of B 3/13, 10/7/13, 10/ Active completed prior to Active Collins. 2 by Duane w/ Vi Removed 1 by Commercia Removed the area at this there is construct	3/2013 3MP by 08/20/2013. (15/13, 10/30/13, (15/13, 10/30, (15/13, 10, 10/30, (15/13, 1		
Current Condition: SB B Current Condition: SF A Current Condition: SF B Current Condition: SF C	Legacy Homes was sent a pla Not done as of last inspection. 11/8/13, 12/4/13. Sediment Basin Good Condition - 23% filled Cleaned out 10/2007 by Dave by M.E. Collins. Sediment Basin Good Condition - 25% filled Cleanout and riser maintenand The East side of the basin was Silt Fence Partially removed due to good The remainder of silt fence was Silt Fence Silt fence run was removed du on 3/24/10 by CS. Note: Silt fence Silt Fence	n lot 9 and no BMP is n requesting to instal Legacy Homes was W96d00m00s Hausman. Erosion m N41d00m00s W96d00m00s ce was completed on s sodded prior to insp N41d00m00s W96d00m00s vegetation and a ber is removed prior to in N41d00m00s w96d00m00s ie to good vegetation ence may need to be N41d00m00s W96d00m00s	I silt fence or son reminded on 9/3 I n Place naintenance was 10/6/2007 4/1/09 by M.E. C pection on 9/13/12 rm installed. spection on 4/4/1 and no activity ir reinstalled once t	spection on 08/1 the other type of B 3/13, 10/7/13, 10/ Active completed prior to Active Collins. 2 by Duane w/ Vi Removed 1 by Commercia Removed the area at this there is construct	3/2013 3MP by 08/20/2013. (15/13, 10/30/13, (15/13, 10/30, (15/13, 10, 10/30,		

		N41d00m00s				
STR	Street Cleaning	W96d00m00s		Active	No	
Current Condition:	Good Condition-No major signs of trackoff.					
	-Trackoff from lot 2 was cleaned up by Tom with Legacy Homes prior to inspection on 10/30/13.					
	-Runoff from lot 9 was cleaned up by Tom with Legacy Homes prior to inspection on 10/30/13.					
SWPPP Sign	SWPPP Sign	Two signs on site.	8/8/2008	Active	No	
Current Condition:	Good Condition A SWPPP sign has been installed at 22nd & Chandler Road and 25th and Sautter Ave entrances. SWPPP sign was removed from 19th Street as of inspection on 3/28/12.					
Inspector Signature:						