E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC **Environmental Services Dept. Manager**  E & A CONSULTING GROUP, INC.

ENGINEERING · PLANNING · ENVIRONMENTAL & FIELD SERVICES

## E&A - P2006.135.000 Stage Inspector: Alex Emerson **Kennedy Town Center** NER110532 Project Name: 6/14/2014 For Week Ending: 68147 **Project Location:** 25th & Chandler Road- Bellevue, NE (Sarpy County) Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% Seeding: 100% Utilities: 100% Overall Development: 30% RAIN FALL AMOUNTS Amount in tenths Date inspected Weather Conditions Week 2.80" Sunday: Monday 0.39" 05/12/14 62/48 Rain Tuesday 0.00" Wednesday 0.02 Thursday 0.00" Friday 0.00" Saturday 0.00" Week 2 Sunday: 0.00" Monday 0.00" Tuesday 0.00" Wednesday 0.00" Thursday 05/22/14 68/55 Cloudy 0.58 Friday 0.00" Saturday 0.00" Week Sunday: 0.27" Monday 0.05" Tuesday 0.63 Wednesday 0.00" 05/28/14 84/60 Partly Cloudy Thursday 0.00" Friday 0.00" Saturday 0.00" Week 4 Sunday: 0.88" Monday 0.00" 06/02/14 82/61 Sunny Tuesday 1.67" 77/62 Partly Cloudy Wednesday 06/04/14 0.19" Thursday 0.00" Friday 0.00" Saturday 0.32" Week 0.00" Sunday: Monday 0.00" Tuesday 0.00" Wednesday 0.00" Thursday

0.00"

0.00"

Friday

Caturday	0.00"							
Saturday	0.00"							
	None	None						
Complaints:								
Construction Sequenci	ng.	ļ.	+	· · · · · · · · · · · · · · · · · · ·	!			
		mporary or permanent cessation of g	rading, earthwork, or	ground disturbance in t	ne last 14 days?			
Times person(e) (see arassag		po.a.y o. poao occoao o. g	· aag, oa. a o, o.	ground alotal zamoo iii t	io lact 1 : aayo :			
Entire Site, Grading was	completed and entire site wa	es sooded Fall 2006						
Littile Site, Grading was	completed and entire site wa	as seeded I all 2000.						
Which portion(s) (i.e. drainag	e basins) of the site do not have o	grading, earthwork, or ground disturb	ance scheduled in the	e next 14 days? :				
	,			•				
Entire Cite Creding was	accomplated and autima aita wa	22 22 ded Fell 2000						
Entire Site, Grading was	completed and entire site wa	as seeded Fall 2006.						
What temporary or permanen	t stabilization measures listed in	this section are being implemented?		l				
		<u> </u>	4 (0007). D		f OD D/4/0000\: D -			
O (		ts (10/2007), Paved entrance (1	, .	•				
		a inlet was installed(4/2009); Re		,	**			
	•	nter Replat Three was re-seeded		· ·	•			
was hydro seeded (8/201	<li>12); The East side of Basin B</li>	was sodded 9/13/12; The Wes	t side of the R.O.	W. along 19th Circle	was seeded(10/10/12)			
0	<u> </u>		<del></del>		1			
Comments:								
Comments:								
	struction at this time. Dirt is h	eing stockpiled on lots 10-11 ar	nd 81					
		oning decomplied on lots to trial						
Findings / Corrective A	ctions (Date):							

## Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section.
- 2) Tom with Legacy Homes was notified to install concrete washout to prevent numerous piles of concrete spoils accumulating throughout the development, no date was given to complete. Not done as of last inspection. Legacy Homes was reminded on 08/16/2013, 9/3/2013, 10/7/13, 10/15/13, 10/30/13, 11/8/13, 12/4/13, 1/15/14, 2/12/14, 3/19/14, 4/16/14. There is very little construction activity on site, so a concrete washout is no longer being requested as of inspection on 5/12/14. E&A Inspector will monitor for changes.
- 3) Silt fence needs retied on the corner of Kennedy Ave and 19th Cir. as of inspection on 3/19/14. Legacy Homes was requested to retie the silt fence by 3/26/14. The silt fence was retied by Legacy Homes prior to inspection on 5/12/14.

			Projected Install			
Unique Name	Туре	Location	Date	Status	Maintenance	
		N41d00m00s				
CE A	Construction Entrance	W96d00m00s		Removed		
Current Condition:	Removed paved entrance					
		N41d00m00s				
DD 1	Swale	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - Partially removed due to paving of street.					
	Diversion ditch was redefined prior to inspection on 4/8/09 by M.E. Collins.					
		N41d00m00s				
DD 2	Swale	W96d00m00s		Removed		
Current Condition:	Removed due to paving of street.					
		Lot 4 Kennedy				
Lot 4 Kennedy Town Center Replat		Town Center Replat				
Three	Silt Fence	Three	10/10/2012	Active	No	
Current Condition: Good Condition						
	Silt fence check was installed prior to inspection on 10/10/12 by CS.					
POD B	Misc/Other	Lots 28-44	2/9/2011	Active	Yes	

Current Condition:	Fair Condition						
	Portable toilet was removed	prior to inspection on 7	7/16/13 by Legacy Ho	mes.			
	1) There is a pile of construct				· · · · · · · · · · · · · · · · · · ·		
	2) There is some concrete sp						
	<ul> <li>3) There is some concrete debris on lot 28 as of inspection on 08/15/2013.</li> <li>4) The silt fence along the North side of lot 28 needs retied as of inspection on 2/11/14. Silt fence also needs retied on the Northeast corner of lot 28 as of inspection on 3/19/14.</li> </ul>						
	1) (See previous reports) Leg	gacy Homes was reque	ested to clean up con	struction/concr	ete debris on 4/23/13.		
	Not done as of last inspection	0 ,					
	08/16/2013, 9/3/2013, 10/7/1 2) (See previous reports) Leg						
	inspection. Legacy Homes w	vas reminded on 5/20/	13, 5/29/13, 6/5/13, 6	<mark>/25/13, 7/18/1</mark> 3			
	9/3/2013, 10/7/13, 11/8/13, 1 3) Legacy Homes was sent a				as of last inspection. I		
	4) Legacy Homes was reque						
POD C	Misc/Other	Lots 10-27	11/28/2012	Active	Yes		
Current Condition:	Active- Lot 25 -The stockpile of dirt on lot 20	6 was removed from th	ne ROW by Legacy H	omes prior to i	espection on 12/18/13		
	-The stockpile of dift of for 20	o was removed from the	ie NOW by Legacy II	offics prior to i	13pection on 12/10/13.		
	1) There is some concrete sp	poils in the R.O.W. alor	ng Albert Street on Io	t 10 and it need	ds to be cleaned up.		
	(See previous reports) Legac	cy Homes was request	ed to clean up concre	ete spoils on 4/2	23/13. Not done as of		
	last inspection. Legacy Hom	es was reminded on 5	<mark>/20/13, 5/29/13, 6/5/1</mark>	3, 6/25/13, 7/	18/13, 08/16/2013,		
	9/3/13, 10/7/13, 10/15/13, 10	/30/13, 11/8/13, 12/4/1	13, 1/15/14, 2/12/14,	4/16/14, 5/14/1	4.		
POD D	Misc/Other	Lots 1-9	8/23/2013	Active	Yes		
Current Condition:	Active- Lot 2,9 -The portable toilet on lot 3 w	vas staked down by Le	gacy Homes prior to	nspection on 1	0/30/13.		
	1) Home construction is active on lot 9 and no BMP is in place as of inspection on 08/13/2013						
	2) Construction on lot 2 is complete and the lot needs sodded as of inspection on 1/15/14.						
	3) There is concrete debris on lot 8 as of inspection on 4/14/14.						
	1) Legacy Homes was sent a plan requesting to install silt fence or some other type of BMP by 08/20/2013.						
Not done as of last inspection. Legacy Homes was reminded on 9/3/13, 10/7/13, 10/15/13, 10							
12/4/13, 1/15/14, 2/12/14, 3/19/14, 4/16/14. Legacy Homes was requASAP on 5/14/14.					equested to install silt fence or sod the lot		
	2) Legacy Homes was requested to sod the lot on 1/15/14. Not done as of last inspection. Leg						
	was reminded on 4/16/14, 5/14/14.						
	3) Legacy Homes was requested to remove concrete debris by 4/21/14. Not done as of Legacy Homes was reminded on 5/14/14.				last inspection.		
		N 44 - 100 00-	1				
SB A	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No		
SB A Current Condition:	Good Condition - 23% filled	W96d00m00s					
	Good Condition - 23% filled Cleaned out 10/2007 by Dave	W96d00m00s					
	Good Condition - 23% filled	W96d00m00s e Hausman. Erosion m					
Current Condition: SB B	Good Condition - 23% filled Cleaned out 10/2007 by Dav M.E. Collins.	W96d00m00s					
Current Condition:	Good Condition - 23% filled Cleaned out 10/2007 by Dav M.E. Collins.  Sediment Basin Good Condition - 25% filled	W96d00m00s e Hausman. Erosion m  N41d00m00s W96d00m00s	naintenance was com	pleted prior to  Active	inspection on 4/8/09 by		
Current Condition: SB B	Good Condition - 23% filled Cleaned out 10/2007 by Dav M.E. Collins.	W96d00m00s  e Hausman. Erosion m  N41d00m00s  W96d00m00s  nce was completed on	10/6/2007 4/1/09 by M.E. Collin	pleted prior to  Active	inspection on 4/8/09 by No		
Current Condition:  SB B  Current Condition:	Good Condition - 23% filled Cleaned out 10/2007 by Dav M.E. Collins.  Sediment Basin Good Condition - 25% filled Cleanout and riser maintenar The East side of the basin wa	W96d00m00s  e Hausman. Erosion m  N41d00m00s  W96d00m00s  nce was completed on as sodded prior to insp  N41d00m00s	10/6/2007 4/1/09 by M.E. Collin	Active  S.  Duane w/ Villa	inspection on 4/8/09 by No		
SB B Current Condition:	Good Condition - 23% filled Cleaned out 10/2007 by Davi M.E. Collins.  Sediment Basin Good Condition - 25% filled Cleanout and riser maintenar The East side of the basin was	W96d00m00s  e Hausman. Erosion m  N41d00m00s  W96d00m00s  nce was completed on as sodded prior to insp  N41d00m00s  W96d00m00s	10/6/2007 4/1/09 by M.E. Collinection on 9/13/12 by	pleted prior to  Active	inspection on 4/8/09 by No		
Current Condition:  SB B  Current Condition:	Good Condition - 23% filled Cleaned out 10/2007 by Dav M.E. Collins.  Sediment Basin Good Condition - 25% filled Cleanout and riser maintenar The East side of the basin wa	W96d00m00s  e Hausman. Erosion m  N41d00m00s  W96d00m00s  nce was completed on as sodded prior to insp  N41d00m00s  W96d00m00s  d vegetation and a bei	10/6/2007 4/1/09 by M.E. Collinection on 9/13/12 by	Active  S. Duane w/ Villa  Removed	No Noge Builders.		
SB B Current Condition:  SF A Current Condition:	Good Condition - 23% filled Cleaned out 10/2007 by Dave M.E. Collins.  Sediment Basin Good Condition - 25% filled Cleanout and riser maintenar The East side of the basin was Silt Fence Partially removed due to goo The remainder of silt fence was	W96d00m00s  e Hausman. Erosion m  N41d00m00s W96d00m00s  nce was completed on as sodded prior to insp N41d00m00s W96d00m00s d vegetation and a bereas removed prior to insp N41d00m00s	10/6/2007 4/1/09 by M.E. Collinection on 9/13/12 by	Active  S.  Duane w/ Villa  Removed	No Noge Builders.		
SB B Current Condition:	Good Condition - 23% filled Cleaned out 10/2007 by Dave M.E. Collins.  Sediment Basin Good Condition - 25% filled Cleanout and riser maintenar The East side of the basin was Silt Fence Partially removed due to goo	W96d00m00s  e Hausman. Erosion m  N41d00m00s W96d00m00s  nce was completed on as sodded prior to insp N41d00m00s W96d00m00s d vegetation and a bereas removed prior to insp N41d00m00s W96d00m00s W96d00m00s	10/6/2007  4/1/09 by M.E. Collinection on 9/13/12 by m installed. spection on 4/4/11 by	Active  S. Duane w/ Villa  Removed  Commercial S  Removed	No  ge Builders.  seeding.		

		N41d00m00s			
SF C	Silt Fence	W96d00m00s		Removed	
Current Condition:	Silt fence run was removed due to good vegetation prior to inspection on 3/24/10 by CS.				
		N41d00m00s			
SF D	Silt Fence	W96d00m00s		Removed	
Current Condition:	Silt Fence removed and diversion ditch installed in this area.				
		N41d00m00s			
STR	Street Cleaning	W96d00m00s	In Place	Active	Yes
Current Condition:	Fair Condition-No major signs of trackoff. Minor silt along the curbs near lots 2, 3, 7, 8, 16, and 81 was not				
	observed during inspection on 4/14/14.				
	There is some runoff from lot 9 as of inspection on 4/14/14.				
	Legacy Homes was requested to clean up runoff ASAP on 4/16/14. Not done as of last inspection. Legacy				
	Homes was reminded on 5/14/14, 5/28/14.				
SWPPP Sign	SWPPP Sign	Two signs on site.	8/8/2008	Active	No
Current Condition:	Good Condition				
	A SWPPP sign has been installed at 22nd & Chandler Road and 25th and Sautter Ave entrances.				
	SWPPP sign was removed from 19th Street as of inspection on 3/28/12.				
			<u> </u>	I	
Cachrany R. Gil					Zachany L. Jilek
Inspector Signature: Reviewed By:				: 0	