E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek. CPESC. CISEC

Enaineerina Answers

Zachary A. Jilek, CPESC, CISE			Engineering Answers			
Environmental Services Dept. N		- P2006.135.00	0			
Inspector: Matthew Russell				Stage		
Duningt Name	l l	Kennedy Tov	vn Center	3		
Project Name:		NER110532				
For Week Ending:	nding: 12/9/2017					
Project Location:	25th & Cha	68147				
Grading:	1009	y <u>.</u> I	T			
Sanitary Sewer:	100%					
Storm Sewer:	1009					
Paving:	1009	_				
Seeding:	1009					
Utilities:	1009					
Overall Development:	1009					
DAIN FALL AMOUNTS	Amount in touths	<u></u>				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Week		
Sunday:	0.03"			- Hock		
Monday	0.00"					
Tuesday	0.01"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00" 0.11"	_				
Saturday	0.11			Week		
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
				Week		
Sunday:	0.00"					
Monday	0.00"	11/27/17	Clear 68/32			
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"	1				
Saturday	0.00"			Maria		
Sunday:	0.00"			Week		
Monday	0.00"	1				
Tuesday	0.00"	1				
Wednesday	MM"	1				
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
				Week		
Sunday:	N/A					
Monday	N/A					
Tuesday	N/A					
Wednesday	N/A					
Thursday	N/A					

Friday	N/A				
Saturday	N/A				
		•	•	•	•
	None				
Complaints:	1				
Construction Sequencing:					
Which portion(s) (i.e. drainage basins) of the	e site have had a temporary or perm	anent cessation of gradi	ng, earthwork, or ground distu	urbance in the la	ast 14 days?
Entire Site, Grading was completed a	ind entire site was seeded Fall	2006. All active lots a	are completed as of 11/27	7/17.	
Which portion(s) (i.e. drainage basins) of the	e site do not have grading, earthwor	k, or ground disturbance	scheduled in the next 14 day	s?:	
Entire Site, Grading was completed a	ind entire site was seeded Fall	2006. All active lots a	are completed as of 11/27	7/17.	
What temporary or permanent stabilization	measures listed in this section are b	eing implemented?			-
Dense vegetation (2014). All active lo	ots are sodded (11/27/17).				
Summary Questions:					
Are approved entrances and adjacent street	s being maintained adequately?				
Yes	1				r
Are receiving waters adjacent to the project	t free of any significant signs of eros	sion or sediment that wo	uld be associated with the co	nstruction activ	ity?
Yes		1			Γ
0. 1					
Checklist Questions:					
Are waste materials (concrete, construction Yes	materiai, nazardous, etc.) being ma	naged properly?			
165		1		I	
Are waste materials (concrete, construction	material, hazardous, etc.) being ma	naged properly?			
Yes					
Comments:					
Comments:					
The site is complete. All lots are sodo	led. Future commercial lots ma	y begin construction	at a later date.		
Findings / Corrective Actions (Date	e):				
Findings / Corrective Actions (Date	e):				
1) No maintenance is required at this	time.				

	1	I	I			
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CW	Concrete Washout	TBD		Removed		
Current Condition:	Removed - Paving on site has	Removed - Paving on site has ceased as of inspection on 11/6/17.				
DD 1	Swale	East of SB A	In Place	Active	No	
Current Condition:	Good Condition-The diversion	ditch remains in pla	ce on the east side of SB	A as of inspe	ction on 1/15/15.	
Lot 4 Replat 3	Silt Fence	Lot 4 Replat 3		Removed		
Current Condition:	Removed- this area is part of the Corwin Toyota SWPPP as of 7/30/16. See Corwin Toyota SWPPP for details.					
Lot 81	Concrete Washout	Lot 81		Removed		
Current Condition:	Removed- this area is part of the Corwin Toyota SWPPP as of 7/30/16. The concrete washout has been removed.					
POD B	Silt Fence	Lots 28-44		Removed		
Current Condition:	Removed - All lots were sodde	Removed - All lots were sodded prior to inspection on 11/6/17.				
POD C	Silt Fence	Lots 10-27		Removed		
Current Condition:	Removed - Bo with 4C Construction sodded lot 24 prior to inspection on 9/26/17. All lots in this pod are sodded.					
POD D	Silt Fence	Lots 1-9		Removed		
Current Condition:	Removed- Lot 2 was sodded by 4C Construction prior to inspection on 7/13/16. All lots in the Pod are now stabilized as of 7/13/16.					
SB A	Sediment Basin	Lot 75	In Place	Active	No	
Current Condition:	Good Condition - 23% filled					
SB B	Sediment Basin	Outlot A	10/6/2007	Active	No	
Current Condition:	Good Condition - 25% filled					
STR	Street Cleaning	In Place	In Place	Active	No	
Current Condition:	Good Condition - All lots have been sodded and the streets were cleaned prior to inspection on 11/6/17.					

SWPPP Sign	SWPPP Notification Sign	One Sign	8/8/2008	Active	No		
	t Condition:  Good Condition-22nd and Chandler Rd. The SWPPP sign at 25th and Sautter Ave could not be located and will not be reinstalled as of inspection on 12/1/15.						
Inspector Signature:	Dino		Reviewed By:	Posts Si	4)		