E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC **Environmental Services Dept. Manager Engineering Answers** E&A - P2008.194.000 Inspector: Patrick Sechser Stage Kiltera Villas @ Waterford NER111205 Project Name: 2/13/2016 For Week Ending: Project Location: 144th and Ida Streets- Omaha, NE (Douglas County) 68007 Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% Seeding: 100% Utilities: 100% Overall Development: 70% RAIN FALL AMOUNTS Amount in inches Date inspected Weather Conditions Week 1 Sunday: 0.00" Monday 0.00" Tuesday 0.00" Wednesday 0.00" Thursday 0.00" 0.00" Friday Saturday 0.00" Week: Sunday: 0.00" Monday 0.00" Tuesday 0.04" 1/19/2016 Snow 19/7 Wednesday 0.00" Thursday 0.00" 0.00" Friday Saturday 0.00" Week Sunday: 0.00" Monday 0.00" Tuesday 0.00" Wednesday 0.00" Thursday 0.00" 0.00" Friday Saturday 0.00" Sunday: 0.00" Monday 0.00" Tuesday 0.38" 0.00" Wednesday Thursday 0.00" 0.00" Friday Saturday 0.00" Week 5 0.00" Sunday: Monday 0.00" Tuesday 0.00" Wednesday 0.01" Thursday 0.00" 0.00" Friday Saturday 0.00"

None

	,							
Construction Sequencing:								
Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?								
Entire Site, grading was completed prior to taking this project over on 8/28/2008.								
Entire Site; McArdle completed regarding of the I	ots 12-18 along	155th Street as of 6/20	11.					
Which portion(s) (i.e. drainage basins) of the site do not I	nave grading, earth	work, or ground disturband	e scheduled in the next 1	4 days? :				
Entire Site, grading was completed prior to taking this project over on 8/28/2008.								
Entire Site; McArdle completed regarding of the I	ots 12-18 along	155th Street as of 6/20 <sup>-</sup>	11.					
What temporary or permanent stabilization measures list	ed in this section a	re being implemented?						
Existing vegetation / Sod (8-2008), seed on S.B.' (10/5/2013).	B' (removed bas	sin) (4/09), Lots 11-18 w	as re-seeded (6/2011)	) Lots 12, 13, 14 we	ere sodded			
Summary Questions:								
Are approved entrances and adjacent streets being maint	tained adequately?							
Yes		Т		Γ				
Are receiving waters adjacent to the project free of any s	ignificant signs of	erosion or sediment that we	ould be associated with th	e construction activity	<i>i</i> ?			
Yes								
Checklist Questions:								
Are waste materials (concrete, construction material, haz	ardous, etc.) being	managed properly?						
Yes								
Is dust associated with the construction activity adequate	ely controlled on th	ne site?						
Yes								
Comments:								
Home construction is active in the development. on lots 4 and 7. Silt fence items will be transf Findings / Corrective Actions (Date):					ion from to policing			
` '								
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section	on.							
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section	_	Location	Projected Install	Status	Maintonanco			
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section  Unique Name	Туре	Location Lot 5	Projected Install Date 4/21/2015	Status Active	Maintenance Yes			
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section	Type Silt Fence	Location Lot 5 Lot was excavated prior	<b>Date</b> 4/21/2015	Active	Maintenance Yes			
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section  Unique Name  Lot 5	Type Silt Fence Fair Condition- Silt fence needs the west.	Lot 5 Lot was excavated prior to be repaired on the r es was informed to com	Date 4/21/2015 to 10/24/2015 by Lan northeast corner and e	Active dmark Homes. xtended in the north	Yes			
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section  Unique Name  Lot 5  Current Condition:	Type Silt Fence Fair Condition- Silt fence needs the west.  Landmark Hom was reminded co	Lot 5 Lot was excavated prior to be repaired on the research 12/16/15.  Lot 6	Date 4/21/2015 to 10/24/2015 by Lan northeast corner and e	Active dmark Homes. xtended in the north	Yes			
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section  Unique Name  Lot 5  Current Condition:  Lot 6  Current Condition:	Type Silt Fence Fair Condition- Silt fence needs the west.  Landmark Hom was reminded co Silt Fence Removed- Lanc	Lot 5 Lot was excavated prior to be repaired on the research 12/16/15. Lot 6 dmark Homes sodded p	Date 4/21/2015 to 10/24/2015 by Lan northeast corner and e	Active dmark Homes.  xtended in the north ot done as of last in Removed	Yes			
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section  Unique Name  Lot 5  Current Condition:  Lot 6  Current Condition:  Lot 12	Type Silt Fence Fair Condition- Silt fence needs the west.  Landmark Hom was reminded c Silt Fence Removed- Lanc Silt Fence	Lot 5 Lot was excavated prior s to be repaired on the r es was informed to com on 12/16/15.  Lot 6 dmark Homes sodded p Lot 12	Date 4/21/2015 to 10/24/2015 by Lan northeast corner and e	Active dmark Homes.  xtended in the north ot done as of last in Removed  Removed	Yes			
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section  Unique Name  Lot 5  Current Condition:  Lot 6  Current Condition:  Lot 12  Current Condition:  Lot 13	Type Silt Fence Fair Condition- Silt fence needs the west.  Landmark Hom was reminded of Silt Fence Removed- Lanc Silt Fence Removed-Land Silt Fence	Lot 5 Lot was excavated prior to be repaired on the repaired on the repaired to compon 12/16/15.  Lot 6 Imark Homes sodded p Lot 12 mark Homes sodded th Lot 13	Date 4/21/2015 to 10/24/2015 by Lan northeast corner and e	Active dmark Homes.  xtended in the north of done as of last in Removed  Removed  Removed  n on 12/15/15.  Removed	Yes			
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section  Unique Name  Lot 5  Current Condition:  Lot 6  Current Condition:  Lot 12  Current Condition:  Lot 13  Current Condition:	Type Silt Fence Fair Condition- Silt fence needs the west.  Landmark Hom was reminded c Silt Fence Removed- Land Silt Fence Removed-Land Silt Fence Removed-Land	Lot 5 Lot was excavated prior to be repaired on the repaired on the repaired to compon 12/16/15.  Lot 6 dmark Homes sodded p Lot 12 mark Homes sodded th Lot 13 mark Homes sodded th	Date 4/21/2015 to 10/24/2015 by Lan northeast corner and e supplete by 7/23/2015. No rior to 7/16/2015. e lot prior to inspection e lot prior to inspection	Active dmark Homes.  xtended in the north of done as of last in Removed  Removed  Removed  n on 12/15/15.  Removed n on 12/15/15.	Yes  hwest corner further to  hispection. Landmark			
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section  Unique Name  Lot 5  Current Condition:  Lot 12  Current Condition:  Lot 13  Current Condition:  Lot 26	Type Silt Fence Fair Condition- Silt fence needs the west.  Landmark Hom was reminded of Silt Fence Removed- Land Silt Fence Removed-Land Silt Fence Removed-Land Silt Fence	Lot 5 Lot was excavated prior s to be repaired on the repaired on the repaired on 12/16/15.  Lot 6 Imark Homes sodded p Lot 12 mark Homes sodded th Lot 13 mark Homes sodded th Lot 13 mark Homes sodded th Lot 26	Date 4/21/2015 to 10/24/2015 by Lan northeast corner and e suplete by 7/23/2015. N rior to 7/16/2015. e lot prior to inspection 12/2/2014	Active dmark Homes.  xtended in the north ot done as of last in Removed n on 12/15/15. Removed n on 12/15/15. Active	Yes  nwest corner further to  nspection. Landmark  No			
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section  Unique Name  Lot 5  Current Condition:  Lot 12  Current Condition:  Lot 13  Current Condition:  Lot 26  Current Condition:	Type Silt Fence Fair Condition- Silt fence needs the west.  Landmark Hom was reminded of Silt Fence Removed-Land Silt Fence Removed-Land Silt Fence Removed-Land Silt Fence Good Condition	Lot 5 Lot was excavated prior s to be repaired on the repaired on the repaired on the repaired to company 12/16/15.  Lot 6 Imark Homes sodded p Lot 12 mark Homes sodded th Lot 13 mark Homes sodded th Lot 26 Landmark tied SF bace	Date 4/21/2015 to 10/24/2015 by Lan northeast corner and e suplete by 7/23/2015. N rior to 7/16/2015. e lot prior to inspection 12/2/2014	Active dmark Homes.  xtended in the north ot done as of last in Removed n on 12/15/15. Removed n on 12/15/15. Active the inspection on 1	Yes  nwest corner further to  nspection. Landmark  No 0/23/2014.			
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section  Unique Name  Lot 5  Current Condition:  Lot 12  Current Condition:  Lot 13  Current Condition:  Lot 26	Type Silt Fence Fair Condition- Silt fence needs the west.  Landmark Hom was reminded of Silt Fence Removed-Land Silt Fence Removed-Land Silt Fence Removed-Land Silt Fence Good Condition Silt Fence	Lot 5 Lot was excavated prior s to be repaired on the repaired on the repaired on 12/16/15.  Lot 6 Imark Homes sodded p Lot 12 mark Homes sodded th Lot 13 mark Homes sodded th Lot 13 mark Homes sodded th Lot 26	Date 4/21/2015 to 10/24/2015 by Lan northeast corner and e applete by 7/23/2015. N  rior to 7/16/2015. e lot prior to inspection 12/2/2014 k to the posts prior to 8/4/2014	Active dmark Homes.  xtended in the north ot done as of last in Removed Removed n on 12/15/15. Removed n on 12/15/15. Active the inspection on 1 Active	Yes  nwest corner further to  nspection. Landmark  No 0/23/2014. No			
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section  Unique Name  Lot 5  Current Condition:  Lot 12  Current Condition:  Lot 13  Current Condition:  Lot 26  Current Condition:  Lot 26  Current Condition:  Lot 29	Type Silt Fence Fair Condition- Silt fence needs the west.  Landmark Hom was reminded of Silt Fence Removed-Land Silt Fence Removed-Land Silt Fence Removed-Land Silt Fence Good Condition Silt Fence Good Condition 8/4/14. Individual Lot	Lot 5 Lot was excavated prior as to be repaired on the repaired on the repaired on the repaired on 12/16/15.  Lot 6 dmark Homes sodded p Lot 12 mark Homes sodded th Lot 13 mark Homes sodded th Lot 26 I- Landmark tied SF bace Lot 29 I-SF check remains from	Date 4/21/2015 to 10/24/2015 by Lan northeast corner and e supplete by 7/23/2015. N rior to 7/16/2015. e lot prior to inspection 12/2/2014 kk to the posts prior to 8/4/2014 n construction on lot 2	Active dmark Homes.  In the north of done as of last in the Removed  Removed  Removed  Removed  Removed  Removed  n on 12/15/15.  Removed  n on 12/15/15.  Active the inspection on 1  Active 8 in the NW corner  Removed	No 0/23/2014. No as of inspection on			
Findings / Corrective Actions (Date):  1) Some required maintenance in the BMP section  Unique Name  Lot 5  Current Condition:  Lot 12  Current Condition:  Lot 13  Current Condition:  Lot 26  Current Condition:  Lot 26  Current Condition:  Lot 29  Current Condition:	Type Silt Fence Fair Condition- Silt fence needs the west.  Landmark Hom was reminded of Silt Fence Removed-Land Silt Fence Removed-Land Silt Fence Removed-Land Silt Fence Good Condition Silt Fence Good Condition Silt Fence Good Condition Silt Fence How Good Condition How	Lot 5 Lot was excavated prior is to be repaired on the repaired on the repaired on the repaired on 12/16/15.  Lot 6 dmark Homes sodded p Lot 12 mark Homes sodded th Lot 13 mark Homes sodded th Lot 26 I- Landmark tied SF back Lot 29 I-SF check remains from	Date 4/21/2015 to 10/24/2015 by Lan northeast corner and e supplete by 7/23/2015. N rior to 7/16/2015. e lot prior to inspection 12/2/2014 kk to the posts prior to 8/4/2014 n construction on lot 2	Active dmark Homes.  In the north of done as of last in the Removed  Removed  Removed  Removed  Removed  Removed  n on 12/15/15.  Removed  n on 12/15/15.  Active the inspection on 1  Active 8 in the NW corner  Removed	No 0/23/2014. No as of inspection on			

Current Condition:	Good Conditio	n- Streets have been	scraped by plows pri	or to 1/19/2016. No	signs of trackout.		
SWPPP signs	signs	1 sign	10/27/2008	Active	No		
Current Condition:	Good Condition- Installed on 10-27-08 on 156th and Potter						
Inspector Signature:			Reviewed By:	Zadrany	L. gilde		