E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept. Man	ager			Engineering Al	ISWEIS	
		E&A - P2008.19	94.000			
Inspector: Chase Wickard					Stage	
Project Name:		Kiltera Villas @ Waterford NER111205				
For Week Ending:			2/9/2019			
Project Location:		atv)	68007			
roject Location.		144th and Ida Streets- Omaha, NE (Douglas County)				
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100% 100%					
Seeding: Utilities:	100%					
Overall Development:	97%					
Overall Bovelopinent.	31 70			l l		
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions		Week	
Sunday:	0.00"				Week	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.01"					
Friday	0.00"					
Saturday	0.00"					
					Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday Wednesday	0.00" 0.00"	01/23/19	27/14 Snow			
Thursday	0.00"	01/23/19	27/14 31low			
Friday	0.00"					
Saturday	0.00"					
Saturday	0.00				Week	
Sunday:	0.00"				Week	
Monday Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
Sunday:	0.00"	ı			Week	
Sunday: Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"				\MI	
Sunday:	NA				Week	
Sunday: Monday	NA NA	 				
Tuesday	NA NA					
Wednesday	NA					
Thursday	NA					
Friday	NA					
Saturday	NA					
	Tay.					
Complaints:	None					

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site, grading was completed prior to taking this project over on 8/28/2008.

Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire Site, grading was completed prior to taking this project over on 8/28/2008.

Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation / Sod (8-2008), seed on S.B. 'B' (removed basin) (4/09), Lots 11-18 was re-seeded (6/2011) Lots 12, 13, 14 were sodded (10/5/2013).

Summary Questions:

Are approved entrances and adjacent streets being maintained adequately?

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Checklist Questions:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments

Comments:

One house is under construction at this time. Due to winter conditions, not all BMPs could be visually verified.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1. Some maintenance is required in the BMP section.
- 2. Lot 10 needs to be stabilized due to being disturbed from construction. Landmark Homes was informed to complete by 8/31/18. Not done as of the last inspection. Landmark Homes was reminded on 9/26/18, 11/9/18.

Unique Name	Type	Location	Projected Install Date	Status	Maintenanc
Lot 1 Replat 1	Silt Fence	Lot 21		Removed	
Current Condition:			the lot prior to the inspection		
Lot 2	Silt Fence	Lot 2		Removed	
Current Condition:			the lot prior to the inspection		I.
Lot 3	Silt Fence	Lot 3		Removed	
Current Condition:			the lot prior to the inspection		1
Lot 8	Silt Fence	Lot 8		Removed	
Current Condition:			the lot prior to the inspection		
Lot 9	Active Lot	Lot 9		Removed	
Current Condition:			the lot prior to the inspection		
Lot 10	Silt Fence	Lot 10	9/25/2019	Active	Yes
Current Condition:			lled silt fence on the back of		
		es was informed to conninded on 11/9/18, 1/2 4	nplete by 10/2/18. Not done a	as of the last inspec	ction. Landmark
				as of the last inspec	ction. Landmark
	Homes was ren	ninded on 11/9/18, 1/2 4	./ <mark>19.</mark>	·	
Lot 23	Homes was ren Individual Lot	ninded on 11/9/18, 1/24 Lot 23	6/20/2018	Active	Yes
Lot 23 Current Condition:	Individual Lot Fair Condition - 7/29/18. 1. The silt need 2. The silt fence 1. Landmark Ho Homes was ren 2. Landmark Ho	Lot 23 Landmark Homes instance repaired the eastern seneds extended to the comes was informed to coninded on 11/9/18, 1/24	6/20/2018 6/20/2018 alled silt fence on the eastern sidewalk. south and back of the lot. complete by 10/2/18. Not done i/19. complete by 10/2/18. Not done i/19.	Active side of the lot prior	Yes or to the inspection
	Individual Lot Fair Condition - 7/29/18. 1. The silt need 2. The silt fence 1. Landmark Ho Homes was ren 2. Landmark Ho	Lot 23 Landmark Homes instance repaired the eastern service eneeds extended to the comes was informed to conside on 11/9/18, 1/24 comes was informed to comes was informed to comes was informed to come the comes was in	6/20/2018 6/20/2018 alled silt fence on the eastern sidewalk. south and back of the lot. complete by 10/2/18. Not done i/19. complete by 10/2/18. Not done i/19.	Active side of the lot prior	Yes or to the inspection
	Individual Lot Fair Condition - 7/29/18. 1. The silt need 2. The silt fence 1. Landmark Ho Homes was ren 2. Landmark Ho	Lot 23 Landmark Homes instance repaired the eastern see needs extended to the comes was informed to conside on 11/9/18, 1/24 comes was informed to conside on 11/9/18, 1/24 comes was informed to conside on 11/9/18, 1/24	6/20/2018 6/20/2018 alled silt fence on the eastern sidewalk. south and back of the lot. complete by 10/2/18. Not done i/19. complete by 10/2/18. Not done i/19.	Active side of the lot prior	Yes or to the inspection
Current Condition:	Individual Lot Fair Condition - 7/29/18. 1. The silt need: 2. The silt fence: 1. Landmark Hot Homes was ren 2. Landmark Hot Homes was ren Streets	Lot 23 Landmark Homes instance repaired the eastern service extended to the comes was informed to conside on 11/9/18, 1/24 comes was informed to conside on 11/9/18, 1/24 N41d11m34s W96d12m23s	6/20/2018 6/20/2018 alled silt fence on the eastern sidewalk. south and back of the lot. complete by 10/2/18. Not done f/19. complete by 10/2/18. Not done f/19.	Active a side of the lot prior as as of the last inspect as of the l	Yes or to the inspection pection. Landman
Current Condition:	Individual Lot Fair Condition - 7/29/18. 1. The silt need: 2. The silt fence: 1. Landmark Hot Homes was ren 2. Landmark Hot Homes was ren Streets	Lot 23 Landmark Homes instance repaired the eastern service extended to the comes was informed to conside on 11/9/18, 1/24 comes was informed to conside on 11/9/18, 1/24 N41d11m34s W96d12m23s	6/20/2018 alled silt fence on the eastern sidewalk. south and back of the lot. complete by 10/2/18. Not done of the lot. complete by 10/2/18. Not done of the lot. somplete by 10/2/18. Not done of the lot. somplete by 10/2/18. Not done of the lot. somplete by 10/2/18. Not done of the lot.	Active a side of the lot prior as as of the last inspect as of the l	Yes or to the inspection pection. Landman
Current Condition: STR Current Condition:	Homes was ren Individual Lot Fair Condition - 7/29/18. 1. The silt need 2. The silt fence 1. Landmark Ho Homes was ren 2. Landmark Ho Homes was ren Streets Good Condition	Lot 23 Landmark Homes instance of the eastern service needs extended to the comes was informed to cominded on 11/9/18, 1/24 N41d11m34s W96d12m23s - Landmark Homes cle 1 sign	6/20/2018 alled silt fence on the eastern sidewalk. south and back of the lot. complete by 10/2/18. Not done 1/19. 8/28/2008 aned the streets prior to the i	Active as of the last inspectations Active Active nspection on 11/27	Yes or to the inspection pection. Landmar spection. Landmar

Inspector Signature:

Reviewed By: