E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Construction Sequencing:



Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager

Erosion Control Specialist- Manag				THEED CERTIFICATION	
	E&A -	P2004.045.000			
Inspector: Mike Jacobson, CISEC				Stage	
	Meridian Park			3	
Project Name:		NER110696			
For Week Ending:					
Project Location:	168th & Harri	ntv)	68136		
r rojoct zoodnom	168th & Harrison Street- Omaha, NE (Sarpy County) 68136				
Grading:	100%				
Sanitary Sewer:	90%				
Storm Sewer:	90%				
Paving:	90%				
Seeding:	100%				
Utilities:	65%				
Overall Development:	20%				
		<u> </u>			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected			
				Week 1	
Sunday:	Trace				
Monday	0.00"				
Tuesday	Trace				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.28"				
Saturday	0.00"				
				Week 2	
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"		-		
Saturday	0.15"			Week 0	
Cundou	0.00"			Week 3	
Sunday: Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"	04/02/10			
Saturday	0.00"	04/02/10			
outui duy	0.00			Week 4/5	
Sunday:	0.00"				
Monday	0.00"				
Tuesday	1.41"				
Wednesday	0.18"	04/07/10			
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
				·	
Compleinter	None				
Complaints:	-				
	+		Γ		
		1			

Entire Site, grading completed and site	e seeded Summer/Fall 2005.				
Which portion's) (i.e. drainage basins) of the	site do not have grading, earthwo	ork, or ground disturband	ce scheduled in the	next 14 days?	
Entire Site, grading completed and site	e seeded Summer/Fall 2005.				
What temporary or permanent stabilization r	neasures listed in this section are	being implemented?			
Site seeded Fall 2005 & 5/2007, stabil	ized entrances installed Sum	mer 2005, Re-Seed	5/2007 by Geis; \$	Sediment Basin E	area seeded
(9/2008); Areas around where handicate	ap ramps were installed was	re-seeded (4/2009); \$	Sediment basin E	area was re-see	eded(4/2009)
,		, ,			, ,
Comments:					

Comments:

Home construction remains active on site at this time.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) A few areas and the R.O.W. in the commercial area needs to be seeded. Developer Mike Huber was informed to seed areas by 9/3/09. Maintenance not completed as of last inspection, but due to the recent rains another seven days is given to complete maintenance until 9/10/09. Maintenance not completed as of last inspection. As of inspection on 12/7/09 seeding has not been completed and now due to frost in the ground seeding will have to take place in the spring of 2010. On 3/12/10 Developer Mike Huber was reminded that maintenance needs to be completed once seeding season begins. Maintenance not completed as of last inspection.
- 2) A few areas of lot level silt fence and gator gaurd is damaged and/or full in the home construction area and needs to be repaired. A few areas needs silt fence installed. Mert w/ Hearthstone Production was informed to complete maintenance by 4/14/10.
- 3) There are a few full dumpsters in the home construction area and they need to be emptied or covered. Mert w/ Hearthstone Production was informed to complete maintenance by 4/14/10.
- 4) There is some construction debris/trash in a few outlot areas around sediment basin F and needs to be cleaned up. Commercial Seeding was 5) A few areas of lot level silt fence is damaged in the home construction area and needs to be repaired. Mert w/ Hearthstone Production was in
- 6) Silt fence checks on the North side of Meridian Street in the commercial area is down/damaged in varies areas and needs to be repaired. Dev
- 7) Inlet filter along 167th Street just to the South of SB G is damaged and needs to be replaced. Developer Mike Huber was to complete mainter
- 8) Due to silt running onto a few sodded lots from the home construction area the sodded lots needs to be cleaned off. Mert w/ Hearthstone Production
- 9) Construction debris on empty lot 173 needs to be cleaned up. Mert w/ Hearthstone Production was informed to complete maintenance by 4/1
- 11) Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
		N41d00m00s				
CE A	Construction Entrance	W96d00m00s		Removed		
Current Condition:	Entrance Paved	Woodcomoo	1	rtomovou		
		N41d00m00s				
SB E	Sediment Basin	W96d00m00s		Removed		
Current Condition:	Basin was removed due to	Basin was removed due to lot development prior to inspection on 6/12/08 by Double D Excavating.				
		N41d00m00s				
SB F	Sediment Basin	W96d00m00s	07/01/05	Active	No	
Current Condition:	Good Condition- 20% Filled					
	Cleaned out 7/2008 by Bob Roth					
	Baffle maintenance was cor	mpleted prior to inspe	ction on 6/6/09 by	y Mike Stafford.		
		N41d00m00s				
SB G	Sediment Basin	W96d00m00s	08/26/05	Active	No	
Current Condition:	Good Condition- 18% Filled					
	-Cleaned 5/2007 by Dave Hausman & riser was repaired prior to inspection on 9/9/08.					
		N41d00m00s				
SF A	Silt Fence	W96d00m00s	07/19/05	Removed		
Current Condition:	Removed					
		N41d00m00s				
SF B	Silt Fence	W96d00m00s		Removed		
Current Condition:	Removed - Not needed due	to established veget	ative cover in are	a.		
		N41d00m00s				
SF C	Silt Fence	W96d00m00s	07/01/05	Active	No	

Current Condition:	Good Condition- Partially removed due to developed lots and good vegetation in out lots. Maintenance was completed prior to inspection on 3/9/09 by Tim Geis.					
ST A	Silt Trap	N41d00m00s W96d00m00s		Removed		
Current Condition:	Trap Closed June 2006.					
STR	Streets	N41d14m44s W96d12m59s	8/10/2007	Active	Yes	
Current Condition:	1) Some minor signs of track off in the home construction area and it needs to be cleaned up. 2) Some minor signs of run off in the commercial area in front of the bank and it needs to be cleaned up. 1) Tim Geis was informed to cleaned streets by 4/8/10. On 4/8/10 Tim Geis called inspector and stated that the streets were cleaned up. 2) Developer Mike Huber was informed to cleaned up by 4/8/10.					
SWPPP Sign	SWPPP Sign	Two signs on site	3/28/2008	Active	No	
Current Condition:	Good Condition On 3/28/08 a SWPPP sign was installed at 164th & Giles and 168th & Meridian St. entrance.					
Inspector Signature:	spector Signature:			Reviewed By:	Zadnany L. Jildk	