E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC			ENGINEERING • PLANNIN	G • FIELD SERVICES
Erosion Control Specialist- Manage				
	E&A - F	P2004.045.000		T
Inspector: Mike Jacobson, CISEC				Stage
		Meridian Park		3
Project Name:		NER110696		
For Week Ending:		10/9/2010		
Project Location:	168th & Harris	(Sarpy County)	68136	
	1	1	<u> </u>	T
Grading:	100%			
Sanitary Sewer:	90%			
Storm Sewer:	90%			
Paving:	90%			
Seeding: Utilities:	100%			
Overall Development:	20%			
Overali Developinent.	2070	'	L	
DAIN FALL AMOUNTS	Amount in tenths	But to the last		
RAIN FALL AMOUNTS	Amount in tentris	Date inspected		Wook 1
Sunday:	0.00"			Week 1
Monday	0.26"			
Tuesday	0.00"			
Wednesday	0.16"			
Thursday	Trace	09/16/10		
Friday	0.00"			
Saturday	0.79"	09/18/10		
				Week 2
Sunday:	0.03"			
Monday	0.01"	09/20/10		
Tuesday	0.12"			
Wednesday	0.00"			
Thursday	0.70"	09/23/10		
Friday	0.05"			
Saturday	0.54"	09/25/10		
	2.00"			Week 3
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"	00/00/40		
Wednesday Thursday	0.00"	09/29/10		
Friday	0.00"			
Saturday	0.00"			
- Catal day	0.00			Week 4
Sunday:	0.00"			Week 4
Monday	0.00"			
Tuesday	0.00"	10/05/10		
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
				Week 5
Sunday:	N/A	N/A		
Monday	N/A	N/A		
Tuesday	N/A	N/A		
Wednesday	N/A	N/A		
Thursday	N/A	N/A		

Friday	N/A	N/A			
Saturday	N/A	N/A			
	None				
Complaints:					
Construction Sequencing					
Which portion(s) (i.e. drainage b	pasins) of the site have had a temp	orary or permanent cessat	ion of grading, earth	work, or ground dis	sturbance in the last 14 days?
Entire Site, grading comple	ted and site seeded Summer/	Fall 2005.		_	
Which portion's) (i.e. drainage b	asins) of the site do not have grad	ing, earthwork, or ground	disturbance schedule	ed in the next 14 da	iys?
Entire Site, grading comple	ted and site seeded Summer/	Fall 2005.			
What temporary or permanent s	tabilization measures listed in this	section are being impleme	ented?	•	•
Site seeded Fall 2005 & 5/2	2007, stabilized entrances ins	talled Summer 2005, R	e-Seed 5/2007 by	/ Geis; Sediment	t Basin E area seeded
(9/2008); Areas around whe	ere handicap ramps were inst	alled was re-seeded (4	/2009); Sediment	basin E area wa	as re-seeded(4/2009)
Comments:	·		·	•	
Comments:					
Home construction remains	active on site at this time.				
On 10/5/10 inspector met o	n site with Developer Mike Hu	uber and contractor Bo	b Roth about the r	maintenance on	sediment basin G. Bob Roth
is start the maintenance by	the end of this week.				
Findings / Corrective Acti	ons (Date):				

Findings / Corrective Actions (Date):

1) Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
CE A	Construction Entrance	N41d00m00s W96d00m00s		Removed	
Current Condition:	Entrance Paved	1			
POD A	Silt Fence	Lots 37-50	5/4/2010	Active	No
Current Condition:	Good Condition- Maintenance was completed prior to inspection on 9/1/10 by Chris w/ Hearthstone Production.				
POD B	Silt Fence	Lots 63-73		Removed	
Current Condition:	Silt fence is no longer needed due to the all lots being sodded in this pod prior to inspection on 6/3/10 by Chris w/ Hearthstone Production.				
POD C	Silt Fence	Lots 97-122	5/4/2010	Active	No
Current Condition:	Good Condition- Silt fence installed on the back of a varies lots in this POD. Lot 97 silt maintenance was removed due to the lot being sodded prior to inspection on 7/12/10 by Chris w/ Hearthstone Production.				
POD D Current Condition:	Silt Fence	Lots 123-162	5/4/2010	Active	No
Current Condition:	Good Condition- Silt fence installed on the back of a varies lots in this POD.				
POD E	Silt Fence	Lots 163-199		Removed	
Current Condition:	Silt fence installed on the back of lot 175 was removed prior to inspection on 9/29/10 by Chris w/ Hearthstone Production due to the lot being sodded. All the homes in this pod have been completed.				
SB E	Sediment Basin	N41d00m00s W96d00m00s		Removed	

Current Condition:	Basin was removed due to	Basin was removed due to lot development prior to inspection on 6/12/08 by Double D Excavating.				
		N41d00m00s				
SB F	Sediment Basin	W96d00m00s	07/01/05	Active	No	
Current Condition:	Good Condition- 25% Filled Cleaned out 7/2008 by Bob Roth Baffle maintenance was completed prior to inspection on 6/6/09 by Mike Stafford.					
	0 11 15 1	N41d00m00s			.,	
SB G Current Condition:	Sediment Basin	W96d00m00s	08/26/05	Active	Yes	
	-Cleaned 5/2007 by Dave During the inspection on the therefore it does not need. Due to the baffle being fulneeded. Developer Mike Huber was inspection due to wet and maintenance until 6/13/10 conditions, therefore anothinspection maintenance is given to complete mainto wet and muddy conditions.	Fair Condition- 31% Filled -Cleaned 5/2007 by Dave Hausman & riser was repaired prior to inspection on 9/9/08. During the inspection on the basin on 10/5/10 it was determined that the riser was not undermining, therefore it does not need to be repaired. Due to the baffle being full the basin needs to be cleaned out and the baffle needs to be repaired, if needed. Developer Mike Huber was informed to start clean out by 5/28/10. Maintenance not completed as last inspection due to wet and muddy conditions, therefore another seven days is given to complete maintenance until 6/13/10. Maintenance not completed as last inspection due to wet and muddy conditions, therefore another seven days is given to complete maintenance until 6/18/10. As of last inspection maintenance not completed due to wet and muddy conditions, therefore another seven days is given to complete maintenance not completed due to wet and muddy conditions, therefore another seven days is given to complete maintenance until 6/22/10. As of last inspection maintenance until 6/25/10. As of last inspection maintenance until 6/25/10. As of last inspection maintenance until 6/25/10. As of last inspection maintenance not completed due to wet and muddy conditions, therefore				
		N41d00m00s				
SF A	Silt Fence	W96d00m00s	07/19/05	Removed		
Current Condition:	Removed	<u>, </u>		_	1	
05.5	074.5	N41d00m00s				
SF B	Silt Fence	W96d00m00s		Removed		
Current Condition:	Removed - Not needed do		etative cover in a	area.	T	
05.0	07/4 5 2 2 2 2	N41d00m00s		Demonstra		
SF C	Silt Fence	W96d00m00s		Removed		
Current Condition:	Removed - Not needed do	ue to established veg	etative cover in a	ared.		
		N41d00m00s				
ST A	Silt Trap	W96d00m00s		Removed		
Current Condition:	Trap Closed June 2006.					
		N41d14m44s				
STR	Streets	W96d12m59s	8/10/2007	Active	No	
Current Condition:	Good Condition- No majo	r signs of track off.		1		
SWPPP Sign	SWPPP Sign	Two signs on site	3/28/2008	Active	No	
Current Condition:	Good Condition	1 110 digito dil dito	5/25/2000	, 100170	140	
Carrent Condition.	On 3/28/08 a SWPPP sign	n was installed at 164	th & Giles and 1	68th & Meridian	St. entrance.	
spector Signature:	hel Jawlan			Reviewed By:	Zachany K. Jili	