E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Zachary A. Jilek, CPESC, CISEC

Erosion Control Specialist- Manager



E&A CONSULTING GROUP, INC. ENGINEERING • PLANNING • FIELD SERVICES

	E&A - F	2004.045.000		
Inspector: Mike Jacobson, CISEC				Stage
			3	
Project Name:				
For Week Ending:			69426	
Project Location:	168th & Harris	inty)	68136	
Grading:	100%			
Sanitary Sewer:	90%			
Storm Sewer:	90%			
Paving:	90%			
Seeding:	100%			
Utilities:	65%			
Overall Development:	20%			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected		Merch 4
Sunday:	0.01"			Week 1
Monday	0.01"			
Tuesday	0.00"	10/12/2010		
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
Cum dour	0.00			Week 2
Sunday: Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
Que las	0.00			Week 3
Sunday: Monday	0.00" 0.25 "			
Tuesday	0.12"			
Wednesday	Trace			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
2 malan	-			Week 4
Sunday:	Trace 0.00"			
Monday Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
				Week 5
Sunday:	0.00"			
Monday	0.00" 0.00"			
Tuesday Wednesday	Trace			
Thursday	0.06"			
Indioday	0.00	I I	1	I

Est days	4.40"	44/40/	0010		
Friday	1.49"	<mark>11/12/</mark>	2010		
Saturday	0.03"				
	None				
Complaints:					
•					
Construction Sequencing:	I	•		·	
Which portion(s) (i.e. drainage basins) of the site have had a ten	nporary or permanent c	essation of grading, ear	thwork, or ground distu	Irbance in the last 14 days?
Entire Site, grading completed a	ind site seeded Summe	er/Fall 2005.			
Which portion's) (i.e. drainage basins) of the site do not have gr	ading, earthwork, or gr	ound disturbance sched	uled in the next 14 days	\$?
Entire Site, grading completed a	ind site seeded Summe	er/Fall 2005.			
What temporary or permanent stabiliz	ation measures listed in th	nis section are being im	plemented?		· ·
Site seeded Fall 2005 & 5/2007,	, stabilized entrances ir	nstalled Summer 20	05, Re-Seed 5/2007	by Geis; Sediment E	Basin E area seeded
(9/2008); Areas around where h	andicap ramps were in	stalled was re-seed	ed (4/2009); Sedime	nt basin E area was	re-seeded(4/2009)
Comments:	ł		•	•	
Comments:					
Home construction remains activ	ve on site at this time.				
Findings / Corrective Actions	(Date):				
Findings / Corrective Actions	(Date):				
1) No maintenance is required in	· /				
1, to maintenance to required in	1 110 2111 3000011.				

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
		N41d00m00s			
CE A	Construction Entrance	W96d00m00s		Removed	
Current Condition:	Entrance Paved	· · · · · · · · · · · · · · · · · · ·			
POD A	Silt Fence	Lots 37-50	5/4/2010	Active	No
Current Condition:	Good Condition-	2010 01 00	0, 112010	7.00170	
	Maintenance was completed prior to inspection on 9/1/10 by Chris w/ Hearthstone Production				e Production.
		Lata 00.70		Damad	
POD B Current Condition:	Silt Fence	Lots 63-73	a baing aaddad iy	Removed	increation on 6/2
Current Condition.	Silt fence is no longer needed due to the all lots being sodded in this pod prior to inspect by Chris w/ Hearthstone Production.				inspection on 0/3
	by child w/ Hearthstone Fit				
POD C	Silt Fence	Lots 97-122	5/4/2010	Active	Yes
Current Condition:	Fair Condition- Silt fence installed on the back of a various lots in this POD.				
	 Silt fence is damaged on lot 97 and it needs to be repaired. Dirt piled in the R.O.W. on lot 100 and it needs to be removed or silt fence needs to be around it. Portable toilet on lot 104 and lot 111 needs to be staked down. Chris w/ Hearthstone Production was informed to complete maintenance by 11/20/10. Chris w/ Hearthstone Production was informed to complete maintenance by 11/20/10. Chris w/ Hearthstone Production was informed to complete maintenance by 11/20/10. 				eds to be installed
					1/20/10.

POD D Silt Fence Lots 123-162 5/4/2010 Active Yes **Current Condition:** Fair Condition- Silt fence installed on the back of a various lots in this POD. Silt fence is damaged on the back of lot134 and it needs to be repaired. Chris w/ Hearthstone Production was informed to complete maintenance by 11/20/10. POD E Lots 163-199 Silt Fence Removed

Current Condition:	Silt fence installed on the				
	Hearthstone Production d	ue to the lot being so	dded. All the hor	mes in this pod hav	e been comple
		N41d00m00s			
SB E	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Basin was removed due t	o lot development pric	or to inspection of	on 6/12/08 by Dou	ble D Excavati
		N41d00m00s			
SB F	Sediment Basin	W96d00m00s	07/01/05	Active	No
Current Condition:	Good Condition- 25% Fill				
	Cleaned out 7/2008 by Bo				
	Baffle maintenance was o	completed prior to insp	pection on 6/6/09	9 by Mike Stafford.	
		N41d00m00s			
SB G	Sediment Basin	W96d00m00s	08/26/05	Active	No
Current Condition:	Good Condition- 5% Fille	-			
	Partially Cleaned out and	baffle repaired prior to	o inspection on	10/12/10 by Bob R	oth.
		N41d00m00s			
SF A	Silt Fence	W96d00m00s	07/19/05	Removed	
Current Condition:	Removed				
		N41d00m00s			
SF B	Silt Fence	W96d00m00s		Removed	
Current Condition:	Removed - Not needed d		etative cover in a	area.	
		N41d00m00s			
SF C	Silt Fence	W96d00m00s		Removed	
Current Condition:	Removed - Not needed d	ue to established veg	etative cover in a	area.	
		N41d00m00s			
ST A	Silt Trap	W96d00m00s		Removed	
Current Condition:	Trap Closed June 2006.				
		N41d14m44s			
STR	Streets	W96d12m59s	8/10/2007	Active	No
Current Condition:	Good Condition- No majo	r signs of track off.		1	
SWPPP Sign	SWPPP Sign	Two signs on site	3/28/2008	Active	No
Current Condition:	Good Condition			+ ····· +	
	On 3/28/08 a SWPPP sig	n was installed at 164	th & Giles and 1	68th & Meridian S	t. entrance.
/	I P Q l			-	Z+ /
or Signature	und yourson	-		Paviawad Bur	Zachary K.
or Signature:	<i>v</i>			Reviewed By:	0