E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

| Environmental Services Dept. I | | | | |
|--------------------------------|-------------------------|-------------------------|--------------------|---------|
| | E&A | A - P2004.045.000 | | |
| Inspector: Patrick Sechser | | | | Stage |
| moposion i usion occines. | Meridian Park | | | |
| | | | | 3 |
| Project Name: | | NER110696 | | |
| For Week Ending: | | 2/13/2016 | | |
| | 40046 9 0 | | - (Samue Carrete) | 68136 |
| Project Location: | 16811 & C | Giles Street- Omaha, NE | E (Sarpy County) | 60130 |
| Cradina | 100% | · | 1 | 1 |
| Grading: Sanitary Sewer: | 100% | | | |
| Storm Sewer: | 100% | | | |
| Paving: | 100% | I . | + | |
| Seeding: | 100% | | + | |
| Utilities: | 75% | | + | + |
| Overall Development: | 68% | | + | |
| Overall Development. | 0076 | 0 | | |
| | | | | |
| RAIN FALL AMOUNTS | Amount in tenths | Date inspected | Weather Conditions | |
| | 0.00 | | | Week 1 |
| Sunday: | 0.00" | | | |
| Monday | 0.00" | | | |
| Tuesday | 0.01" | | | |
| Wednesday | 0.00" | | | |
| Thursday | 0.00" | | | |
| Friday | 0.00" | | | |
| Saturday | 0.00" | | | |
| | 2.22 | | | Week 2 |
| Sunday: | 0.00" | | | |
| Monday | 0.00" | | | |
| Tuesday | 0.05" | 1/00/00 | | |
| Wednesday | 0.00" | 1/20/201 | 6 Cloudy 25/14 | |
| Thursday | 0.00" | | | |
| Friday | 0.00" | | | |
| Saturday | 0.00" | | | W 1 |
| | 0.00# | | | Week 3 |
| Sunday: | 0.00" | | | |
| Monday | 0.00" | | | |
| Tuesday Wednesday | 0.00" | | + | |
| Thursday | 0.00" | | | |
| Thursday Friday | 0.00" | | | |
| Saturday | 0.00" | + | | |
| Jaturuay | 10.00 | | | Week 4 |
| Sunday: | 0.00" | | | vveek 4 |
| Monday | 0.01" | | + | |
| Tuesday | 0.55" | | + | |
| Wednesday | 0.02" | | + | |
| Thursday | 0.02 | | + | |
| Friday | 0.01" | | + | |
| Saturday | 0.00" | | | |
| - Catal day | 10.00 | | | Week 5 |
| Sunday: | 0.00" | | | Week |
| Monday | 0.00" | + | | |
| Tuesday | 0.00" | | + | |
| Wednesday | 0.00 | | + | |
| | 0.01" | | | |
| | 0.01" | | | |
| Thursday Friday | 0.01" 0.00" 0.00" | | | |

| | None | | | | |
|--|---------------------------------------|--|--|-----------------------|------------------------|
| Complaints: | | | | | |
| | 7 | | | | |
| | | | | | |
| Construction Sequencing: | | | | | |
| Which portion(s) (i.e. drainage basins) of the | he site have had a temporary or per | rmanent cessation of grading, | earthwork, or groun | nd disturbance in the | a last 14 days? |
| | | | | | |
| Entire Site, grading completed and s | ite seeded Summer/Fall 2005 | 5. | | | |
| | | | | | |
| Entire Site, grading was completed in | n Replat Three area Lots 1-54 | prior to inspection on 10 | /5/11 by Double I | D. | |
| | | 1 | 1 | 1 | |
| Which portion's) (i.e. drainage basins) of the | ne site do not have grading, earthw | ork, or ground disturbance so | heduled in the next | 14 days? | |
| Entire Site, grading completed and s | | | - I Carrier III Carrier II Carrie | | |
| Entire Site, grading completed and s | nie seeded Summen Fam 2003 |). | | | |
| Entire Cite anading was semulated in | n Daniet Three area Late 4 Fe | 1 maior to impropotion on 10 | IEI11 by Daubla I | D | |
| Entire Site, grading was completed in | n Replat Three area Lots 1-54 | prior to inspection on Tu | /5/11 by Double | D. | |
| | | | | | |
| What temporary or permanent stabilization | measures listed in this section are | e being implemented? | | | |
| Site seeded Fall 2005 & 5/2007, stat | bilized entrances installed Sur | mmer 2005, Re-Seed 5/20 | 007 by Geis; Sed | iment Basin E ar | ea seeded (9/2008); |
| Areas around where handicap ramps | s were installed was re-seede | d (4/2009); Sediment basi | in E area was re- | seeded(4/2009); | Replat three lots 1-54 |
| was seeded (10/2011); Replat Three | | | | , ,, | ' |
| , , , | | <u>,</u> | | 1 | |
| SUMMARY QUESTIONS: | | | | | |
| Are approved entrances and adjacent street | eta baina maintainad adagustalu? | | | | |
| Yes | ns being maintained adequatery: | | | | |
| 100 | | | | | |
| Are receiving waters adjacent to the project | t free of any significant signs of er | osion or sediment that would | be associated with | the construction act | ivity? |
| Yes | , , , | | | | |
| | | | | | |
| CHECKLIST QUESTIONS: | | | | | |
| Are waste materials (concrete, construction | n material, hazardous, etc.) being r | nanaged properly? | | | |
| Yes | | | | | |
| | | | | | |
| Is dust associated with the construction ac | tivity adequately controlled on the | site? | | | |
| Yes Comments: | | | | | |
| | | | | | |
| Comments: | 64 1 1 | 6.11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | 0 | | |
| Home construction is active in variou | | | | | |
| inspection on 1/20/2016. Rain insp | <u>.</u> | | • | | |
| the moisture being snow and due | to dangerous driving condi- | tions. Inspections will b | e conducted at | normal intervals | ì. |
| | | | | | |
| | | | | | |
| Findings / Corrective Actions (Dat | (a): | | | | |
| indings / Corrective Actions (Dat | | | | | |

Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP section.

| | | | Projected | | |
|--------------------|---|--------------------------|------------------|---------|-------------|
| Unique Name | Type | Location | Install Date | Status | Maintenance |
| CW 4 | Concrete Washout Pit | Lot 2 | | Removed | |
| Current Condition: | Removed- Washout pit was | removed prior to 11/18/2 | 015 by Celebrity | Homes. | |
| | | Lot 182 along | | | |
| Lot 182 | Silt Fence | Greenfield Street | | Removed | |
| Current Condition: | Removed- Legacy Homes sodded the lot prior to 6/12/2015. | | | | |
| | | Lot 243 along | | | |
| Lot 243 | Silt Fence | Greenfield Street | | Removed | |
| Current Condition: | Removed- Legacy Homes sodded the lot prior to 6/12/2015. | | | | |
| Lot 56 | Silt Fence | Lot 56 | 10/2/2015 | Pending | Yes |
| Current Condition: | Pending- Silt fence needs to be installed along the curb line due to the new excavation. Legacy Homes was informed to complete by 10/02/2015. Not done as of the last inspection. Legacy Homes was reminded on 10/30/2015, 12/16/2015. | | | | |
| Lots 271 | Silt Fence | 167th Street | | Removed | |
| Current Condition: | Removed- Lot has been sodded by Legacy Homes prior to 1/20/2016. | | | | |
| POD F | Silt Fence | Lots 209-217 | | Removed | |

| Current Condition: | rrent Condition: Removed- Lot 211 was sodded by Legacy Homes prior to 10/29/2015. | | | | |
|--------------------|---|---|-------------------|---------------------|----------------------------|
| | | Lots 38-51 Meridian | | | |
| POD G | Silt Fence | Park Replat Three | 4/10/2013 | Active | No |
| Current Condition: | | Homes cleaned the sideward of the sideward of the silt fences repaired the silt fences. | | | |
| | | Lots 1-37 Meridian Park | | | |
| POD H | Silt Fence | Replat Three | 10/2/2013 | Active | Yes |
| Current Condition: | Celebrity Homes. Celebrit to 12/24/2015. 1.) PP needs to be stake 2.) Silt fence on the side 1.) Celebrity Homes was | was reinstalled on the front by Homes repaired the silt fe and down on lot 1. and front of lot 6 needs to be informed to complete by be informed once snow n | o be repaired. | 3, lot 28 and exten | ded on lot 27 _l |
| SB E | Sediment Basin | Outlot "A" | 08/26/05 | Active | No |
| Current Condition: | Good Condition- 20% Fille | II. | 00/20/00 | 7.101.10 | |
| Carrone Condition. | Cood Condition 20701 in | Lot 9 Meridian | | | |
| SB G | Sediment Basin | Marketplace | 08/26/05 | Active | No |
| Current Condition: | Good Condition- 25% Fille | | | | |
| | Partially Cleaned out and baffle repaired prior to inspection on 10/12/10 by Bob Roth. | | | | |
| | | North of Replat three | | | |
| ST 1 | Sediment Trap | Lots 1 and 2 | 10/5/2011 | Active | No |
| Current Condition: | Good Condition- 23% Fille | ed | | • | |
| | | Southeast corner of | | | |
| ST 2 | Sediment Trap | Replat three lot 1 | | Removed | |
| Current Condition: | Removed- Removed by Celebrity Homes prior to 12/14/2015 for construction on lot. Will be converted to | | | | |
| | post construction feature | at a later time. | | | |
| | | Between Replat three | | | |
| ST 4 | Sediment Trap | Lots 26 and 27 | 10/5/2011 | Active | No |
| Current Condition: | Good Condition- 37% Fille | | | | |
| | | N41d14m44s | | | |
| STR | Streets | W96d12m59s | 8/10/2007 | Active | No |
| Current Condition: | <mark>1/20/2016.</mark> | have been scraped up by | Celebrity Hom | es and snow plow | vs prior to |
| SWPPP Sign | SWPPP Sign | Two signs on site | | Removed | · |
| Current Condition: | Removed- All of the SWP reasons prior to 6/16/2015 | PP signs have been remov 5. | ed, including the | one off 168th Stre | et for unknow |
| tor Signature: | The Sur | | | Reviewed By: | Zadrany K. L |