E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept.	Manager			Engineerin	g Answers
		E&A - P2004.04	5.000		
Inspector: Matthew Vanicek					Stage
		Meridi	an Park		
Project Name:			10696		3
Project Name:					
For Week Ending:			2/2020		
Project Location:		168th & Giles Street- O	maha, NE (Sarpy County)		68136
		1			
Grading:		100%			
Sanitary Sewer: Storm Sewer:		100% 100%			
Paving:		100%			
Seeding:		100%			
Utilities:		100%			
Overall Development:		91%			
	•	•	•	•	•
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	West
Sunday:	0.00"				Week 1
Monday	0.00"			1	
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week 2
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.16"				
Wednesday	0.18"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
Sunday	0.00"			1	Week 3
Sunday: Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week 4
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"			1	
Thursday	0.00"	12/10/2020	53/31 Mostly Sunny	11:00 AM	
Friday	0.39"			1	
Saturday	0.10"				Week 5
Sunday:	N/A	N/A			vveek 5
Monday	N/A N/A	N/A		+	
Tuesday	N/A	N/A			
Wednesday	N/A	N/A			
Thursday	N/A	N/A		1	
Friday	N/A	N/A			
Saturday	N/A	N/A			
	None				
Complaints:					
0					
Construction Sequencing:	North Control of the		and the second s		
Which portion(s) (i.e. drainage basins	i) or the site have had a temporary	or permanent cessation of gra	ading, eartnwork, or ground disturba	nce in the last 14 day	Sf

Entire Site, grading completed and site seeded Summer/Fall 2005. Entire Site, grading was completed in Replat Three area Lots 1-54 prior to inspection on 10/5/11 by Double D.

Which portion's) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire Site, grading completed and site seeded Summer/Fall 2005. Entire Site, grading was completed in Replat Three area Lots 1-54 prior to inspection on 10/5/11 by Double D.

What temporary or permanent stabilization measures listed in this section are being implemented?

Site seeded Fall 2005 & 5/2007, stabilized entrances installed Summer 2005, Re-Seed 5/2007 by Geis; Sediment Basin E area seeded (9/2008); Areas around where handicap ramps were installed was re-seeded (4/2009); Sediment basin E area was re-seeded(4/2009); Replat three lots 1-54 was seeded (10/2011); Replat Three lots 1-54 was re-seeded (4/2012)

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

MIC W

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments

Comments:

No construction was active during the last inspection. Inspector will continue to monitor for activity on the undeveloped portion of the site.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) No maintenance is required in the BMP section.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
CW 4	Concrete Washout Pit	Lot 2		Removed			
Current Condition:	Removed - Washout pit was removed prior to 11/18/2015 by Celebrity Homes.						
		Lot 9 Meridian					
SB G	Sediment Basin	Marketplace	08/26/05	Active	No		
Current Condition:	Good Condition - 25% Filled. The basin was partially cleaned out and the baffle was repaired by Bob Roth prior to the inspection on 10/12/10.						
		North of Replat three					
ST 1	Sediment Trap	Lots 1 and 2		Removed			
Current Condition:	Removed - Trap was converted to post construction pond prior to 4/21/2016.						
		Southeast corner of					
ST 2	Sediment Trap	Replat three lot 1		Removed			
Current Condition:	,	Removed - Removed by Celebrity Homes prior to 12/14/2015 for construction on lot. Will be converted to post construction feature at a later time.					
		Between Replat three					
ST 4	Sediment Trap	Lots 26 and 27		Removed			
	Removed - Trap was converted to post construction pond prior to 4/21/2016.						
Current Condition:	Removed - Trap was conver	ted to post construction po	nd prior to 4/21/2016.	•			
Current Condition:	Removed - Trap was conver	ted to post construction po N41d14m44s	nd prior to 4/21/2016.				
Current Condition: STR	Removed - Trap was conver Streets		nd prior to 4/21/2016. 8/10/2007	Active	No		
		N41d14m44s W96d12m59s	8/10/2007		No		
STR	Streets	N41d14m44s W96d12m59s	8/10/2007 idewalk and streets prior to		No No		
STR Current Condition:	Streets Good Condition - Celebrity H	N41d14m44s W96d12m59s lomes street cleaned the s S 168th and Meridian St.	8/10/2007 idewalk and streets prior to 5/2/2017	5/12/2016. Pending	No		

Inspector Signature: Reviewed B

Reviewed By: