E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	E&A - P2004.	045.000		
Inspector: Matthew Vanicek			Stage	
Project Name:	Meridian Park NER110696			
For Week Ending:	4/			
Project Location:	168th & Giles Street	68136		
Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
	91%			

RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	
					Week
Sunday:	2.78"				
Monday	0.11"	3/15/2021	40 Overcast	12:00 PM	-
Fuesday	0.10"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Weel
Sunday:	0.00"				
Vonday	0.34"				
Tuesday	0.83"				
Wednesday	0.00"				
Thursday	0.00"	3/25/2021	42 Overcast	9:00 AM	
Friday	0.00"				
Saturday	0.00"				
	0100				Weel
Sunday:	0.00"				- Heel
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
Saturday	0.00				Week
Sunday:	0.00"				Week
Monday	0.00"				
Tuesday	0.00				
Wednesday	0.49"				
Thursday	0.49	4/8/2021	49 Drizzle	2:15 PM	
Friday	0.21	4/8/2021	49 Drizzie	2:15 PW	
	0.00"				-
Saturday	0.00				Maal
Sunday:	N/A	N/A			Week
Sunday: Monday	N/A N/A	N/A N/A			
Monday Tuesday	N/A N/A	N/A N/A			
Wednesday	N/A N/A	N/A N/A			
wednesday Thursday	N/A N/A	N/A N/A			
Friday	N/A N/A	N/A N/A			
	N/A N/A	N/A N/A			
Saturday	N/A	N/A			
	None				
Complaints:					
Construction Sequencing:		•	•	· · ·	
and the second s	s) of the site have had a tempora				

Entire Site, grading completed and site seeded Summer/Fall 2005. Entire Site, grading was completed in Replat Three area Lots 1-54 prior to inspection on 10/5/11 by Double D.								
Which portion's) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?								
Entire Site, grading completed and site seeded Summer/Fall 2005. Entire Site, grading was completed in Replat Three area Lots 1-54 prior to inspection on 10/5/11 by Double D.								
What temporary or permanent stabilization m	neasures listed in this section are	being implemented?						
Site seeded Fall 2005 & 5/2007, stabilized entrances installed Summer 2005, Re-Seed 5/2007 by Geis; Sediment Basin E area seeded (9/2008); Areas around where handicap ramps were installed was re-seeded (4/2009); Sediment basin E area was re-seeded(4/2009); Replat three lots 1-54 was seeded (10/2011); Replat Three lots 1-54 was re-seeded (4/2012)								
	,							
Checklist Questions:								
Are receiving waters adjacent to the pro	ject free of any significant sigi	ns of erosion or sediment	that would be associated wit	th the construction	n activity?			
Yes								
Create Corrective Action?								
N/A								
Have disturbed areas been seeded or ot prevent erosion.	herwise stabilized as required	? List inactive portions of	the project and if stabilizatio	n measures are ac	lequate or needed to			
Yes								
Create Corrective Action?								
N/A								
Are waste materials (concrete, construc	tion material hazardous etc.)	being managed properly?						
Yes		being managed property.						
Create Corrective Action?								
N/A								
A								
Are construction entrances and adjacen Yes	t streets being maintained ade	equately?						
Create Corrective Action?								
N/A								
Is dust associated with the construction	activity adequately controlled	I on the site?						
Yes								
Create Corrective Action?								
N/A								
Comments:								
Comments:								
No construction was active during the la	ast inspection. Inspector will co	ontinue to monitor for activ	vity on the undeveloped port	ion of the site.				
Findings / Corrective Actions (Date):								
Findings / Corrective Actions (Date): 1.) No maintenance is required in the B								
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CW 4	Concrete Washout Pit	Lot 2		Removed				
Current Condition:	Removed - Washout pit was	removed prior to 11/18/20	15 by Celebrity Homes.					
		Lot 9 Meridian						
SB G	Sediment Basin	Marketplace	08/26/05	Active	No			
Current Condition:	Good Condition - 25% Filled.	The basin was partially cl	eaned out and the baffle wa	s repaired by Bob	Roth prior to the			
	inspection on 10/12/10.							
		North of Replat three						
ST 1	Sediment Trap	Lots 1 and 2		Removed				
Current Condition:	Removed - Trap was convert		nd prior to 4/21/2016.					
27.0	o "	Southeast corner of						
ST 2	Sediment Trap	Replat three lot 1	1/00155	Removed				
Current Condition:	Removed - Removed by Cele construction feature at a later	time.	4/2015 for construction on ic	ot. vvili de convert	ed to post			
ST 4	Sediment Trap	Between Replat three Lots 26 and 27		Removed				
Current Condition:	Removed - Trap was convert		nd prior to 4/21/2016.	I				
OTD	04	N41d14m44s	0/40/0007	A -41	N1-			
STR	Streets	W96d12m59s	8/10/2007	Active	No			
Current Condition: SWPPP Sign	Good Condition - Celebrity H SWPPP Sign	omes street cleaned the s S 165th and Giles	idewalk and streets prior to 5/2/2017	5/12/2016. Active	No			
Current Condition:	Good Condition - The E&A in							
	3/4/21.							
-n.					Costo Sul			
Inspector Signature:	to Vann			Reviewed By:	and bre			