E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



chary A Jilok CPESC CISEC

Environmental Services Dept.	EC Manager		En	gineering Answei	S
Inanastari Priva Wright		E&A - P2021.32	21.000		Stage
Inspector: Bryce Wright		Morgan Ridge CSW-202207264  10/12/2024 Southwest corner of Kempten Creek Drive and 156th Street - Bennington, NE (Douglas County)			
Project Name: For Week Ending:					
Project Location:	Southwest corner of				
Trojout Location.		300			
Grading:		5%			
Sanitary Sewer:		0%			
Storm Sewer:		<mark>0%</mark>			
Paving:		0%			
Seeding:	5	0%			
Utilities:		0%			
Overall Development:		5%			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
Sundayı	0.00"				Week
Sunday:	0.00"				
Monday	0.00"	40/0/2224	0	4:50 511	
Tuesday	0.00"	10/8/2024	Sunny 75	1:50 PM	
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
Complaints:  Construction Sequencing:					
Which portion(s) (i.e. drainage 14 days?		a temporary or permane	ent cessation of grading,	earthwork, or ground	disturbance in the last
Grading the site (4/20/23). Sanit	, , ,				4.40
	e basins) of the site do not have	e grading, earthwork, o	or ground disturbance sci	neaulea in the next 1	4 days?
Grading the site (4/20/23). Sanit What temporary or permanent		! 4l.!4! l!.			
Existing vegetation (4/20/23). No					
		,	(0/11/20).		
Checklist Questions:					
Are receiving waters adjacent to the p Yes	roject free of any significant signs of e	rosion or sediment that woul	d be associated with the constru	ction activity?	
100					
Create Corrective Action?					
Create Corrective Action?					
Create Corrective Action?					
Create Corrective Action? N/A Have disturbed areas been seeded or	otherwise stabilized as required? List	inactive portions of the projec	ct and if stabilization measure ar	e adequate or needed to p	revent erosion.
Create Corrective Action? N/A	otherwise stabilized as required? List	inactive portions of the projec	ct and if stabilization measure an	e adequate or needed to p	revent erosion.
Create Corrective Action? N/A  Have disturbed areas been seeded or Yes Create Corrective Action?	otherwise stabilized as required? List	inactive portions of the projec	ct and if stabilization measure an	e adequate or needed to p	revent erosion.
Create Corrective Action? N/A  Have disturbed areas been seeded or Yes Create Corrective Action? N/A			ct and if stabilization measure an	e adequate or needed to p	revent erosion.
Create Corrective Action? N/A  Have disturbed areas been seeded or Yes Create Corrective Action? N/A	otherwise stabilized as required? List uction material, hazardous, etc.) being		ct and if stabilization measure an	e adequate or needed to p	revent erosion.
Create Corrective Action? N/A  Have disturbed areas been seeded or Yes Create Corrective Action? N/A  Are waste materials (concrete, constri			ct and if stabilization measure an	e adequate or needed to p	revent erosion.
Create Corrective Action? N/A  Have disturbed areas been seeded or Yes Create Corrective Action? N/A  Are waste materials (concrete, construyes			ct and if stabilization measure an	e adequate or needed to p	revent erosion.
Create Corrective Action? N/A  Have disturbed areas been seeded or Yes Create Corrective Action? N/A  Are waste materials (concrete, constri Yes Create Corrective Action? N/A		managed properly?	ct and if stabilization measure an	e adequate or needed to p	revent erosion.
Create Corrective Action? N/A  Have disturbed areas been seeded or Yes Create Corrective Action? N/A  Are waste materials (concrete, construyes Create Corrective Action? N/A  Are construction entrances and adjace No	uction material, hazardous, etc.) being	managed properly?	ct and if stabilization measure an	e adequate or needed to p	revent erosion.
Create Corrective Action? N/A  Have disturbed areas been seeded or Yes Create Corrective Action? N/A  Are waste materials (concrete, construy Yes Create Corrective Action? N/A  Are construction entrances and adjace No Create Corrective Action?	uction material, hazardous, etc.) being	managed properly?	ct and if stabilization measure an	e adequate or needed to p	revent erosion.
Create Corrective Action? N/A  Have disturbed areas been seeded or Yes Create Corrective Action? N/A  Are waste materials (concrete, construyes Create Corrective Action? N/A  Are construction entrances and adjace No	uction material, hazardous, etc.) being	managed properly?	ct and if stabilization measure an	e adequate or needed to p	revent erosion.
Create Corrective Action? N/A  Have disturbed areas been seeded or Yes Create Corrective Action? N/A  Are waste materials (concrete, constrictly const	uction material, hazardous, etc.) being	managed properly?	ct and if stabilization measure an	e adequate or needed to p	revent erosion.
Create Corrective Action?  N/A  Have disturbed areas been seeded or Yes  Create Corrective Action?  N/A  Are waste materials (concrete, construyes  Create Corrective Action?  N/A  Are construction entrances and adjace No  Create Corrective Action?  No, See BMP section.	uction material, hazardous, etc.) being	managed properly?	ct and if stabilization measure an	e adequate or needed to p	revent erosion.
Create Corrective Action?  N/A  Have disturbed areas been seeded or Yes  Create Corrective Action?  N/A  Are waste materials (concrete, construyes  Create Corrective Action?  N/A  Are construction entrances and adjace No  Create Corrective Action?  No, See BMP section.	uction material, hazardous, etc.) being	managed properly?	ct and if stabilization measure an	e adequate or needed to p	revent erosion.

Comments:
Comments:
The site was active during the most recent inspection.

Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
Some maintenance is needed in the BMP section.

CE 4	Туре	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	00-23	4/20/2023	Active	Yes	
Current Condition:	Fair Condition - 10% Effective - Ruff Grading installed the construction entrance prior to the 6/15/23 inspection. Ruff Gradinal added more rock to the construction entrance prior to the 8/17/23 inspection. Construction entrance was moved to the Benjamin Street stub road prior to the inspection on 8/20/24.					
	Construction entrance should have more rock added and be lengthened.					
	Ruff Grading and Hubbell Hubbell Homes were reminded on 8/22/24, 10/2/2	ded on 10/19/23, 11/10/				
D 1	Diversion	BB-4	6/29/2023	Active	No	
Current Condition:	Good Condition - Ruff Gradi	ng installed the diversio	n prior to the 6/29/23 inspec	ction.	•	
D 2	Diversion	R-5 to Z-4	7/27/2023	Active	Yes	
Current Condition:	inspection on 7/23/24.  Erosion rills should be repai	Fair Condition - Ruff Grading installed the diversion prior to the 7/27/23 inspection. Roloff repaired the diversion prior to the				
	Ruff Grading and Hubbell Hoto complete by 6/20/24. Hub reminded on 8/22/24, 10/2/2	bell Homes and Ruff wa				
D 3	Diversion	R-5 to S-4		Removed		
Current Condition:	Removed - Diversion no Ion	ger needed as of the 11	/16/23 inspection.			
D 4	Diversion	I-9 to R-3	8/10/2023	Active	Yes	
Current Condition:	Fair Condition - Ruff Grading	g installed the diversion	prior to the 8/10/23 inspect	on. Ruff Grading re	e-defined the diversion	
	Ruff Grading and Hubbell Hubbell Homes were reminded on 7/17/24. Hubbell Hubbe	ded on 5/24/24. Roloff w	as informed to complete by	6/20/24. Hubbell H		
D 5	Diversion	I-8 to E-8		Removed		
Current Condition:	Removed - Ruff Grading rer recommended.	noved the diversion dur	ing grading of Phase II prior	to the 9/17/24 insp	pection. Reinstallation	
D 6	Diversion	C-8 to D-8		Removed		
Current Condition:	Removed - Ruff Grading rer recommended.	noved the diversion dur	ing grading of Phase II prior	to the 9/17/24 insp	pection. Reinstallation	
	Di	BB-11 to BB-12	9/21/2023	Active		
D 7	Diversion	<u> </u>			Yes	
D 7 Current Condition:	Fair Condition - Ruff Grading Diversion should be re-defin Ruff Grading and Hubbell H Hubbell Homes were remind reminded on 8/22/24, 10/2/2	g installed the diversion led. omes were informed to ded on 11/10/23, 3/15/2	prior to the 9/21/23 inspection	done as of last insp	pection. Ruff Grading a	
	Fair Condition - Ruff Grading Diversion should be re-defin Ruff Grading and Hubbell H Hubbell Homes were remind	g installed the diversion led. omes were informed to ded on 11/10/23, 3/15/2	prior to the 9/21/23 inspection	done as of last insp	pection. Ruff Grading a	
Current Condition:	Fair Condition - Ruff Grading Diversion should be re-defin Ruff Grading and Hubbell H Hubbell Homes were reminded on 8/22/24, 10/2/2	g installed the diversion ned. omes were informed to ded on 11/10/23, 3/15/2- 4 BB-18 to BB-20	complete by 10/26/23. Not of 4, 5/24/24, 6/13/24, 7/17/24	done as of last insp Hubbell Homes a Active	pection. Ruff Grading a nd K2 Construction wa	
Current Condition:	Fair Condition - Ruff Grading Diversion should be re-defin Ruff Grading and Hubbell H Hubbell Homes were remind reminded on 8/22/24, 10/2/2 Diversion Good Condition - Ruff Gradin	g installed the diversion need.  omes were informed to ded on 11/10/23, 3/15/24  BB-18 to BB-20 ng installed the diversion NN-23	prior to the 9/21/23 inspection of the 9/21/23 inspection of the 9/21/24. Not of 4, 5/24/24, 6/13/24, 7/17/24  9/21/2023  n prior to the 9/21/23 inspection of the 9/21/2024	done as of last insp . Hubbell Homes a Active ction. Active	pection. Ruff Grading a nd K2 Construction wa	
Current Condition:  D 8  Current Condition:	Fair Condition - Ruff Grading Diversion should be re-defin Ruff Grading and Hubbell H Hubbell Homes were remind reminded on 8/22/24, 10/2/2 Diversion Good Condition - Ruff Grading	g installed the diversion need.  omes were informed to ded on 11/10/23, 3/15/24  BB-18 to BB-20 ng installed the diversion NN-23	prior to the 9/21/23 inspection of the 9/21/23 inspection of the 9/21/24. Not of 4, 5/24/24, 6/13/24, 7/17/24  9/21/2023  n prior to the 9/21/23 inspection of the 9/21/2024	done as of last insp . Hubbell Homes a Active ction. Active	pection. Ruff Grading a nd K2 Construction wa	
D 8 Current Condition:  D 9 Current Condition: D 9 Current Condition:	Fair Condition - Ruff Grading Diversion should be re-defin Ruff Grading and Hubbell H Hubbell Homes were remind reminded on 8/22/24, 10/2/2 Diversion Good Condition - Ruff Gradi Diversion Good Condition - Ruff Gradi Diversion Good Condition - Ruff Gradi	g installed the diversion led.  led.	prior to the 9/21/23 inspection of the 9/21/23 inspection of the 9/21/23. Not of 4, 5/24/24, 6/13/24, 7/17/24  9/21/2023  n prior to the 9/21/23 inspection of the 9/21/2024  n prior to the 4/25/24 inspection of the 4/25/24	Active ction.  Removed	oection. Ruff Grading a nd K2 Construction wa No	
D 8 Current Condition:  D 9 Current Condition:	Fair Condition - Ruff Grading Diversion should be re-defin Ruff Grading and Hubbell H Hubbell Homes were remind reminded on 8/22/24, 10/2/2 Diversion Good Condition - Ruff Gradi Diversion Good Condition - Ruff Gradi	g installed the diversion led.  led.	prior to the 9/21/23 inspection of the 9/21/23 inspection of the 9/21/23. Not of 4, 5/24/24, 6/13/24, 7/17/24  9/21/2023  n prior to the 9/21/23 inspection of the 9/21/2024  n prior to the 4/25/24 inspection of the 4/25/24	Active ction.  Removed	oection. Ruff Grading a nd K2 Construction wa No	
D 8 Current Condition:  D 9 Current Condition: D 9 Current Condition:	Fair Condition - Ruff Grading Diversion should be re-defin Ruff Grading and Hubbell H Hubbell Homes were remind reminded on 8/22/24, 10/2/2 Diversion Good Condition - Ruff Gradi Diversion Good Condition - Ruff Gradi Diversion Removed - Ruff Grading rer	g installed the diversion led.  led.	prior to the 9/21/23 inspect complete by 10/26/23. Not of 4, 5/24/24, 6/13/24, 7/17/24 9/21/2023 In prior to the 9/21/23 inspect 4/25/2024 In prior to the 4/25/24 inspect ing grading of Phase II prior	Active etion.  Removed to the 4/25/24 inspectors.	No No Rection. Ruff Grading a nd K2 Construction was No No Rection. Reinstallation	
D 8 Current Condition:  D 9 Current Condition: D 10 Current Condition: D 11	Fair Condition - Ruff Grading Diversion should be re-defin Ruff Grading and Hubbell H Hubbell Homes were remind reminded on 8/22/24, 10/2/2 Diversion Good Condition - Ruff Gradi Diversion Good Condition - Ruff Gradi Diversion Removed - Ruff Grading rer recommended. Diversion Removed - Ruff Grading rer Removed - Ruff Grading rer	g installed the diversion led.  led.	prior to the 9/21/23 inspect complete by 10/26/23. Not of 4, 5/24/24, 6/13/24, 7/17/24 9/21/2023 In prior to the 9/21/23 inspect 4/25/2024 In prior to the 4/25/24 inspect ing grading of Phase II prior	Active etion.  Removed to the 4/25/24 inspectors.	No No Rection. Ruff Grading a nd K2 Construction was No No Rection. Reinstallation	
D 8 Current Condition:  D 9 Current Condition:  D 10 Current Condition:  D 11 Current Condition:	Fair Condition - Ruff Grading Diversion should be re-defir Ruff Grading and Hubbell H Hubbell Homes were remine reminded on 8/22/24, 10/2/2 Diversion Good Condition - Ruff Gradi Diversion Good Condition - Ruff Gradi Diversion Removed - Ruff Grading rer recommended. Diversion Removed - Ruff Grading rer recommended.	g installed the diversion need.  omes were informed to ded on 11/10/23, 3/15/2-24  BB-18 to BB-20 ng installed the diversion NN-23 ng installed the diversion AA-33 noved the diversion dur  G-13 to H-13 noved the diversion dur  K-14 to H-14	complete by 10/26/23. Not of 1, 5/24/24, 6/13/24, 7/17/24  9/21/2023 n prior to the 9/21/23 inspect 4/25/2024 n prior to the 4/25/24 inspecting grading of Phase II prior ing grading of Phase II prior	Active etion.  Removed to the 9/17/24 inspectors.	No No No Dection. Reinstallation	
D 8 Current Condition:  D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 11 Current Condition:	Fair Condition - Ruff Grading Diversion should be re-define Ruff Grading and Hubbell H Hubbell Homes were remind reminded on 8/22/24, 10/2/2 Diversion Good Condition - Ruff Gradin Diversion Good Condition - Ruff Gradin Diversion Removed - Ruff Grading rer recommended. Diversion Removed - Ruff Grading rer recommended. Diversion Removed - Ruff Grading rer recommended. Diversion Removed - Ruff Grading rer Removed - Ruff Grading rer Removed - Ruff Grading rer	g installed the diversion need.  omes were informed to ded on 11/10/23, 3/15/2-24  BB-18 to BB-20 ng installed the diversion NN-23 ng installed the diversion AA-33 noved the diversion dur  G-13 to H-13 noved the diversion dur  K-14 to H-14	complete by 10/26/23. Not of 1, 5/24/24, 6/13/24, 7/17/24  9/21/2023 n prior to the 9/21/23 inspect 4/25/2024 n prior to the 4/25/24 inspecting grading of Phase II prior ing grading of Phase II prior	Active etion.  Removed to the 9/17/24 inspectors.	No No No Dection. Reinstallation	
D 8 Current Condition:  D 9 Current Condition:  D 10 Current Condition:  D 11 Current Condition:  D 12 Current Condition:	Fair Condition - Ruff Grading Diversion should be re-defir Ruff Grading and Hubbell H Hubbell Homes were remine reminded on 8/22/24, 10/2/2 Diversion Good Condition - Ruff Gradin Diversion Good Condition - Ruff Gradin Diversion Removed - Ruff Grading rer recommended. Removed - Ruff Grading rer recommended.	g installed the diversion need.  Deed.  Deed.  Deed on 11/10/23, 3/15/2-24  BB-18 to BB-20 Ing installed the diversion NN-23 Ing installed the diversion AA-33 Individual of the diversion dure the diversi	prior to the 9/21/23 inspection of the 9/21/23 inspection of the 9/21/24. Not of 4, 5/24/24, 6/13/24, 7/17/24 and 9/21/2023 inspection of the 9/21/23 inspection of the 9/21/23 inspection of the 4/25/2024 inspection of the 4/25/24 inspection of the 4/25/2024 inspection of the 4/25/24 inspection of the 4/	Active Stion.  Active Stion.  Removed to the 9/17/24 inspector of the 9	No No No No Reinstallation Dection. Reinstallation	
D 8 Current Condition:  D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12 Current Condition:	Fair Condition - Ruff Grading Diversion should be re-define Ruff Grading and Hubbell H Hubbell Homes were remind reminded on 8/22/24, 10/2/2 Diversion Good Condition - Ruff Gradin Diversion Good Condition - Ruff Gradin Diversion Removed - Ruff Grading rer recommended. Erosion Matting	g installed the diversion need.  Deed.  Deed.  Deed on 11/10/23, 3/15/2-24  BB-18 to BB-20 Ing installed the diversion NN-23 Ing installed the diversion AA-33 Individual of the diversion dure the diversi	prior to the 9/21/23 inspection of the 9/21/23 inspection of the 9/21/24. Not of 4, 5/24/24, 6/13/24, 7/17/24 and 9/21/2023 inspection of the 9/21/23 inspection of the 9/21/23 inspection of the 4/25/2024 inspection of the 4/25/24 inspection of the 4/25/2024 inspection of the 4/25/24 inspection of the 4/	Active Stion.  Active Stion.  Removed to the 9/17/24 inspector of the 9	No No No No Reinstallation Dection. Reinstallation	
D 8 Current Condition:  D 9 Current Condition: D 10 Current Condition:  D 11 Current Condition:  D 12 Current Condition:  EM 1 Current Condition:	Fair Condition - Ruff Grading Diversion should be re-define Ruff Grading and Hubbell H Hubbell Homes were remind reminded on 8/22/24, 10/2/2 Diversion Good Condition - Ruff Gradin Diversion Good Condition - Ruff Gradin Diversion Removed - Ruff Grading rer recommended. Erosion Matting Pending - BMP will be instal	g installed the diversion led.  led.  led.  led.  led.  led.  led.  led on 11/10/23, 3/15/2-24  BB-18 to BB-20  Ing installed the diversion led	prior to the 9/21/23 inspect complete by 10/26/23. Not of 4, 5/24/24, 6/13/24, 7/17/24  9/21/2023 n prior to the 9/21/23 inspect 4/25/2024 n prior to the 4/25/24 inspect ing grading of Phase II prior  grading of Phase II prior  4/20/2023 nds in the area. E&A inspect 4/20/2023	Active etion.  Removed to the 9/17/24 inspector will monitor.  Pending etor will monitor.  Pending	No No No No No Reinstallation Dection. Reinstallation No	
D 8 Current Condition:  D 8 Current Condition: D 9 Current Condition: D 10 Current Condition:  D 11 Current Condition:  D 12 Current Condition:  EM 1 Current Condition: EM 2	Fair Condition - Ruff Grading Diversion should be re-define Ruff Grading and Hubbell H Hubbell Homes were remine reminded on 8/22/24, 10/2/2 Diversion Good Condition - Ruff Grading Diversion Good Condition - Ruff Grading Diversion Removed - Ruff Grading rer recommended. Erosion Matting Pending - BMP will be install	g installed the diversion led.  led.  led.  led.  led.  led.  led.  led on 11/10/23, 3/15/2-24  BB-18 to BB-20  Ing installed the diversion led	prior to the 9/21/23 inspect complete by 10/26/23. Not of 4, 5/24/24, 6/13/24, 7/17/24  9/21/2023 n prior to the 9/21/23 inspect 4/25/2024 n prior to the 4/25/24 inspect ing grading of Phase II prior  grading of Phase II prior  4/20/2023 nds in the area. E&A inspect 4/20/2023	Active etion.  Removed to the 9/17/24 inspector will monitor.  Pending etor will monitor.  Pending	No No No No No Reinstallation Dection. Reinstallation No	
D 8 Current Condition:  D 8 Current Condition:  D 9 Current Condition:  D 10 Current Condition:  D 11 Current Condition:  D 12 Current Condition:  EM 1 Current Condition:  EM 2 Current Condition:	Fair Condition - Ruff Grading Diversion should be re-define Ruff Grading and Hubbell H Hubbell Homes were remind reminded on 8/22/24, 10/2/2 Diversion Good Condition - Ruff Grading Diversion Good Condition - Ruff Grading Diversion Removed - Ruff Grading rer recommended. Erosion Matting Pending - BMP will be install Erosion Matting	g installed the diversion led.  led.	prior to the 9/21/23 inspect complete by 10/26/23. Not of 4, 5/24/24, 6/13/24, 7/17/24  9/21/2023 n prior to the 9/21/23 inspect 4/25/2024 n prior to the 4/25/24 inspect ing grading of Phase II prior grading of Phase II prior  4/20/2023 nds in the area. E&A inspect 4/20/2023 nds in the area. E&A inspect	Active  Active  ction.  Removed to the 9/17/24 insp	No No No Dection. Reinstallation No	

Current Condition:	Pending - BMP will be installe	d when work begins/er	nds in the area. E&A inspe	ctor will monitor.		
EM 5	Erosion Matting	See SWPPP	6/13/2024	Pending	Yes	
Current Condition:	Pending -					
	Facility of cold by accepted on		to a charalal background and	urad OD A		
	Erosion should be repaired an	id erosion control matt	ing should be installed arou	und SB A.		
	Roloff was informed to comple	ete by 6/20/24. Not dor	ne as of last inspection. Ru	ff and Hubbell Hom	es was reminded on	
	7/17/24, 10/2/24	,				
EM 6	Erosion Matting	See SWPPP	6/13/2024	Pending	Yes	
Current Condition:	Pending -					
	Erosion should be repaired an	d erosion control matt	ing should be installed arou	und SB B.		
	Roloff was informed to comple	ate by 6/20/24. Not don	ne as of last inspection. Pur	ff and Hubbell Hom	es was reminded on	
	7/17/24, 10/2/24	ste by 0/20/24. Not do	ie as of last mapection. Ru	ii and Hubbell Holli	es was reminded on	
ET 1	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No	
Current Condition:	Good Condition - Ruff Grading				140	
ET 2	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No	
Current Condition:	Good Condition - Ruff Grading					
ET 3	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No	
Current Condition:	Good Condition - Ruff Grading			9/21/23 inspection.		
ET 4	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No	
Current Condition:	Good Condition - Ruff Grading	installed the erosion	control terrace prior to the			
ET 5	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No	
Current Condition:	Good Condition - Ruff Grading	installed the erosion	control terrace prior to the	9/21/23 inspection.		
ET 6	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be installe	d when grading begins	ends in the area. E&A ins	pector will monitor.		
ET 7	Erosion Control Terrace	See SWPPP		Removed		
Current Condition:	Removed - Ruff Grading remo		ol terrace during grading of	Phase II prior to the	e 4/25/24 inspection.	
	Reinstallation not recommend	ed.				
ET 8	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No	
Current Condition:	Good Condition - Ruff Grading	installed the erosion	control terrace prior to the	9/21/23 inspection.		
ET 9	Erosion Control Terrace	See SWPPP		Removed		
Current Condition:	Removed - Ruff Grading remo		ol terrace during grading of	Phase II prior to the	e 9/17/24 inspection.	
	Reinstallation not recommend	ea.				
FT 1	Fuel Tank	On site	8/27/2024	Active	No	
Current Condition:	Good Condition - K2 Construc	tion installed a double	· ·	or to the inspection	on 8/27/24.	
PB 1	Portable toilet	On site	8/20/2024	Active	No	
Current Condition:	Good Condition - K2 Construct		e toilet on site prior to the i	nspection on 8/20/2	24. K2 Construction secured	
	the portable toilet prior to the i	·				
RN 4	Erosion Control Matting	West of SB A	4/18/2024	Pending	No	
Current Condition:	Pending - Erosion Control Ma			i e		
RN 6	Erosion Control Matting	West of SB B	4/18/2024	Pending	No	
Current Condition:	Pending - Erosion Control Ma				.,	
SB A	Sediment Basin Fair Condition - 65% Filled - R	AA-4	4/20/2023	Pending	Yes	
Current Condition:						
	process of installing the riser and outflow pipe during the 11/2/23 inspection. Ruff Grading installed the riser and outflow pipe prior to the 11/16/23 inspection.					
	1.) Basin should be installed per SWPPP (Baffle, de-watering holes on riser).					
	2.) Basin should be cleaned out.					
	3.) Erosion below the outfall should be repaired.					
	1.) Ruff Grading was informed to complete by 5/25/23. Not done as of the last inspection. Ruff Grading was reminded on					
	6/1/23, 7/14/23, 8/4/23, 8/10/23, 10/15/23, 10/19/23, 11/10/23					
	2.) Contractor will be hired to clean the basin out in the Spring. E&A will evaluate contractor and inform them to complete					
	ASAP as of 6/7/2024.					
	3.) Contractor will be hired to	complete this maintena	ance once approved by the	SID. Not done as	of the last inspection.	
SB B	Sediment Basin	R-4	4/20/2023	Active	Yes	
Current Condition:	Fair Condition - 65% Filled - F					
	riser and outflow pipe prior to	the 11/2/23 inspection			· ·	
	1.) Basin should be installed p					
	2.) Basin should be cleaned o	ut.				
	1.) Ruff Grading was informed	to complete by 5/25/2	3 Not done as of the last i	nspection Ruff Gra	ading was reminded on	
	6/1/23, 7/14/23, 8/4/23, 8/10/2			noposion. Nun Gla	iding was reminded on	
	2.) Contractor will be hired to			te contractor and in	form them to complete	
	ASAP as of 6/7/2024.					
SB C	Sediment Basin	D-8		Removed		
Current Condition:	Removed - Ruff Grading remo	oved the basin during g	rading for Morgan Ridge 2	prior to the inspect	tion on 9/3/24.	
SB D	Sediment Basin	HH-32 to NN-29	4/20/2023	Active	Yes	
-	_ ·		•	•		

Current Condition:	Fair Condition - 70% filled - Ruff Grading began excavation on the basin prior to the 12/21/23 inspection. Ruff Grading installed the riser prior to the inspection on 7/23/24.					
	<ol> <li>Baffle should be installed per SWPPP.</li> <li>Basin should be cleaned out.</li> <li>Ruff Grading and Hubbell Homes were informed to complete by 11/16/23. Not done as of last inspection. Ruff Grading Hubbell Homes were reminded on 3/15/24, 5/24/24, 6/13/24, 7/17/24</li> </ol>					
SF 1 Current Condition:	Silt Fence Fair Condition - Ruff Grading	Western Perimeter	e silt fence was installed o	Active	Yes	
	inspection. Ruff Grading instance prior to the 8/31/23 instance prior to the 8/31/23 instance prior to the 8/31/23 instance prior to the 8/31/24 instance prior to the stance prior to the 8/31/23 instance prior to the stance prior to the	spection. A portion of the the west prior to the 11/l out and repaired.  so complete by 10/12/23. 20/23, 3/15/24, 5/24/24, 6/	e silt fence was removed fo 23/23 inspection. Re-instal Not done as of last inspec	r grading activity by llation not recommon stion. Ruff Grading	y Pruss Excavation for t ended. and Hubbell Homes we	
	Terrifficed off 6/22/24, 10/2/2	.4				
		Southeastern				
SF 2	Silt Fence	Perimeter		Removed		
Current Condition:	Removed - Ruff Grading ren recommended.		ng grading of Phase II prior	to the 4/25/24 insp	pection. Reinstallation r	
SF 3	Silt Fence	Southeastern		Removed		
Current Condition:	Removed - Ruff Grading ren	Perimeter noved the silt fence during	l ng grading of Phase II prior		L pection. Reinstallation n	
	recommended.		33 3 1	,		
SF 4	Silt Fence	Eastern Perimeter		Removed		
Current Condition:	Removed - Ruff Grading ren recommended.		ng grading of Phase II prior	to the 4/25/24 insp	pection. Reinstallation n	
SF 5	Silt Fence	Northeastern Perimeter		Removed		
Current Condition:	Removed - Ruff Grading ren recommended.		ng grading of Phase II prior		pection. Reinstallation n	
SF 6	Silt Fence	Northern Perimeter	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be instal		e/ends in the area. E&A ins	pector will monitor.		
SF 7	Silt Fence	Northeastern Perimeter	8/31/2023	Active	No	
Current Condition:	Silt Fence   Perimeter   State   Active   No Good Condition - Ruff Grading installed silt fence prior to the 8/31/23 inspection. Ruff Grading and Hubbell Homes repaire the silt fence and added an additional row of silt fence prior to the 10/10/23 inspection. Ruff Grading cleaned out and repaire the silt fence prior to the inspection on 10/1/24.					
ST A	Sediment Trap	H-13		Removed		
Current Condition:	Removed - Ruff Grading ren				on on 9/3/24.	
MS 1	Material Storage	On Site	4/20/2023	Pending	No	
Current Condition: WO 1	Pending - Materials will be s Concrete Washout	tored in designated area On Site	is. 4/20/2023	Pending	No	
Current Condition:	Pending - Concrete will be p		17-07-0-0			
WS 1	Waste Storage	On Site	4/20/2023	Pending	No	
Current Condition: STR	Pending - Waste will be stor Streets	ed in proper containmer  N 156th Street	t. 4/20/2023	Active	Na	
Current Condition:	Good Condition - The street 8/17/23 inspection. K2 Cons	s were free of track out a	as of the 4/20/23 inspection		No tially cleaned prior to the	
SWPPP Sign	SWPPP Notification Sign	On Site	5/11/2023	Active	No	
Current Condition:	Good Condition - E&A inspe				•	
Certification Statement:	"I certify, under penalty of lat direction or supervision in an properly gathered and evalu persons who manage the sy the information submitted is am aware that there are sign of fines and imprisonment for	coordance with a system ated the information sub estem or those persons on to the best of my knowl dificant penalties for sub	designed to assure that quinitted. Based on my inqui lirectly responsible for gathedge and belief, true, accu	ualified personnel ry of the person or ering the information rate, and complete	e. I	
	Broga M Waght	J			Get Sur	