E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A - P2021.3	21.000		
Inspector: Bryce Wright					Stage
		Morgar	n Ridge		
		CSW-202	-		1
Project Name:					
For Week Ending:		11/30	/2024		
	Southwest corner of Ker	npten Creek Drive a	and 156th Street - Benning	ton, NE (Douglas	69007
Project Location:		Cou			68007
Grading:	95%				
Sanitary Sewer:	100%				
Storm Sewer:	30%				
Paving:	5%				
Seeding:	50%				
Utilities:	0%				
Overall Development:	5%				
	- F	T			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"	11/26/2024	Overcast 43	1:40 PM	
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
	1				
Complaints:					
	•				
Construction Sequencing:					
Construction Sequencing: Which portion(s) (i.e. drainage bas 14 days?					d disturbance in the last
Grading the site (4/20/23). Sanitary	began (3/14/24). Storm sewer ir	nstallation began (11	/5/24). Paving on site begar	n (11/5/24).	
Which portion(s) (i.e. drainage bas	sins) of the site do not have g	rading, earthwork,	or ground disturbance scl	heduled in the next 1	4 days?
Grading the site (4/20/23). Sanitary				n (11/5/24).	
What temporary or permanent sta	bilization measures listed in t	his section are beir	ng implemented?		
Existing vegetation (4/20/23). Northy					
Checklist Questions:					
Are receiving waters adjacent to the project	t free of any significant signs of erosi	on or sediment that woul	d be associated with the constru	ction activity?	
Yes					
Create Corrective Action? N/A					
Have disturbed areas been seeded or other	wise stabilized as required? List inact	tive portions of the proje	ct and if stabilization measure ar	e adequate or needed to p	revent erosion.
Yes					
Create Corrective Action?					
N/A					
Are waste materials (concrete, construction	material bazardous etc.) being man	aged properly?			
Yes	Thaterial, hazardous, etc./ sering han	aged property.			
Create Corrective Action?					
N/A					
Are construction entrances and adjacent st	reets being maintained adequately?				
No Create Corrective Action?					
No, See BMP section.					
Is dust associated with the construction ac	tivity adequately controlled on the site	9?			
Yes					
Create Corrective Action?					

N/A

Comments:

Comments: The site was active during the most recent inspection. Findings / Corrective Actions (Date) Findings / Corrective Actions (Date): Some maintenance is needed in the BMP section. Unique Name Location Projected Install Date Status Maintenance Туре CE 1 Construction Entrance 00-23 4/20/2023 Active Yes Current Condition: Fair Condition - 10% Effective - Ruff Grading installed the construction entrance prior to the 6/15/23 inspection. Ruff Grading added more rock to the construction entrance prior to the 8/17/23 inspection. Construction entrance was moved to the Benjamin Street stub road prior to the inspection on 8/20/24. Construction entrance should have more rock added and be lengthened. Ruff Grading and Hubbell Homes were informed to complete by 10/12/23. Not done as of last inspection. Ruff Grading and Hubbell Homes were reminded on 10/19/23, 11/10/23, 3/15/24, 5/24/24, 6/13/24, 7/12/24, 7/17/24 K2 Construction was reminded on 8/22/24, 10/2/24, 11/7/24 D 1 Diversion BB-4 6/29/2023 Active No Current Condition: Good Condition - Ruff Grading installed the diversion prior to the 6/29/23 inspection. D 2 R-5 to Z-4 7/27/2023 No Diversion Active Current Condition: Good Condition - Ruff Grading installed the diversion prior to the 7/27/23 inspection. Roloff repaired the diversion prior to the inspection on 7/23/24. Ruff Grading repaired the erosion rills prior to the inspection on 10/22/24. Diversion R-5 to S-4 Removed Current Condition: Removed - Diversion no longer needed as of the 11/16/23 inspection. D 4 8/10/2023 I-9 to R-3 Diversion Active Yes Current Condition: Fair Condition - Ruff Grading installed the diversion prior to the 8/10/23 inspection. Ruff Grading re-defined the diversion prior to the 11/9/23 inspection. Roloff repaired the diversion prior to the inspection on 7/23/24. 1.) Erosion rills should be repaired. 2.) Diversion should be reinstalled where removed for storm sewer installation. 1.) Ruff Grading and Hubbell Homes were informed to complete by 11/16/23. Not done as of last inspection. Ruff Grading and Hubbell Homes were reminded on 5/24/24. Roloff was informed to complete by 6/20/24. Hubbell Homes and Ruff was reminded on 7/17/24. Hubbell Homes and K2 Construction was reminded on 8/22/24, 10/2/24 , 11/7/24 2.) Hubbell Homes and K2 Construction was informed to complete by 11/12/24. Not done as of the last inspection. I-8 to E-8 D 5 Diversion Removed Removed - Ruff Grading removed the diversion during grading of Phase II prior to the 9/17/24 inspection. Reinstallation not Current Condition: recommended D 6 Diversion C-8 to D-8 Removed Current Condition Removed - Ruff Grading removed the diversion during grading of Phase II prior to the 9/17/24 inspection. Reinstallation not recommended. BB-11 to BB-12 D 7 Diversion 9/21/2023 Active No Current Condition: Good Condition - Ruff Grading installed the diversion prior to the 9/21/23 inspection. Ruff Grading re-defined the diversion prior to the inspection on 10/22/24. D 8 Diversion BB-18 to BB-20 9/21/2023 No Active Good Condition - Ruff Grading installed the diversion prior to the 9/21/23 inspection. Current Condition: NN-23 4/25/2024 D 9 Diversion Active No Current Condition: Good Condition - Ruff Grading installed the diversion prior to the 4/25/24 inspection D 10 Diversion AA-33 Removed **Current Condition:** Removed - Ruff Grading removed the diversion during grading of Phase II prior to the 4/25/24 inspection. Reinstallation not recommended D 11 Diversion G-13 to H-13 Removed Removed - Ruff Grading removed the diversion during grading of Phase II prior to the 9/17/24 inspection. Reinstallation not

recommended D 12 Diversion K-14 to H-14 Removed **Current Condition** Removed - Ruff Grading removed the diversion during grading of Phase II prior to the 9/17/24 inspection. Reinstallation not ecommended. Erosion Matting See SWPPP EM 1 4/20/2023 Pending No Current Condition: Pending - BMP will be installed when work begins/ends in the area. E&A inspector will monitor See SWPPP Pending FM 2 Erosion Matting 4/20/2023 No Current Condition: Pending - BMP will be installed when work begins/ends in the area. E&A inspector will monitor. Erosion Matting See SWPPP Removed EM 3 **Current Condition** Removed - Ruff Grading removed the erosion control matting during grading of Phase II prior to the inspection on 9/17/24. EM 4 Erosion Matting See SWPPP 4/20/2023 Pending No Current Condition: Pending - BMP will be installed when work begins/ends in the area. E&A inspector will monitor. EM 5 See SWPPP 6/13/2024 Pending Erosion Matting Yes

Current Condition:	Pending -						
	Erosion should be repaired and erosion control matting should be installed around SB A. Roloff was informed to complete by 6/20/24. Not done as of last inspection. Ruff and Hubbell Homes was reminded on 7/17/24, 10/2/24, 11/7/24						
EM 6	Erosion Matting	See SWPPP	6/13/2024	Pending	Yes		
Current Condition:	Pending -						
	Erosion should be repaired and erosion control matting should be installed around SB B.						
	Roloff was informed to com	vploto by 6/20/24. Not do	and as of last inspection. P	uff and Hubboll Hom	as was reminded on		
	7/17/24, 10/2/24, 11/7/24		ine as of last inspection. Ru				
ET 1	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad	ling installed the erosion	control terrace prior to the	9/21/23 inspection.			
ET 2	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad	ling installed the erosion	control terrace prior to the	9/21/23 inspection.			
ET 3	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad	ling installed the erosion	control terrace prior to the	9/21/23 inspection.			
ET 4	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad	ling installed the erosion	control terrace prior to the	9/21/23 inspection.	•		
ET 5	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad	ling installed the erosion	control terrace prior to the	9/21/23 inspection.			
ET 6	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No		
Current Condition:	Pending - BMP will be insta			5			
ET 7	Erosion Control Terrace	See SWPPP		Removed			
Current Condition:	Removed - Ruff Grading re		I terrace during grading o		e 4/25/24 inspection		
	Reinstallation not recomme	ended.					
ET 8	Erosion Control Terrace	See SWPPP	9/21/2023	Active	No		
Current Condition:	Good Condition - Ruff Grad	ling installed the erosion	control terrace prior to the	9/21/23 inspection.			
ET 9	Erosion Control Terrace	See SWPPP		Removed			
Current Condition:	Removed - Ruff Grading re	moved the erosion cont	ol terrace during grading o	f Phase II prior to th	e 9/17/24 inspection.		
	Reinstallation not recomme	ended.					
FT 1	Fuel Tank	On site	8/27/2024	Active	No		
Current Condition:	Good Condition - K2 Const						
PB 1	Portable toilet	On site	8/20/2024	Active	No		
Current Condition:	Good Condition - K2 Const						
	the portable toilet prior to the						
					N		
RN 4	Erosion Control Matting	West of SB A	4/18/2024	Pending	No		
Current Condition:	Pending - Erosion Control N		1				
RN 6	Erosion Control Matting	West of SB B	4/18/2024	Pending	No		
Current Condition:	Pending - Erosion Control	Matting will be installed o	once work in the area is cor	nplete.			
SB A	Sediment Basin	AA-4	4/20/2023	Active	Yes		
Current Condition:	Fair Condition - 0% Filled -	Ruff Grading began sha	ping the basin prior to the (	6/8/23 inspection. R	uff Grading was in the		
	process of installing the rise						
	prior to the 11/16/23 inspec	tion. Ruff Grading was i	n the process of cleaning o	ut the basin and rep	pairing the erosion during t		
	inspection on 10/15/24. Ru						
	to the inspection on 10/22/24. Ruff Grading cleaned out the basin and the E&A inspector painted the cleanout mark during th						
	inspection on 10/29/24.						
	Basin should be installed per SWPPP (Baffle).						
	Ruff Grading was informed to complete by 5/25/23. Not done as of the last inspection. Ruff Grading was reminded on 6/1/23 7/14/23, 8/4/23, 8/10/23, 10/5/23, 10/19/23, 11/10/23						
00.0			A/00/0000	Λ - 45	Mar		
SB B	Sediment Basin	R-4	4/20/2023	Active	Yes		
Current Condition:	Fair Condition - 0% Filled -						
	riser and outflow pipe prior to the 11/2/23 inspection. Ruff Grading was in the process of cleaning out the basin during the inspection on 10/15/24. Ruff Grading cleaned out the basin prior to the inspection on 10/22/24. E&A inspector repainted the						
	clean out mark during the inspection on 10/22/24.						
	Basin should be installed per SWPPP (Baffle).						
	Ruff Grading was informed to complete by 5/25/23. Not done as of the last inspection. Ruff Grading was reminded on 6/1/23 7/14/23, 8/4/23, 8/10/23, 10/5/23, 10/19/23, 11/10/23						
SB C	Sediment Basin	D-8		Removed			
300					1		
Current Condition:	Removed . Puff Crading to	moved the basin during	arading for Morgon Didgo (	2 prior to the increa	tion on 0/3/2/		
Current Condition: SB D	Removed - Ruff Grading re Sediment Basin	moved the basin during HH-32 to NN-29	grading for Morgan Ridge 2 4/20/2023	2 prior to the inspec	tion on 9/3/24. Yes		

Current Condition:	Fair Condition - 5% filled - Ruff Grading began excavation on the basin prior to the 12/21/23 inspection. Ruff Grading installed the riser prior to the inspection on 7/23/24. Ruff Grading was in the process of cleaning out the basin during the inspection on 10/22/24. Ruff Grading cleaned out the basin prior to the inspection on 11/12/24.						
	Baffle should be installed per SWPPP (Baffle).						
	Ruff Grading and Hubbell Ho Hubbell Homes were remind			done as of last insp	pection. Ruff Grading and		
SF 1	Silt Fence	Western Perimeter	4/20/2023	Active	Yes		
Current Condition:	Fair Condition - Ruff Grading	installed a portion of th	e silt fence was installed o	n the west side of t	he site prior to the 4/20/23		
	inspection. Ruff Grading installed the remainder of the silt fence prior to the 5/4/23 inspection. Ruff Grading maintained the s fence prior to the 8/31/23 inspection. A portion of the silt fence was removed for grading activity by Pruss Excavation for the Hagen Hills East property to the west prior to the 11/23/23 inspection. Re-installation not recommended.						
	Ruff Grading was informed to reminded on 10/19/23, 11/10	Silt fence should be cleaned out and repaired. Ruff Grading was informed to complete by 10/12/23. Not done as of last inspection. Ruff Grading and Hubbell Homes were reminded on 10/19/23, 11/10/23, 3/15/24, 5/24/24, 6/13/24, 7/12/24, 7/17/24. Hubbell Homes and K2 Construction was reminded on 8/22/24, 10/2/24, 11/7/24					
		Southeastern		1	I		
SF 2	Silt Fence	Perimeter		Removed			
Current Condition:	Removed - Ruff Grading rem		o grading of Phase II prior		ection Reinstallation not		
	recommended.						
<b>SE 2</b>	Silt Eanaa	Southeastern		Bomovod			
SF 3 Current Condition:	Silt Fence Removed - Ruff Grading rem	Perimeter	a grading of Phase II prior	Removed	ection Reinstallation not		
	recommended.		ig grading of Fliase if phot	1 to the 4/23/24 ms			
SF 4	Silt Fence	Eastern Perimeter		Removed			
Current Condition:	Removed - Ruff Grading rem	oved the silt fence durir	ng grading of Phase II prior	r to the 4/25/24 ins	pection. Reinstallation not		
SF 5	Silt Fence	Northeastern Perimeter		Removed			
Current Condition:	Removed - Ruff Grading rem	oved the silt fence durir	ng grading of Phase II prion	r to the 4/25/24 ins	pection. Reinstallation not		
SF 6	Silt Fence	Northern Perimeter	4/20/2023	Pending	No		
Current Condition:	Pending - BMP will be install	ed when grading begins	/ends in the area. E&A ins	pector will monitor.			
SF 7	Silt Fence	Northeastern Perimeter	8/31/2023	Active	No		
Current Condition:	Good Condition - Ruff Gradir the silt fence and added an a the silt fence prior to the insp	additional row of silt fend		n. Ruff Grading and	Hubbell Homes repaired		
ST A	Sediment Trap	H-13		Removed			
Current Condition:	Removed - Ruff Grading rem	loved the trap during gra	ading for Morgan Ridge 2 p	prior to the inspection	on on 9/3/24.		
MS 1	Material Storage	On Site	4/20/2023	Pending	No		
Current Condition:	Pending - Materials will be st	ored in designated area	S.	, v	1		
WO 1	Concrete Washout	On Site	4/20/2023	Pending	No		
Current Condition:	Pending - Concrete will be pr	operly contained. Ruff (	Grading removed the conc	rete waste prior to	the 3/14/24 inspection.		
WS 1	Waste Storage	On Site	4/20/2023	Pending	No		
Current Condition:	Pending - Waste will be store	<u> </u>		1			
STR	Streets	N 156th Street	4/20/2023	Active	Yes		
Current Condition:	Fair Condition - The streets v 8/17/23 inspection. K2 Const	truction cleaned all exter	rior streets prior to the insp		ally cleaned prior to the		
	Exterior streets should be cle K2 Construction was informe	,		inspection			
SWPPP Sign	SWPPP Notification Sign	On Site		-	No		
Current Condition:	Good Condition - E&A inspec		5/11/2023 P sign during the 5/11/23 i	Active	No		
Certification Statement:	"I certify, under penalty of law direction or supervision in ac properly gathered and evalua persons who manage the sys the information submitted is, am aware that there are sign of fines and imprisonment fo	w, that this document an coordance with a system ated the information sub stem or those persons d to the best of my knowle ificant penalties for subr	d all attachments were pre designed to assure that q mitted. Based on my inqui irectly responsible for gath edge and belief, true, accu	epared under my ualified personnel ry of the person or rering the informati urate, and complete	e. I		
ctor Signature:	Breya M Wayt			Reviewed By:	6-4 S. 4)		