E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

ENGINEERING • PLANNING • FIELD SERVICES Erosion Control Specialist- Manager E&A - P2004.020.000 Stage Inspector: Mike Jacobson, CISEC **Palisades** NER110500 Project Name: 11/13/2010 For Week Ending: 68136 Project Location: 168th & Cornhusker Road- Omaha, NE (Sarpy County) RAIN FALL AMOUNTS Amount in tenths Date inspected Sunday: 0.01 Monday 0.01 10/12/10 Tuesday 0.00" Wednesday 0.00" 0.00" Thursday Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.00" Tuesday 0.00 Wednesday 0.00" Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday Tuesday 0.12" Wednesday Trace Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: Trace Monday 0.00" Tuesday 0.00" Wednesday 0.00" Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.00" Tuesday 0.00" Wednesday Trace Thursday Friday 1.49" Saturday 0.03" None Complaints: Construction Sequencing: sins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Entire site; grading completed and site seeded Spring 2005. Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Entire site; grading completed and site seeded Spring 2005. on are being implemented? Paving, seeding (Spring 05), dense vegetative cover; Drainage way west of sediment basin 3 was re-graded and seeded/matt (9/2008); Area around SB 3 and where silt was placed was re-seeded (4/2009) Comments:

Comments:

Home construction is active in various areas on site.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) Some required maintenance in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenan
Lot 21	Silt Fence	Lot 21		Removed	
Current Condition:	Lot was sodded prior to i		by Urban Homes.		1
Lot 22	Silt Fence	Lot 22	9/18/2010	Active	Yes
Current Condition:	No BMP's installed on lot Lot was cleaned up prior		2/10 by Urban Homes.		
	The disturbed areas of the prevent from run off until 21. Urban Homes was called Maintenance not complete.	the vegetation is esta	ablished on the lot due to	the home constru	uction that was o
Lot 36	Silt Fence	Lot 36	11/12/2010	Active	No
Current Condition:	Good Condition-Active he	ome construction on l	ot.		1 110
	Silt fence was installed p	rior to inspection on 1	1/12/10 by Regency Hor	nes.	
Lot 51	Misc/Other	Lot 51		Removed	
Current Condition:	Lot was sodded prior to i	inspection on 8/18/10	by Timberline Homes.		ı
Lot 62	Silt Fence	Lot 62		Removed	
Current Condition:	Lot was sodded prior to i				
			1		T
Lot 80	Silt Fence	Lot 80		Removed	
Current Condition:	The part of the outlot beh		that was disturbed and		eeded has filled
	of inspection on 9/28/10.		1		T
Lot 81	Silt Fence	Lot 81	8/18/2010	Active	No
Current Condition:	No BMP installed on the	lot- Active home cons			
	Silt fence was removed of	due to the lot being fin	e graded prior to inspec	tion on 11/12/10 b	y Sherwood Ho
Lot 101	Silt Fence	Lot 101	4/9/2010	Active	No
Current Condition:	Good Condition- Vacant		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
	Empty lot was cleaned up Construction.	p and the disturbed ar	rea was re-seeded prior	to inspection on 7	/21/10 by Muhle
Lot 113	Silt Fence	Lot 113	5/4/2010	Active	No
Current Condition:	Good Condition- Silt fend				1
	Silt fence was tied up ins	pector during inspecti	on on 8/24/10.		1
Lot 134	Silt Fence	Lot 134		Removed	
Current Condition:	Silt fence check on vaca		ior to inspection on 10/1		ial Seeding.
1 - 1 100	071.5	1 400	44/40/0040	A	
Lot 180 Current Condition:	Silt Fence No BMP installed on the	Lot 180 lot- Active home cons	11/12/2010 struction on lot.	Active	No
					T
Lot 185	Silt Fence	Lot 185	11/12/2010	Active	No
Current Condition:	No BMP installed on the				
Lot 245	Silt Fence	Lot 245		Removed	
Current Condition:	Lot was sodded prior to i	inspection on 11/12/10) by Jim w/ Charleston F	lomes.	
Lot 257 Current Condition:	Silt Fence Lot was sodded prior to i	Lot 257) by Sudbeck construction	Removed	
Carrent Condition.	Lot was souded prior to i		o by Oddbook Constituction	711-	
Lot 291	Silt Fence	Lot 291	11/12/2010	Active	No

Lot 292	Silt Fence	Lot 292	11/12/2010	Active	No		
Current Condition:	No BMP installed on the lot- Active home construction on lot by Charleston Homes.						
1.4040	O'II F	1,4040					
Lot 313 Current Condition:	Silt Fence Lot was sodded prior to	Lot 313 inspection on 10/12/10	by Horizon Homes	Removed			
Current Condition.	Lot was seaded prior to						
Lot 347	Silt Fence	Lot 347	11/12/2010	Active	Yes		
Current Condition:	Good Condition- Active I	home construction on lo	t.				
	Additional silt fence needs to be installed along the front of the lot.						
	Bob w/ Dream Scape Homes was informed to complete maintenance by 11/20/10.						
Lot 379	Silt Fence	Lot 379	11/12/2010	Active	No		
Current Condition:	Good Condition-Active h			Active	No		
	Silt fence was installed p	prior to inspection on 11	/12/10 by Zych constru	iction.			
Lot 389	Silt Fence	Lot 389	8/18/2010	Active	Yes		
Current Condition:	Pending- Active home or		8/10/2010	Active	163		
	Lot level silt fence needs to be installed on the back of the lot.						
	Lot level slit refice fleeds	s to be installed on the t	back of the lot.				
	Horizon Homes was info						
	message reminding ther last inspection.	m that maintenance nee	ds to be completed AS	SAP. Maintenance	not completed as of		
Lot 402	Silt Fence	Lot 402		Removed			
Current Condition:	Lot was sodded prior to inspection on 11/12/10 by Zych Construction.						
Let 445	Cilt Force	Lot 415	9/49/2040	A atinua	Voc		
Lot 415 Current Condition:	Silt Fence Pending- Active home of		8/18/2010	Active	Yes		
	Lot level silt fence needs to be installed on the back of the lot.						
	Builder is unknown at this time. When builder is determined then they will be informed to complete						
	maintenance.						
Lot 420 Current Condition:	Silt Fence Lot was sodded prior to	Lot 420	hy Charleston Homes	Removed			
Current Condition.	Lot was souded prior to		by Chanesion Homes.				
SB 1	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active			
Current Condition:	Good Condition - 31% F				No		
	Cleaned out 06/05	N44 d0000-			No		
SB 2	Sediment Basin	N41d00m00s			No		
Current Condition:	This has been convert to permanent pond for the school site.						
	This has been convert to	W96d00m00s o permanent pond for the	In Place e school site.	Active	No No		
25.2		permanent pond for th N41d00m00s	e school site.		No		
SB 3	Sediment Basin	permanent pond for the N41d00m00s W96d00m00s		Active Active			
SB 3 Current Condition:		permanent pond for the N41d00m00s W96d00m00s illed	e school site. In Place	Active	No		
	Sediment Basin Good Condition - 19% F	permanent pond for the N41d00m00s W96d00m00s illed	e school site. In Place	Active	No		
Current Condition:	Sediment Basin Good Condition - 19% F Clean out was complete Sediment Basin	D permanent pond for the N41d00m00s W96d00m00s illed d prior to inspection on N41d00m00s W96d00m00s	e school site. In Place	Active	No		
Current Condition:	Sediment Basin Good Condition - 19% F Clean out was complete	D permanent pond for the N41d00m00s W96d00m00s illed d prior to inspection on N41d00m00s W96d00m00s	e school site. In Place 1/22/09 by M.E. Collins	Active	No No		
Current Condition: SB 4 Current Condition:	Sediment Basin Good Condition - 19% F Clean out was complete Sediment Basin Good Condition - 39% F Cleaned out 07/05	D permanent pond for the N41d00m00s W96d00m00s illed d prior to inspection on N41d00m00s W96d00m00s illed N41d00m00s	e school site. In Place 1/22/09 by M.E. Collins	Active	No No		
Current Condition: SB 4 Current Condition: SF 1	Sediment Basin Good Condition - 19% F Clean out was complete Sediment Basin Good Condition - 39% F Cleaned out 07/05 Silt Fence	D permanent pond for the N41d00m00s W96d00m00s illed d prior to inspection on N41d00m00s W96d00m00s illed N41d00m00s W96d00m00s	e school site. In Place 1/22/09 by M.E. Collin: In Place	Active S. Active Removed	No No No		
Current Condition: SB 4 Current Condition:	Sediment Basin Good Condition - 19% F Clean out was complete Sediment Basin Good Condition - 39% F Cleaned out 07/05	D permanent pond for the N41d00m00s W96d00m00s illed d prior to inspection on N41d00m00s W96d00m00s illed N41d00m00s W96d00m00s ce was removed prior to	e school site. In Place 1/22/09 by M.E. Collins In Place o inspection on 8/8/09	Active S. Active Removed by Boyer Young du	No No No		
Current Condition: SB 4 Current Condition: SF 1	Sediment Basin Good Condition - 19% F Clean out was complete Sediment Basin Good Condition - 39% F Cleaned out 07/05 Silt Fence The remainder of silt fen vegetation. The builder w this area.	D permanent pond for the N41d00m00s W96d00m00s illed d prior to inspection on N41d00m00s W96d00m00s illed N41d00m00s W96d00m00s ice was removed prior tellowill be responsible for results.	e school site. In Place 1/22/09 by M.E. Collins In Place o inspection on 8/8/09 -installation of silt fence	Active Active Removed by Boyer Young due prior to activity h	No No No et to good ome construction in		
Current Condition: SB 4 Current Condition: SF 1	Sediment Basin Good Condition - 19% F Clean out was complete Sediment Basin Good Condition - 39% F Cleaned out 07/05 Silt Fence The remainder of silt fen vegetation. The builder v this area. Lot 293 was sodded price	D permanent pond for the N41d00m00s W96d00m00s illed d prior to inspection on N41d00m00s W96d00m00s illed N41d00m00s W96d00m00s ice was removed prior tellowill be responsible for results.	e school site. In Place 1/22/09 by M.E. Collins In Place o inspection on 8/8/09 -installation of silt fence	Active Active Removed by Boyer Young due prior to activity h	No No No et to good ome construction in		
Current Condition: SB 4 Current Condition: SF 1	Sediment Basin Good Condition - 19% F Clean out was complete Sediment Basin Good Condition - 39% F Cleaned out 07/05 Silt Fence The remainder of silt fen vegetation. The builder w this area.	D permanent pond for the N41d00m00s W96d00m00s illed d prior to inspection on N41d00m00s W96d00m00s illed N41d00m00s W96d00m00s ice was removed prior to will be responsible for report to inspection on 9/28/	e school site. In Place 1/22/09 by M.E. Collins In Place o inspection on 8/8/09 -installation of silt fence	Active Active Removed by Boyer Young due prior to activity h	No No No et to good ome construction in		
SB 4 Current Condition: SF 1 Current Condition: SF 1 ST 1	Sediment Basin Good Condition - 19% F Clean out was complete Sediment Basin Good Condition - 39% F Cleaned out 07/05 Silt Fence The remainder of silt fen vegetation. The builder withis area. Lot 293 was sodded price longer needed. Silt Trap	D permanent pond for the N41d00m00s W96d00m00s illed d prior to inspection on N41d00m00s W96d00m00s illed N41d00m00s W96d00m00s ince was removed prior to will be responsible for responsible for responsible for to inspection on 9/28/ N41d00m00s W96d00m00s	e school site. In Place 1/22/09 by M.E. Collin: In Place o inspection on 8/8/09 o-installation of silt fenc	Active Active Removed by Boyer Young due prior to activity h	No No No et to good ome construction in		
SB 4 Current Condition: SB 4 Current Condition: SF 1 Current Condition:	Sediment Basin Good Condition - 19% F Clean out was complete Sediment Basin Good Condition - 39% F Cleaned out 07/05 Silt Fence The remainder of silt fen vegetation. The builder v this area. Lot 293 was sodded pric longer needed.	D permanent pond for the N41d00m00s W96d00m00s illed d prior to inspection on N41d00m00s W96d00m00s illed N41d00m00s W96d00m00s ice was removed prior to will be responsible for responsible	e school site. In Place 1/22/09 by M.E. Collin: In Place o inspection on 8/8/09 o-installation of silt fenc	Active Active Removed by Boyer Young due prior to activity helomes, therefore the	No No No et to good ome construction in		
SB 4 Current Condition: SF 1 Current Condition: SF 1 ST 1	Sediment Basin Good Condition - 19% F Clean out was complete Sediment Basin Good Condition - 39% F Cleaned out 07/05 Silt Fence The remainder of silt fen vegetation. The builder withis area. Lot 293 was sodded price longer needed. Silt Trap	D permanent pond for the N41d00m00s W96d00m00s illed d prior to inspection on N41d00m00s W96d00m00s illed N41d00m00s W96d00m00s ince was removed prior to will be responsible for responsible for responsible for to inspection on 9/28/ N41d00m00s W96d00m00s	e school site. In Place 1/22/09 by M.E. Collin: In Place o inspection on 8/8/09 o-installation of silt fenc	Active Active Removed by Boyer Young due prior to activity helomes, therefore the	No No No et to good ome construction in		

Current Condition:	Fair Condition- Some minor signs of rur Bob w/ Dream Scape Ho	· ·		lot 347 and it need	s to be cleaned up.	
SWPPP Sign	SWPPP Sign	Three signs on site	3/28/2008	Active	No	
Current Condition:	Good Condition On 3/28/08 inspector install SWPPP a sign at 172nd & Cornhusker Rd., 168th & Chutney Dr and 168th & Palisades Drive entrance.					
Inspector Signature:	of Jawlon			Reviewed By:	Ednary L. Jilde	