E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Zachary A. Jilek, CPESC, CISEC

t temporary or pe

Environmental Services Dept. Manager



Engineering Answers

E&A - P2004.020.000 Inspector: Patrick Sechser Stage 3 Palisades NER110500 Project Name: 10/10/2015 For Week Ending: 68136 Project Location: 168th & Cornhusker Road- Omaha, NE (Sarpy County) Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% Paving: 100% Seeding: Utilities: 100% 100% Overall Development: 70% RAIN FALL AMOUNTS Amount in tenths Date inspected Weather Conditions Sunday: 0.00' Monday 0.00" Tuesday 0.00" Wednesday 0.00" Thursday 0.00" Friday 0.12" Saturday 0.00" Sunday: 0.00" Monday 0.00" Tuesday 0.00" Wednesday 1.30" 9/24/2015 Cloudy 74/65 1.13" Thursday Friday 0.00" 9/25/2015 Cloudy 81/64 Saturday 0.00" Wee Sunday: 0.00" Monday 0.00" Tuesday 0.21' Wednesday 0.00' Thursday 0.00' Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.00" Tuesday .**0**1' Wednesday 0.00" Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: N/A N/A Monday N/A N/A Tuesday N/A N/A Wednesday N/A N/A Thursday N/A N/A Friday N/A N/A Saturday N/A N/A None Complaints: Construction Sequencing . 1(s) (i.e. d ite have had a te ce in the last 14 days? Entire site; grading completed and site seeded Spring 2005. Entire site; grading completed and site seeded Spring 2005

Paving, seeding (Spring 05), dense vegetative cover; Drainage way west of sediment basin 3 was re-graded and seeded/matt (9/2008); Area around Si
3 and where silt was placed was re-seeded (4/2009); The drainage area just West of SB 3 was repaired and seeded/matted(10/2011)
Swale down to basin #3 was regraded, seeded and matted prior to inspection on 9/11/2013; Matting was installed on SB 3 Slopes (8/28/2015).

SUMMARY QUESTIONS:						
Are approved entrances and adjacent streets	being maintained adequately?	?				
No. See BMP Section						
Are receiving waters adjacent to the project fi	ree of any significant signs of	erosion or sediment that would	d be associated with the co	nstruction activity?		
Yes						
CHECKLIST QUESTIONS:	CHECKLIST QUESTIONS:					
Are waste materials (concrete, construction m	naterial, hazardous, etc.) being	g managed properly?				
No. See BMP section.						
Is dust associated with the construction activity adequately controlled on the site?						
Yes						
Comments:						
Comments:						
Home construction is active in various areas on site as of the last inspections.						

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some required maintenance in the BMP section.

	-	1			i
	_		Projected Install	.	
Unique Name	Туре	Location South end of Outlot C	Date	Status	Maintenance
CW 1	Concrete Washout	along Palisades Drive	6/11/2012	Active	Yes
Current Condition:	Fair Condition-	along i alloadeo Diffe	0/11/2012	7101170	100
ourient oonation.					
	Washout pit needs to be	e cleaned out.			
	Celebrity Homes was inf	formed to complete by 9/4/	2015. Not done as of t	ne last inspection.	CH was reminded on
	<mark>9/9/2015.</mark>				
		South end of Outlot C			
CW 2	Concrete Washout	along Palisades Drive	4/1/2015	Pending	Yes
Current Condition:	Pending-		•	, i i i i i i i i i i i i i i i i i i i	
	-				
	Washout pit needed and	d the rubble/debris needs t	to be cleaned up.		
		ned to complete by 4/1/201	5. Not completed as of	the last inspection	. Boyer Young was
	reminded again on 6/12				
Lot 8	Silt fence	Lot 8	6/12/2015	Active	No
Current Condition:		excavated the lot prior to 6	6/12/2015. Due to a veg	getated buffer strip	in the rear, BMPs
	are presently not neede	d.			
Lot 22	Silt fence	Lot 22	6/12/2015	Pending	Yes
Current Condition:	Pending-		•	, i i i i i i i i i i i i i i i i i i i	
	Due to the sidewalk inst	allation, silt fence needed	in the rear corner of the	e lot as of 8/28/201	5.
	Oakwood Homes was in	formed to complete by 9/4	/2015. Not done as of t	he last inspection.	
Lot 23	Misc/Other	Lot 23		Removed	
Current Condition:	Removed-Regency Hor	nes sodded the lot prior to	inspection on 5/8/15.		
Lot 25	Silt fence	Lot 25	8/28/2015	Active	No
Current Condition:	Active- Due to the sidew	alk installation, silt fence i	s no longer needed on	the front as of 8/28	3/2015 by the Home
	Company. E&A will mor	nitor.			
Lot 38	Silt fence	Lot 38		Removed	
Current Condition:	Removed- Lot was sodd	led by Charleston Homes	prior to 6/12/2015.		
Lot 39	Silt fence	Lot 39	6/12/2015	Active	Yes
Current Condition:	Fair Condition- Legacy	/ Homes cleaned out the	silt fence prior to 9/24	4/2015.	
	Silt fence needs to be	re-tied on the side of the	lot.		
	Legacy Homes was inf	formed to complete by 10	0/02/2015.		
Lot 45	Silt fence	Lot 45		Removed	
Current Condition:		lomes sodded the lot prior	to 8/18/2015.		
Lot 59	Individual lot	Lot 59		Removed	
Current Condition:		odded by The Home Comp			
Lot 60	Silt fence	Lot 60	6/12/2015	Active	Yes
Current Condition:	Fair Condition-				
	1.) Silt fence on the front of the lot needs repair.				
	2.) Silt fence in the rear needs to be reinstalled.				
	1.) Legacy Homes was informed to complete by 9/4/2015. Not done as of the last inspection. Legacy Homes				
	was reminded on 9/26/2015. 2.) Legacy Homes was informed to complete by 10/02/2015.				
1	, , ,			A -1:	X
Lot 77	Silt fence	Lot 77	6/19/2015	Active	Yes

Current Condition:	Fair Condition-				
	 Silt fence in the rear needs to be cleaned out. Silt fence on the north side needs to be entrenched. H3 Homes was informed to complete by 8/7/2015. Not done as of the last inspection. 				
		ned to complete by 8/7/20	15. Not done as of the		-
Lot 78	Silt fence	Lot 78		Removed	
Current Condition: Lot 82	Silt Fence	ed by The Home Compan Lot 82	y prior to 6/12/2015.	Removed	
Current Condition:		ed by Timberline Homes p	prior to the inspection o		
Lot 85	Individual lot	Lot 85		Removed	
Current Condition:		nes sodded the lot prior to	inspection on 5/8/15.		1
Lot 86	Individual lot	Lot 86 sodded the lot prior to ins	neation on E/0/4E	Removed	
Current Condition: Lot 87	Silt fence	Lot 87	pection on 5/8/15.	Removed	
Current Condition:		sodded by THC. As of 8/	10/2015, lot has filled i		egetation and will be
	removed from the report				
Lot 92	Silt fence	Lot 92	6/19/2015	Pending	Yes
Current Condition:	Pending-				
	Silt fence is needed in th	ne rear of the lot.			
	The Home Company wa	s informed to complete by	6/19/2015. Not done a	s of the last inspe	ction.
Lot 163	Silt fence	Lot 163	9/9/2015	Active	No
Current Condition:		on Custom Homes installe			
Lot 166	Silt fence	Lot 166	8/7/2015	Pending	Yes
Current Condition:	Pending-				
	Silt fence check needed	on the northwest front cor	mer of the lot.		
		rmed to complete by 8/7/2	015. Not done as of th	ne last inspection	n. Legacy Homes
	was reminded on 9/1/2		0/7/0015		
Lot 168 Current Condition:	Silt fence Poor Condition-	Lot 168	8/7/2015	Active	Yes
Current Condition:					
	Silt fence on the north a	nd south sides need to be	entrenched and cleane	ed out.	
	Logan Home Construction	on, LLC was informed to c	omplete by 8/7/2015. N	lot done as of the	last inspection.
Lot 178	Silt fence	Lot 178		Removed	
Current Condition:		ed by Legacy Homes prior	r to 7/31/2015.	Demoved	
Lot 187 Current Condition:	Individual lot Removed-The lot was so	Lot 187 odded by The Home Comp	any prior to inspection	Removed	
Lot 196	Silt Fence	Lot 196	any phot to mopeouon	Removed	
Current Condition:	Removed- Lot was sodd	ed by Homeowner prior to	7/31/2015.		•
Lot 197	Silt Fence	Lot 197		Removed	
Current Condition: Lot 198	Removed- Lot was sodd Silt Fence	ed by Heavican Homes pr Lot 198	ior to 7/31/2015. 5/8/2015	Active	No
Current Condition:		s a silt fence on the west s			INU
Lot 200	Silt fence	Lot 200	10/2/2015	Pending	Yes
Current Condition:	Pending-				
	Silt fence check is nee	ded on the front-side of	the lot.		
	Charleston Homes was	s informed to complete b	v 10/02/2015.		
Lots 237-241	Silt Fence	Lots 237-241		Removed	
Current Condition:		nes sodded the lot 239 pri	or to 8/28/2015.		·
Lots 265-267	Silt Fence	Lots 265-267		Removed	
Current Condition:	Removed- Celebrity Hor Individual lot	nes sodded the lot 267 pri Lot 273	or to 9/9/2015. 6/23/2015	Active	No
Lot 273 Current Condition:		Lot 273 LC removed the dirt from t			
	not needed. E&A will mo				
Lot 290	Silt Fence	Lot 290		Removed	
Current Condition:	Removed- Lot was sodd	ed by Celebrity Homes pri	or to 7/31/2015.		
Lot 324	Silt Fence	Lot 324		Removed	
Current Condition: Lot 363-367	Removed- Outlot E was Silt fence	Lot 363-367	Celebrity Homes prior to 6/19/2015	o 7/31/2015. Active	No
Current Condition:		prity Homes repaired the			
		, and a life			
Lot 378	Silt fence	Lot 378	7/27/2015	Active	No
Current Condition:	Good Condition- Celeb	rity Homes repaired the		t of the lot prior t	
Lot 388	Silt Fence	Lot 388		Removed	
Current Condition:		mes sodded the lot prio		A office	No
Lot 399 Current Condition:	Silt fence Good Condition- Celebri	Lot 399 ity Homes repaired the silt	7/27/2015 fence on the front of th	Active ne lot prior to 8/10	No 2015 and extended
	the silt fence prior to 9/9				
SB 3	Sediment Basin	Commercial Lot #5	In Place	Active	No
Current Condition:	Good Condition - 9% Fil	led-Cleaned out was comp	pleted prior to inspection	n on 7/31/15 by D	ousty Roth.
		173rd Street and			
SB 4	Sediment Basin	Palisades Drive	In Place	Active	No
SB 4 Current Condition:	Sediment Basin Good Condition - 47% F Cleaned out 07/05	Palisades Drive	In Place	Active	No

		Cornhusker, 168th, and				
STR	Streets	Interior Streets	In Place	Active	Yes	
Current Condition:	Celebrity Homes prior	Fair Condition- Streets were cleaned in front of lot 378 and in front of lot 178 by Legacy Homes and Celebrity Homes prior to 7/31/2015. 1.) Palisades Drive needs to be cleaned where the road ends. 2.) Rampart Street and 172nd Street needs to be cleaned.				
	 The Home Company was informed to complete street cleaning by 7/26/2014. Not completed as of the l inspection. THC was reminded again on 8/28/2014, 9/13/2014 and 10/15/2014. Boyer Young was reminde again on 3/27/2015. Oakwood Homes was informed to clean on 9/1/2015. Commercial Seeding was informed to complete by 9/26/2015. 					
SWPPP Sign	SWPPP Sign	Three signs on site	3/28/2008	Active	No	
Current Condition:	Good Condition- On 3/28/08 inspector installed SWPPPs at 172nd & Cornhusker Rd., 168th & Chutney Dr and 168th & Palisades Drive entrance.					
Inspector Signature:	Parts Sul,			Reviewed By:	Sichary K. Jilik	