E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept. Ma	anager			Engineering	MIISWEIS	
		E&A - P2004.02	20 000			
Inspector: Matthew Vanicek		LOM - F2004.02	.0.000		Stage	
ispector. matthew values		Palisades				
					3	
Project Name:		NER110500 2/8/2020				
For Week Ending:						
Project Location:		168th & Cornhusker Road- Omaha, NE (Sarpy County)				
Grading:	10	00%		1		
Sanitary Sewer:		00%				
Storm Sewer:		00%				
Paving:	10	00%				
Seeding:		00%				
Utilities: Overall Development:		00% 99%				
Overali Development:		99%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		Wask	
Sunday:	0.13"				Week 1	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.01"					
Thursday Friday	0.00" 0.11"					
Saturday	0.01"					
Outurday	0.01				Week 2	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.02"					
Wednesday	0.4"					
Thursday	0.26" 0.00"					
Friday Saturday	0.00"					
outur day	0.00				Week 3	
Sunday:	0.02"				W CONT	
Monday	0.00"					
Tuesday	0.02"					
Wednesday Thursday	0.04" 0.00"	1/29/2020	Cloudy 33/28			
Friday	0.00"		+			
Saturday	0.00"					
					Week 4	
Sunday:	0.00"					
Monday	0.00"					
Tuesday Wednesday	0.00"					
Thursday	0.00"					
Friday	0.08"					
Saturday	0.00"				Week !	
Sunday:	N/A	N/A				
Monday	N/A	N/A				
Tuesday Wednesday	N/A N/A	N/A N/A				
Thursday	N/A N/A	N/A N/A				
Friday	N/A	N/A				
Saturday	N/A	N/A				
		-				
Complaints:	None					
Complaints.	 					
Construction Sequencing:	<u> </u>	<u> </u>				

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and site seeded Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site; grading completed and site seeded Spring 2005.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, seeding (Spring 05), dense vegetative cover; Drainage way west of sediment basin 3 was re-graded and seeded/matt (9/2008); Area around SB 3 and where silt was placed was re-seeded (4/2009); The drainage area just West of SB 3 was repaired and seeded/matted(10/2011)

Swale down to basin #3 was regraded, seeded and matted prior to inspection on 9/11/2013; Matting was installed on SB 3 Slopes (8/28/2015). The outlot adjacent to lot 88 were seeded and matted (4/25/18).

SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

CHECKLIST QUESTIONS:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

Home construction is inactive as of the last inspection. One vacant lot remains.

Plette Jam

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) No maintenance is required at this time.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
		South end of Outlet C					
CW 1	Concrete Washout	along Palisades Drive		Removed			
Current Condition:	Removed - Washout pit was removed by Celebrity Homes prior to 11/12/2015.						
		South end of Outlet C					
CW 2	Concrete Washout	along Palisades Drive		Removed			
Current Condition:	Removed - Washout pit was removed by Boyer Young prior to 11/12/2015.						
		South end of Outlet C					
CW 3	Concrete Washout	along Palisades Drive		Removed			
Current Condition:	Removed - Celebrity Homes removed the washout in preparation for sod on lot 203. The inspector will monitor the nee to re-install.						
Lot 24	Individual lot	Lot 24		Removed			
Current Condition:	Removed - The lot has naturally vegetated and no runoff was observed during the inspection on 4/25/18. The inspecto will remove the lot from the report and continue to monitor the need for stabilization.						
Lot 35					I		
Lot 35 Current Condition:	will remove the lot from the Silt Fence	ne report and continue to m	nonitor the need for stabilizati	on.			
	will remove the lot from the Silt Fence	ne report and continue to m		on.	No		
Current Condition:	will remove the lot from the Silt Fence Removed - Nathan Dalry Sediment Basin	Lot 35 mple sodded the lot prior to Commercial Lot #5	nonitor the need for stabilization the inspection on 12/5/19.	on. Removed Active	No		
Current Condition: SB 3	will remove the lot from the Silt Fence Removed - Nathan Dalry Sediment Basin	Lot 35 mple sodded the lot prior to Commercial Lot #5	nonitor the need for stabilization the inspection on 12/5/19. In Place	on. Removed Active	No		
Current Condition: SB 3	will remove the lot from the Silt Fence Removed - Nathan Dalry Sediment Basin	Lot 35 mple sodded the lot prior to Commercial Lot #5 lled - Cleaned out was com	nonitor the need for stabilization the inspection on 12/5/19. In Place	on. Removed Active	No		
Current Condition: SB 3 Current Condition:	will remove the lot from the Silt Fence Removed - Nathan Dalry Sediment Basin Good Condition - 15% Fi	Lot 35 mple sodded the lot prior to Commercial Lot #5 lled - Cleaned out was com 173rd Street and	nonitor the need for stabilization the inspection on 12/5/19. In Place pleted prior to inspection on	on. Removed Active 7/31/15 by Dusty R	No		
Current Condition: SB 3 Current Condition: SB 4 Current Condition:	will remove the lot from the Silt Fence Removed - Nathan Dalry Sediment Basin Good Condition - 15% Fit Sediment Basin Removed - Basin was re	Lot 35 mple sodded the lot prior to Commercial Lot #5 lled - Cleaned out was com 173rd Street and Palisades Drive	nonitor the need for stabilization the inspection on 12/5/19. In Place pleted prior to inspection on	on. Removed Active 7/31/15 by Dusty R	No		
Current Condition: SB 3 Current Condition: SB 4	will remove the lot from the Silt Fence Removed - Nathan Dalry Sediment Basin Good Condition - 15% Fi	Lot 35 mple sodded the lot prior to Commercial Lot #5 lled - Cleaned out was com 173rd Street and Palisades Drive moved prior to the inspection	nonitor the need for stabilization the inspection on 12/5/19. In Place pleted prior to inspection on	on. Removed Active 7/31/15 by Dusty R	No		
Current Condition: SB 3 Current Condition: SB 4 Current Condition:	will remove the lot from the Silt Fence Removed - Nathan Dalry Sediment Basin Good Condition - 15% Fit Sediment Basin Removed - Basin was researched.	Lot 35 mple sodded the lot prior to Commercial Lot #5 lled - Cleaned out was com 173rd Street and Palisades Drive moved prior to the inspectio Cornhusker, 168th, and Interior Streets	nonitor the need for stabilization the inspection on 12/5/19. In Place pleted prior to inspection on on 3/24/16.	on. Removed Active 7/31/15 by Dusty R Removed Active	No oth.		
Current Condition: SB 3 Current Condition: SB 4 Current Condition: STR	will remove the lot from the Silt Fence Removed - Nathan Dalry Sediment Basin Good Condition - 15% Fit Sediment Basin Removed - Basin was researched.	Lot 35 mple sodded the lot prior to Commercial Lot #5 lled - Cleaned out was com 173rd Street and Palisades Drive moved prior to the inspectio Cornhusker, 168th, and Interior Streets	on on 3/24/16.	on. Removed Active 7/31/15 by Dusty R Removed Active	No oth.		

Inspector Signature:

Reviewed By:

Set Su