E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept. Manager Engineering Answers							
		E&A - P2004.020	0.000				
Inspector: Matthew Vanicek		L&A - F2004.020	0.000		Stage		
inspector. Matthew various		Palisades					
			110500		3		
Project Name:							
For Week Ending:		3/14/2020					
Project Location:	168	168th & Cornhusker Road- Omaha, NE (Sarpy County) 68136					
Grading:	100%						
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving:	100%						
Seeding: Utilities:	100% 100%						
Overall Development:	99%		-				
Overall Development.	3970						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	Wester		
Sunday:	0.00"				Week 1		
Monday	0.00"			+			
Tuesday	0.00"						
Wednesday	0.05"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
	2.22				Week 2		
Sunday:	0.00"						
Monday Tuesday	0.02" 0.00"						
Wednesday	0.08"						
Thursday	0.00"		+				
Friday	0.00"						
Saturday	0.00"						
j					Week 3		
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"	2/26/2020	Partly Cloudy 39/24	9:30 AM			
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00				Week 4		
Sunday:	0.00"				WCCK -		
Monday	0.01"						
Tuesday	0.00"						
Wednesday	0.01"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"				Wook		
Sunday:	0.00"				Week 5		
Monday	0.30"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.04"						
Saturday	0.45"						
	None						
Complaints:	INOTIC						
Construction Sequencing:							

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and site seeded Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site; grading completed and site seeded Spring 2005.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, seeding (Spring 05), dense vegetative cover; Drainage way west of sediment basin 3 was re-graded and seeded/matt (9/2008); Area around SB 3 and where silt was placed was re-seeded (4/2009); The drainage area just West of SB 3 was repaired and seeded/matted(10/2011)

Swale down to basin #3 was regraded, seeded and matted prior to inspection on 9/11/2013; Matting was installed on SB 3 Slopes (8/28/2015). The outlot adjacent to lot 88 were seeded and matted (4/25/18).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.

/es

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

Home construction is inactive as of the last inspection. Two vacant lots remain.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) No maintenance is required at this time.

Hadana Nama	T	1	Due in stand I wastell Date	04-4	Maintanana	
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
		South end of Outlet C				
CW 1	Concrete Washout	along Palisades Drive		Removed		
Current Condition:	Removed - Washout pit was removed by Celebrity Homes prior to 11/12/2015.					
		South end of Outlet C				
CW 2	Concrete Washout	along Palisades Drive		Removed		
Current Condition:	Removed - Washout pit was removed by Boyer Young prior to 11/12/2015.					
		South end of Outlet C				
CW 3	Concrete Washout	along Palisades Drive		Removed		
Current Condition:	Removed - Celebrity Hor	Removed - Celebrity Homes removed the washout in preparation for sod on lot 203. The inspector will monitor the need				
	to re-install.					
Lot 24	Individual lot	Lot 24		Removed		
Current Condition:	Removed - The lot has naturally vegetated and no runoff was observed during the inspection on 4/25/18. The inspector					
	will remove the lot from the report and continue to monitor the need for stabilization.					
Lot 35	Silt Fence	Lot 35		Removed		
Current Condition:	Removed - Nathan Dalrymple sodded the lot prior to the inspection on 12/5/19.					
SB 3	Sediment Basin	Commercial Lot #5	In Place	Active	No	
Current Condition:	Good Condition - 15% Filled - Cleaned out was completed prior to inspection on 7/31/15 by Dusty Roth.					
		173rd Street and				
SB 4	Sediment Basin	Palisades Drive		Removed		
Current Condition:	Removed - Basin was removed prior to the inspection on 3/24/16.					
		Cornhusker, 168th, and				
STR	Streets	Interior Streets	In Place	Active	No	
Current Condition:	Good Condition - The streets around lot 35 were clean as of the inspection on 12/5/19.					
SWPPP Sign	SWPPP Sign	Three signs on site	3/28/2008	Active	No	

Current Condition:	Good Condition - On 3/28 Palisades Drive entrance	Condition - On 3/28/08 inspector installed SWPPPs at 172nd & Cornhusker Rd., 168th & Chutney Dr and 168th & des Drive entrance.			
Inspector Signature:	Van		Reviewed By:	Sto Sur	