E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept. Manager

Enaineerina Answers

nvironmental Services Dept. Manager Engineering Answers							
		E&A - P2004.	020.000				
Inspector: Alex Brown					Stage		
		P	alisades		•		
Project Name:			R110500		3		
<u> </u>							
For Week Ending:		10/9/2021					
Project Location:		168th & Cornhusker Road- Omaha, NE (Sarpy County)					
Grading:	1	00%					
Sanitary Sewer:		00%					
Storm Sewer:		00%					
Paving:		00%					
Seeding:		00%					
Utilities:		00%					
Overall Development:		99%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	West		
Sunday:	0.00"				Week		
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"				Mode		
Sunday:	0.00"				Week		
Monday	0.12"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
Sunday:	0.00"				Week		
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.03"						
Thursday	0.33"						
Friday	0.01"	10/1/2021	Cloudy 74/67	9:20 AM			
Saturday	0.00"				Week		
Sunday:	0.00"				vveek		
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"				Week		
Sunday:	N/A				vveek		
Monday	N/A						
Tuesday	N/A						
Wednesday	N/A						
Thursday	N/A						
Friday	N/A						
Saturday	N/A						
Complaints:	None						
Construction Sequencing:	A children and the chil		Franklin and St.				
Which portion(s) (i.e. drainage basin	is) of the site have had a tempora	ary or permanent cessation of	of grading, earthwork, or ground dis	sturbance in the last 14 days	?		

Entire site; grading completed and site seeded Spring 2005.

h portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site; grading completed and site seeded Spring 2005.

ted in this section are being implemented?

Paving, seeding (Spring 05), dense vegetative cover; Drainage way west of sediment basin 3 was re-graded and seeded/matt (9/2008); Area around SB 3 and where silt was placed was re-seeded (4/2009); The drainage area just West of SB 3 was repaired and seeded/matted(10/2011)

Swale down to basin #3 was regraded, seeded and matted prior to inspection on 9/11/2013; Matting was installed on SB 3 Slopes (8/28/2015). The outlot adjacent to lot 204 and the outlot adjacent to lot 88 were seeded and matted (4/25/18).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes Create Corrective Action?

N/A

Comments:

Home construction is inactive as of the last inspection. Two vacant lots remain.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) No maintenance is required at this time.

Unique Name	Type	Location	Projected Install Date	Status	Maintenan	
		South end of Outlet C				
CW 1	Concrete Washout	along Palisades Drive		Removed		
Current Condition:	Removed - Washout pit was removed by Celebrity Homes prior to 11/12/2015.					
	·	South end of Outlet C	•			
CW 2	Concrete Washout	along Palisades Drive		Removed		
Current Condition:	Removed - Washout pit was removed by Boyer Young prior to 11/12/2015.					
		South end of Outlet C				
CW 3	Concrete Washout	along Palisades Drive		Removed		
Current Condition:	Removed - Celebrity Homes removed the washout in preparation for sod on lot 203. The inspector will monit					
	to re-install.					
Lot 24	Individual lot	Lot 24		Removed		
Current Condition: Removed - The lot has naturally vegetated and no runoff was observed during the inspection on					5/18. The inspe	
	will remove the lot from t	he report and continue to m	nonitor the need for stabilizati	ion.	•	
Lot 35	Silt Fence	Lot 35		Removed		
Current Condition:	Removed - Nathan Dalry	mple sodded the lot prior to	the inspection on 12/5/19.	•	•	
SB 3	Sediment Basin	Commercial Lot #5	In Place	Active	No	
Current Condition:	Good Condition - 15% Fi	lled - Cleaned out was com	pleted prior to inspection on	7/31/15 by Dusty R	oth.	
		173rd Street and				
SB 4	Sediment Basin	Palisades Drive		Removed		
Current Condition:	Removed - Basin was removed prior to the inspection on 3/24/16.					
		Cornhusker, 168th, and				
STR	Streets	Interior Streets	In Place	Active	No	
Current Condition:	Good Condition - The str	Good Condition - The streets around lot 35 were clean as of the inspection on 12/5/19.				
SWPPP Sign	SWPPP Sign	Three signs on site	3/28/2008	Active	No	
	SWPPP Sign Good Condition - On 3/2	Three signs on site 8/08 inspector installed SW		Active	tney Dr a	
	Palisades Drive entrance	<u>)</u> .				

Increase Signature:	Reviewed By:
Inspector Signature:	Reviewed by: