E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

## E&A\_ D2017 /63 001

		E&A- P20	17.463.001			
Inspector: Chase Wickard					Stage	
Project Name:	Prairie Ho	•	den Hollow per ND 201802726	EQ NOI)	1	
For Week Ending:			9/2019		68007	
Project Location:	156th Str	3/9/2019 156th Street and Highway 36 (Bennington Ne, Douglas County)				
	13611 311	eet and mighway 50	(Bernington Ne, Douglas)	county)		
Grading:	30%					
Sanitary Sewer:	0%					
Storm Sewer:	0%					
Paving:	0%					
Seeding:	0%					
Utilities:	0%					
Overall Development:	4%					
RAIN FALL AMOUNTS	Amount in tenths	Data increased	Weather Conditions			
KAIN FALL AMOUNTS		Date inspected	Weather Conditions		Week4	
Sunday:	0.00"				Week 1	
Monday:	0.00"	+		+		
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Week 2	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"	3/5/2019	19/4 Mostly Sunny			
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.52"					
					Week 3	
Sunday:	NA					
Monday Tuesday	NA					
Wednesday	NA NA					
Thursday	NA					
Friday	NA					
Saturday	NA					
		1		- I	1	
Complaints:	None					
Construction Sequencing:						
Which portion(s) (i.e. drainage ba	sins) of the site have had a temp	oorary or permanent ces	sation of grading, earthwork, or g	round disturbance in the	e last 14 days?	
Entire Site: Grading commer	nced (11/8/18). Grading terr	porarily ceased due	to winter conditions (3/5/19)			
Which portion(s) (i.e. drainage ba						
Entire Site: Grading commer						
What temporary or permanent sta		section are being impl	emented?			
Existing vegetation (11/8/18)	).					
SUMMARY QUESTIONS:						
Are approved entrances and adja	cent streets being maintained ac	lequately?				
No, See BMP Section	Also supplies the set of the set of the	A stress of solution	alter and the dama of the second state	which also a set of the set	1.16.0	
Are receiving waters adjacent to No, See BMP Section	the project free of any significar	it signs of erosion or se	diment that would be associated	with the construction act	avity?	
CHECKLIST QUESTIONS:						

CHECKLIST QUESTIONS: Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

#### No, Seefindings Section

Is dust associated with the construction activity	y adequately controlled on the site?
Ves	

# Comments:

### Comments:

Site was inactive as of the last inspection. Due to 8" of snow not all BMP's could be verified during the last inspection.

Findings / Corrective Actions (Date):

### Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP section.

2.) The t-posts along the entire run of perimeter silt fence needs to be spaced properly. They are currently too wide. Negus & Son's Construction was informed to complete by 11/29/18. Not done as of the last inspection. Negus & Son's Construction was reminded on 12/19/18, 1/23/19.

3.) Repair of equipment is underway adjacent to SB A. Oil was present on the ground and should be cleaned up. Negus & Son's Construction was informed to complete by 12/25/18, 1/23/19.

4.) A temporary diversion was installed draining into the waterway. The diversion is adjacent to SF 3. The inspector has recommended SF 3 be installed to protect the waterway as of the inspection on 12/22/19. Negus & Son's Construction was reminded on 1/23/19.

5.) A temporary entrance is being used off of N 2nd St. Rock needs added to the entrance. Negus & Son's Construction was informed to complete by 1/15/19. Due to winter conditions the inspector could not verify.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 1	Stabilized Construction Entrance	N Molley Street (EE11)	11/20/2018	Active	Yes	
Current Condition:	Fair Condition - 50% effective- Negus & Son's Construction installed the entrance prior to the inspection on 11/20/18 Rock needs added to the entrance. Negus & Son's Construction was informed to complete by 1/15/19. Due to winter conditions the inspector could not verify on 1/22/19.					
CW 1	Concrete Washout	Site	11/15/2018	Pending	No	
Current Condition:		hout will be recommende	d when paving is close to c	0	1	
D1	Temporary Diversion Ditch	(Z17-II17)	11/15/2018	Pending	Yes	
Current Condition:	Pending -					
	The diversion needs to be Negus & Son's Construct conditions the inspector of	ion was informed to comp	olete by 12/25/18. Not done ).	as of the last inspe	ection. Due to winte	
	Temporary Diversion					
D2	Ditch	(F25-P21)	11/15/2018	Pending	Yes	
	The diversion needs to be installed. Negus & Son's Construction was informed to complete by 12/25/18. Not done as of the last inspection. Due to winter conditions the inspector could not verify on 1/22/19.					
	conditions the inspector of	ould not verify on 1/22/19	).			
	Temporary Diversion					
D3	Temporary Diversion Ditch	(P21-R20)	11/15/2018	Pending	Yes	
D3 Current Condition:	Temporary Diversion Ditch Pending - The diversion needs to be Negus & Son's Construct conditions the inspector of	(P21-R20) e installed.	11/15/2018 Diete by 12/25/18. Not done			
-	Temporary Diversion Ditch Pending - The diversion needs to be Negus & Son's Construct	(P21-R20) e installed.	11/15/2018 Diete by 12/25/18. Not done			
Current Condition:	Temporary Diversion Ditch Pending - The diversion needs to be Negus & Son's Construct conditions the inspector of Temporary Diversion Ditch Pending - The diversion needs to be	(P21-R20) e installed. ion was informed to comp ould not verify on 1/22/19 (B26-D26) e installed.	11/15/2018 Dete by 12/25/18. Not done 0. 11/15/2018	as of the last inspe Pending	ection. Due to winte	
Current Condition: D4 Current Condition:	Temporary Diversion Ditch         Pending -         The diversion needs to be         Negus & Son's Construct conditions the inspector of Temporary Diversion Ditch         Pending -         The diversion needs to be         Negus & Son's Construct conditions the inspector of Ditch	(P21-R20) e installed. ion was informed to comp ould not verify on 1/22/19 (B26-D26) e installed. ion was informed to comp ould not verify on 1/22/19	11/15/2018	as of the last inspe Pending	ection. Due to winte	
Current Condition: D4 Current Condition: EM 1	Temporary Diversion Ditch Pending - The diversion needs to be Negus & Son's Construct conditions the inspector of Temporary Diversion Ditch Pending - The diversion needs to be Negus & Son's Construct conditions the inspector of Erosion Control Matting	(P21-R20) e installed. ion was informed to comp ould not verify on 1/22/19 (B26-D26) e installed. ion was informed to comp ould not verify on 1/22/19 (C22-DD11)	11/15/2018	as of the last inspe Pending	ection. Due to winte	
Current Condition: D4 Current Condition:	Temporary Diversion Ditch Pending - The diversion needs to be Negus & Son's Construct conditions the inspector of Temporary Diversion Ditch Pending - The diversion needs to be Negus & Son's Construct conditions the inspector of	(P21-R20) e installed. ion was informed to comp ould not verify on 1/22/19 (B26-D26) e installed. ion was informed to comp ould not verify on 1/22/19 (C22-DD11)	11/15/2018	as of the last inspe Pending as of the last inspe	ection. Due to winte Yes ection. Due to winte	

Current Condition:	Pending -						
	The basin should be ins	The basin should be installed.					
	Negus & Son's Construction was informed to complete by 12/25/18. Not done as of the last inspection. Due to winter conditions the inspector could not verify on 1/22/19.						
SB B	Sediment Basin	R20	. 11/15/2018	Pending	Yes		
Current Condition:	Pending -	1120	11/13/2010		103		
	The basin should be installed.						
		ction was informed to comp could not verify on 1/22/19		one as of the last inspec	ction. Due to winter		
SF 1	Silt fence	(A25-II18)	11/8/2018	Active	Yes		
Current Condition:	Fair Condition - Negus &	Son's Construction install	ed the silt fence prior to	the inspection on 11/8	/18.		
	<ol> <li>Negus &amp; Son's Construction was informed to complete by 11/29/18. Not done as of the last inspection. Negus &amp; Son's Construction was reminded on 12/19/18. Due to winter conditions the inspector could not verify on 1/22/19.</li> <li>Negus &amp; Son's Construction was informed to complete by 1/15/19. Due to winter conditions the inspector could not verify on 1/22/19.</li> <li>Negus &amp; Son's Construction was informed to complete by 1/15/19. Due to winter conditions the inspector could not verify on 1/22/19.</li> <li>Negus &amp; Son's Construction was informed to complete by 1/15/19. Due to winter conditions the inspector could not verify on 1/22/19.</li> </ol>						
SF 2	verify on 1/22/19.	114.0	11/0/0010	A ative	N-		
Current Condition:	Silt fence	II18 & Son's Construction insta	11/8/2018	Active	No		
SF 3	Silt fence		11/29/2018	Pendina	o/ to. Yes		
Current Condition:	Pending -		11/20/2010		100		
	Negus & Son's Construc	be installed to cover the ad stion was informed to comp ded on 12/19/18, 1/23/19.	·	one as of the last inspec	ction. Negis		
SF 4	Silt fence	(DD1-DD14)	11/8/2018	Active	Yes		
Current Condition:	The silt fence needs repaired. Negis & Son's Construction will be informed to complete when winter conitions allow as of the inspection						
STR	done as of the last inspe		11/0/2010	A etitue	Ne		
Current Condition:	Streets Good Condition- No ma	Site	11/8/2018	Active	No		
		168th Street/					
SWPPP Sign	Misc/Other	Military Road	12/17/2018	Active	No		
Current Condition:	Good Condition- The ins	spector installed the sign du	iring the inspection on 1	2/17/18.			
spector Signature:	Jane auleed			Reviewed By:	But Sul		