	E&A- 2	005.030.000				
Inspector: Patrick Pierce						
Project Name:		3				
For Week Ending:		The Heritage 1/9/2010				
Candings	100	20/				
Grading: Sanitary Sewer:	100					
Storm Sewer:	100					
Paving:	100	100%				
Seeding:		100%				
Utilities:		100% 40%				
Overall Development:	40	1%				
RAINFALL AMOUNTS:	Amount in inches	Date inspected				
				Week 1		
Sunday:	0.00"					
Monday Tuesday	0.10" 0.00"	12/15/09				
Wednesday	0.00"	12/13/09				
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
	0.00"			Week 2		
Sunday: Monday	0.00" 0.00"					
Tuesday	0.00"					
Wednesday	0.49"					
Thursday	0.55"					
Friday	0.61"					
Saturday	0.10"					
Sunday:	0.00"			Week 3		
Monday:	0.00"	12/29/09				
Tuesday	0.00"	12/23/03				
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.09"					
Sunday:	0.10"			Week 4 / 5		
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.30"					
Thursday	0.03"					
Friday	0.00"					
Saturday	0.00"					
	None					
Complaints:						
Construction Sequencing:						
Which portion(s) (i.e. drainage basins) of the days?	site have had a temporary or pe	ermanent cessation of gra	ading, earthwork, or g	round disturbance in the last 14		
Entire site, grading completed 7/2006 a	nd site seeded 9/5/06.					
Which portion(s) (i.e. drainage basins) of the	site do not have grading, earthy	vork, or ground disturbar	nce scheduled in the r	next 14 days? :		
Entire site, grading completed 7/2006 a	nd site seeded 9/5/06.					
		1				
What temporary or permanent stabilization m	easures listed in this section ar	e being implemented?		<u> </u>		
Wetlands Mitigation Seeding (5/31/06),	Slones Seeded/Mattad (9/3	80/06) Temp Soodod	1 (0/5/06) Pa-Saad	ad 5/21/07 Ra-Sooded POW		
on 9/5/07 & 11/14/07, Erosion seeded i		олоо, тетр. эееаеа	1 ( <i>0/3/00)</i> , Re-3eed	od 3/21/07, Ne-Seeded ROW		
Comments:						

## Comments:

## Comments

Home construction is the only activity on site.

An inspection was not conducted after snow events from 12/23/09 - 12/26/09 due to very dangerous driving and winter conditions even though the perception was over a ½" due to heavy amounts of snow in the metro area. An inspection will be conducted as soon as conditions allow for each site. Please contact Zach Jilek w/ E&A Consulting Group, Inc. with any questions. (402-895-4700).

Inspections on 12/15/09 and 12/21/09 were drive thru inspections. Site was covered with one foot of snow and all BMP's appeared to be in good working condition unless otherwise noted.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) No maintenance required in the BMP section.

	,	1			_	75
Unique Name	Туре	Location	Projected Install  Date	Status	Maintance	Description of Maintenance/Activity:
Onique Name	Construction	N41d00m00s	Date	Status	Walltance	Maintenance/Activity.
CE 1	Entrance	W96d00m00s		Removed		Repairs Needed/Planned:
Current Condition:	Entrance was been					
	Construction	N41d00m00s				
CE 2	Entrance	W96d00m00s	6/1/2006	Active	No	_
Current Condition:	Good Condition- 75	% Effective (Rocked or	1 6/2006 by Sudbeck)			
00.4	On dian and Danie	N41d00m00s		Damasad		
SB 1 Current Condition:	Sediment Basin	W96d00m00s	constructed when schoo	Removed		4
Current Condition:	Removed per Gradi		onstructed when school	i site is graded.		
		N41d00m00s				
SB 2  Current Condition:	Sediment Basin	W96d00m00s		Removed		-
Current Condition:	Removed per Gradi	ing Modification				
		N41d00m00s				
SB 3	Sediment Basin	W96d00m00s	11/14/2005	Active	No	
Current Condition:	Good Condition- 19					
	Cleanout 9/24/07 by					
00.4	0 " 10 "	N41d00m00s	44/44/0005			
SB 4	Sediment Basin	W96d00m00s	11/14/2005	Active	No	-
Current Condition:	Good Condition- 20	% FIIIea				
		N41d00m00s				1
SB 5	Sediment Basin	W96d00m00s	11/2/2005	Active	No	
Current Condition:	Good Condition- 23					
	Outlet Pipe recompa	acted by Sudbeck due	to undermining- 4/2006			
		N41d00m00s				
SB 6	Sediment Basin	W96d00m00s	11/2/2005	Active	No	4
Current Condition:	Good Condition- 36 Cleanout 10/2006 b					
	Cleariout 10/2000 b	•	,			4
05.4	071.5	N41d00m00s				
SF 1 Current Condition:	Silt Fence	W96d00m00s	pection on 10/15/09 due	Removed		-
Current Condition.	Removed by Nick v	verillinghon phor to insp	pection on 10/15/09 due	to derise vegetation.		
		N41d00m00s				1
SF 2	Silt Fence	W96d00m00s	10/24/2005	Active	No	
Current Condition:	Good Condition					
	-Nick Wenninghoff I	repaired silt fence prior	to inspection on 12/10/0	9.		
		N41d00m00s				=
SF 3	Silt Fence	W96d00m00s	10/24/2005	Active	No	
Current Condition:	Good Condition		•		•	7
	-Nick Wenninghoff I	repaired silt fence prior	to inspection on 12/10/0	9.		
		NI44 -100 00-			1	4
SF 4	Silt Fence	N41d00m00s W96d00m00s		Removed	No	
Current Condition:	Removed due to pe		1	Nontoveu	INU	1
Can contained.		N41d00m00s				1
SF 5	Silt Fence	W96d00m00s	6/19/2006	Active	No	
Current Condition:	Good Condition					
		N41d00m00s	1			
SF 6	Silt Fence	W96d00m00s	11/9/2005	Active	No	4
Current Condition:	Good Condition	reneived eilt f	to increation 40/10/0	00		
	-Nick vvenningnoff i	repaired siit tence prior	to inspection on 12/10/0	ıs.		
		N41d00m00s				
STR	Street Cleaning	W96d00m00s	2/26/2007	Active	No	_
Current Condition:	Good Condition- No	major signs of track of	f.			
		I	1			4
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No	
Current Condition:	Good Condition:	i aigii uii aite	0-13-00	TOUAG	INU	†
Canada Gondalion	156th and Clevelan	d Blvd				
-			-	<del>7.</del> / /1l.		╡
	Fire		4	Zodnavy L. Jilik		
Inspector Signature:			Reviewed By:	0 0		