E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 P •8 tel 402.895.4700 fax 402.895.3599 www.eacg.com E&A CONSULTING GROUP, INC. Zachary A. Jilek, CPESC, CISEC ENGINEERING • PLANNING • FIELD SERVICES Erosion Control Specialist- Manager E&A- P2005.030.000 Stage Inspector: Scott Fryant 3 The Heritage NER110495 Project Name: 9/8/2012 For Week Ending: East of 156th Street and North and South of Rainwood Road- Bennington, NE 68007 (Douglas County) Project Location: Grading: 100% Sanitary Sewer: Storm Sewer: 100% 100% Paving: 100% Seeding: 100% Utilities: 100% Overall Development: 40% RAIN FALL AMOUNTS Amount in inches Date inspected Week Sunday: 0.00" Monday 0.00" Tuesday 0.00" Wednesday 0.00" Thursday 0.00 Friday 0.00" Saturday 0.11" Weel Sunday: 0.00" Monday 0.00" 08/21/12 Tuesday 0.00" Wednesday 0.00" Thursday 0.00" Friday 0.36" Saturday 0.69' Sunday: 0.00" 08/26/12 Monday 0.00' Tuesday 0.00' Wednesday 0.00' Thursday 0.00 Friday 0.00 Saturday 0.00" Sunday: 0.00" Monday 0.00' Tuesday 0.00" Wednesday 0.00" Thursday 0.00" Friday).01 Saturday 0.00" Week 5 Sunday: N/A N/A Monday N/A N/A Tuesday N/A N/A Wednesday N/A N/A Thursday N/A N/A N/A Friday N/A N/A N/A Saturday None Complaints: Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessal ion of grading, earthwork, or ground disturbance in the last 14 days? Entire site, grading completed 7/2006 and site seeded 9/5/06.

	10 1 11 11 11				
Which portion(s) (i.e. drainage basins) of the	e site do not have grading, ear	thwork, or ground distur	bance scheduled in the nex	kt 14 days? :	
Entire site, grading completed 7/2006	and site seeded 9/5/06				
Entire site, grading completed 7/2000					
What temporary or permanent stabilization	measures listed in this section	are being implemented?			
Wetlands Mitigation Seeding (5/31/06	i). Slopes Seeded/Matted ((8/30/06), Temp, See	ded (9/5/06). Re-Seede	ed 5/21/07. Re-Seeded	d ROW on 9/5/07
& 11/14/07, Erosion seeded in variou					
			1	1	
Commentes					
Comments:					
Comments: Home construction is active on site.					
Findings / Corrective Actions (Date	a).				
Findings / Corrective Actions (Date					
1) No required maintenance in the BM	•				
· · ·					
Unique Name	Туро	Location	Projected Install Date	Status	Maintenance
	Type Construction	N41d00m00s	Date	Status	Wallitenance
CE 1	Entrance	W96d00m00s		Removed	
Current Condition:	Entrance has been p				
CE 2	Construction Entrance	N41d00m00s W96d00m00s		Removed	
Current Condition:	Entrance has been p			rtointorou	
CW 1	Concrete Washout	Lot 20	6/14/2010	Active	No
Current Condition:	Good condition- Washout was cleane	d out and silt fence w	as repaired prior to insp	pection on $8/21/12$ by	Cassi with
	Newstyle.			50000000000000000000000000000000000000	
CW 2	Concrete Washout	Lot 162	6/14/2010	Active	No
Current Condition:	Good condition-	ed prior to inspection	on 8/21/12 by Cassi wit	th Newstyle	
	Silt Tence was repaire	ed phor to inspection		III Newstyle.	
Lot 1	Silt Fence	Lot 1		Removed	
Current Condition:			prior to inspection on 5/2		
Lot 2	Silt Fence	Lot 2		Removed	
Current Condition:			inspection on 8-21-12.		
Lot 5	Silt Fence	Lot 5		Removed	
Current Condition:	Lot has been sodded	by Dreamscape Hon	nes prior to inspection of	on 7/6/11.	
Lot 76	Miscellaneous	Lot 76		Removed	
Current Condition:	Lot has been sodded	by Regency Homes	prior to inspection on 0	6/11/12.	
Lot 91 Current Condition:	Silt Fence	Lot 91	s prior to inspection on	Removed	
ourrent condition.	Lot has been souded	by Home Enterprise.		//o/11.	
Lot 110	Berm	Lot 110		Removed	
Current Condition:			prior to inspection on 6/2		
			·		
Lot 195	Silt Fence	Lot 195	4/15/2012	Active	No
Current Condition:	Good condition- Required work was o	completed prior to insr	pection on 5/22/12 by C	commercial Seeding	
				inimerenar occurrig.	
SB 1	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:			constructed when scho		
		N41d00m00s		5	
SB 2	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Removed per Gradin				
		N41d00m00s	1		
SB 3	Sediment Basin	W96d00m00s	11/14/2005	Active	No
Current Condition:	Good Condition- 20%				
	Cleanout 9/24/07 by	N41d00m00s			1
SB 4	Sediment Basin	W96d00m00s	11/14/2005	Active	No

Current Condition:	Good Condition- 22% Filled							
SB 5	Sediment Basin	N41d00m00s W96d00m00s	11/2/2005	Active	No			
Current Condition:	Good Condition-26% Filled Outlet Pipe recompacted by Sudbeck due to undermining- 4/2006							
SB 6	Sediment Basin	N41d00m00s W96d00m00s		Removed				
Current Condition:	Sediment Basin 6 has been removed prior to inspection on 5/2/12 by Ed Jochim. Area was also se and matted.							
SF 1	Silt Fence	N41d00m00s W96d00m00s		Removed				
Current Condition:	Removed by Nick Wenninghoff prior to inspection on 10/15/09 due to dense vegetation.							
SF 2	Silt Fence	N41d00m00s W96d00m00s		Removed				
Current Condition:	Removed- Part of Silt fence #2 has been removed from the Heritage SWPPP due to New SWPPP Bennington Elementary School project. Silt fence has been removed by Mike Woodward prior to inspection on 4/26/11.							
SF 3	Silt Fence	N41d00m00s W96d00m00s		Removed				
Current Condition:	Removed Silt fence has been removed by Mike Woodward prior to inspection on 4/26/11.							
SF 4	Silt Fence	N41d00m00s W96d00m00s		Removed	No			
Current Condition:	Removed due to per		1	1				
SF 5	Silt Fence	N41d00m00s W96d00m00s		Removed				
Current Condition:	Removed Silt fence has been removed by Mike Woodward prior to inspection on 4/26/11.							
SF 6	Silt Fence	N41d00m00s W96d00m00s		Removed				
Current Condition:	Removed Silt fence has been removed by Mike Woodward prior to inspection on 4/26/11.							
STR	Street Cleaning	N41d00m00s W96d00m00s	2/26/2007	Active	N			
Current Condition:	Good Condition- No	major signs of track o	ff and/or run off noted	during last inspection.				
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	N			
Current Condition:	Good Condition: 156th and Cleveland	Blvd						
یکی د tor Signature:	t Fryant		Reviewed By:	Zachany K. Jil	dc			