E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Zachary A. Jilek, CPESC, CISE Environmental Services Dept.			Engineering Answers		
Environmental Services Dept.	wanayer	E&A- P2021.	065.002		
Inspector: Joe Manning					Stage
<u> </u>		Westri	dge Estates		<del>                                     </del>
Project Name:		1			
		68073			
For Week Ending:	Highway	00073			
Project Location:	підпімау	77 West of Eagle D	rive - Yutan, NE (Saund	ers County)	
Grading:	99%				
Sanitary Sewer:	0%				
Storm Sewer:	0%				
Paving:	95%				
Seeding:	25%				
Utilities:	0%				
Overall Development:	10%				
	1 .076	·			1
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
TAIN FALL AMOUNTS	, and and mitterials	Date inspected	Weather Conditions	Time	Week
Sunday:	0.00"				VICCK
Monday:	0.00"	11/28/2022	Sunny 56	3:10 PM	
Tuesday:	0.00"	1112012022			
Wednesday:	0.00"				
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
	None				
Complaints:					
	<u>'</u>				
Construction Sequencing:					
Which portion(s) (i.e. drainage basins	s) of the site have had a tempora	ary or permanent cessa	ition of grading, earthwork, or	ground disturbance in the	e last 14 days?
01:	17/0000\				
Stripping and grading began (5/1	17/2022).				
Which portion(s) (i.e. drainage basins	) of the cite do not have gradin	a conthucid or around	l disturbance ashedulad in th	n novt 14 dovo?	
Stripping and grading began (5/1	<u> </u>	g, earthwork, or ground	a disturbance scheduled in th	e next 14 days?	
Suppling and grading began (5/	1772022).				
What temporary or permanent stabilize	ration measures listed in this se	ection are being implem	nented?		
Existing vegetation (5/17/2022).				ong ROWs (11/16/2022	D)
Existing vegetation (3/17/2022).	Decumy/matting near the c	onstruction entrance	5 (9/ 14/2022). Decuing aid	ong 100003 (11/10/2022	-)-
Checklist Questions:					
Are receiving waters adjacent	to the project free of any	significant signs o	f erosion or sediment th	at would be associate	ed with the
construction activity?	to the project nee or any	aigiiiileant aigna 0	i crosion or seameth th	iat would be associat	CO WILLI LIE
Yes					
Create Corrective Action?					
N/A					

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

#### **Create Corrective Action?**

No - See Findings section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Voo

**Create Corrective Action?** 

N/A

Are construction entrances and adjacent streets being maintained adequately?

Nο

**Create Corrective Action?** 

No - See BMP Section.

Is dust associated with the construction activity adequately controlled on the site?

Yes

**Create Corrective Action?** 

N/A

# Comments:

#### Comments:

1.) Site was inactive during the last inspection.

### Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

- 1.) Some maintenance is required in the BMP section.
- 2.) Inactive portions of the site should be stabilized. Summit Development was informed to complete by 8/16/22. Not done as of last inspection. Summit Development was reminded on 9/14/22, 11/9/22. Summit Development seeded the ROWs prior to the inspection on 11/16/22. E&A inspector will monitor for vegetative establishment.

Unique Name	Type	Location	Projected Install Date	Status	Maintenan		
CE 01	Construction Entrance	H16		Removed			
Current Condition:	Removed - Summit Development paved the construction entrance prior to the inspection on 8/9/22.						
D 01	Diversion	J11 to H9	6/7/2022	Pending	No		
<b>Current Condition:</b>	Pending - The diversion will be installed once grading in the area requires. E&A inspector will continue to mo						
D 02	Diversion	J11 to I13	6/7/2022	Pending	No		
<b>Current Condition:</b>	Pending - The diversion	on will be installed on	ce grading in the area require	s. E&A inspector w	ill continue to m		
D 03	Diversion	J10 to I7		Removed	<u> </u>		
D 03  Current Condition:	Removed - The grade	r installed the diversion	on prior to the first inspection due to grading activity.		version has beer		
	Removed - The grade	r installed the diversion			version has beer		
Current Condition:	Removed - The grade removed prior to the ir	r installed the diversionspection on 7/19/22 On Site	due to grading activity. 6/7/2022	on 5/17/22. The div	1		
Current Condition:  MS 01	Removed - The grade removed prior to the ir Material Storage	r installed the diversionspection on 7/19/22 On Site	due to grading activity. 6/7/2022	on 5/17/22. The div	1		
Current Condition:  MS 01  Current Condition:	Removed - The grade removed prior to the ir  Material Storage Pending - The material  Portable Toilet	on Site On Site On Site	due to grading activity. 6/7/2022	on 5/17/22. The div	No		
MS 01 Current Condition: PT 01	Removed - The grade removed prior to the ir  Material Storage Pending - The material  Portable Toilet	on Site On Site On Site	due to grading activity.  6/7/2022  Illed as necessary.	on 5/17/22. The div	No		
Current Condition:  MS 01  Current Condition:  PT 01  Current Condition:	Removed - The grade removed prior to the ir  Material Storage Pending - The material Portable Toilet Removed - Summit De	r installed the diversion aspection on 7/19/22  On Site all storage will be instaled on Site evelopment removed H6 to G8	due to grading activity.  6/7/2022  Illed as necessary.	Pending  Removed inspection on 9/28 Removed	No //22.		

STR	Streets	ADJ and Internal Streets	5/17/2022	Active	Yes			
Current Condition:	Fair Condition -	Fair Condition -						
	Track off from the site and the internal streets should be cleaned.  Summit Development was informed to complete by 9/15/22. Not done as of the last inspection. Summit Development was reminded on 11/9/22.							
SWPPP Sign 01	SWPPP Signs	Adjacent to CE 1	6/7/2022	Active	No			
Current Condition:		,	SWPPP sign during the ir		INO			
W 01	Straw Wattles	H16	9/14/2022	Active	No			
Current Condition:		*****	ed the straw wattles prior					
W 02	Straw Wattles	H16	9/14/2022	Active	No			
Current Condition:			** * * * * * * * * * * * * * * * * * * *					
Current Condition.		Good Condition - Summit Development installed the straw wattles prior to the inspection on 9/14/22.  East side of internal						
W 03 - 05	Straw Wattles	streets	11/16/2022	Active	No			
Current Condition:		Good Condition - Summit Development installed straw wattles along the east side of the street prior to the inspection on 11/16/22.						
WO 01	Concrete Washout	On site		Removed				
Current Condition:	Removed - Summit D	Removed - Summit Development removed the concrete washout prior to the inspection on 8/9/22.						
WO 02	Concrete Washout	On site		Removed				
Current Condition:	Removed - Summit D	Removed - Summit Development removed the concrete washout prior to the inspection on 9/14/22.						
WS 01	Waste Storage Area	On site		Removed				
Current Condition:	Removed - Summit Development removed the waste storage prior to the inspection on 8/22/22.							
Certification Statement:	I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations.							
Inspector Signature:	If Mun			Reviewed By:	Set Sol			