

**Engineering Answers** 

10909 Mill Valley Road, Suite 100 • Omaha, NE 68154-3950 P 402.895.4700 • F 402.895.3599 www.eacq.com

#### Dear Homeowner:

The SID has contracted concrete work to be done on the streets in your SID. A contractor will be on site to do work which includes removing the existing concrete that is damaged and replacing it with new pavement.

Throughout the course of this project, there could be some minimal damage done to yards and or sprinkler systems. The contractor that is on site will be responsible for replacing any damaged sprinkler lines and/or heads. They will also be replacing any sod that is torn up while on site. Once the new sod is laid, it will be the responsibility of the homeowner at each lot to water the new sod until it has re-established itself.

Before starting the work on site, each contractor must put in a call and have all the utilities in the area located. You might notice some areas in your yard that have been flagged and/or spray painted. This does not indicate the area in which they will be working. It is just to give them an idea of what kind of utilities are in the area that could possibly be hit while the contractor is on site working.

All work that is completed in public Right-of-Way and follow City of Omaha and Sarpy County specifications.

The work in your SID should not take longer than 30 days to complete. Please let me know if you have any questions or concerns on this at all.

Thank You,

**Nelson C Flores** 

Construction Administration Tech.

Engineering Answers...by assisting our clients

E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 • Omaha, NE 68154 402.895.4700 (o)

eacg.com




# **ARBOR VIEW**


## 2023 STREET RECONSTRUCTION

SID NO. 561 DOUGLAS COUNTY, NEBRASKA

# APPROXIMATE BID QUANTITIES

ITEM	DESCRIPTION	QUANTITY	UNIT
1	CONCRETE PAVEMENT REPAIR, LARGE AREA	150	SY
2	CONCRETE PAVEMENT REPAIR, SMALL AREA	348	SY
3	FULL DEPTH SAW CUT EXISTING PAVEMENT	829	LF
4	ADJUST MANHOLE TO GRADE	1	EA
5	REMOVE & REPLACE PCC SIDEWALK	32	SF
6	REMOVE & REPLACE PCC CURB RAMP	77	SF
7	CONSTRUCT DETECTABLE WARNING PANEL (1)	8	SF
8	REMOVE AND REPLACE FAULTY SUBGRADE	25	TN





VICINITY MAP

### **INDEX OF SHEETS**

SHEET NO.	DESCRIPTION
1	COVER
2	SOUTH
3	NORTH
4	WEST
5	TOTAL QUANTITIES
6	COMPOSITE MAP



### APPLICANT

SID 561
Marc Stodola, Chairman
10250 Regency Cir #300
Omaha, NE 68114
P: 402.397.5500
F: 402.397.4853

**INSPECTOR** 

mlapuzza@pheblaw.com

E & A Consulting Group, Inc
Randall L. Pierce, P.E.
10909 Mill Valley Road, Suite 100
Omaha, NE 68154
P: 402.895.4700
F: 402.895.3599
rpierce@eacg.com

E & A Consulting Group, Inc Teresa Wooten, P.E. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 P: 402.895.4700 F: 402.895.3599 twooten@eacg.com

**DESIGNER** 


### CONTRACTOR

	ı
	ı
	ı
	ı
	ı
	ı
	ı
	ı
	ı
	ı
	ı
	ı
	ı
	ı
1	ı

ARBOR VIEW 2023 STREET RECONSTRUCTION SID SEI


E & A CONSULTING GROUP, INC. Engineering • Planning • Environmental & Field Services





2023 STREET RECONSTRUCTION												
AREA NO.	NO. POURS	SAW CUT L.F.	CURB L.F.	WIDTH	Х	LENGTH	LARGE AREA EST S.Y.	SMALL AREA EST S.Y	NOTES			
1	1	88	19	10.3	х	10.3		11.7				
				27.0	х	12.5		37.5				
7	1	61	36	12,5	х	36.0		50.0				
8	1	40		10.0	х	10.0		11.1				
9	1	39		10.0	х	10.0		11.1				
10	1	99		12.5	х	22.0		30.6	Adjust Manhole			
12	1	64		9.0	х	23.0		23.0				
13	1	41	10	10.0	х	16.0		17.8				

	2023 STRE	ET RI	ECO	NSTR	UCTION	
AREA NO.	TYPE	APPR	APPROX. DIMEN.		EST S.F.	NOTES
А	Curb Ramp	7	х	11	77.0	ADA Plate - Cast Iron
В	Sidewalk	4	х	8	32.0	




SMALL AREA CONCRETE PAVEMENT REPAIR DETAIL NOT TO SCALE



		Ш	I			
Proj No:	2013,175,011		Rev	Revisions		
Date:	02/24/2023		Date	Description		
Designed By:						Ē
Drawn By:	ESN					SOUTH
Scale:	1" = 250"					
Sheet:	2 of 6					
Evan	Evan Nelson		l``	124/2023 17	1:38 AM	2/24/2023 11:38 AM K-\Projects\2013\17

ARBOR VIEW 2023 STREET RECONSTRUCTION SID 561

E & A CONSULTING GROUP, INC.
Engineering • Planning • Environmental & Field Services
TIOSO MAIN Judge Road, Suite 61514
PRINAME 4022 514700 • Charles 18154
PRINAME 4022 51470 • Charles 18154






ARBOR VIEW 2023 STREET RECONSTRUCTION SID 561


E & A CONSULTING GROUP, INC.
Engineering • Planning • Environmental & Field Services
TOBOR MINING ACCESSION • Plan ALT 86154
PINNE 4022854700 • Plan 4022855399







			20	23 STRE	ET	RECONS	TRUCTION		
AREA NO.	NO. POURS	SAW CUT L.F.	CURB L.F.	WIDTH	Х	LENGTH	LARGE AREA EST S.Y.	SMALL AREA EST S.Y	NOTES
4	2	74		12.5	Х	25.0		34.7	
5	1	61	36	35.5	Х	12.5		49.3	
6	1	74	48	12.5	Х	48.0	66.7		
(11)	1	49	24	12.5	Х	24.0		33.3	



SMALL AREA CONCRETE PAVEMENT REPAIR DETAIL NOT TO SCALE



E & A CONSULTING GROUP, INC.
Engineering • Planning • Environmental & Field Services
TIGGS HOUSE ALTER SETS PROME ALCE STATES PROME ACCUSES, 2599

(e•a) ARBOR VIEW 2023 STREET RECONSTRUCTION SID 561



	2023 STREET RECONSTRUCTION											
AREA NO.	NO. POURS	SAW CUT L.F.	CURB L.F.	WIDTH	Х	LENGTH	LARGE AREA EST S.Y.	SMALL AREA EST S.Y	NOTES			
1	1	88	19	10.3	х	10,3		11.7				
				27.0	х	12.5		37.5				
2	1	15	7	7.5	х	3,5		2.9				
3	2	75		12.5	х	25.0		34.7				
4	2	74		12.5	х	25.0		34.7				
5	1	61	36	35.5	х	12.5		49.3				
6	1	74	48	12.5	х	48.0	66.7					
7	1	61	36	12.5	х	36.0		50.0				
8	1	40		10.0	х	10.0		11.1				
9	1	39		10.0	х	10.0		11.1				
10	1	99		12.5	х	22.0		30.6	Adjust Manhole			
11	1	49	24	12.5	х	24.0		33.3				
12	1	64		9.0	х	23.0		23.0				
13	1	41	10	10.0	х	16.0		17.8				
14	2	50	30	25.0	х	30.0	83.3					

2023 STREI		EET RI	ECO	NSTR	UCTION	
AREA NO.	TYPE	APPROX. DIMEN.			EST S.F.	NOTES
А	Curb Ramp	7	Х	11	77.0	ADA Plate - Cast Iron
В	Sidewalk	4	х	8	32.0	



E & A CONSULTING GROUP, INC

E & A CONSULTING GROUP, INC.
Engineering • Planning • Environmental & Field Services
TUBBO A 102286 ATTOR • Plannia, NE 88154
Phone 402285 ATTOR • Plan 402285 ATTOR

ARBOR VIEW 2023 STREET RECONSTRUCTION SID 561

TOTAL QUANTITIES

 Prog No.
 2013.17.5.011
 Revisions

 Date:
 0,272.420.23
 AAA
 Date:
 Description

 Description
 TAMM
 TAMM
 Description



