E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

E&A- P2020.056.003

Inspector: Luke Antholz					Stage	
Project Name:	5	5Ds Transportation Trucking Terminal IA - 39263 -38898				
For Week Ending:		51501				
Project Location:	Southwest of S 29t					
Grading:	85%					
Sanitary Sewer:	0%					
Storm Sewer:	0%					
Paving:	0%					
Seeding:	0%					
Utilities:	0%					
Overall Development:	<mark>5%</mark>					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time		
					Week 1	
Sunday	0.06"					
Monday	0.00"					

Tuesday	0.00"	07/13/21	Mostly Cloudy 88/65	11:00 AM	
Wednesday	0.02"				
Thursday	0.46"				
Friday	0.00"				
Saturday	0.00"				
Complaints:	None				

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Rough grading began on site (6/29/21).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Rough grading began on site (6/29/21).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (6/29/21).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes

Create Corrective Action? N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes **Create Corrective Action?**

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes **Create Corrective Action?** N/A

Are construction entrances and adjacent streets being maintained adequately?

Yes Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes Create Corrective Action?

Comments: Comments: 1.) Site was active for rough grading during the last inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 01	Construction Entrance	J3	7/13/2021	Active	No	
Current Condition:	Good Condition - 95% Effective - Rich Engdahl installed the construction entrance on site prior to the inspection on 7/13/21					
CW 01	Concrete Washout	On Site	8/29/2021	Pending	No	
Current Condition:		I be installed once paving/				
IP 01	Inlet Protection	F13	8/29/2021	Pending	No	
Current Condition: IP 02		ill be installed once the inle			NI-	
Current Condition:	Inlet Protection	F3	6/29/2021	Active	No mondation is pooded at 1	
Current Condition:	Active - This is an existing inlet located off of 21st Avenue. Due to the location of the inlet no BMP recommendation is needed at th time. E&A inspector will continue to monitor.					
IP 03	Inlet Protection	F2	6/29/2021	Active	No	
Current Condition:	Active - This is an existing inlet located off of 21st Avenue. Due to the location of the inlet no BMP recommendation is needed at the					
	time. E&A inspector will continue to monitor.					
IP 04	Inlet Protection	M4	8/29/2021	Pendina	No	
Current Condition:		ill be installed once the inle				
IP 05	Inlet Protection	P3	6/29/2021	Active	No	
Current Condition:	Active - This is an existing	inlet located off of 21st Av	enue. Due to the location o	of the inlet no BMP recom	mendation is needed at	
	time. E&A inspector will continue to monitor.					
IP 06	Inlet Protection	P2	6/29/2021	Active	No	
Current Condition:	Active - This is an existing	inlet located off of 21st Av	enue. Due to the location o	f the inlet no BMP recom	mendation is needed at	
	time. E&A inspector will co	ontinue to monitor.				
IP 07	Inlet Protection	Q4	8/29/2021	Pending	No	
Current Condition:	Pending - The inlet filter w	ill be installed once the inle	t is installed and the inlet i	s at or below grade.		
IP 08	Inlet Protection	U4	8/29/2021	Pending	No	
Current Condition:	Pending - The inlet filter w	ill be installed once the inle	t is installed and the inlet i	s at or below grade.		
IP 09	Inlet Protection	X3	6/29/2021	Active	No	
Current Condition:	Active - This is an existing inlet located off of 21st Avenue. Due to the location of the inlet no BMP recommendation is needed at the					
	time. E&A inspector will co	ontinue to monitor.		-		
IP 10	Inlet Protection	X2	6/29/2021	Active	No	
Current Condition:		inlet located off of 21st Av	enue. Due to the location o	of the inlet no BMP recom	mendation is needed at	
	time. E&A inspector will co					
IP 11	Inlet Protection	Y6	8/29/2021	Pending	No	
Current Condition:		ill be installed once the inle			N	
IP 12	Inlet Protection	Y7	8/29/2021	Pending	No	
Current Condition: IP 13		ill be installed once the inle Y8			No	
	Inlet Protection	ill be installed once the inle	8/29/2021	Pending	INO	
Current Condition: IP 14	Inlet Protection	Y11	8/29/2021	Pending	No	
Current Condition:		ill be installed once the inle			INU	
PB 01	Portable toilet	On Site	7/6/2021	Active	No	
Current Condition:		gdahl installed/secured a po				
SF 01 - SF 06				Active	No	
SF 01 - SF 06	Silt Fence	G3 to B15	6/29/2021	Active	No	
Current Condition:	Silt Fence Good Condition - Rich En	G3 to B15 gdahl installed SF 01 to SF	6/29/2021 06 prior to the inspection	on 6/29/21.	-	
	Silt Fence Good Condition - Rich En Silt Fence	G3 to B15 gdahl installed SF 01 to SF B16 to P12	6/29/2021 06 prior to the inspection 6/29/2021	on 6/29/21. Active	No No	
Current Condition: SF 07 - SF 12	Silt Fence Good Condition - Rich En Silt Fence	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF	6/29/2021 06 prior to the inspection 6/29/2021	on 6/29/21. Active	-	
Current Condition: SF 07 - SF 12 Current Condition:	Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF S12 to Z5	6/29/2021 6/29/2021 6/29/2021 12 prior to the inspection 6/29/2021	on 6/29/21. Active on 6/29/21. Active	No	
Current Condition: SF 07 - SF 12 Current Condition: SF 13 - SF 17	Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF	6/29/2021 6/29/2021 6/29/2021 12 prior to the inspection 6/29/2021	on 6/29/21. Active on 6/29/21. Active	No	
Current Condition: SF 07 - SF 12 Current Condition: SF 13 - SF 17 Current Condition:	Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF S12 to Z5 gdahl installed SF 13 to SF	6/29/2021 06 prior to the inspection 6/29/2021 12 prior to the inspection 6/29/2021 17 prior to the inspection 6/29/2021	on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active	No No	
Current Condition: SF 07 - SF 12 Current Condition: SF 13 - SF 17 Current Condition: SF 18 - SF 22	Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF S12 to Z5 gdahl installed SF 13 to SF Z3 to K3	6/29/2021 06 prior to the inspection 6/29/2021 12 prior to the inspection 6/29/2021 17 prior to the inspection 6/29/2021	on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active	No No	
Current Condition: SF 07 - SF 12 Current Condition: SF 13 - SF 17 Current Condition: SF 18 - SF 22 Current Condition: STR Current Condition:	Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Streets Good Condition - No majo	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF S12 to Z5 gdahl installed SF 13 to SF Z3 to K3 gdahl installed SF 18 to SF On Site r signs of track off.	6/29/2021 06 prior to the inspection 6/29/2021 12 prior to the inspection 6/29/2021 17 prior to the inspection 6/29/2021 22 prior to the inspection 6/29/2021	on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active	No No No No	
Current Condition: SF 07 - SF 12 Current Condition: SF 13 - SF 17 Current Condition: SF 18 - SF 22 Current Condition: STR Current Condition: SWPPP Sign 01	Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Streets Good Condition - No majo SWPPP Signs	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF S12 to Z5 gdahl installed SF 13 to SF Z3 to K3 gdahl installed SF 18 to SF On Site	6/29/2021 06 prior to the inspection 6/29/2021 12 prior to the inspection 6/29/2021 17 prior to the inspection 6/29/2021 22 prior to the inspection	on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active on 6/29/21.	No No No	
Current Condition: SF 07 - SF 12 Current Condition: SF 13 - SF 17 Current Condition: SF 18 - SF 22 Current Condition: STR Current Condition:	Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Streets Good Condition - No majo	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF S12 to Z5 gdahl installed SF 13 to SF Z3 to K3 gdahl installed SF 18 to SF On Site r signs of track off.	6/29/2021 06 prior to the inspection 6/29/2021 12 prior to the inspection 6/29/2021 17 prior to the inspection 6/29/2021 22 prior to the inspection 6/29/2021	on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active	No No No No	
Current Condition: SF 07 - SF 12 Current Condition: SF 13 - SF 17 Current Condition: SF 18 - SF 22 Current Condition: STR Current Condition: SWPPP Sign 01	Silt Fence Good Condition - Rich En Streets Good Condition - No majo SWPPP Signs Pending -	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF S12 to Z5 gdahl installed SF 13 to SF Z3 to K3 gdahl installed SF 18 to SF On Site r signs of track off. Adjacent to CE 1	6/29/2021 06 prior to the inspection 6/29/2021 12 prior to the inspection 6/29/2021 17 prior to the inspection 6/29/2021 22 prior to the inspection 6/29/2021	on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active	No No No No	
Current Condition: SF 07 - SF 12 Current Condition: SF 13 - SF 17 Current Condition: SF 18 - SF 22 Current Condition: STR Current Condition: SWPPP Sign 01	Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Streets Good Condition - No majo SWPPP Signs	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF S12 to Z5 gdahl installed SF 13 to SF Z3 to K3 gdahl installed SF 18 to SF On Site r signs of track off. Adjacent to CE 1	6/29/2021 06 prior to the inspection 6/29/2021 12 prior to the inspection 6/29/2021 17 prior to the inspection 6/29/2021 22 prior to the inspection 6/29/2021	on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active	No No No No	
Current Condition: SF 07 - SF 12 Current Condition: SF 13 - SF 17 Current Condition: SF 18 - SF 22 Current Condition: STR Current Condition: SWPPP Sign 01	Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Streets Good Condition - No majo SWPPP Signs Pending - SWPPP sign should be in	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF S12 to Z5 gdahl installed SF 13 to SF Z3 to K3 gdahl installed SF 18 to SF On Site r signs of track off. Adjacent to CE 1	6/29/2021 06 prior to the inspection 6/29/2021 12 prior to the inspection 6/29/2021 17 prior to the inspection 6/29/2021 22 prior to the inspection 6/29/2021 7/6/2021	on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active Pending	No No No No Yes	
Current Condition: SF 07 - SF 12 Current Condition: SF 13 - SF 17 Current Condition: SF 18 - SF 22 Current Condition: STR Current Condition: SWPPP Sign 01	Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Streets Good Condition - No majo SWPPP Signs Pending - SWPPP sign should be in	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF S12 to Z5 gdahl installed SF 13 to SF Z3 to K3 gdahl installed SF 18 to SF On Site r signs of track off. Adjacent to CE 1	6/29/2021 06 prior to the inspection 6/29/2021 12 prior to the inspection 6/29/2021 17 prior to the inspection 6/29/2021 22 prior to the inspection 6/29/2021 7/6/2021	on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active Pending	No No No No Yes	
Current Condition: SF 07 - SF 12 Current Condition: SF 13 - SF 17 Current Condition: SF 18 - SF 22 Current Condition: STR Current Condition: SWPPP Sign 01	Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Streets Good Condition - No majo SWPPP Signs Pending - SWPPP sign should be in The E&A inspector will ins	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF S12 to Z5 gdahl installed SF 13 to SF Z3 to K3 gdahl installed SF 18 to SF On Site r signs of track off. Adjacent to CE 1	6/29/2021 06 prior to the inspection 6/29/2021 12 prior to the inspection 6/29/2021 17 prior to the inspection 6/29/2021 22 prior to the inspection 6/29/2021 7/6/2021	on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active Pending	No No No No Yes	
Current Condition: SF 07 - SF 12 Current Condition: SF 13 - SF 17 Current Condition: SF 18 - SF 22 Current Condition: STR Current Condition: SWPPP Sign 01	Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Silt Fence Good Condition - Rich En Streets Good Condition - No majo SWPPP Signs Pending - SWPPP sign should be in	G3 to B15 gdahl installed SF 01 to SF B16 to P12 gdahl installed SF 07 to SF S12 to Z5 gdahl installed SF 13 to SF Z3 to K3 gdahl installed SF 18 to SF On Site r signs of track off. Adjacent to CE 1	6/29/2021 06 prior to the inspection 6/29/2021 12 prior to the inspection 6/29/2021 17 prior to the inspection 6/29/2021 22 prior to the inspection 6/29/2021 7/6/2021	on 6/29/21. Active on 6/29/21. Active on 6/29/21. Active on 6/29/21. Pending Pending	No No No No Yes	