E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering An

Environmental Services Dep		Engineerii	Engineering Answers				
		P2024.163	3.001	_			
Inspector: Ethan Anderson					Stage 1		
Project Name:	Aca	1					
For Week Ending:		<u>??</u> 7/13/2					
Project Location:	South 24th St and Pic	South 24th St and Richard Downing Ave, Council Bluffs, IA, (Pottawattamie County)					
		nard Downing Ave, oc			51501		
Grading:	5%						
Sanitary Sewer:	0%				-		
Storm Sewer:	0%						
Paving:	0%						
Seeding:	0%						
Utilities:	0%						
Overall Development:	1%						
	.,,						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	Storm Event Times		
					Week		
Sunday:	0.00"						
Monday:	0.00"						
Tuesday:	0.00"	7/9/2024	Sunny 87/64	1:10 PM			
Wednesday:	0.00"						
Thursday:	0.00"						
Friday:	0.00"						
Saturday:	0.00"						
Complaints:	None						
Construction Sequencing: Which portion(s) (i.e. drainage basi	ins) of the site have had a tempora	ry or permanent cessation	of grading, earthwork, or	ground disturbance in the	e last 14 days?		
Grading bagan (7/9/24)							
Grading began (7/9/24). Which portion(s) (i.e. drainage basi	ins) of the site do not have grading	earthwork, or ground dist	turbance scheduled in the	next 14 days?			
	ine, et ale one de not nave grading	, ear annora, or ground dist	and benediated in the				
Grading began (7/9/24). What temporary or permanent stat	pilization measures listed in this se	ction are being implemente	ad?				
Existing Vegetation (7/9/24).		saon are song implemente					
Existing vegetation (7/9/24).							
Checklist Questions:							
	cent to the project free of ar	y significant signs of	erosion or sediment	that would be associ	ated with the construction		
activity?							
Yes							
Create Corrective Action?							
N/A							
	an a second and a second s	line di se annular de Lite	the stine is sufficient to	the must be the soul of the te			

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion. Yes

Create Corrective Action?

N/A

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly? Yes

Create Corrective Action?

4.) Are construction entrances and adjacent streets being maintained adequately? Yes

Create Corrective Action?

N/A

5.) Is dust associated with the construction activity adequately controlled on the site? Yes

Create Corrective Action?

Comments: Comments: Site was active for grading during most recent inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 2	Construction Entrance	S 24th St.	7/9/2024	Active	No		
Current Condition:	Good Condition - Graham						
IF1 - IF3	Inlet filter	W side of site	8/13/2024	Pending	No		
Current Condition:	Pending - Inlet filters will			- Chung			
IF4 - IF7	Inlet filter	Center of site	8/13/2024	Pending	No		
Current Condition:	Pending - Inlet filters will			- i onding			
IF8 - IF10	Inlet filter	Center of site	8/13/2024	Pending	No		
Current Condition:	Pending - Inlet filters will						
IF11 - IF13	Inlet filter	Center of site	8/13/2024	Pending	No		
Current Condition:	Pending - Inlet filters will be installed as necessary.						
IF14	Inlet filter	East entrance to site	8/13/2024	Pending	No		
Current Condition:	Pending - Inlet filter will b						
IF15	Inlet filter	NW entrance to site	8/13/2024	Pending	No		
Current Condition:	Pending - Inlet filter will b		0.10.2021				
MS 1	Material Storage	S 24th St.	7/9/2024	Active	No		
Current Condition:	Good Condition - Graham						
PT X	Portable Toilet	Onsite	8/13/2024		No		
Current Condition:	Pending - Portable toilets			Pending			
Current Condition.	Temporary Sediment	will be installed as field:	55aiy.				
ST A	Trap	SE corner of site	8/13/2024	Pending	No		
Current Condition:	Pending - Sediment trap v			rending			
SF 1	Silt Fence	N side of site	7/9/2024	Active	No		
Current Condition:	Good Condition - Graham						
SF 2	Silt Fence	W side of site	7/9/2024	Active	No		
Current Condition:	Good Condition - Graham						
SF 3	Silt Fence	S side of site	7/9/2024	Active	No		
Current Condition:	Good Condition - Graham	Construction installed t	he silt fence prior to	the inspection on 7/	9/24.		
SF 4	Silt Fence	E side of site	7/9/2024	Active	No		
Current Condition:	Good Condition - Graham	Construction installed t	he silt fence prior to	the inspection on 7/	9/24.		
SF 5	Silt Fence	E side of site	7/9/2024	Active	No		
Current Condition:	Good Condition - Graham	Construction installed a	section of the silt f	ence prior to the insp	ection on 7/9/24.		
STR	Streets	Onsite	7/9/2024	Pending	No		
Current Condition:	Good Condition - Streets	were in good condition d	luring last inspectio	n.			
SWPPP Sign	SWPPP Sign		8/13/2024	Pending	Yes		
Current Condition:	Pending -						
	SWPPP sign should be installed.						
	E&A inspector will install	when sign comes in.					
WO 1	Concrete Washout	S 24th St.	8/13/2024	Pending	No		
Current Condition:	Pending - Concrete wash		cessary.				
WS 1	Waste Storage	Onsite	8/13/2024	Pending	No		
Current Condition:	Pending - Waste storage						
ertification Statement	"I certify, under penalty of la accordance with a system or submitted. Based on my inc gathering the information, th am aware that there are sig for knowing violations."	w, that this document and lesigned to assure that qua uiry of the person or person ne information submitted is	all attachments were alified personnel prop ons who manage the s, to the best of my kn	berly gathered and eva system or those perso owledge and belief, tru	luated the information ns directly responsible fo ue, accurate, and comple		
ector Signature:	In Caston			Reviewed By:	Costo Sul		