E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dent Manager

Engineering Answers

	200-0	E&A - P2022.267	.001						
Inspector: Shaun McGuire					Stage				
•		Alternate	Rain		U				
		CSW-2023		1					
Project Name:									
For Week Ending:		5/6/20	23						
					68064				
Project Location:	N 264th Stree	t and N 264th Circle -	Valley, NE (Douglas Co	ounty)	00004				
Grading:	5%								
Sanitary Sewer:	0%								
Storm Sewer:	0%								
Paving:	0%								
Seeding:	0%								
Utilities:	0%								
Overall Development:	0%								
	Amount in tonthe	Data inapacted	Weather Conditions	Time	[
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Week 1				
Sunday:	0.00"				week i				
Monday	0.00"		1	1					
Tuesday	0.00"								
Wednesday	0.00"								
Thursday	0.00"	5/4/2023	Sunny 83/45	2:45 PM	Dein 1:00 DM 5:00 DM				
Friday Saturday	0.35" 0.08"				Rain 1:00 PM - 5:00 PM				
Saturday	0.00								
Complaints:									
Complaints.									
Construction Sequencing:									
Which portion(s) (i.e. drainage bas	ins) of the site have had a t	emporary or perman	ent cessation of grading	a. earthwork. or ar	ound disturbance in the				
last 14 days?			· · · · · · · · · · · · · · · · · · ·	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
Grading the site (4/27/23).									
Which portion(s) (i.e. drainage bas	ins) of the site do not have	grading, earthwork,	or ground disturbance s	scheduled in the n	ext 14 days?				
Grading the site (4/27/23).									
What temporary or permanent stab	ilization measures listed in	this section are beir	ng implemented?						
Existing vegetation (4/27/23).									
Checklist Questions:	for a formation of a second state of a	- I	late an entry doubt the second	terrentian anti-iter					
Are receiving waters adjacent to the project Yes	free of any significant signs of ero	sion or sediment that wou	id be associated with the cons	truction activity?					
Create Corrective Action?									
N/A									
Have disturbed areas been seeded or otherw	vise stabilized as required? List in:	active portions of the proje	ct and if stabilization measure	are adequate or neede	d to prevent erosion				
Yes					a to provent crosion.				
Create Corrective Action?									
N/A									
Are waste materials (concrete, construction	material hazardous etc.) being m	anaged properly?							
Yes	material, nazardodo, etc./ being m	anaged property .							
Create Corrective Action?									
N/A									
Are construction entrances and adjacent struction	eets being maintained adequately?	•							
Yes	eets being maintained adequately								
Create Corrective Action?									
N/A									
Is dust associated with the construction acti	vity adequately controlled on the s	ite?							
Is dust associated with the construction activity adequately controlled on the site? Yes									
Create Corrective Action?									
N/A									
Comments:									
Comments: The site was active during the most r	ecent inspection								

maintenance is needed in the	ate): ne BMP section.							
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CE 1	Construction Entrance	See SWPPP	5/4/2023	Pending	Yes			
Current Condition:	Pending - Construction entrance shoul Project Engineers were infor		r complete by 5/4/23. Not c	lone as of last ins	pection.			
IP X	Diversion	See SWPPP	5/4/2023	Pending	No			
Current Condition:	Pending - BMP will be installed when inlet is constructed and is at or below grade.							
MT X	Erosion Matting	See SWPPP	5/4/2023	Pending	No			
Current Condition:	Pending - BMP will be installed when work begins/ends in the area. E&A inspector will monitor.							
SF X	Silt Fence	Perimeter	5/4/2023	Pending	Yes			
	Silt fence should be installed Project Engineers were info		r complete by 5/4/23. Not c	lone as of last ins	pection.			
ST X	Silt Trap	On Site	5/4/2023	Pending	No			
Current Condition:	Pending -							
CW 1	Concrete Washout	On Site	5/4/2023	Pending	No			
Current Condition:	Pending - BMP will be instal		s in the area. E&A inspecto	r will monitor.				
CTD.	Chroata	N 264th Street and N	5/4/2023	A atiu a	No			
STR Current Condition:	Streets Good Condition - The streets	264th Circle	as of the $1/27/22$ increation	Active	No			
SG 1	SWPPP Notification Sign	On Site	5/4/2023	Pending	Yes			
Current Condition:	Pending -	On Sile	5/4/2023	Fending	165			
	SWPPP sign should be installed. SWPPP sign will be installed once it is available from the shop. Not done as of last inspection.							
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."							
			bmitting false information ir		ility			