E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

The site was active during the most recent inspection.



Zachary A. Jilek, CPESC, CISI Environmental Services Dent		E&A - P2022.2		gineering Answe	rs		
Inspector: Shaun McGuire		E&A - P2U22.2	.07.001		Stage		
Project Name:		Alterna CSW-20	te Rain 2307758		1		
For Week Ending:		7/22/	/2023				
Project Location:	N 264th Stre	N 264th Street and N 264th Circle - Valley, NE (Douglas County)					
•							
Grading:		%					
Sanitary Sewer:		%					
Storm Sewer:		%					
Paving:		% %					
Seeding: Utilities:		%					
Overall Development:		%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Week		
Sunday:	0.07"				Week		
Monday .	0.45"						
Tuesday	0.24"						
Wednesday	0.00"						
Thursday	0.00"	7/20/2023	Sunny 81/67	9:05 AM			
Friday Saturday	0.00" 0.20"						
Grading the site (4/27/23). What temporary or permanen Existing vegetation (4/27/23). Checklist Questions: Are receiving waters adjacent to the permanent	te basins) of the site do not have the stabilization measures listed project free of any significant signs of e	in this section are b	eing implemented?		ext 14 days?		
Yes Create Corrective Action?							
N/A							
Have disturbed areas been seeded or Yes Create Corrective Action? N/A	r otherwise stabilized as required? List	inactive portions of the pr	roject and if stabilization measur	re are adequate or needed	I to prevent erosion.		
Yes	ruction material, hazardous, etc.) being	managed properly?					
Create Corrective Action? N/A							
-	cent streets being maintained adequate	ly?					
No Create Corrective Action?							
No, See BMP section.							
	ion activity adequately controlled on th	e site?					
Yes			<u> </u>		<u> </u>		
Create Corrective Action? N/A							
IV/A							
Comments:							
Comments:							

Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
Some maintenance is needed in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 1	Construction Entrance	See SWPPP	5/4/2023	Pending	Yes		
Current Condition:	Pending -						
	Construction entrance should be installed.						
	Project Engineers were informed to have contractor complete by 5/4/23. Not done as of last inspection. Doug Bailey reminded on 6/15/23.						
IP X	Diversion	See SWPPP	5/4/2023	Pending	No		
Current Condition:	Pending - BMP will be instal	led when inlet is consti	ructed and is at or below g		-		
MT X	Erosion Matting	See SWPPP	5/4/2023	Pending	No		
Current Condition:	Pending - BMP will be installed when work begins/ends in the area. E&A inspector will monitor.						
SF X	Silt Fence	Perimeter	5/4/2023	Pending	Yes		
Current Condition:	Pending -			, ,			
	Silt fence should be installed. Project Engineers were informed to have contractor complete by 5/4/23. Not done as of last inspection. Doug Bailey reminded on 6/15/23.						
ST X	Silt Trap	On Site	5/4/2023	Danding	No		
Current Condition:	Pending - Sediment trap will		*, ,,	Pending	INU		
CW 1	Concrete Washout	On Site	5/4/2023	Pending	No		
Current Condition:	Pending - BMP will be instal						
Carront Condition.	I criding Divir will be motal	N 264th Street and N	o in the area. Last inopoet	or will intornicor.			
STR	Streets	264th Circle	5/4/2023	Active	No		
STR Current Condition:		264th Circle			No		
	Streets	264th Circle			No No		
Current Condition:	Streets Good Condition - The streets	264th Circle s were free of track out On Site	t as of the 4/27/23 inspection 7/6/2023	on. Active			
Current Condition: SG 1	Streets Good Condition - The street: SWPPP Notification Sign	264th Circle s were free of track out On Site ector installed the SWF w, that this document a coordance with a syste rated the information su stem or those persons to the best of my knownificant penalties for su	at as of the 4/27/23 inspection 7/6/2023 PPP sign during the 7/6/23 and all attachments were pain designed to assure that submitted. Based on my inquidirectly responsible for gawledge and belief, true, according to the submitted states of the sub	on. Active inspection. repared under my qualified personn- uiry of the person thering the inform curate, and comple	No el or ation, ete. I		