E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISE(En	gineering Answ	ers		
FIVITIMENTAL SELVICES LIPETI	WALIAUE	E&A - P2022.2	67.001				
Inspector: Shaun McGuire					Stage		
	Alternate Rain						
Project Name:		1					
For Week Ending:		8/19/	2023				
For Week Ending.		0/13/	2023				
Project Location:	N 264th S	treet and N 264th Circ	le - Valley, NE (Douglas C	County)	68064		
r roject Location.	14 20 4(11 0		valley, NE (Bouglas c	, ounty,			
Grading:		5%					
Sanitary Sewer:		0%					
Storm Sewer:		0%					
Paving:		0%					
Seeding:		0%					
Utilities: Overall Development:		0%					
Overall Development.		0 /6					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time			
					Week 1		
Sunday:	0.83"						
Monday Tuesday	0.00"			+	+		
Wednesday	0.00"						
Thursday	0.00"	8/17/2023	Sunny 81/56	9:00 AM			
Friday	0.00"						
Saturday	0.00"						
Construction Sequencing: Which portion(s) (i.e. drainage last 14 days? Grading the site (4/27/23). Which portion(s) (i.e. drainage Grading the site (4/27/23).	•						
What temporary or permanent s	etabilization moscurae lieta	nd in this saction are h	oing implemented?				
Existing vegetation (4/27/23).	stabilization measures liste	ed in this section are b	eing implemented:				
Checklist Questions:							
Are receiving waters adjacent to the pro Yes	eject free of any significant signs of	of erosion or sediment that w	rould be associated with the cor	nstruction activity?			
Create Corrective Action?							
N/A							
Have disturbed areas been seeded or of	therwise stabilized as required? Li	st inactive portions of the pr	oject and if stabilization measu	re are adequate or neede	ed to prevent erosion.		
Yes							
Create Corrective Action? N/A							
1471							
Are waste materials (concrete, construc	ction material, hazardous, etc.) bei	ng managed properly?					
Yes Create Corrective Action?							
N/A							
Are construction entremose and adjacen	st atracta balan maintained adams	talu2					
Are construction entrances and adjacer No	nt streets being maintained adequa	itely?					
Create Corrective Action?							
No, See BMP section. Is dust associated with the construction	activity adequately controlled on	the site?					
Yes	. assivity adequately controlled off	and onto					
Create Corrective Action?							
N/A							
Comments:							
Comments:							
The site was active during the mo	ost recent inspection.						

Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
Some maintenance is needed in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CE 1	Construction Entrance	See SWPPP	5/4/2023	Pending	Yes			
Current Condition:	Pending -							
	Construction entrance should be installed.							
	Project Engineers were informed to have contractor complete by 5/4/23. Not done as of last inspection. Doug Bailey was projected an 6/45/23, 7/37/23							
	reminded on 6/15/23, 7/27/2							
IP X	Diversion	See SWPPP	5/4/2023	Pending	No			
Current Condition:	Pending - BMP will be installed when inlet is constructed and is at or below grade.							
MT X	Erosion Matting	See SWPPP	5/4/2023	Pending	No			
Current Condition:	Pending - BMP will be installed when work begins/ends in the area. E&A inspector will monitor.							
SF X	Silt Fence	Perimeter	5/4/2023	Pending	Yes			
Current Condition:	Pending -							
	Silt fence should be installed.							
	Project Engineers were informed to have contractor complete by 5/4/23. Not done as of last inspection. Doug Bailey was							
	reminded on 6/15/23, 7/27/23							
ST X	Silt Trap	0 0:						
O I A	Oilt Hap	On Site	5/4/2023	Pending	No			
Current Condition:	Pending - Sediment trap will			Pending	No			
				Pending	No No			
Current Condition:	Pending - Sediment trap will Concrete Washout Pending - BMP will be install	be installed once grad On Site led when paving begin	ing begins in the area. 5/4/2023	Pending	-			
Current Condition: CW 1 Current Condition:	Pending - Sediment trap will Concrete Washout Pending - BMP will be install	be installed once grad On Site led when paving begin N 264th Street and N	ing begins in the area. 5/4/2023 s in the area. E&A inspecto	Pending or will monitor.	No			
Current Condition: CW 1 Current Condition: STR	Pending - Sediment trap will Concrete Washout Pending - BMP will be install Streets	be installed once grad On Site led when paving begin N 264th Street and N 264th Circle	ing begins in the area. 5/4/2023 s in the area. E&A inspect 5/4/2023	Pending or will monitor. Active	-			
Current Condition: CW 1 Current Condition: STR Current Condition:	Pending - Sediment trap will Concrete Washout Pending - BMP will be install Streets Good Condition - The streets	be installed once grad On Site led when paving begin N 264th Street and N 264th Circle s were free of track out	ing begins in the area. 5/4/2023 s in the area. E&A inspect 5/4/2023 as of the 4/27/23 inspecti	Pending or will monitor. Active on.	No No			
Current Condition: CW 1 Current Condition: STR Current Condition: SG 1	Pending - Sediment trap will Concrete Washout Pending - BMP will be install Streets Good Condition - The streets SWPPP Notification Sign	be installed once grad On Site led when paving begin N 264th Street and N 264th Circle s were free of track out On Site	ing begins in the area. 5/4/2023 s in the area. E&A inspect 5/4/2023 as of the 4/27/23 inspecti 7/6/2023	Pending or will monitor. Active on. Active	No			
Current Condition: CW 1 Current Condition: STR Current Condition: SG 1 Current Condition:	Pending - Sediment trap will Concrete Washout Pending - BMP will be install Streets Good Condition - The streets SWPPP Notification Sign Good Condition - E&A inspec	be installed once grad On Site led when paving begin N 264th Street and N 264th Circle s were free of track out On Site ector installed the SWF	ing begins in the area. 5/4/2023 s in the area. E&A inspect 5/4/2023 as of the 4/27/23 inspecti 7/6/2023 PP sign during the 7/6/23	Pending or will monitor. Active on. Active inspection.	No No			
Current Condition: CW 1 Current Condition: STR Current Condition: SG 1	Pending - Sediment trap will Concrete Washout Pending - BMP will be install Streets Good Condition - The streets SWPPP Notification Sign Good Condition - E&A inspe	be installed once grad On Site led when paving begin N 264th Street and N 264th Circle s were free of track out On Site ector installed the SWF w, that this document a	ing begins in the area. 5/4/2023 s in the area. E&A inspecte 5/4/2023 as of the 4/27/23 inspecti 7/6/2023 PP sign during the 7/6/23 and all attachments were p	Pending or will monitor. Active on. Active inspection. repared under my	No No			
Current Condition: CW 1 Current Condition: STR Current Condition: SG 1 Current Condition:	Pending - Sediment trap will Concrete Washout Pending - BMP will be install Streets Good Condition - The streets SWPPP Notification Sign Good Condition - E&A inspe "I certify, under penalty of law direction or supervision in accordance."	be installed once grad On Site led when paving begin N 264th Street and N 264th Circle s were free of track out On Site ector installed the SWF w, that this document a coordance with a syste	ing begins in the area. 5/4/2023 s in the area. E&A inspecto 5/4/2023 as of the 4/27/23 inspecto 7/6/2023 PP sign during the 7/6/23 and all attachments were pen designed to assure that	Pending or will monitor. Active on. Active inspection. repared under my qualified personne	No No No			
Current Condition: CW 1 Current Condition: STR Current Condition: SG 1 Current Condition:	Pending - Sediment trap will Concrete Washout Pending - BMP will be install Streets Good Condition - The streets SWPPP Notification Sign Good Condition - E&A inspe "I certify, under penalty of law direction or supervision in ac properly gathered and evaluation."	be installed once grad On Site led when paving begin N 264th Street and N 264th Circle s were free of track out On Site ector installed the SWF w, that this document a coordance with a syste ated the information su	ing begins in the area. 5/4/2023 s in the area. E&A inspecto 5/4/2023 as of the 4/27/23 inspecto 7/6/2023 PPP sign during the 7/6/23 and all attachments were p m designed to assure that abmitted. Based on my inq	Pending or will monitor. Active on. Active inspection. repared under my qualified personne	No No No el or			
Current Condition: CW 1 Current Condition: STR Current Condition: SG 1 Current Condition:	Pending - Sediment trap will Concrete Washout Pending - BMP will be install Streets Good Condition - The streets SWPPP Notification Sign Good Condition - E&A inspe "I certify, under penalty of law direction or supervision in ac properly gathered and evalue persons who manage the sy	be installed once grad On Site led when paving begin N 264th Street and N 264th Circle s were free of track out On Site ector installed the SWF w, that this document a coordance with a syste ated the information su stem or those persons	ing begins in the area. 5/4/2023 s in the area. E&A inspecto 5/4/2023 as of the 4/27/23 inspection 7/6/2023 PP sign during the 7/6/23 and all attachments were pen designed to assure that institted. Based on my inquirectly responsible for ga	Pending or will monitor. Active on. Active inspection. repared under my qualified personne uiry of the person thering the informa-	No No No or ation,			
Current Condition: CW 1 Current Condition: STR Current Condition: SG 1 Current Condition:	Pending - Sediment trap will Concrete Washout Pending - BMP will be install Streets Good Condition - The streets SWPPP Notification Sign Good Condition - E&A inspe "I certify, under penalty of lav direction or supervision in ac properly gathered and evalue persons who manage the sy the information submitted is,	be installed once grade On Site led when paving begin N 264th Street and N 264th Circle s were free of track out On Site ector installed the SWF w, that this document a coordance with a syste atted the information su stem or those persons to the best of my know	ing begins in the area. 5/4/2023 s in the area. E&A inspecto 5/4/2023 as of the 4/27/23 inspecto 7/6/2023 PP sign during the 7/6/23 and all attachments were p m designed to assure that ibmitted. Based on my inq directly responsible for ga	Pending or will monitor. Active on. Active inspection. repared under my qualified personne uiry of the person thering the inform curate, and comple	No No No or ation, ete. I			
Current Condition: CW 1 Current Condition: STR Current Condition: SG 1 Current Condition:	Pending - Sediment trap will Concrete Washout Pending - BMP will be install Streets Good Condition - The streets SWPPP Notification Sign Good Condition - E&A inspe "I certify, under penalty of law direction or supervision in ac properly gathered and evalue, persons who manage the sy the information submitted is, am aware that there are sign	be installed once grade On Site led when paving begin N 264th Street and N 264th Circle s were free of track out On Site ector installed the SWF w, that this document a coordance with a syste ated the information su stem or those persons t to the best of my know ifficant penalties for su	ing begins in the area. 5/4/2023 s in the area. E&A inspecto 5/4/2023 as of the 4/27/23 inspecto 7/6/2023 PP sign during the 7/6/23 and all attachments were p m designed to assure that ibmitted. Based on my inq directly responsible for ga	Pending or will monitor. Active on. Active inspection. repared under my qualified personne uiry of the person thering the inform curate, and comple	No No No or ation, ete. I			
Current Condition: CW 1 Current Condition: STR Current Condition: SG 1 Current Condition:	Pending - Sediment trap will Concrete Washout Pending - BMP will be install Streets Good Condition - The streets SWPPP Notification Sign Good Condition - E&A inspe "I certify, under penalty of lav direction or supervision in ac properly gathered and evalue persons who manage the sy the information submitted is,	be installed once grade On Site led when paving begin N 264th Street and N 264th Circle s were free of track out On Site ector installed the SWF w, that this document a coordance with a syste ated the information su stem or those persons t to the best of my know ifficant penalties for su	ing begins in the area. 5/4/2023 s in the area. E&A inspecto 5/4/2023 as of the 4/27/23 inspecto 7/6/2023 PP sign during the 7/6/23 and all attachments were p m designed to assure that ibmitted. Based on my inq directly responsible for ga	Pending or will monitor. Active on. Active inspection. repared under my qualified personne uiry of the person thering the inform curate, and comple	No No No or ation, ete. I			
Current Condition: CW 1 Current Condition: STR Current Condition: SG 1 Current Condition:	Pending - Sediment trap will Concrete Washout Pending - BMP will be install Streets Good Condition - The streets SWPPP Notification Sign Good Condition - E&A inspe "I certify, under penalty of law direction or supervision in ac properly gathered and evalue, persons who manage the sy the information submitted is, am aware that there are sign	be installed once grade On Site led when paving begin N 264th Street and N 264th Circle s were free of track out On Site ector installed the SWF w, that this document a coordance with a syste ated the information su stem or those persons t to the best of my know ifficant penalties for su	ing begins in the area. 5/4/2023 s in the area. E&A inspecto 5/4/2023 as of the 4/27/23 inspecto 7/6/2023 PP sign during the 7/6/23 and all attachments were p m designed to assure that ibmitted. Based on my inq directly responsible for ga	Pending or will monitor. Active on. Active inspection. repared under my qualified personne uiry of the person thering the inform curate, and comple	No No No or ation, ete. I			