E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599

www.eacg.com

re construction entrances and adjacent streets being maintained adequately?



Zachary A. Jilek, CPESC, CISEC

		E&A - P2022.2	067 002		
Increases: Jose Filipatos		E&A - P2022.2	.07.002	T	Stage
Inspector: Josh Ellington		111			
		Alternate Rain			1
Project Name:	CSW-202307758				
For Week Ending:		11/4/2023			68064
Project Location:	N 264th Street and N 264th Circle - Valley, NE (Douglas County)			ounty)	
			, , , , , , , , , , , , , , , , , , ,	3,	
Grading:		5%			
Sanitary Sewer:		0%			
Storm Sewer:		0%			
Paving:		0%			
Seeding:		0%			
Utilities:		0%			
Overall Development:		0%			
·					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"				
Thursday:	0.00"	11/2/2023	Sunny 59/42	11:45 AM	
Friday:	0.00"				
Saturday:	0.00"				
Complaints:					
Construction Sequencing:					
Which portion(s) (i.e. drainage	basins) of the site have had	a temporary or perman	ent cessation of grading, e	earthwork, or ground di	sturbance in the last 14
days? Grading the site (4/27/23).					
	basins) of the site of a set bas			and all and the Alban are as A. A. al	
Which portion(s) (i.e. drainage	basins) of the site do not have	ve grading, earthwork, (or ground disturbance sch	eaulea in the next 14 a	ays?
Grading the site (4/27/23).					
What temporary or permanent	stabilization measures listed	in this section are beir	ig implemented?		
Existing vegetation (4/27/23).					
Checklist Questions:	alout from all annual controls and all and all and all and all and all annual and all all and all and all and all all and all all and all all and all all all and all all all all all all all all all al	anadan an andi	lal has appearing and collective and the	etion cetivity.	
Are receiving waters adjacent to the pro Yes	oject iree of any significant signs of	erosion or sealment that wou	iu de associated with the constru	ction activity?	
Create Corrective Action?					
N/A					
	· · · · · · · · · · · · · · · · · · ·				
Have disturbed areas been seeded or o	therwise stabilized as required? List	inactive portions of the proje	ct and if stabilization measure ar	e adequate or needed to preve	ent erosion.
Yes					
Create Corrective Action? N/A					
1 1// 1					
Are waste materials (concrete, construc	ction material, hazardous, etc.) being	managed properly?			
Yes					
Create Corrective Action?					
N/A					

Create Corrective Action? No, See BMP section. Is dust associated with the construction activity adequately controlled on the site? Yes N/A Comments: Comments: The site was inactive during the most recent inspection. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): Some maintenance is needed in the BMP section. Unique Name Type Location **Projected Install Date** Status Maintenance See SWPPP CF 1 Construction Entrance 5/4/2023 Pending **Current Condition:** Construction entrance should be installed. Project Engineers were informed to have contractor complete by 5/4/23. Not done as of last inspection. Doug Bailey was reminded on 6/15/23, 7/27/23, 8/24/23, 10/20/23 IP X Diversion See SWPPP 5/4/2023 Pending **Current Condition:** Pending - BMP will be installed when inlet is constructed and is at or below grade. MT X Erosion Matting See SWPPP Pending 5/4/2023 **Current Condition:** Pending - BMP will be installed when work begins/ends in the area. E&A inspector will monitor. Silt Fence SF X Perimeter 5/4/2023 Pendina **Current Condition:** Pending -Silt fence should be installed. Project Engineers were informed to have contractor complete by 5/4/23. Not done as of last inspection. Doug Bailey was reminded on 6/15/23, 7/27/23, 8/24/23, 10/20/23 ST X Silt Trap On Site 5/4/2023 Pending **Current Condition:** Pending - Sediment trap will be installed once grading begins in the area. CW 1 Concrete Washout On Site 5/4/2023 Pending **Current Condition:** Pending - BMP will be installed when paving begins in the area. E&A inspector will monitor.

Good Condition - E&A inspector installed the SWPPP sign during the 7/6/23 inspection. **Current Condition:** "I certify, under penalty of law, that this document and all attachments were prepared under my **Certification Statement:** direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations." Jel 6

Streets

SWPPP Notification Sign

N 264th Street and N

264th Circle

On Site

Good Condition - The streets were free of track out as of the 4/27/23 inspection.

5/4/2023

7/6/2023

Inspector Signature:

STR

Current Condition:

SG 1

Reviewed By:

Active

Active

No

No

Yes

No

No

No

No

Get See