E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com

E & A CONSULTING GROUP, INC.

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

		E&A - P2022.26	67.002						
Inspector: Josh Ellington		Stage							
Project Name:		1							
For Week Ending:		11/11/2023							
Project Location:	N 264th S	68064							
Project Location: N 264th Street and N 264th Circle - Valley, NE (Douglas County) 68064									
Grading:		5%							
Sanitary Sewer:		0%							
Storm Sewer:		0%							
Paving:		0%							
Seeding:		0%							
Utilities:		0%							
Overall Development:		0%							
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time					
					Week 1				
Sunday:	0.00"								
Monday:	0.00"	11/6/2023	Mostly cloudy 52	9:10 AM					
Tuesday:	0.01"								
Wednesday:	0.00"								
Thursday:	0.00"								
Friday:	0.00"								
Saturday:	0.00"								
	<u>_</u>								
Complaints:									
Construction Sequencing:									
Which portion(s) (i.e. drainage I days?	basins) of the site have had a	temporary or permane	nt cessation of grading, ea	rthwork, or ground dis	sturbance in the last 14				

Grading the site (4/27/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading the site (4/27/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (4/27/23).

## Checklist Questions:

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

4.) Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?  No, See BMP section.									
No, See BMP Section.									
5 ) is dust associated with the construction	activity adequately controlled on the s	ito?							
5.) Is dust associated with the construction activity adequately controlled on the site? Yes									
Create Corrective Action?									
N/A									
Comments:									
Comments:									
The site was inactive during the mos	st recent inspection								
	•								
Findings / Corrective Actions (Dat	•								
Findings / Corrective Actions (Dat Some maintenance is needed in the									
Some maintenance is needed in the	BIMP Section.								
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance				
CE 1	Construction Entrance	See SWPPP	5/4/2023	Pending	Yes				
Current Condition:	Pending -								
	Construction entrance should be installed.								
	Project Engineers were informed to have contractor complete by 5/4/23. Not done as of last inspection. Doug Bailey was								
	reminded on 6/15/23, 7/27/23, 8/24/23, 10/20/23								
CW 1	Concrete Washout	On Site	5/4/2023	Pending	No				
Current Condition:	Pending - BMP will be installed				140				
IP X	Diversion	See SWPPP	5/4/2023	Pendina	No				
Current Condition:	Pending - BMP will be installed			J	NO				
MT X	Erosion Matting See SWPPP 5/4/2023 Pending No								
Current Condition:	Pending - BMP will be installed when work begins/ends in the area. E&A inspector will monitor.								
SF X	Silt Fence	Perimeter	5/4/2023	Pending	Yes				
Current Condition:	Pending -								
	Silt fence should be installed.								
	Project Engineers were informed to have contractor complete by 5/4/23. Not done as of last inspection. Doug Bailey was reminded on 6/15/23, 7/27/23, 8/24/23, 10/20/23								
	Terrificaed off 6/15/25, 1121/25	0, 0/24/23, 10/20/23							
SG 1	SWPPP Notification Sign	On Site	7/6/2023	Active	No				
Current Condition:	Good Condition - E&A inspec								
ST X	Silt Trap	On Site	5/4/2023	Pending	No				
Current Condition:	Pending - Sediment trap will I		***************************************	i chaing	110				
Current Condition.	, sharing Seamhent trap will h	N 264th Street and N	g sognio in the area.						
STR	Streets	264th Circle	5/4/2023	Active	No				
Current Condition:	Good Condition - The streets		s of the most recent inspec	7.04.70	140				
Current Condition.	Good Colidition - The streets	were nee or track out a	s of the most recent inspec	tion.					
Certification Statement:	"I certify, under penalty of law	that this document and	d all attachments were prer	pared under my					
Continuation Statement.									
	direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or								
	persons who manage the system or those persons directly responsible for gathering the information,								
	the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I								
	am aware that there are significant penalties for submitting false information including the possibility								
	of fines and imprisonment for knowing violations."								
	<u> </u>	-	-						
	11/2-								
l	JLE				Coto See				
Inspector Signature:				Reviewed By:					