E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

		E&A - P2022.2	67.002			
Inspector: Josh Ellington		Alterna			Stage	
		1				
Project Name:		CSW-20	2307758		I	
For Week Ending:						
Project Location:	N 264th	12/16/2023 N 264th Street and N 264th Circle - Valley, NE (Douglas County)				
			• • • • • • • • • • • • • • • • • • •		68064	
Grading:		5%				
Sanitary Sewer:		0%				
Storm Sewer:		0%				
Paving:		0%				
Seeding:		0%				
Utilities:		0%				
Overall Development:		0%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time		
		Bate moperiou			Week	
Sunday:	0.00"					
Monday:	0.00"	12/11/2023	Sunny 25	9:10 AM		
Tuesday:	0.00"					
Wednesday:	0.00"					
Thursday:	0.01"					
Friday:	0.22" (06:00)					
Saturday:	0.06" (03:00)					
Construction Sequencing: Which portion(s) (i.e. drainage	e basins) of the site have had	a temporary or permane	nt cessation of grading, e	arthwork, or ground d	listurbance in the last 14	
days? Grading the site (4/27/23).						
Which portion(s) (i.e. drainage	basing) of the site do not be	ve greding earthwork a	r ground disturbance oab	adulad in the next 14	dava2	
	a basins) of the site do not ha	ve grading, earthwork, o	r ground disturbance sch	equied in the next 14 (uays ?	
Grading the site (4/27/23).		n an				
What temporary or permanent Existing vegetation (4/27/23).	stabilization measures listed	i in this section are bein	g implemented?			
Existing vegetation (4/27/23).						
Checklist Questions:						
1.) Are receiving waters adjacent to th	e project free of any significant signs	of erosion or sediment that we	ould be associated with the cons	truction activity?		
Yes				,,,,,,		
Create Corrective Action?						
N/A						
2.) Have disturbed areas been seeded	or otherwise stabilized as required?	List inactive portions of the pro	iest and if stabilization measure	are adequate or peeded to	arevent erection	
Yes	or otherwise stabilized as required?	List mactive portions of the pro	gect and it stabilization measure	are adequate or needed to	prevent erosion.	
Create Corrective Action?						
N/A						
3.) Are waste materials (concrete, con: No	struction material, hazardous, etc.) b	eing managed properly?				
INO Create Corrective Action?						
No - see Finding section						
4.) Are construction entrances and ad	jacent streets being maintained adeq	uately?				
No				the second s		

Create Corrective Action?
No - see BMP section
5.) Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A
Comments:
Comments:
The site was inactive during the most recent inspection

The site was inactive during the most recent inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date): 1.) Some maintenance is needed in the BMP section. 2.) Stained soils should be removed by the grading equipment. Doug Bailey was informed to complete by 11/20/23. Not done as of last inspection. Doug Bailey was reminded on 12/11/23.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 1	Construction Entrance	See SWPPP	5/4/2023	Pending	Yes		
Current Condition:	Pending -						
	Construction entrance should be installed.						
	Project Engineers were informed to have contractor complete by 5/4/23. Not done as of last inspection. Doug Bailey was						
	reminded on 6/15/23, 7/27/23	3, 8/24/23, 10/20/23					
CW 1	Concrete Washout	On Site	5/4/2023	Pending	No		
Current Condition:	Pending - BMP will be installe	-			110		
	Diversion	See SWPPP	5/4/2023	Pendina	No		
Current Condition:	Pending - BMP will be installe			J			
MT X	Erosion Matting	See SWPPP	5/4/2023	Pending	No		
Current Condition:	Pending - BMP will be installe			0	1		
SF X	Silt Fence	Perimeter	5/4/2023	Pending	Yes		
Current Condition:	Pending -			<u>_</u>			
	Project Engineers were inform	med to have contractor	complete by 5/4/23. Not dor	ne as of last inspec	tion. Doug Bailey was		
	reminded on 6/15/23, 7/27/23			ne as of last inspec	tion. Doug Bailey was		
SG 1	SWPPP Notification Sign	3, 8/24/23, 10/20/23 On Site	7/6/2023	Active	tion. Doug Bailey was		
Current Condition:	reminded on 6/15/23, 7/27/23	3, 8/24/23, 10/20/23 On Site	7/6/2023	Active			
Current Condition: ST X	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspec Silt Trap	3, 8/24/23, 10/20/23 On Site ctor installed the SWPP On Site	7/6/2023 P sign during the 7/6/23 insr 5/4/2023	Active			
Current Condition:	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspec	3, 8/24/23, 10/20/23 On Site tor installed the SWPP On Site be installed once gradin	7/6/2023 P sign during the 7/6/23 insr 5/4/2023	Active pection.	No		
Current Condition: ST X Current Condition:	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspec Silt Trap Pending - Sediment trap will	3, 8/24/23, 10/20/23 On Site tor installed the SWPP On Site be installed once gradin N 264th Street and N	7/6/2023 P sign during the 7/6/23 insr 5/4/2023	Active pection. Pending	No No		
Current Condition: ST X Current Condition: STR	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspec Silt Trap Pending - Sediment trap will Streets	3, 8/24/23, 10/20/23 On Site ctor installed the SWPP On Site be installed once gradin N 264th Street and N 264th Circle	7/6/2023 P sign during the 7/6/23 insp 5/4/2023 g begins in the area. 5/4/2023	Active pection. Pending Active	No		
Current Condition: ST X Current Condition:	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspec Silt Trap Pending - Sediment trap will	3, 8/24/23, 10/20/23 On Site ctor installed the SWPP On Site be installed once gradin N 264th Street and N 264th Circle	7/6/2023 P sign during the 7/6/23 insp 5/4/2023 g begins in the area. 5/4/2023	Active pection. Pending Active	No No		
Current Condition: ST X Current Condition: STR Current Condition:	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspec Silt Trap Pending - Sediment trap will Streets Good Condition - The streets	3, 8/24/23, 10/20/23 On Site ctor installed the SWPP On Site be installed once gradin N 264th Street and N 264th Circle	7/6/2023 P sign during the 7/6/23 insp 5/4/2023 g begins in the area. 5/4/2023 as of the most recent inspect	Active pection. Pending Active tion.	No No		
Current Condition: ST X Current Condition: STR	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspec Silt Trap Pending - Sediment trap will Streets	3, 8/24/23, 10/20/23 On Site Cor installed the SWPP On Site be installed once gradin N 264th Street and N 264th Circle were free of track out a	7/6/2023 P sign during the 7/6/23 insp 5/4/2023 g begins in the area. 5/4/2023 as of the most recent inspected d all attachments were prep	Active pection. Pending Active tion.	No No		
Current Condition: ST X Current Condition: STR Current Condition:	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspec Silt Trap Pending - Sediment trap will Streets Good Condition - The streets "I certify, under penalty of law direction or supervision in acc properly gathered and evalua	3, 8/24/23, 10/20/23 On Site Cor installed the SWPP Don Site be installed once gradin N 264th Street and N 264th Circle were free of track out a v, that this document an cordance with a system ated the information sub	7/6/2023 P sign during the 7/6/23 insp 5/4/2023 g begins in the area. 5/4/2023 as of the most recent inspect d all attachments were prep designed to assure that qua mitted. Based on my inquiry	Active pection. Pending Active tion. ared under my alified personnel y of the person or	No No		
Current Condition: ST X Current Condition: STR Current Condition:	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspec Silt Trap Pending - Sediment trap will Streets Good Condition - The streets "I certify, under penalty of law direction or supervision in acc properly gathered and evalua persons who manage the sys	3, 8/24/23, 10/20/23 On Site ctor installed the SWPP On Site be installed once gradir N 264th Street and N 264th Circle were free of track out a v, that this document an cordance with a system ated the information sub	7/6/2023 P sign during the 7/6/23 insp 5/4/2023 g begins in the area. 5/4/2023 as of the most recent inspect d all attachments were prep designed to assure that qua mitted. Based on my inquiry lirectly responsible for gathe	Active pection. Pending Active tion. ared under my alified personnel of the person or ring the informatio	No No		
Current Condition: ST X Current Condition: STR Current Condition:	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspect Silt Trap Pending - Sediment trap will Streets Good Condition - The streets "I certify, under penalty of law direction or supervision in acc properly gathered and evaluat persons who manage the syst the information submitted is,	3, 8/24/23, 10/20/23 On Site Cor installed the SWPP On Site be installed once gradin N 264th Street and N 264th Circle were free of track out a v, that this document an cordance with a system ated the information sub stem or those persons d to the best of my knowl	7/6/2023 P sign during the 7/6/23 insp 5/4/2023 g begins in the area. 5/4/2023 is of the most recent inspect d all attachments were prep designed to assure that qua mitted. Based on my inquiry lirectly responsible for gathe edge and belief, true, accura	Active pection. Pending Active tion. ared under my alified personnel of the person or ring the informatio ate, and complete.	No No		
Current Condition: ST X Current Condition: STR Current Condition:	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspec Silt Trap Pending - Sediment trap will Streets Good Condition - The streets "I certify, under penalty of law direction or supervision in acc properly gathered and evalua persons who manage the sys the information submitted is, am aware that there are sign	3, 8/24/23, 10/20/23 On Site tor installed the SWPP Don Site be installed once gradin N 264th Street and N 264th Circle were free of track out a v, that this document an cordance with a system ated the information sub stem or those persons d to the best of my knowl ificant penalties for sub	7/6/2023 P sign during the 7/6/23 insp 5/4/2023 g begins in the area. 5/4/2023 is of the most recent inspect d all attachments were prep designed to assure that qua mitted. Based on my inquiry lirectly responsible for gathe edge and belief, true, accura	Active pection. Pending Active tion. ared under my alified personnel of the person or ring the informatio ate, and complete.	No No		
Current Condition: ST X Current Condition: STR Current Condition:	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspect Silt Trap Pending - Sediment trap will Streets Good Condition - The streets "I certify, under penalty of law direction or supervision in acc properly gathered and evaluat persons who manage the syst the information submitted is,	3, 8/24/23, 10/20/23 On Site tor installed the SWPP Don Site be installed once gradin N 264th Street and N 264th Circle were free of track out a v, that this document an cordance with a system ated the information sub stem or those persons d to the best of my knowl ificant penalties for sub	7/6/2023 P sign during the 7/6/23 insp 5/4/2023 g begins in the area. 5/4/2023 is of the most recent inspect d all attachments were prep designed to assure that qua mitted. Based on my inquiry lirectly responsible for gathe edge and belief, true, accura	Active pection. Pending Active tion. ared under my alified personnel of the person or ring the informatio ate, and complete.	No No		
Current Condition: ST X Current Condition: STR Current Condition:	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspect Silt Trap Pending - Sediment trap will Streets Good Condition - The streets "I certify, under penalty of law direction or supervision in acc properly gathered and evalua persons who manage the syst the information submitted is, am aware that there are sign of fines and imprisonment for	3, 8/24/23, 10/20/23 On Site tor installed the SWPP Don Site be installed once gradin N 264th Street and N 264th Circle were free of track out a v, that this document an cordance with a system ated the information sub stem or those persons d to the best of my knowl ificant penalties for sub	7/6/2023 P sign during the 7/6/23 insp 5/4/2023 g begins in the area. 5/4/2023 is of the most recent inspect d all attachments were prep designed to assure that qua mitted. Based on my inquiry lirectly responsible for gathe edge and belief, true, accura	Active pection. Pending Active tion. ared under my alified personnel of the person or ring the informatio ate, and complete.	No No No		
Current Condition: ST X Current Condition: STR Current Condition:	reminded on 6/15/23, 7/27/23 SWPPP Notification Sign Good Condition - E&A inspec Silt Trap Pending - Sediment trap will Streets Good Condition - The streets "I certify, under penalty of law direction or supervision in acc properly gathered and evalua persons who manage the sys the information submitted is, am aware that there are sign	3, 8/24/23, 10/20/23 On Site tor installed the SWPP Don Site be installed once gradin N 264th Street and N 264th Circle were free of track out a v, that this document an cordance with a system ated the information sub stem or those persons d to the best of my knowl ificant penalties for sub	7/6/2023 P sign during the 7/6/23 insp 5/4/2023 ig begins in the area. 5/4/2023 as of the most recent inspect d all attachments were prep designed to assure that qua mitted. Based on my inquiry pirectly responsible for gather edge and belief, true, accura mitting false information inclu	Active pection. Pending Active tion. ared under my alified personnel of the person or ring the informatio ate, and complete.	No No		