E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager E&A CONSULTING GROUP, INC. ENGINEERING • PLANNING • FIELD SERVICES

		E&A- P2008.2	.07.000		
Inspector: Mike Jacobson, CISEC					Stage
Project Name:		E	Bell Brook		3
•			1/14/2012		
For Week Ending: Project Location:	Couthwoot			ha, NE (Sarpy County)	69425
Project Location:	Southwest	corner of 192nd and	Harrison Street- Oma	na, NE (Sarpy County)	68135
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	100%				
Utilities:	100%				
Overall Development:	60%				
	[
RAIN FALL AMOUNTS	Amount in tenths	Date inspected			Weel
Sunday:	0.00"				Wee
Monday	0.00"				
Tuesday	0.20"			1	
Wednesday	0.18"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Wee
Sunday:	0.00"				
Monday	0.00"				
Tuesday Wadaaaday	0.00"				
Wednesday Thursday	0.00" 0.01"				
Friday	0.00"				
Saturday	0.00"				
outuruty	0.00				Wee
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.01"				
Saturday	0.06"				Mee
Cum days	0.00"				Wee
Sunday: Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"			1	
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Weel
Sunday:	0.00"				
Monday	0.00"	01/09/12			
Tuesday	0.00"				
Wednesday	Trace				
Thursday	Trace				
Friday	0.00"				
Saturday	0.00"	ļ	-	ļ	Į
	None				
Complaints:					
•					
Construction Sequencing:	•				
Which portion(s) (i.e. drainage basins) of the si	te have had a temporary of	r permanent cessation of	grading, earthwork, or grou	nd disturbance in the last 14 days?	•
Entire Site; grading completed and site s	seeded prior to 4/2008				
		1			
		1			

Which portion(s) (i.e. drainage basins) of the s	ite do not have grading, earth	work, or ground disturba	nce scheduled in the next 1	l4 days? :				
Entire Site; grading completed and site	cooded prior to 1/2008							
Entite Site, grading completed and site	seeded pilot to 4/2006.							
What temporary or permanent stabilization me								
Existing Vegetation (4/2008), Harrison Seeding and Matting on the hill south or (05/09), Silt Basin 3 seeded and matter	f the ROW between 197th	n and 199th St. (9/08),	seeding and matting o	n outlot 'O' (3/09), removed I	basin 8 seeded			
Comments:								
Comments: Comments: Home construction is active in many are	eas of the development.							
Findings / Corrective Actions (Date):	•							
Findings / Corrective Actions (Date): 1) Some maintenance is required in the								
			Designed a la stall					
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
onque Name	Concrete	Location	Date	Olalus	Maintenance			
CW 1	Washout	Lot 393	11/4/2010	Active	No			
Current Condition:	Good Condition	201000	11/ 1/2010	7,01170	110			
	Washout was clean	ed out prior to inspec	tion on 6/18/11 by Chao	d with Synergy.				
Lot 42	Silt Fence	Lot 42	7/6/2011	Active	Yes			
Current Condition:	Fair Condition- Vac		110/2011	7,01170	100			
	Silt fence is full and	Silt fence is full and it needs to be cleaned out.						
	Proline Homes was informed to complete maintenance by 7/13/11. On 8/23/11, 10/3/11, 11/28/11 and again on 1/9/12 Proline homes was reminded that maintenance needs to be completed ASAP.							
Lot 53 Current Condition:	Misc/Other	Lot 53	1/9/2012	Active	Yes			
Current Condition:	Fair Condition Active Home construction on the lot.							
	One area is full and it needs to be cleaned out. A few area are down/damaged and needs to be replaced.							
	Zych construction w	as informed to compl	ete maintenance by 1/1	6/12.				
Lot 87	Silt Fence	Lot 87	7/6/2011	Active	No			
Current Condition:	Good Condition- Active home construction on lot. A berm was installed on the back of the lot prior to inspection on 7/6/11 by Proline Homes.							
	A berm was installe	d on the back of the le	ot prior to inspection on	7/6/11 by Proline Homes.				
Lot 93	Silt Fence	Lot 93	5/14/2011	Active	Yes			
Current Condition:	Fair Condition- Vac	ant Lot (There is a fe	w rows of silt fence on t	this lot.)				
	1) The East section of the lot has down/damaged silt fence and it needs to be removed. (Note: This silt fence was							
	installed by the builder from lot 94.)							
	2) The West section of the lot has down/damaged silt fence and it needs to be removed. (Note: This silt fence was							
	installed by the builder from lot 92.)							
	1) Builder Proline H	omes was informed to	o complete maintenanc	e by 1/16/12.				
			complete maintenance					
Lot 111	Misc/Other	Lot 111	11/3/2011	Active	Yes			
Current Condition:		ive Home construction						
	Maintenance was c	ompleted prior to insp	ection on 1/9/12 by KR	I construction.				
	A few areas are dow	wn/damaged and it ne	eds to be replaced. On	e area is full and it needs to	be cleaned out.			
		Ŭ						
	KRT Construction w	as informed to compl	ete maintenance by 1/1	16/12.				
Lot 208	Silt Fence	Lot 208	8/5/2011	Active	No			
Current Condition:		tive Home construction						
	Dirt was removed p	rior to inspection on 8	/7/11 by Proline Homes	5.				
Lot 233	Misc/Other	Lot 235	8/14/2011	Active	No			
Current Condition:		ctive Home constructi		Proline Homes				
1	Dirt in the R.O.W. W	vas removed prior to l	nspection on 8/30/11 by	y FIUILLE HULLES.				

Lot 236 Current Condition:	Misc/Other Pending - Active H	Lot 236	8/5/2011	Active	Ye		
current condition.	Pending Active Home construction on the lot. Dirt in the R.O.W. was removed prior to inspection on 8/30/11 by Proline Homes.						
	Silt fence needs to	be installed on the No	ortheast corner of the lot.				
				. Maintenance not comple en days is given to compl			
				ions therefore another sev			
				lue to wet and muddy con			
				 On 10/3/11 Proline Horr pleted as of last inspection 			
			nded to complete overdue				
Lot 245	Silt Fence	Lot 245	8/8/2011	Active	N		
Current Condition:	Good Condition- V Maintenance was		ection on 8/30/11 by Prol	ine Homes.			
Lot 304	Misc/Other	Lot 304	8/5/2011	Active	Ye		
Current Condition:		or to inspection on 11		Active			
	Due to active home	e construction on this I	ot the Outlot needs to be	re-seeded.			
	On 11/28/11 HBC	was informed to comp	ete maintenance by 12/5/	(11. Maintenance not com	pleted as of		
		winter conditions this i	maintenance will need to l	be completed when condi	tions allow in		
	spring.				1		
Lot 339	Silt Fence	Lot 339	11/21/2011	Active	N		
Current Condition:		ctive Home constructi		Active	IN		
	Silt fence is installe	ed along the back of th	e lot prior to inspection or	n 11/28/11			
Lot 346	Silt Fence	Lot 346	5/20/2011	Active	N		
Current Condition:	Good Condition- V Silt fence installed		prior to inspection on 5/22	20/2011 by Bob Roth.			
Lot 347	Silt Fence	Lot 347	5/20/2011	Active	N		
Current Condition:	Good Condition- V		•				
	Silt fence installed	on the back of the lot	prior to inspection on 5/22	20/2011 by Bob Roth.			
Lot 356	Silt Fence	Lot 356		Removed			
Current Condition:	Lot was sodded pr	or to inspection on 11.	/3/11 by Butch Michael Ho	omes.	_		
Lot 438	Misc/Other	Lot 438	1/9/2012	Active	Ye		
Current Condition:	Pending- Active ho	me construction on the	e lot				
	Silt fence needs to be installed on the back of the lot.						
	John Caniglia was	informed to complete	maintenance by 1/16/12.				
Lot 457	MicerOther	1 01 457	1/0/2010	Active			
Lot 457 Current Condition:	Misc/Other Pending- Active ho	Lot 457 me construction on the	1/9/2012	Active	Ye		
Ganeni Condition:							
	Silt fence needs to be installed on the back of the lot.						
	Barr Homes was informed to complete maintenance by 1/16/12.						
		N41d00m00s					
SB 3	Sediment Basin	W96d00m00s		Removed			
Current Condition:	Basin has been re	moved and seeded ar	d matted prior to inspection	on on 4/17/11 by Beaver I	Excavation.		
	October 10	N41d00m00s	In Division	A - 4			
SB 4 Current Condition:	Sediment Basin Good Condition- 24	W96d00m00s 4% Filled	In Place	Active	N		
callon condition.			n area by Commercial Se	eding prior to inspection of	on 8/16/09.		
		N41d00m00s	1		1		
SB 5	Sediment Basin	W96d00m00s		Removed			
Current Condition:	Removed		•I		•		
		N41d00m00s	<u>т</u>				
SB 6	Sediment Basin	W96d00m00s	In Place	Active	N		
0.00							

		N41d00m00s					
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- 29	Good Condition- 2% Filled					
		Basin was cleaned out prior to inspection on 6/18/11 by Bob Roth.					
	The outlet pipe was buried and extended to the creek area prior to inspection on 10/3/11 by Tim Geis.						
		N41d00m00s					
SB 8	Sediment Basin	W96d00m00s		Removed			
Current Condition:			o inspection on 5-13-09	Silt fence has been install	ed on the toe of th		
	slope, and the area seeded.						
		N41d00m00s					
SB 9	Sediment Basin	W96d00m00s		Removed			
Current Condition:	Removed	Removed					
		N41d00m00s					
SF 1	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed due to de	Removed due to dense vegetation					
		N41d00m00s					
STR	Streets	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- N	Good Condition- No major signs of track off.					
					No		
SWPPP Sign	SWPPP Sign	5 signs	8-19-08	Active			
Current Condition:	Good condition						
	PQP			Tak	and Alle		
or's Signature:	1 Jawan	Reviewed By: Zachary K. Julk					