E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Matthew Russell		E&A- P2008.			Stage	
	Bell Brook				3	
Project Name:		NER111506				
For Week Ending:		<u> </u>	6/10/2017			
Project Location:	Southwes	68028				
Tojoot Location.	Counting	or corner or regina uni	a mamoon on ou ou	ia, itz (daipy ddaity)	68028	
Grading:	1000					
Sanitary Sewer:	100°					
Storm Sewer:	1000					
Paving:	1009					
Seeding: Utilities:	100°					
Overall Development:	820					
		, , ,				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions			
Sunday:	0.00"	1				
Monday	0.00"					
Tuesday Modnosday	1.43" 0.11"	05/17/17	76/64 Clouds			
Nednesday Fhursday	0.45"	05/1//1/	76/61 Cloudy			
rnursday Friday	0.45	05/19/17	56/50 Cloudy			
Saturday	0.00"	30/10/11	- Co.Co Cloudy			
					Wee	
Sunday:	0.01"					
Monday	0.35"	05/22/17	73/51 P. Cloudy			
Tuesday	0.08"					
Wednesday	0.00"					
Thursday	0.00"					
Friday Saturday	0.00" 0.22"					
saturday	0.22				Wee	
Sunday:	0.00"				Woo	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.03"					
Saturday	0.00"				West	
Sunday:	0.00"				Wee	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"	06/08/17	Clear 88/58			
Friday	0.01"					
Saturday	0.00"					
	- Inve				Wee	
Sunday:	N/A					
Monday Tuesday	N/A N/A					
Nednesday	N/A N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					
	None					
Complaints:						
		•	<u> </u>	·		
Which portion(s) (i.e. drainage basins) of the			f grading, earthwork, or groui	nd disturbance in the last 14 days?		
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the Entire Site; grading completed and sit			f grading, earthwork, or grou	nd disturbance in the last 14 days?		
Which portion(s) (i.e. drainage basins) of the	e seeded prior to 4/200	08.				

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (4/2008), Harrison St. ROW between 201st and 197th St seed and matting by Sarpy County (8/19/08)

Seeding and Matting on the hill south of the ROW between 197th and 199th St. (9/08), seeding and matting on outlot 'O' (3/09), removed basin 8 seeded (05/09), Silt Basin 3 seeded and matted (4/2011); Disturbed area behind sediment basin #7 was re-seeded/matted(10/2011); lots 331-335;340-345 were reseeded(6/5/12); Basin #7 area was seeded and the area where the outfall was removed was matted (4/29/2014).

SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes

CHECKLIST QUESTIONS:

terial, hazardous, etc.) being managed properly?

Yes

Yes

Comments:

Comments:

Home construction is active in a few areas of the development as of the last inspections.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP section.

			Projected Install		1
Unique Name	Туре	Location	Date	Status	Maintenance
	Concrete				
CW 1	Washout	Lot 393		Removed	
Current Condition:			pit prior to 11/13/2015.		
Lot 10	Silt Fence	Lot 10		Removed	
Current Condition:	Removed - Oakwoo	od Homes sodded the	lot prior to the 6/25/15 ins	spection.	
Lot 20	Silt Fence	Lot 20		Removed	
Current Condition:	Removed-				
Lot 23	Misc/Other	Lot 23	T T	Removed	T
Current Condition:			e lot prior to 9/9/2015.	rtemoved	
Lot 30	Misc/Other	Lot 30		Removed	
Current Condition:			els behind the lot prior to		115
	Silt Fence	Lot 32	T Defind the lot prior to	Removed	10.
Lot 32			1 0/05/0045	Removed	
Current Condition:			ne lot prior to 9/25/2015.		
Lot 41	Silt Fence	Lot 41		Removed	
Current Condition:			lot prior to 9/25/2015.		
Lot 46	Silt Fence	Lot 46		Removed	
Current Condition:		odded the lot prior to	5/12/2015.		
Lot 54	Individual Lot	Lot 54		Removed	
Current Condition:	Removed- Proline I	Homes sodded the lot	prior to 4/21/2016.		
Lot 78	Silt Fence	Lot 78		Removed	
Current Condition:	Removed- Outlot C	has been come esta	blished as of 6/12/2015.		
Lot 88	Individual Lot	Lot 88		Removed	
Current Condition:		lomes sodded the lot	prior to 4/21/2016	7.007.04	-
Lot 135	Silt Fence	Lot 135		Removed	
Current Condition:		sodded by Landmark	prior to 6/12/2015	rtomovou	
Lot 138	Silt Fence	Lot 138		Removed	
Current Condition:		t sodded the lot prior	to 9/12/2016	removed	
Lot 149	Individual Lot	Lot 149	I I	Removed	
			1.1		
Current Condition:			lot prior to the 10/24/16 in		
Lot 247	Misc/Other	Lot 247		Removed	
Current Condition:			ot prior to the 5/5/15 inspe		
Lot 269	Silt Fence	Lot 269		Removed	
Current Condition:			lot prior to 9/25/2015.		
Lot 301	Silt Fence	Lot 301		Removed	
Current Condition:			l in area was sodded prior		/2015.
Lot 306	Silt Fence	Lot 306		Removed	
Current Condition:	Removed-Landmar	k Homes sodded the	lot prior to 11/23/2016.		
Lot 308	Silt Fence	Lot 308		Removed	
Current Condition:	Removed- Lot was	sodded by Woodland	ls prior to 6/12/2015.		
Lot 314	Silt Fence	Lot 314		Removed	
Current Condition:			lot prior to 11/23/2016.		·
Lot 315	Silt fence	Lot 315	1.51 p51 to 11/20/2010.	Removed	
Current Condition:			lot prior to the 5/5/15 ins		1
Lot 320	Silt Fence	Lot 320		Removed	
Current Condition:		sodded by Landmark	prior to 11/2/2015	removed	
			•		
Lot 322	Silt Fence	Lot 322	12/27/2016	Active	Yes
Current Condition:	Silt fence in the real	r and extending to t	of the lot was removed pr he side needs to be repa lete by 3/3/2017. Not done	uired/cleaned out.	

1 -4 204	Cilk famas	1 -4 204		Damassad	
Lot 324 Current Condition:	Silt fence	Lot 324	 	Removed	
Lot 333	Silt Fence	s sodded by Landmark I Lot 333	Tomes prior to 8/29/20	Removed	
Current Condition:			Hamas prior to 6/20/20)16. Trail was cleaned up by	Landmark Hamas
Current Condition.					Landinark nomes
1 1001	•		west is vegetated as of	f the 10/24/16 inspection.	
Lot 334	Individual Lot	Lot 334	1	Removed	
Current Condition:		ark Homes sodded the	lot prior to 12/15/2015.		
Lot 335	Silt Fence	Lot 335		Removed	
Current Condition:		Homes removed the sil	It fence prior to 9/9/201		
Lot 340	Silt Fence	Lot 340		Removed	
Current Condition:		s sodded by Landmark	Homes prior to 8/5/201		
Lot 347	Silt Fence	Lot 347		Removed	
Current Condition:	Removed-Landma Silt fence	ark Homes sodded the I	ot prior to inspection of		
Lot 348		Lot 348	11	Removed	
Current Condition: Lot 360	Silt Fence	s sodded by Landmark Lot 360	Homes prior to 6/18/20	Removed	
		Homes sodded the lot p		Removed	
Current Condition: Lot 361	Silt Fence	Lot 361	101 10 10/7/2016.	Removed	
Current Condition:		Construction sodded the	Lot prior to 6/12/2015		
Lot 364	Silt Fence	Lot 364	3 101 prior to 6/12/2015.	Removed	
		ssance Builders sodded	the let prior to 2/25/20		
Current Condition: Lot 366	Silt Fence	Lot 366	The lot prior to 2/25/20	Removed	
			Lot prior to 10/7/2016	Removed	
Current Condition: Lot 370	Silt fence	ark Homes sodded the I Lot 370	οι ρποι το 10///2016.	Removed	
Current Condition:		ark Homes sodded the I	lot prior to 10/7/2016	removed	
			υι ριτοι το 10///2016. Τ		
Lot 372	Silt Fence	Lot 372		Removed	
Current Condition:		and Homes sodded the	lot prior to 6/3/2016.		
Lot 374	Silt fence	Lot 374		Removed	
Current Condition:		tone Custom Builders so	odded the lot prior to th		
Lot 378	Silt Fence	Lot 378	1.4	Removed	
Current Condition:		nark Homes sodded the	lot prior to the 5/5/15 i		
Lot 384	Silt Fence	Lot 384		Removed	
Current Condition:		s sodded by Landmark	prior to 6/12/2015.		
Lot 390	Silt fence	Lot 390		Removed	
Current Condition:	Removed - Trade	mark Homes sodded the	e lot prior to the 12/26/	16 inspection.	
Lot 391	Silt Fence	Lot 391		Removed	
Current Condition:		s sodded by Landmark	prior to 6/12/2015.		
Lot 392	Silt Fence	Lot 392		Removed	
Current Condition:	Removed- Lot wa	s sodded by Landmark	prior to 6/12/2015.	-	
Lot 393	Silt fence	Lot 393		Removed	
Current Condition:	Removed-Landma	ark Homes sodded the I	ot prior to inspection or	n 6/3/2016.	
Lot 398	Silt Fence	Lot 398		Removed	
Current Condition:	Removed - Landn	nark Homes sodded the	lot prior to the 12/26/1	6 inspection.	
Lot 399	Silt Fence	Lot 399		Removed	
Current Condition:			e lot prior to the inspec	tion on 7/24/2014. Lot 399 w	ill be removed as o
	11/2/2015. See Lo				
Lot 421	Silt Fence	Lot 421		Removed	
Current Condition:		land Homes sodded the	lot prior to the 5/5/15		
Lot 431	Individual Lot	Lot 431	lot prior to the 3/3/13	Removed	
Current Condition:		s sodded by the homeov	wher prior to 6/3/2016	rtemoveu	
Current Condition.					
	Silt Fence	I of 432	When prior to 0/3/2010.	Removed	
Lot 432	Silt Fence	Lot 432	·	Removed	
Lot 432 Current Condition:	Removed- D&E C	ustom Homes sodded t	the lot prior to 4/21/201	5.	Vac
Lot 432 Current Condition: Lot 461	Removed- D&E C Silt Fence	ustom Homes sodded t Lot 461	the lot prior to 4/21/201 12/17/2014	5. Active	Yes
Lot 432 Current Condition:	Removed- D&E C Silt Fence	ustom Homes sodded t	the lot prior to 4/21/201 12/17/2014	5. Active	Yes
Lot 432 Current Condition: Lot 461	Removed- D&E C Silt Fence Fair Condition-The	Lustom Homes sodded t Lot 461 e stockpile was remove	the lot prior to 4/21/201 12/17/2014 d from the ROW as of	5. Active the 5/23/17 inspection.	Yes
Lot 432 Current Condition: Lot 461	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs	Lustom Homes sodded to Lot 461 e stockpile was remove s to be installed on the s	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the r	5. Active the 5/23/17 inspection.	Yes
Lot 432 Current Condition: Lot 461	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs	Lustom Homes sodded t Lot 461 e stockpile was remove	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the r	5. Active the 5/23/17 inspection.	Yes
Lot 432 Current Condition: Lot 461	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs	Lustom Homes sodded to Lot 461 e stockpile was remove s to be installed on the s to be removed from the	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the readjacent east lot.	5. Active the 5/23/17 inspection. northeast corner.	
Lot 432 Current Condition: Lot 461	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Hom	Lustom Homes sodded to Lot 461 e stockpile was remove s to be installed on the s to be removed from the swas informed to content to the swas informed to content to the swas informed to content to the swas informed to con	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the readjacent east lot.	5. Active the 5/23/17 inspection.	
Lot 432 Current Condition: Lot 461	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Homreminded on 5/2/1	Lustom Homes sodded to Lot 461 e stockpile was remove so to be installed on the so to be removed from the sound to content to the sound to content to cont	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the rie adjacent east lot.	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W	oodland Homes wa
Lot 432 Current Condition: Lot 461	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Homreminded on 5/2/1	Lot 461 e stockpile was remove s to be installed on the s s to be removed from the nes was informed to con 17. hes was informed to con 18.	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the rie adjacent east lot.	5. Active the 5/23/17 inspection. northeast corner.	oodland Homes wa
Lot 432 Current Condition: Lot 461	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Hom reminded on 5/2/1 2. Woodland Hom	Lot 461 e stockpile was remove s to be installed on the s s to be removed from the nes was informed to con 17. hes was informed to con 18.	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the rie adjacent east lot.	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W	oodland Homes wa
Lot 432 Current Condition: Lot 461 Current Condition:	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Hom reminded on 5/2/1 2. Woodland Hom reminded on 5/2/1 Silt Fence	ustom Homes sodded to Lot 461 e stockpile was remove so to be installed on the so to be removed from the sound in the soun	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the rie adjacent east lot. inplete by 4/26/17. Not implete by 4/26/17. Not	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W	oodland Homes wa
Lot 432 Current Condition: Lot 461 Current Condition:	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Hom reminded on 5/2/1 2. Woodland Hom reminded on 5/2/1 Silt Fence	Lustom Homes sodded to Lot 461 e stockpile was remove sto be installed on the stockpile was informed to control to the stockpile was informed to control.	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the rie adjacent east lot. inplete by 4/26/17. Not implete by 4/26/17. Not	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W	oodland Homes wa
Lot 432 Current Condition: Lot 461 Current Condition: Lot 463 Current Condition:	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Homreminded on 5/2/1 2. Woodland Homreminded on 5/2/1 Silt Fence Removed- Landm	ustom Homes sodded to Lot 461 e stockpile was remove so to be installed on the so to be removed from the solution of the solut	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the rie adjacent east lot. inplete by 4/26/17. Not implete by 4/26/17. Not	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W Removed on 5/11/17.	oodland Homes wa
Lot 432 Current Condition: Lot 461 Current Condition: Lot 463 Current Condition: Lot 464	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Hom reminded on 5/2/1 2. Woodland Hom reminded on 5/2/1 Silt Fence Removed- Landm Silt Fence	Lot 461 Lot 461 e stockpile was remove s to be installed on the s s to be removed from the nes was informed to con 17. Lot 463 Lot 464 Lot 464	the lot prior to 4/21/201 12/17/2014 defrom the ROW as of side of the lot and the readjacent east lot. Implete by 4/26/17. Not implete by 4/26/17. Not implete by 4/26/17.	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W Removed on 5/11/17. Removed	oodland Homes wa
Lot 432 Current Condition: Lot 461 Current Condition: Lot 463 Current Condition: Lot 464 Current Condition:	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Hom reminded on 5/2/1 2. Woodland Hom reminded on 5/2/1 Silt Fence Removed- Landm Silt Fence Removed - Landm	Lot 463 Lot 464 Lot 464 Lot 464 Lot 464 Lot 467 Lot 467 Lot 468 Lot 468 Lot 464 Lot 46	the lot prior to 4/21/201 12/17/2014 defrom the ROW as of side of the lot and the readjacent east lot. Implete by 4/26/17. Not implete by 4/26/17. Not implete by 4/26/17.	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W Removed on 5/11/17. Removed	oodland Homes wa
Lot 432 Current Condition: Lot 461 Current Condition: Lot 463 Current Condition: Lot 464 Current Condition: Lot 464 Current Condition: Lot 482	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Homereminded on 5/2/1 2. Woodland Homereminded on 5/2/1 Silt Fence Removed- Landm Silt Fence Removed - Landm Silt Fence	Lot 461 Lot 461 e stockpile was remove s to be installed on the s s to be removed from the nes was informed to con 17. Lot 463 Lot 464 Lot 464 Lot 464 Lot 482	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the readjacent east lot. Inplete by 4/26/17. Not	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W Removed on 5/11/17. Removed inspection. Removed	oodland Homes wa
Lot 432 Current Condition: Lot 461 Current Condition: Lot 463 Current Condition: Lot 464 Current Condition: Lot 482 Current Condition:	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Homereminded on 5/2/1 2. Woodland Homereminded on 5/2/1 Silt Fence Removed- Landm Silt Fence Removed - Landn Silt Fence Removed - Landn Removed - Landn	Lot 463 Lot 464 Lot 464 Lot 464 Lot 465 Lot 465 Lot 466 Lot 466 Lot 466 Lot 466 Lot 466 Lot 466 Lot 482	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the readjacent east lot. Inplete by 4/26/17. Not side of prior to inspection of lot prior to the 7/31/15 lot prior to the 7/31/15 lot prior to 6/12/201	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W Removed on 5/11/17. Removed inspection. Removed 5.	oodland Homes wa
Lot 432 Current Condition: Lot 461 Current Condition: Lot 463 Current Condition: Lot 464 Current Condition: Lot 482 Current Condition: STR	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Hom reminded on 5/2/1 2. Woodland Hom reminded on 5/2/1 Silt Fence Removed- Landm Silt Fence Removed- Landm Silt Fence Removed- Lot was Streets	Lot 461 Lot 461 e stockpile was remove s to be installed on the s s to be removed from the nes was informed to con 17. Lot 463 Lot 464 Lot 464 Lot 464 Lot 482	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the readjacent east lot. Inplete by 4/26/17. Not	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W Removed on 5/11/17. Removed inspection. Removed	oodland Homes wa
Lot 432 Current Condition: Lot 461 Current Condition: Lot 463 Current Condition: Lot 464 Current Condition: Lot 482 Current Condition:	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Homereminded on 5/2/1 2. Woodland Homereminded on 5/2/1 Silt Fence Removed- Landm Silt Fence Removed - Landn Silt Fence Removed - Landn Removed - Landn	Lot 463 Lot 464 Lot 464 Lot 464 Lot 465 Lot 465 Lot 466 Lot 466 Lot 466 Lot 466 Lot 466 Lot 466 Lot 482	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the readjacent east lot. Inplete by 4/26/17. Not side of prior to inspection of lot prior to the 7/31/15 lot prior to the 7/31/15 lot prior to 6/12/201	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W Removed on 5/11/17. Removed inspection. Removed 5.	oodland Homes wa
Lot 432 Current Condition: Lot 461 Current Condition: Lot 463 Current Condition: Lot 464 Current Condition: Lot 482 Current Condition: STR	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Hom reminded on 5/2/1 2. Woodland Hom reminded on 5/2/1 Silt Fence Removed- Landm Silt Fence Removed- Landm Silt Fence Removed- Lot was Streets Fair Condition-	Lot 461 Lot 461 e stockpile was remove s to be installed on the s s to be removed from the s to be removed fr	the lot prior to 4/21/201 12/17/2014 defrom the ROW as of side of the lot and the readjacent east lot. Inplete by 4/26/17. Not inplete by 4/26/17. No	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W Removed on 5/11/17. Removed inspection. Removed 5. Active	oodland Homes water to the control of the control o
Lot 432 Current Condition: Lot 461 Current Condition: Lot 463 Current Condition: Lot 464 Current Condition: Lot 482 Current Condition: STR	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Homereminded on 5/2/1 2. Woodland Homereminded on 5/2/1 Silt Fence Removed- Landm Silt Fence Removed- Landm Silt Fence Removed- Lot was Streets Fair Condition- 1. Sediment was of	Lot 461 e stockpile was remove s to be installed on the s s to be removed from the s s was informed to consider the s Lot 463 lark Homes sodded the Lot 464 nark Homes sodded the Lot 482 s sodded by Marasco H Streets	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the readjacent east lot. Inplete by 4/26/17. Not side of prior to inspection of lot prior to the 7/31/15 lot prior to the 7/31/15 lot prior to 6/12/201 In Place	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W Removed on 5/11/17. Removed inspection. Removed 5. Active	oodland Homes water to the control of the control o
Lot 432 Current Condition: Lot 461 Current Condition: Lot 463 Current Condition: Lot 464 Current Condition: Lot 482 Current Condition: STR	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Homereminded on 5/2/1 2. Woodland Homereminded on 5/2/1 Silt Fence Removed- Landm Silt Fence Removed- Landm Silt Fence Removed- Lot was Streets Fair Condition- 1. Sediment was of	Lot 461 e stockpile was remove s to be installed on the s s to be removed from the s s was informed to consider the s Lot 463 lark Homes sodded the Lot 464 nark Homes sodded the Lot 482 s sodded by Marasco H Streets	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the readjacent east lot. Inplete by 4/26/17. Not side of prior to inspection of lot prior to the 7/31/15 lot prior to the 7/31/15 lot prior to 6/12/201 In Place	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W Removed on 5/11/17. Removed inspection. Removed 5. Active	oodland Homes water to the control of the control o
Lot 432 Current Condition: Lot 461 Current Condition: Lot 463 Current Condition: Lot 464 Current Condition: Lot 482 Current Condition: STR	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Hom reminded on 5/2/1 2. Woodland Hom reminded on 5/2/1 Silt Fence Removed- Landm Silt Fence Removed - Landn Silt Fence Removed- Lot wa Sitreets Fair Condition- 1. Sediment was 6 2. Sediment was 6	Lot 461 e stockpile was remove s to be installed on the s s to be removed from the nes was informed to con 17. Lot 463 eark Homes sodded the Lot 464 nark Homes sodded the Lot 482 s sodded by Marasco H Streets	the lot prior to 4/21/201 12/17/2014 d from the ROW as of side of the lot and the readjacent east lot. Implete by 4/26/17. Not	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W Removed on 5/11/17. Removed inspection. Removed 5. Active	Yes
Lot 432 Current Condition: Lot 461 Current Condition: Lot 463 Current Condition: Lot 464 Current Condition: Lot 482 Current Condition: STR	Removed- D&E C Silt Fence Fair Condition-The 1. Silt fence needs 2. Sediment needs 1. Woodland Hom reminded on 5/2/1 2. Woodland Hom reminded on 5/2/1 Silt Fence Removed- Landm Silt Fence Removed- Landm Silt Fence Removed- Landm Silt Fence Removed- Landm Silt Fence Removed- Loudn Silt Fence Removed- Lou	Lot 461 Lot 461 e stockpile was remove s to be installed on the s s to be removed from the s ses was informed to con 17. Lot 463 Lark Homes sodded the Lot 464 Lot 464 Lot 482 s sodded by Marasco H Streets	the lot prior to 4/21/201 12/17/2014 Id from the ROW as of side of the lot and the readjacent east lot. Inplete by 4/26/17. Not inplete by 4/26/17.	5. Active the 5/23/17 inspection. northeast corner. done as of last inspection. W done as of last inspection. W Removed on 5/11/17. Removed inspection. Removed 5. Active	Yes ds removed.

Current Condition:	Good Condition- E&A inspector reinstalled the SWPPP sign at 197th and Harrison during the inspection on 4/11/2014.			
pa	eno		Get Sie	
Inspector's Signature:			Reviewed By:	