Inspector: Mike Jacobsor		002.153.000	T	Stage
Project Name:		marron Woods	s	3
For Week Ending:	3/8/2008			
		1		
Grading:	100%			
Sanitary Sewer: Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
Overall Development:	61%			
RAIN FALL AMOUNTS	Amount in inches	Date inspected		
Sunday:	0.00"			Week 1
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			-W
Sunday:	0.01"			Week 2
Monday:	0.00"	1		
Tuesday	0.00"	1		
Wednesday	0.00"	1		
Thursday	0.00"	02/21/08		
Friday	0.00"	02/22/08		
Saturday	0.00"			Wasta
Sunday:	0.00"			Week 3
Monday	0.28"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			Week 4 / 5
Sunday:	0.12"			Week 4/3
Monday	0.00"			
Tuesday	0.00"	03/04/08		
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.02"			
Saturday	0.00"			
Complaints:	None			
Construction Sequencing				
	asins) of the site have had a tempor	ary or permanent cessat	ion of grading, earthwork, or g	round disturbance in
the last 14 days? Entire site, grading complet	ed and stabilized prior to Spri	ng 2005.		
Which portion(s) (i.e. drainage ba	asins) of the site do not have gradin	g, earthwork, or ground	disturbance scheduled in the r	ext 14 days? :
Entire site, grading complet	ed and stabilized prior to Spri	ng 2005.		
	abilization measures listed in this see-seeding in Spring 2005), se			ng. (Some re-
Comments:				
Comments:				
Home construction is active	through out the site.			
Findings / Corrective Acti				
Findings / Corrective Acti				
No required maintenance	• •			
., roquirou maintenante	o Divir occitori.			

						Description of	
			Projected Install			Maintenance/Activity:	
Unique Name	Type	Location	Date	Status	Maintenance		

05.4	Oznatnicki 5 :	N41d00m00s		Dan I		Repairs
CE 1 Current Condition:	Construction Entrance Entrance Paved.	W96d00m00s	l	Removed		Needed/Planned
		N41d00m00s				
IF 1	Inlet Filters	W96d00m00s	an and continual alor	Removed		
Current Condition:	Removed, due to problems		on and continual stop	De erosion.		
IE o	Inlet Citero	N41d00m00s		Damayad		
IF 2	Inlet Filters Removed, due to problems	W96d00m00s	on and continual alor	Removed		
Current Condition:	Removed, due to problems		on and continual stop	De erosion.		
CD 1	Codiment Bosin	N41d00m00s W96d00m00s	In Diago	Activo	No	
SB 1 Current Condition:	Sediment Basin  Good Condition- 40% Filled		In Place	Active	No	
Current Condition:	Sediment Basin to be close		eneant nand this car	estruction season by	developer due	
	to drainage area meeting st					
	since basins meets require	mnts to be closed it will	be left as for now.			
		N41d00m00s		1		
SB 2	Sediment Basin	W96d00m00s		Removed		
Current Condition:	Removed due to lot develo			Removed		
Current Condition.	Removed due to lot develo	N41d00m00s	1			
SB 3	Sediment Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition- 10% Filled		III Flace	Active	INU	
Current Condition:	Cleaned on 1/19/05 by Tim		also repaired at time	of cleaning		
	3.0404 On 1, 10,00 by 11111	N41d00m00s				1
SB 4	Sediment Basin	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - 10% Fille		11111400	710070	140	
	Cleaned on 5/05 by BHIM		pe on 5/30/07.			
		N41d00m00s				
SF 1	Silt Fence	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - Partially r					
	Maintanced 7/05 by BHI					
		N41d00m00s				
SF 2	Silt Fence	W96d00m00s		Removed		
Current Condition:	Removed; due to lot develo	pment				1
		N41d00m00s				1
SF 3	Silt Fence	W96d00m00s		Removed		
Current Condition:	Removed; due to lot develo	pment				
		N41d00m00s				
SF 4	Silt Fence	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - Portions of -Maintenanced 7/26/07 by .		removed for trail con	struction.		
		N41d00m00s				
SF 5	Silt Fence	W96d00m00s	In Place	Active	No	
Current Condition:	Good Condition - Portions of	of silt fence have been	removed for trail con	struction.		
	Maintanced 4/2007 by BHI					
	<b>-</b>	N41d00m00s				
SF 6	Silt Fence	W96d00m00s	In Place	Active	No	4
Current Condition:	Good Condition - Portions of		removed for trail con	struction.		
	-Maintenanced 7/26/07 by		T			4
05.5	0:11 =	N41d00m00s	. 5:			
SF 7	Silt Fence	W96d00m00s	In Place	Active	No	4
Current Condition:	Good Condition - Portions of		removed for trail con	struction.		
	-Maintenanced 7/26/07 by		<u> </u>	1		
OT 4	On dian and Tone	N41d00m00s		Damad		
ST 1	Sediment Trap	W96d00m00s	<u> </u>	Removed		-
Current Condition:	Removed due to lot develo			<u> </u>		-
OT 0	On the state	N41d00m00s		D		
ST 2	Sediment Trap	W96d00m00s		Removed		4
Current Condition:	Removed due to lot develo		ı	<u> </u>		-
OTD	0, .	N41d00m00s	la Di	A - ::	N/	
STR	Streets	W96d00m00s	In Place	Active	No	-
Current Condition:	Good Condition -No major :	Signs of track-off.	ı		1	1
spector Signature:	Spelect Jawlan		Reviewed By:	Zachany k. Jil	dC	